

Surveyor

REF: (0/LAW18015235 / Uvber

Special Instruction:

ASSIGNMENT (Office)

L/S: \$ 4,400.00

From (Person): Irene Lim of M Nedumaran Date/Time: 20082018

Third Parties:

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

Claimant:

OD/(TP Re-inspection) / Evaluation

Surveyor: Treasure Appraisal & Team

To Inspect Vehicle No: SKT 6078B Insured: PA 8604K

Workshop: Bluwel

at Workshop m/s Bluwel Automotive Tel: 6745 2088

of Blk 1 Kaki Bukit Ave 6 #01-55

Policy No: \_\_\_\_\_ Claim No: MM-TH-BI-1711658

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 04062017

(Client's Record)

~~31.08.2018 (Friday) @ 10am~~  
~~10.09.2018 (Monday) @ 9.30am.~~

H.O.D. Endorsement/Date: \_\_\_\_\_

SJE

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle  IN /  OUT

Date/Time: \_\_\_\_\_ Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_\_ days (Red \$ \_\_\_\_\_ / \_\_\_\_\_ %; Original 6 days)

Date/Time: 12/12 Submit Final Fig 3750, 5 days (Red \$ 650 / 15 %; Original \_\_\_\_\_ days)

Date/Time	Action/Instruction
	SKT 6078B - CS/TP16003258 / Uvber2 PA 8604K - NA/HGB10024078 / r
<u>Soft 4.29pm</u>	<u>Workshop called owner demands cannot make it. Change the appointment to 10/9/2018 9.30am.</u>

D.O.A: 27.02.2016

D.O.A: 27.11.10

RECEIVED 12 DEC 2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value : \_\_\_\_\_  
 Salvage Value : \_\_\_\_\_  
 Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by:

Fee Charged:

Basic & Add  
 Transport  
 Photos  
 Others  
 Total

Date:

1000
1000

- 1) Date/Time 12/12 - typist File Pass to \_\_\_\_\_ 2) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_
- 3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_ 4) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_
- 5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_ 6) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

REF:

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Veh No: **SKT 6078B** Yr Regn: **12 08**  
 Type: **C** M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or **CA**  
 Make: **Toyota Estima** C.C. **2362**  
 Colour: **Blue** A/C: Insured / Std / NI / NA  
 Sp. Reading: **129340** T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **ACR50 0081379**  
 Gen. Cond: **Good** / Fair / Poor / Burnt  
 Steering: **Good** / Jammed / Leaked / Burnt or  
 Brake: **Good** / Jammed / Leaked / Burnt or  
 Modi: **SR** / Nil / STD A/Rim or  
 Tyre Size: F: **235/50R18**  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front **5** mm Rear **5** mm  
 R/Bal. **5** mm R/Bal. **5** mm  
 L/Bal. **5** mm L/Bal. **5** mm  
 D.O.A. **4/6/2017** D.O.I. **10/9/18**  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>Spot run cost PSD under quote. already.</i>
	<i>[Signature]</i>
	<b>12/12/2018</b>

Date/Time. File Pass to?  : Preli. Report  : Final Report

1) \_\_\_\_\_

Date/Time. File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

1) \$ + RS \$ \_\_\_\_\_

2) Photos \_\_\_\_\_

3) Other \_\_\_\_\_

4) \_\_\_\_\_

TOTAL \_\_\_\_\_

Add Fee:  Site Insp (\$)  Interview (\$)  Tech. Invs (\$)  Weekend (\$)

## Catherine Chong (LKK Auto)

---

**From:** Igene Lim <igene.lim@mneduco.com.sg>  
**Sent:** Tuesday, 21 August, 2018 12:18 PM  
**To:** Catherine Chong (LKK Auto)  
**Cc:** 'Celine Fong (LKKAuto)'; Linda Phua  
**Subject:** RE: CHUA KANG SENG - APPOINTMENT AS SINGLE JOINT EXPERT PURSUANT TO ORDER OF COURT DATED 31/07/2018 BY DEPUTY REGISTRAR, KEVIN KWEK TZE HERN | RE-INSPECTION ON SKT 6078B

Our Ref : MN.IG.B1.1711658

Dear Catherine,

Further to our email below, we have made an arrangement for our client's vehicle **SKT 6078B** to be re-inspected by the appointed SJE, Mr Chua Kang Seng on:

**Date** : **31 August 2018 (Friday)**  
**Time** : **10.00 a.m.**  
**Venue** : **Bluwel Automotive Service Pte Ltd**  
**1 Kaki Bukit Avenue 6, #01-55, Autobay**  
**Contact** : **Ms Sally @ 6745-2088**

Kindly ensure that your surveyor attends to the above without fail.

Please also let us have your written confirmation on the above arrangement soon.

With thanks & regards,

Igene Lim

*(For and on behalf of Mr Nedumaran Muthukrishnan)*

**M NEDUMARAN & CO**

**Advocates & Solicitors**

**Commissioner for Oaths**

Branch Office :

No. 11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Tel : 6509-8480 / 6509-8481

Fax : 6509-8482

Email : [igene.lim@mneduco.com.sg](mailto:igene.lim@mneduco.com.sg)

**IMPORTANT NOTE:** This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509-8480 if you have received this message in error. Thank you.

**Catherine Chong (LKK Auto)**

---

**From:** Igene Lim <igene.lim@mneduco.com.sg>  
**Sent:** Monday, 20 August, 2018 4:48 PM  
**To:** Catherine Chong (LKK Auto)  
**Cc:** 'Celine Fong (LKKAuto)'; Linda Phua  
**Subject:** CHUA KANG SENG - APPOINTMENT AS SINGLE JOINT EXPERT PURSUANT TO ORDER OF COURT DATED 31/07/2018 BY DEPUTY REGISTRAR, KEVIN KWEK TZE HERN | RE-INSPECTION ON SKT 6078B  
**Attachments:** 20082018161950.pdf; 20082018162138.pdf; 20082018162205.pdf; 20082018162235.pdf

Our Ref : MN.IG.B1.1711658  
Your Ref : LP/MSIG/2017-0384

**SINGLE JOINT EXPERT FOR THE PLAINTIFF'S MOTOR VEHICLE NO. SKT 6078B  
M C SUIT NO. 15483 OF 2017  
ROAD TRAFFIC ACCIDENT ON 4/6/2017 INVOLVING VEHICLE NOS. SKT 6078B AND PA 8604K**

---

Dear Catherine,

We refer to the above-captioned matter.

We act for the Plaintiff (motor vehicle no. SKT 6078B) and M/s Linda Phua Law Practice acts for the Defendants (motor vehicle no. PA 8604K) in the abovementioned suit arising out of a road traffic accident on 4 June 2017.

Please be informed that by consent of all parties, **MR CHUA KANG SENG** is appointed as a Single Joint Expert ("hereinafter referred to as SJE") for this action to provide an independent assessment in respect of the costs of repairs for vehicle no. SKT 6078B. Mr Chua Kang Seng is to determine the issue on quantum and to draw up an Affidavit of Evidence in Chief (AEIC) annexing a copy of the re-inspection report on the Plaintiff's vehicle SKT 6078B.

Kindly note that as a Single Joint Expert appointed by the Court, your primary duty is to the Court and you are required to give a fair and reasonable assessment of costs for the Plaintiff's motor vehicle SKT 6078B.

We enclose herewith relevant document as follows:

- (1) The Plaintiff and the Defendant's GIA reports;
- (2) Plaintiff's final repair bill;
- (3) Enquire Transfer fees on the Plaintiff's vehicle;
- (4) Plaintiff's surveyor's report by Treasure Appraisal Services;
- (5) 53 coloured photos depicting damage to the Plaintiff's vehicle; and

We would be grateful if your surveyor Mr Chua Kang Seng could let us know whether he will be available to conduct a **physical re-inspection** on the Plaintiff's motor vehicle SKT 6078B.

Thereafter, Mr Chua is required to produce his re-surveyed report, inter alia, the estimated cost of repairs and number of days for repairs to the Plaintiff's motor vehicle, as well as the reason for the same.

Meanwhile, please also let us know the **(1) fees/costs chargeable for the preparation of the re-inspection report; (2) affirmation of the Affidavit of Evidence in Chief** with regard to the Plaintiff's motor vehicle SKT 6078B and **(3) the fees chargeable for the surveyor's attendance in Court** should this matter proceed for a half day hearing.

As the costs/charges would be borne equally by parties, please let us have separate invoices issued to:

- (1) M Nedumaran & Co;
- (2) Linda Phua Law Practice LLC.

Should you require further clarification on the above, please do not hesitate to call our Ms Igene Lim at 66509-8480.

With thanks & regards,

Igene Lim

**M NEDUMARAN & CO**

**Advocates & Solicitors**

**Commissioner for Oaths**

Branch Office :

No. 11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Tel : 6509-8480 / 6509-8481

Fax : 6509-8482

Email : [igene.lim@mneduco.com.sg](mailto:igene.lim@mneduco.com.sg)

**IMPORTANT NOTE:** This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509-8480 if you have received this message in error. Thank you.

MSME17074650 / SME Motor Pte Ltd - Kaki Bukit  
ENTRY DATE & TIME: 06/06/2017 16:39

Your NCD will be affected due to late reporting  
Actual e-Filing Submission Date & Time: 06/06/2017 16:46

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	06/06/2017 16:39
Date Of Accident	04/06/2017 18:00
Exact Location Of Accident	BLK 60A MULTI STOREY CARPARK
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT6078B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MOHAMMAD NAZRIN BIN MUSTAFA
NRIC No	S7707639E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96931239
Alternative Phone No	OFFICE-96931239

#### Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

#### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80404632QMX
Cover Note Number	

#### Driver

Name of Driver	MOHAMMAD NAZRIN BIN MUSTAFA
NRIC No	S7707639E
Date Of Birth	20/03/1977
Occupation	INDOOR
Date Of Driving Pass	22/02/1999
Driving Experience	18 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96931239
Fax Number	
Contact Number	OFFICE-96931239
EEmail Address	NOEMAIL

Address BLK 59C GEYLANG BAHRU #16-3323  
 Postcode 332059  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident DAMAGED WHILST PARKED  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

I PARK MY CAR AT MULTI STOREY CARPARK BLK 60A GEYLANG BAHRU. I PARK ON SAT 03/06/2017 AT 1600HRS. ON 05/06/2017 AT 2100HRS, I REALISED A PAPER ON MY WINDSCREEN. THE PAPER SAY "MY CAR REVERSE HIT YOUR CAR. PLEASE CONTACT 90980466". WHEN I CHECK MY CAR, THE LEFT PASSENGER SIDE GOT DAMAGE. I CALL THE MOBILE NUMBER AND HE ADMIT HE HIT MY CAR AT 1800HRS ON 05/06/2017 WHEN HE TRY TO PARK. HE THEN ASK ME TO MAKE INSURANCE REPORT. NOBODY INJURED.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number PA8604K  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number 90980466  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**Details of Witness**

Name  
 Phone Number  
 Email Address

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to renew policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
 Policyholder's Signature / Date & Time  
 5/6/17 10:15  
 Sketch Plan

  
 Driver's Signature (if driver is not the policyholder) / Date & Time

!  
 Witnessed by Reporting Centre Personnel

B 816 604 604 604

--	--	--	--	--	--	--	--	--	--	--

B 816 604 604 604  


Sketch Plan #2 Pg. 1

Describe Circumstances of the Accident

I park my car at multi story car-park block 60A, Geylang  
Behm. I park on Sat, 3rd Jun at 1600hrs.

On the 5th Jun at 2100h I notice a paper on my  
wind screen. The paper says


" My car reverse hit your car - P/d Contact  
9098 0466 . "


When I check my car, the left passenger side got  
damage. I call the mobile number and he admits  
he hit my car at 1800h on the 5th Jun 2017 when he  
try to park. He then ask me to make insurance report.

Hoburny front impact.

Declaration

We declare the foregoing particulars are true in every respect.

5/06/17  
  
 Policyholder's Signature / Date &  
 Time, 1715h.

  
 Driver's Signature (if driver is not the policyholder) / Date  
 & Time

Witnessed by Reporting Centre Personnel

Insurance Co. msc

Vehicle NO. SE-7 60A55 Date Of Accident 04, 06, 2017

Reporting Only

Own Damage Claim

Third Party Claim BUNWA

D

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/06/2017 17:12
Date Of Accident	04/06/2017 18:00
Exact Location Of Accident	MSCP OF BLK 60A GEYLANG BAHRU
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PA8604K
Insured/Policyholder	
Name Of Registered Owner	SENG CHOON ENGINEERING PTE LTD
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62988633

### Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-3.0 D DX (A)
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28617607MKC
Cover Note Number	

### Driver

Name of Driver	LEE KENG WAH
NRIC No	S1585098A
Address	BLK 461 PASIR RIS DRIVE 4 #09-283

### General Information of the Accident

Type Of Accident	UNKNOWN - REFER TO THE SKETCH PLAN
Weather Conditions	CLEAR

### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	1

### Circumstances of Accident

REFER TO THE SKETCH PLAN

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SKT6078B

Vehicle Make/Model/Colour

Name of Driver

Insurance Company Name

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of thereport being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA) I understand, acknowledge, agree and consent that :
  - (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect use, disclose and/or process my Personal Information for one or more of the above Purpose; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.




Policyholder's Signature / Date &

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre

Sketch Plan



Sketch Plan Pg. 2

Describe Circumstances of the Accident

On 4/6/17 at 1800 hrs, I was reversing my vehicle to park into a car park lot in Blk 60A, Geylang Bahru MSCP. While reversing, the rear side of my vehicle accidentally hit on the front left side of vehicle B. No one was injured in this accident. I left my contact on the underscreen of vehicle B and the owner has contacted me.

Declaration

I/We declare the foregoing particulars are true in every respect.

<input type="checkbox"/> Claim own policy
<input type="checkbox"/> Claim third party
<input type="checkbox"/> Claim OD / TP at other workshop _____
<input checked="" type="checkbox"/> For record purpose
Policy No. <u>KA 28617607 MLC.</u>
Insurer _____ Veh.No. <u>PIA 11041K.</u>



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



# BLUWEL AUTOMOTIVE SERVICE PTE LTD

1 Kaki Bukit Ave 6 Blk C #01-28/53/55/56 Singapore 417883

Tel: 67452088 Fax: 68412088

E-mail: bluwel2088@yahoo.com.sg

GST Reg No.: 200704951N

Co Reg No.: 200704951N

Date: 19/06/2017  
Vehicle No.: SKT6078B  
Model: TOYOTA ESTIMA  
Name: MOHAMMAD NAZRIN BIN MUSTAFA  
Address: BLK 59 GEYLANG BAHRU #16-3323 SINGAPORE 332059

## Repair Bill For SKT6078B

NO.	DESCRIPTIONS	AMOUNT
	LUMP SUM REPAIR	\$ 4,400.00

TOTAL: \$ 4,400.00  
7% GST: \$ 308.00  
**GRAND TOTAL: \$ 4,708.00**

Text size + -

**Enquire Transfer Fee****Vehicle Details**

Vehicle No.: SKT6078B  
 Vehicle Type: P11 - Passenger Station Wagon/Jeep/Land Rover  
 Vehicle Attachment 1: No Attachment  
 Vehicle Scheme: Normal  
 Vehicle Make: TOYOTA  
 Vehicle Model: ESTIMA AERAS 2.4 G-EDITION A  
 Chassis No.: ACR500081379  
 Propellant: Petrol  
 Engine No.: 2AZC501957  
 Engine Capacity: 2362 cc  
 Maximum Power Output: 125.0 kW (167 bhp)  
 Maximum Laden Weight: 2135 kg  
 Unladen Weight: 1750 kg  
 Year Of Manufacture: 2008  
 Original Registration Date: 03 Dec 2008  
 Lifespan Expiry Date: -  
 COE Category: E - Open Category  
 Quota Premium : \$12,001.00  
 COE Expiry Date: 02 Dec 2018  
 Road Tax Expiry Date: 02 Jun 2016  
 PARF Eligibility Expiry Date: 02 Dec 2018  
 Inspection Due Date: 02 Dec 2017  
 Intended Transfer Date: 22 Feb 2016  
 CO2 Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

**Amount Payable**

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	11.00	-	11.00
<b>Total Amount Payable:</b>			<b>11.00</b>

You may print this page for reference.

OK Print

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
HP: (65) 9833 1618 Fax: (65) 6747 1017  
Email: treasureappraisal@gmail.com  
Reg No: 53218791A



## TAX INVOICE

Bill to : Mohammad Nazrin Bin Mustafa  
C/O : Bluwel Automotive Service Pte Ltd  
1 Kaki Bukit Avenue 6 Blk C  
#01-51/53/55 Autobay @ Kaki Bukit  
Singapore 417883  
Tel: 6745 2088 Fax: 6841 2088  
Contact: Kenny Yap (Ah Soon) HP: 9755 2088

Invoice No : TAS-1706-1055  
Date : 14-Jun-17  
Report No : T-BW-170606/6078B  
Terms : COD

S/N	Descriptions	Amount (S\$)
1	Service Rendered In Respect of:  Vehicle Number : SKT 6078 B Vehicle Make/Model : Toyota Estima Aeras Date of Inspection : 06-Jun-17 Date of Accident : 04-Jun-17  Appraisal fees include transportation and follow-up inspection.  Submission of appraisal report by hand.  Photography services including storage of media and submission of color photograph copies by hand.  SINGAPORE DOLLARS SIX HUNDRED AND THIRTY-THREE ONLY	\$ 633.00
Total		\$ 633.00

E. & O.E

All cheques should be crossed and made payable to "Treasure Appraisal Services".

All cheques should indicate our "Invoice No" on the reverse side of the cheque.

for Treasure Appraisal Services



# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
HP: (65) 9833 1618 Fax: (65) 6747 1017  
Email: treasureappraisal@gmail.com  
Reg No: 53218791A



## VEHICLE ASSESSMENT REPORT

Report No : T-BW-170606/6078B  
Date : 14-Jun-17

### REFERENCE

Assigned By : Mohammad Nazrin Bin Mustafa  
Name of Workshop : Bluwel Automotive Service Pte Ltd  
Place of Inspection : 1 Kaki Bukit Avenue 6 Blk C #01-55 Autobay @ Kaki Bukit Singapore 417883  
Date of Assignment : 06-Jun-17  
Date of Accident : 04-Jun-17  
Date of Inspection : 06-Jun-17

### PARTICULARS OF DAMAGED VEHICLE

Vehicle Reg No	: SKT 6078 B	Chassis No	: ACR500081379
Year of Reg	: Dec-08	Odometer/km	: 113638
Make/Model	: Toyota Estima Aeras	Engine No	: 2AZC501957
Vehicle Colour	: Pearl White	Engine Capacity	: 2362 cc
Vehicle Type	: MPV	Transmission Type	: Auto

### PRE-ACCIDENT CONDITION OF VEHICLE (STATIC TESTS ONLY)

General Condition	: Good		
Body Paint Work	: Good	Footbrake	: Serviceable
Steering	: Affected	Handbrake	: Serviceable
Front Undercarriage	: LHS Damaged	Rear Undercarriage	: Serviceable

TIRES CONDITION	Tire Brand	Size	Tread Balance
Front RH	: Michelin	: 235/50 R18	: 80%
Rear RH	: Michelin	: 235/50 R18	: 80%
Front LH	: Michelin	: 235/50 R18	: 80%
Rear LH	: Michelin	: 235/50 R18	: 80%

Road Wheels Type : Sport Rim

Note: The above percentages represent the estimated remaining balance of the tire treads in mm.  
\* Denotes damaged components.

### SYNOPSIS OF DAMAGES

At the time of survey, we noted that the vehicle has sustained an impact damages on the front LHS portions.

For further detail of the damages, please refer to our schedule and 53 pcs of surveyed photograph attached.

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
HP: (65) 9833 1618 Fax: (65) 6747 1017  
Email: treasureappraisal@gmail.com  
Reg No: 53218791A



## RECOMMENDATIONS

We referred to your instruction to appraise the above vehicle SKT 6078 B on 06-Jun-17 and in the accordance, we have carried out a physical assessment at your appointed workshop.

A static inspection was carried out and report is enclosed for your reference. The estimated repair cost submitted by the repairer for SGD 8,025.50 as per attached schedule has been scrutinised and revised by us against the actual damages found on the vehicle and we recommended the replacements and rectifications accordingly.

The repair cost has been revised to SGD 5,451.54 and therefore in the consideration of the repairer giving a further 20% even discount, it was agreed that the repairs to be carried out at a contractual lump sum of SGD 4,400.00 nett.

In such event, the repairer shall has the prerogative to either use new, OEM, re-conditioned parts and/or repair any damaged body parts that the repairer is confident and capable of repairing as long as the vehicle is put on the road in its pre-accident and road worthy condition and to the entire satisfaction of the owner.

Under normal circumstances, the estimated period of repairs is Six (6) working days.

Pursuant to your instructions, we have NOT AUTHORISED to carry out the repairs on your behalf and we are submitting this report for your consideration.

This survey and/or appraisal was carried out to the best of our knowledge, ability and on a "STRICTLY WITHOUT PREJUDICE" basis to any party concern.

We are reverting the matter to you for your discretion.

Yours Truly,  
Treasure Appraisal Services

  
  
Automobile Appraiser

The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified to the company within Fourteen (14) days from the date thereof. Otherwise, the revised amount should deem to be valid.

This report is strictly confidential and is given for the use of client and their authorised assigned agent and any disclosure or publication of it or part or whole shall be the responsibility of such person and no liability shall be attached to TREASURE APPRAISAL SERVICES thereof.

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
 HP: (65) 9833 1618 Fax: (65) 6747 1017  
 Email: treasureappraisal@gmail.com  
 Reg No: 53218791A



## APPRAISEMENT SCHEDULE

Vehicle Registration No: SKT 6078 B

Report No: T-BW-170606/6078B

S/N	Descriptions	Condition	Qty	Repairer's Estimate	Our Assessment
<b>LIST ITEMS</b>					
1	Front LH fender panel	Damage	1 pc	\$ 582.40	\$ 582.40 ✓
2	Front LH fender garnish	Damage	1 pc	\$ 129.90	\$ 129.90 ✓
3	Front LH fender mud shield	Damage	1 pc	\$ 143.20	\$ 143.20 ✓
4	Front LH fender shield clip	Necessary	1 set	\$ 35.00	\$ 35.00 ✓
5	Front LH door panel	Repair	1 pc	\$ 1,595.95	\$ <del>1,595.95</del> ✓
6	Front LH door garnish	Damage	1 pc	\$ 389.65	\$ <del>389.65</del> ✓
7	Front LH wheel hub with bearing	Damage ✗	1 pc	\$ 412.90	\$ 412.90 ✓
8	Front LH shock absorber	Damage ✗	1 pc	\$ 451.60	\$ 451.60 ✓
9	Front LH knuckle arm	Damage ✗	1 pc	\$ 547.45	\$ 547.45 ✓
10	Front LH lower arm	Damage ↗	1 pc	\$ 549.95	\$ 549.95 ✓
11	Front stabilizer bar LH link	Re-usable	1 pc	\$ <del>36.00</del>	\$ <del>36.00</del> ✓
				\$ 4,874.00	\$ 3,242.05
		Less Discount : 25%		\$ 1,218.50	\$ 810.51
		List Parts Sub-Total :		\$ 3,655.50	\$ 2,431.54
<b>SPECIAL NETT ITEMS</b>					
1	Sport wheel rim	Damage	1 set	\$ 600.00	\$ 550.00 ✓
2	Wheel tire (dep 20%)	Damage	1 pc	\$ 300.00	\$ <del>300.00</del> ✓
		Special Nett Parts Total :		\$ 900.00	\$ 790.00
		Parts Total :		\$ 4,555.50	\$ 3,221.54

S/N	Labour Descriptions	Repairer's Estimate	Our Assessment
1	Transfer front LHS door mechanism, door glass and wiring assy to facilitate body repairs.	\$ 150.00	\$ 80.00 ✓
2	Dismantle, replace, repair and/or re-install front LHS undercarriage suspension and drive train system.	\$ 450.00	\$ 350.00 200 ✓
3	Conduct computerise wheel alignment, adjustments, measurement and rectification to specification.	\$ 150.00	\$ 120.00 ✓
4	To carry out accident body repairs; dismantle vehicle body part/s, dismember affected damaged body panel/s, replace and/or repair, re-construction, weld to re-join and re-align vehicle body structures to pre-accident condition.	\$ 1,200.00	\$ 660.00 ✓
5	To furnish, putty, sanding, masking, prepare paint mixture & toning, complete cleaning, spray paint, polishing and waxing on affected areas.	\$ 1,200.00	\$ 800.00 ✓

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
HP: (65) 9833 1618 Fax: (65) 6747 1017  
Email: treasureappraisal@gmail.com  
Reg No: 53218791A



S/N	Labour Descriptions	Repairer's Estimate	Our Assessment
6	To furnish and apply under-sealing & rust proofing coats on accident affected area.	\$ 200.00	\$ 160.00 80
7	Conduct water leakage tests to ensure proper air and water sealing.	\$ 120.00	\$ 60.00 ✓
Labour Total :		<u>\$ 3,470.00</u>	<u>\$ 2,230.00</u>
Parts & Labour Total :		<u>\$ 8,025.50</u>	<u>\$ 5,451.54</u>

Note: The repairer has agreed to undertake the repairs at our adjusted amount of SGD 4,400.00 on a \*Contractual Lump Sum Basis corresponding to supply of all parts, labour and spray painting charges.

N.B: \*Under Contractual Lump Sum Basis, the repairer shall have the prerogative to either use new, OEM, re-conditioned parts and/or repair any damaged body parts that the repairer is confident and capable of repairing as long as the vehicle is put on the road in its pre-accident and road worthy condition and to the entire satisfaction of the owner.

Under normal circumstances, the estimated period of repairs is Six (6) working days. Pursuant to your instruction, we have NOT AUTHORISED the repairs on your behalf.

Treasure Appraisal Services



Dixon, T W  
Automobile Appraiser

FormTeam Consultancy Pte Ltd (Co.Reg.No:200819280D)  
 33 Ubi Avenue3 #02-15, Vertex  
 Singapore 408868  
 Tel: 6509 1788 Fax: 6509 6221 Email: motorsurvey@fta.com.sg

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: RRM17-  
 063191/PRS/KT/ADJ/KT  
 Date: 13/09/2017

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28617607MKC  
 Claimant Vehicle No: SKT6078B Insured Vehicle No: PA8604K  
 Date of Loss: 04/06/2017 Nature of Claim: TP Claim No: 517611

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKT6078B  
 Make & Model: TOYOTA ESTIMA, 2.4 Aeras G (A) Engine No: 2AZC501957  
 Reg. Date: 03/12/2008 (Man. Year: 2008) Chassis No: ACR500081379  
 Colour: White Odometer: 113638 km  
 Engine Capacity: 2362 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18  
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm  
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,221.54	1,217.87	2,003.67	62.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	1,280.00	950.00	42.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,451.54</b>	<b>2,497.87</b>	<b>2,953.67</b>	<b>54.18</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,451.54</b>	<b>2,000.00</b>	<b>3,451.54</b>	<b>63.31</b>

### INSPECTION

Date of Assignment: 06/06/2017  
 Date Inspected: 06/06/2017, 12/09/2017 Inspected At: PAPER SURVEY REPORT  
 (Repairer: Bluwel Automotive Service Pte Ltd)  
 Estimated Period of Repair: 5.0 days

Adjuster: Kenji Tan

Manager: Frankie

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**REPAIR DETAILS**

Reference	
Part Source:	MRM-SG Version: 1.0 (Last Synchronised: 13 Sep 2017)
Parts:	M1-MPV TOYOTA ESTIMA 2.4 Aeras G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	FormTeam Consultancy Pte Ltd/SKT6078B/13/09/2017 20:10
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front LH Fender Panel	Buckled	582.40 FL	*582.40 FL
2	1		*Front LH Fender Garnish	Deformed	129.90 FL	*129.90 FL
3	1		*Front LH Fender Mud Shield	Deformed	143.20 FL	*143.20 FL
4	1		*Front LH Fender Shield Clip (Set)	Necessary	35.00 FL	*35.00 FL
5	1		*Front LH Door Panel	Repair	0.00 FL	*- FL
6	1		*Front LH Door Garnish	Not Necessary	389.65 FL	*- FL
7	1		*Front LH Wheel Hub With Bearing	Not Necessary	412.90 FL	*- FL
8	1		*Front LH Shock Absorber	Not Necessary	451.60 FL	*- FL
9	1		*Front LH Knuckle Arm	Not Necessary	547.45 FL	*- FL
10	1		*Front LH Lower Arm	Not Necessary	549.95 FL	*- FL
11	1		*Front Stabilizer Bar LH Link	Re-usable	0.00 FL	*- FL
12	1		*Sport Wheel Rim (Set)	Damaged	550.00 FS	*550.00 FS
13	1		*Wheel Tire (Dep 20%)	Not Necessary	240.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,032.05	1,440.50
- List Item Discount on L Items 25.00/25.00% (S\$)	810.51	222.63
Total Parts (S\$)	3,221.54	1,217.87

FormTeam Consultancy Pte Ltd/SKT6078B/13/09/2017 20:10. Not valid without Reference section.
--

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Transfer front LHS door mechanism, door glass and wiring assy to facilitate body repairs.	New	80.00	60.00
2	Dismantle, replace, repair and/or re-install front LHS undercarriage suspension and drive train system.	New	350.00	0.00
3	Conduct computerize wheel alignment, adjustments, measurement and rectification to specification.	New	120.00	60.00
4	To carry out accident body repairs; dismantle vehicle body part/s. dismember affected damaged body panel/s, replace and /or repair, re-construction, weld to re-join and re-align vehicle body structures to pre-accident condition.	New	660.00	500.00
5	To furnish, putty, sanding, masking, prepare paint mixture & toning, complete cleaning, spray paint, polishing and waxing on affected areas.	New	800.00	600.00
6	To furnish and apply under-sealing & rust proofing coats on accident affected area.	New	160.00	60.00
7	Conduct water leakages tests to ensure proper air and water sealing.	New	60.00	0.00
Gross Labour Cost (S\$)			2,230.00	1,280.00


FormTeam Consultancy Pte Ltd/SKT6078B/13/09/2017 20:10. Not valid without Reference section.

< END OF ESTIMATES >





PEOPLES AUTO TRADING  
 BLK 3007 UBI ROAD 1 #01-400  
 TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS


CUSTOMER	BLUWEL	DATE	Jun 6, 2017 9:29:06 AM
LICENSE NO.	SKT 6078 B		
MILEAGE	113635		
REFERENCE	CUSTOM	MODEL	TOYOTA ESTIMA CR50

Front Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.00	0.00	1.00			-2.00				-2.20		
PARTIAL TOE	-0.50	0.00	0.50		-0.80		-1.20		-2.50		0.20	
SET BACK	---	---	---				-0°04"				-0°04"	
CAMBER	-1°06"	-0°22"	0°22"		-2°48"		-1°02" 1°44"		-2°44"		-1°04" 1°38"	
CASTER	5°44"	6°44"	7°44"		6°00"		6°28" 0°28"		6°00"		6°28" 0°28"	
KING-PIN	---	---	---		12°48"		13°20" 0°32"		12°48"		13°20" 0°32"	
INCL ANGLE	---	---	---		10°00"		12°18"		10°04"		12°14"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	---	---	---			5.30				5.30		
PARTIAL TOE	---	---	---		3.60		1.70		3.60		1.70	
SET BACK	---	---	---				0°16"				0°16"	
CAMBER	---	---	---		-1°20"		-1°44" 0°24"		-1°20"		-1°44" 0°24"	
THRUST ANGLE	-0°08"	0.00	0°08"				0°08"				0°08"	



PEOPLES AUTO TRADING  
 BLK 3007 UBI ROAD 1 #01-400  
 TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	BLUWEL	DATE	Jun 12, 2017 1:31:24 PM
LICENSE NO.	SKT 6078 B		
MILEAGE	113642		
REFERENCE	CUSTOM	MODEL	TOYOTA ESTIMA CR50

Front Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.00	0.00	1.00			-1.90				-0.10		
PARTIAL TOE	-0.50	0.00	0.50		-3.40		1.40		0.00		0.00	
SET BACK	---	---	---			-0°02"				-0°02"		
CAMBER	-1°06"	-0°22"	0°22"		-0°18"		-0°30" 0°10"		-0°32"		-0°30" 0°02"	
CASTER	5°44"	6°44"	7°44"		6°10"		6°32" 0°22"		6°10"		6°32" 0°22"	
KING-PIN	---	---	---		12°02"		12°02" 0°00"		12°02"		12°02" 0°00"	
INCL ANGLE	---	---	---		11°42"		11°32"		11°28"		11°32"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	---	---	---			4.80				4.80		
PARTIAL TOE	---	---	---		4.40		0.30		4.40		0.30	
SET BACK	---	---	---			0°00"				0°00"		
CAMBER	---	---	---		-1°20"		-1°40" 0°20"		-1°20"		-1°40" 0°20"	
THRUST ANGLE	-0°08"	0.00	0°08"			0°18"				0°18"		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
M NEDUMARAN & CO*		Ref : CS/LAW18015235/Uvbe2	
No. 11 SIN MING ROAD #B2-09 (UNIT 2), THOMSON V TWO SINGAPORE 575629		Date : 13-12-2018	
		Code : L134	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	PA 8604K	Veh. Inspected	SKT 6078B
Policy No.		Coverage (\$)	0.00
Claim No.	MB.IG.B1.1711658	Excess (\$)	0.00
Assign From	IGENE LIM	Assign Date	20/08/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ESTIMA (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	ACR500081379	Colour	BLUE
Odometer	129340	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/50 R18	MICHELIN	5 mm
L/H Front Tyre	235/50 R18	MICHELIN	5 mm
R/H Rear Tyre	235/50 R18	MICHELIN	5 mm
L/H Rear Tyre	235/50 R18	MICHELIN	5 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	04/06/2017	Inspection Date	10/09/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 6078B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT LH FENDER PANEL	REPLACED	582.40	582.40
1	FRONT LH FENDER GARNISH	REPLACED	129.90	129.90
1	FRONT LH FENDER MUD SHIELD	REPLACED	143.20	143.20
1	SET FRONT LH FENDER SHIELD CLIP	REPLACED	35.00	35.00
1	FRONT LH DOOR PANEL	REPAIRED SEE LABOUR	1,595.95	-
1	FRONT LH DOOR GARNISH	REPAIRED SEE LABOUR	389.65	-
1	FRONT LH WHEEL HUB WITH BEARING	REPLACED	412.90	412.90
1	FRONT LH SHOCK ABSORBER	REPLACED	451.60	451.60
1	FRONT LH KNUCKLE ARM	REPLACED	547.45	547.45
1	FRONT LH LOWER ARM	REPLACED	549.95	549.95
1	FRONT STABILIZER BAR LH LINK	NOT NECESSARY	36.00	-
	LESS 25% DISCOUNT		-1,218.50	-713.10
			3,655.50	2,139.30
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SPORT WHEEL RIM (SN)	REPLACED	600.00	550.00
1	WHEEL TIRE (SN)	NOT NECESSARY	300.00	-
			900.00	550.00
<b><u>LABOUR</u></b>				
	TRANSFER FRONT LHS DOOR MECHANISM, DOOR GLASS AND WIRING ASSY TO FACILITATE BODY REPAIRS.		150.00	80.00
	DISMANTLE, REPLACE, REPAIR AND / OR RE-INSTALL FRONT LHS UNDERCARRIAGE SUSPENSION AND DRIVE TRAIN SYSTEM.		450.00	200.00
	CONDUCT COMPUTERISE WHEEL ALIGNMENT, ADJUSTMENTS, MEASUREMENT AND RECTIFICATION TO SPECIFICATION.		150.00	120.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CARRY OUT ACCIDENT BODY REPAIRS; DISMANTLE VEHICLE BODY PART/S, DISMEMBER AFFECTED DAMAGED BODY PANEL/S, REPLACE AND / OR REPAIR, RE-CONSTRUCTION, WELD TO RE-JOIN AND RE-ALIGN VEHICLE BODY STRUCTURES TO PRE-ACCIDENT CONDITION. INCLUSIVE OF THE REPAIR OF FRONT LH DOOR PANEL AND FRONT LH DOOR GARNISH.		1,200.00	660.00
	TO FURNISH, PUTTY, SANDING, MASKING, PREPARE PAINT MIXTURE & TONING, COMPLETE CLEANING, SPRAY PAINT, POLISHING AND WAXING ON AFFECTED AREAS.		1,200.00	800.00
	TO FURNISH AND APPLY UNDER-SEALING & RUST PROOFING COATS ON ACCIDENT AFFECTED AREA.		200.00	80.00
	CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND WATER SEALING.		120.00	60.00
			3,470.00	2,000.00
<b>GRAND TOTAL</b>			<b>8,025.50</b>	<b>4,689.30</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,750.00</b>

Report Ref No. CS/LAW18015235/Uvbe2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.