

SS REC. BY:

REF:

CS/CTI18015244/Kgd3ch

Special Instruction:

Survivor:
menmen

Kenneth

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

21/8/18 @ 3:21pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG 1132K

Insured:

SGQ 4211J

at Workshop m/s

City Auto

Tel:

64531235

of

160 8m Ming Drive #05-01

Policy No:

DMPC SN1656711701

Claim No:

SNM18D0404C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/08/2018

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

4:22pm @ 21/8/18

Person Contacted:

vronica

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

GBG 1132K-X

SGQ 4211J - NA/CTI18015152/21

DUA: 18/8/18

26/10

812840.46 email to confirm credit 156229.65, 33% (7)

ASS. REC. BY:

REF: CTZ/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

11 days

Res.: Yes or No

Lum Sum:

1.131 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBG 1132K

Yr Regn:

05, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS NV200

c.c

1461

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

29292

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VSKYBAM 20.80141427

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

3

mm

L/Bal.

4

mm

L/Bal.

3

mm

D.O.A.

18/8/18

D.O.I.

21/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

2/41

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/8

File pass to Catherine

RECEIVED 20 OCT 2018

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I.: (\$

12840.46

Days Of Repair:

11

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

220

Transportation:

S + RS. SI

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Aug 2018		21 Aug 2018 15:21 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NG SOON TIEN, ID: S7604485F		
Main Claimant:	GASPURGE ENGINEERING AND ENTERPRISE PTE. LTD., Co. Reg. No.: 201000335Z		
Vehicle Reg. No.:	GBG1132K	Date of Loss:	18/08/2018 16:00 - :59
Claim Type:	TP / SNM18D04042C02	Policy/Cover Note No.:	DMPCSN1656711701 (Comprehensive)
Vehicle Reg. No. (Insured):	SGQ4211J	Policy No. (Claimant):	A 29080436 MKC
		Excess:	S\$0.00
Repairer:	City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01,, Sin Ming AutoCity,, 575722 Sin Ming - Tel: 6453 1235		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/08/2018]		
Driver/Custodian (Insured):	NG SOON TIEN (HUANG SHUNTIAN) (42 / Male), NRIC: S7604485F, Tel: +6596808460		
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18015244/Kqd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 21-08-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGQ 4211J	Veh. Inspected	GBG 1132K
Policy No.	DMPCSN1656711701	Coverage (\$)	0.00
Claim No.	SNM18D04042C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	21/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/08/2018	Inspection Date	21/08/2018
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	20/08/2018 12:18
Date Of Accident	18/08/2018 16:00
Exact Location Of Accident	SLIP RO BETWEEN BRADELL ROAD EXIT AND CTE ENTRANCE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBG1132K
Insured/Policyholder	
Name Of Registered Owner	GASPURGE ENGINEERING AND ENTERPRISE PTE. LTD.
Co Reg No	201000335Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96815537
Vehicle Particulars	
Manufacturer	NISSAN
Model	NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 29080436 MKC
Cover Note Number	
Driver	
Name of Driver	ANG SOON MENG (HONG SHUNMING)
NRIC No	S7529205H
Date Of Birth	01/10/1975
Occupation	OUTDOOR
Date Of Driving Pass	16/07/2007
Driving Experience	11 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96815537
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	APT BLK 232 HOUGANG AVENUE 1 #11-244
Postcode	530232
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGQ4211J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG SOON TIEN
NRIC/Passport Number	S7604485F
Contact Number	96808460
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJV5319P
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	WANG SHUN GUO
NRIC/Passport Number	G7726283R
Contact Number	93839602
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SLH1969P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ALBERT CHELLIAH S/O JAMES
NRIC/Passport Number	S8034439B
Contact Number	97437380
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is *not* an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for compliance with requirements under any regulations, laws or court orders



CITY AUTO PTE LTD
Blk 8 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 515843
Tel: 6453 1235 Fax: 6453 7944
(Claims Section)


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along flyover towards CTE traffic was slow, when vehicle in front stop, I also ~~stop~~ Brake and stop my van suddenly I feel an impact from my rear and ~~for~~ due to impact push my van to hit into front vehicle no SLH 1969P when I came down I notice my van was hit by vehicle no SGA 4211J and another vehicle no STV 5319P also involved in this accident.

DECLARATION

I/We declare the following particulars are true in every respect

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

CITY AUTO PTE LTD
Blk 8 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 575643
Tel: 6453 1235 Fax: 6453 7944
(Claims Section)

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201808-000350(00)

Date : 20/08/2018

Vehicle No. : GBG1132K

Make/Model : NISSAN NV200 1.5 MT ABS
AIRBAG 2WD 6DR E5 W/R

Mileage (km) : 0

Chassis No. : VSKYBAM20Z0141427

Accident Date : 18/08/2018 00:00:00

Claim No. : SGQ4211J

Reference : GBG1132K

Policy No. : A 29080436 MKC

CHINA TAIPING INSURANCE (S) PTE LTD

NO. 3

ANSON RD

SPRINGLEAF TOWER

SINGAPORE 079909

Attention: Ang Soon Meng

Contact : 96815537

Fax No. : 62247175

Not Notation
1. B.1
Put away B4 paint
812840.46 *11 days*

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

NET ITEMS :

1	Front bumper	1.0	536.10	536.10	✓
2	Front bumper sponge	1.0	291.60	291.60	✓
3	Front bumper reinforcement	1.0	614.90	614.90	✓
4	Front bumper reinforcement bracket	2.0	120.00	240.00	✓
5	Front bumper retainer	2.0	35.20	70.40	✓
6	Front bumper tow hook cover	1.0	28.10	28.10	✓
7	Front bumper side garnish	2.0	329.30	658.60	✓
8	Front grille	1.0	338.00	338.00	✓
9	Front grille logo	1.0	66.40	66.40	✓
10	Headlamp	2.0	466.40	932.80	✓
11	Bonnet	1.0	830.30	830.30	✓
12	Bonnet hinge	2.0	49.60	99.20	✓
13	Bonnet lock	1.0	64.20	64.20	✓
14	Support top panel	1.0	507.50	507.50	✓
15	LH Tail door	1.0	1,281.10	1,281.10	✓
16	LH Tail door lower lock	1.0	112.50	112.50	✓
17	LH Tail door lower striker	1.0	57.20	57.20	✓
18	LH Tail door weatherstrip	1.0	96.40	96.40	✓
19	LH Tail door hinge lower	1.0	119.90	119.90	✓
20	LH Tail door checker	1.0	75.70	75.70	✓
21	RH Tail door	1.0	960.90	960.90	✓
22	RH Tail door lower lock	1.0	112.50	112.50	✓
23	RH Tail door lower striker	1.0	57.20	57.20	✓
24	RH Tail door hinge lower	1.0	119.90	119.90	✓
25	RH Tail door checker	1.0	75.70	75.70	✓
26	RH Tail door glass	1.0	449.50	449.50	✓
27	LH Tail door inner trim	1.0	204.80	204.80	✓
28	RH Tail door inner trim	1.0	152.80	152.80	✓
29	Tail door inner trim clip	17.0	5.50	93.50	✓
30	Tail door weatherstrip	1.0	96.40	96.40	✓
31	LH Tail door outer garnish with handle	1.0	336.00	336.00	✓
32	Rear bumper	1.0	624.80	624.80	✓
33	Rear bumper sponge	1.0	133.80	133.80	✓
34	Rear bumper retainer	2.0	35.20	70.40	✓

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201808-000350(00)

CHINA TAIPING INSURANCE (S) PTE LTD

NO. 3

ANSON RD

SPRINGLEAF TOWER

SINGAPORE 079909

Attention: Ang Soon Meng

Contact : 96815537

Fax No. : 62247175

Date : 20/08/2018

Vehicle No. : GBG1132K

Make/Model : NISSAN NV200 1.5 MT ABS
AIRBAG 2WD 6DR E5 W/R

Mileage (km) : 0

Chassis No. : VSKYBAM20Z0141427

Accident Date : 18/08/2018 00:00:00

Claim No. : SGQ4211J

Reference : GBG1132K

Policy No. : A 29080436 MKC

S/No	Particular	Quantity	Unit Price	Amount S\$
35	Rear bumper reflector	2.0	66.60	133.20 X
36	Rear end panel outer	1.0	246.20	246.20 ✓
37	Rear end panel inner	1.0	841.00	841.00 ✓
38	Rear end panel top garnish	1.0	85.00	85.00 ✓
39	Rear floor panel	1.0	1,848.00	1,848.00 X
40	Spare tyre hanger	1.0	198.45	198.45 ✓
41	Spare tyre hanger bracket	2.0	82.00	164.00 ✓
42	Spare tyre hanger clamp	1.0	98.00	98.00 X
43	Rear floor trim	1.0	495.00	495.00 ✓
44	Emblem - Nv200	1.0	125.10	125.10 ✓
45	Emblem - Logo	1.0	66.40	66.40 ✓
46	Rear number plate lamp	2.0	78.40	156.80 X
47	RH taillamp	1.0	258.76	258.76 X
48	Rear RH quater panel	1.0	264.00	264.00 X
List Total :				15,489.01
10% Discount S\$				1,548.90
				13,940.11

SPECIAL NET :

1	Number plate	1.0	20.00	20.00 } 45
2	Number plate casing	1.0	25.00	25.00 ✓
3	Glass sealant	2.0	30.00	60.00 ✓
4	Reverse sensor	1.0	300.00	300.00 ✓
5	Rear floor wooden board	1.0	280.00	280.00 ✓
6	Sticker - 70Km/h	1.0	10.00	10.00 ✓
7	Sticker - 6 pax	1.0	10.00	10.00 ✓
8	Rear number plate	1.0	20.00	20.00 } ✓
9	Rear number plate casing	1.0	25.00	25.00 ✓
SPECIAL NET Total S\$:				750.00

LABOUR :

*To remove and install tail doors glass	1.0	200.00	200.00 120
*To supply panel sealant and to seal off all weld seam and gaps	1.0	90.00	90.00 30
*To spray under coating	1.0	120.00	120.00 ✓
*To check wiring and lighting	1.0	60.00	60.00 60

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201808-000350(00)

CHINA TAIPING INSURANCE (S) PTE LTD

NO. 3

ANSON RD

SPRINGLEAF TOWER

SINGAPORE 079909

Attention: Ang Soon Meng

Contact : 96815537

Fax No. : 62247175

Date : 20/08/2018

Vehicle No. : GBG1132K

Make/Model : NISSAN NV200 1.5 MT ABS
AIRBAG 2WD 6DR E5 W/RC

Mileage (km) : 0

Chassis No. : VSKYBAM20Z0141427


Accident Date : 18/08/2018 00:00:00

Claim No. : SGQ4211J

Reference : GBG1132K

Policy No. : A 29080436 MKC

S/No	Particular	Quantity	Unit Price	Amount S\$
	*To remove and install rear view camera and reverse sensor	1.0	150.00	150.00
	*To pull and realign rear chassis member	1.0	250.00	250.00
	*To remove and install door trime and upholstery	1.0	110.00	110.00
	-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	1,900.00	1,900.00
	-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	1,500.00	1,500.00
				<hr/> 4,380.00



E. & O.E.

Total S\$: 19,070.11

GST 7% S\$: 1,334.91

Amount Due S\$: 20,405.02

for CITY AUTO PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Aug 2018		21 Aug 2018 15:21 Edit Adj Rpt	S\$12,840.45 Edit Estimates	S\$12,840.45 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: NG SOON TIEN , ID: S7604485F									
Main Claimant: GASPURGE ENGINEERING AND ENTERPRISE PTE. LTD., Co. Reg. No.: 201000335Z									
Vehicle Reg. No.: GBG1132K		Date of Loss: 18/08/2018 16:00 - :59 [14 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D04042C02		Policy/Cover Note No.: DMPCSN1656711701 (Comprehensive)							
Vehicle Reg. No. (Insured): SGQ4211J		Policy No. (Claimant): A 29080436 MKC							
		Excess: S\$0.00							
Repairer: City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01,, Sin Ming AutoCity,, 575722 Sin Ming - Tel: 6453 1235									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 31/08/2018]									
Driver/Custodian (Insured): NG SOON TIEN (HUANG SHUNTIAN) (42 / Male), NRIC: S7604485F, Tel: +6596808460									
Adj Asg. Remarks: NO EST, ASSIGN KENNETH KONG AS SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBG1132K (SNM18D04042C02)

[SGQ4211J]

TP

GASPURGE ENGINEERING AND ENTERPRISE PTE. LTD.

Aug 18 2018 4:00PM

[NG SOON TIEN]


City Auto Pte Ltd













Upload Documents			Upload Photos			Compose New Letter			View			View in Browser			
Assessment Reports									1 per page			<input checked="" type="checkbox"/>			
No	Finalized On	City Auto Pte Ltd (HQ)										Thumbnail		Print	
1	20/08/18 12:27	Accident Statement										Load HTM			
Photos/Images									3 per page			<input checked="" type="checkbox"/>			
No	Finalized On	City Auto Pte Ltd (HQ)										Thumbnail		Print	
1	20/08/18 12:26	Accident Photo [Linked Accident Report Documents]										Load JPG		<input checked="" type="checkbox"/>	
2	20/08/18 12:26	Accident Photo [Linked Accident Report Documents]										Load JPG		<input checked="" type="checkbox"/>	
3	20/08/18 12:26	Accident Photo [Linked Accident Report Documents]										Load JPG		<input checked="" type="checkbox"/>	
4	20/08/18 12:26	Accident Photo [Linked Accident Report Documents]										Load JPG		<input checked="" type="checkbox"/>	
5	20/08/18 12:26	Accident Photo [Linked Accident Report Documents]										Load JPG		<input checked="" type="checkbox"/>	
6	20/08/18 12:26	Accident Photo [Linked Accident Report Documents]										Load JPG		<input checked="" type="checkbox"/>	
7	20/08/18 12:26	Accident Photo [Linked Accident Report Documents]										Load JPG		<input checked="" type="checkbox"/>	
8	20/08/18 12:26	Accident Photo [Linked Accident Report Documents]										Load JPG		<input checked="" type="checkbox"/>	
9	20/08/18 12:26	Accident Photo [Linked Accident Report Documents]										Load JPG		<input checked="" type="checkbox"/>	
10	20/08/18 12:26	Accident Photo [Linked Accident Report Documents]										Load JPG		<input checked="" type="checkbox"/>	
11	20/08/18 12:26	Accident Photo [Linked Accident Report Documents]										Load JPG		<input checked="" type="checkbox"/>	
12	20/08/18 12:26	Accident Photo [Linked Accident Report Documents]										Load JPG		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print	
1	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
2	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
3	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
4	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
5	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
6	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
7	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
8	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
9	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
10	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
11	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
12	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
13	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
14	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
15	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
16	26/10/18 10:13	General View										Load JPG		<input checked="" type="checkbox"/>	
17	26/10/18 10:13	General View										Load JPG			





Assessment Reports			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)		Thumbnail	Print
					<input checked="" type="checkbox"/>
18	26/10/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
19	26/10/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
20	26/10/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
21	26/10/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
22	26/10/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
23	26/10/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
24	26/10/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
25	26/10/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
26	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
27	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
28	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
29	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
30	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
31	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
33	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
34	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
35	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
36	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
37	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
38	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
39	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
40	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
41	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
42	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
44	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
45	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
46	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
47	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
48	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
49	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
50	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
51	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
52	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
53	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
54	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
55	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
56	26/10/18 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/08/18 15:20	PRS		Load PDF	
2	21/08/18 15:20	OI GIA		Load PDF	
No	Finalized On	City Auto Pte Ltd (HQ)		Thumbnail	Print
1	20/08/18 12:26	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	20/08/18 12:26	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	20/08/18 12:26	CI [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	20/08/18 12:26	NRIC & Driving license		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
		[Linked Accident Report Documents]		

Linked Accident Report Documents

Assessment Reports			View	View in Browser	
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print	
1	20/08/18 12:27	Accident Statement		Load HTM	<input checked="" type="checkbox"/>

Photos/Images			3 per page		
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print	
1	20/08/18 12:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	20/08/18 12:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	20/08/18 12:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	20/08/18 12:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	20/08/18 12:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	20/08/18 12:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	20/08/18 12:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	20/08/18 12:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	20/08/18 12:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	20/08/18 12:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	20/08/18 12:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	20/08/18 12:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page		
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print	
1	20/08/18 12:26	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	20/08/18 12:26	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
3	20/08/18 12:26	CI		Load JPG	<input checked="" type="checkbox"/>
4	20/08/18 12:26	NRIC & Driving license		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118015244/KQD3E2

Date: 29/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1656711701

Claimant Vehicle
No: GBG1132KInsured Vehicle
No: SGQ4211J

Date of Loss: 18/08/2018

Nature of Claim: TP

Claim
No: SNM18D04042C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG1132K**Make & Model: NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR
(A)

Engine No: K9KC400D056637

Reg. Date: 31/05/2017 (Man. Year: 2016)

Chassis No: VSKYBAM20Z0141427

Colour: Metallic Grey

Odometer: 29292 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70R14

Rear Tyre Size: 175/70R14

Front Left Side: Yokohama 4 mm

Rear Left Side: Yokohama 3 mm

Front Right Side: Yokohama 4 mm

Rear Right Side: Yokohama 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,690.11	9,240.45	5,449.66	37.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	3,600.00	780.00	17.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,070.11	12,840.45	6,229.66	32.67
+ GST 7.00/7.00% (S\$)	1,334.91	898.83	436.08	32.67
Nett Amount (S\$)	20,405.02	13,739.28	6,665.74	32.67

INSPECTION

Date of Assignment: 21/08/2018

Date Inspected: 21/08/2018 Inspected At:

City Auto Pte Ltd (HQ)
160 Sin Ming Drive #05-01., Sin Ming
AutoCity,
Singapore 575722

Estimated Period of Repair: 11.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$12,840.46

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Oct 2018)	
Parts:	N/A	NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG1132K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	536.10 FN	*536.10 FN
2	1		*FRONT BUMPER SPONGE	Cracked	291.60 FN	*291.60 FN
3	1		*FRONT BUMPER REINFORCEMENT	Bent	614.90 FN	*614.90 FN
4	2		*FRONT BUMPER REINFORCEMENT BRACKET	Repair	240.00 FN	*- FN
5	1		*FRONT BUMPER RETAINER	O/s Distorted	70.40 FN	*35.20 FN
6	1		*FRONT BUMPER TOW HOOK COVER	Serviceable	28.10 FN	*- FN
7	2		*FRONT BUMPER SIDE GARNISH	Mtg Cracked	658.60 FN	*658.60 FN
8	1		*FRONT GRILLE	Mtg Cracked	338.00 FN	*338.00 FN
9	1		*FRONT GRILLE LOGO	Serviceable	66.40 FN	*- FN
10	2		*HEADLAMP	Serviceable	932.80 FN	*- FN
11	1		*BONNET	Bent	830.30 FN	*830.30 FN
12	2		*BONNET HINGE	Repair	99.20 FN	*- FN
13	1		*BONNET LOCK	Repair	64.20 FN	*- FN
14	1		*SUPPORT TOP PANEL	Repair	507.50 FN	*- FN
15	1		*LH TAIL DOOR	Bent	1,281.10 FN	*1,281.10 FN
16	1		*LH TAIL DOOR LOWER LOCK	Dented	112.50 FN	*112.50 FN
17	1		*LH TAIL DOOR LOWER STRIKER	Distorted	57.20 FN	*57.20 FN
18	1		*LH TAIL DOOR WEATHERSTRIP	Dented/Distorted	96.40 FN	*96.40 FN
19	1		*LH TAIL DOOR HINGE LOWER	Repair	119.90 FN	*- FN
20	1		*LH TAIL DOOR CHECKER	Serviceable	75.70 FN	*- FN
21	1		*RH TAIL DOOR	Bent	960.90 FN	*960.90 FN
22	1		*RH TAIL DOOR LOWER LOCK	Dented	112.50 FN	*112.50 FN
23	1		*RH TAIL DOOR LOWER STRIKER	Distorted	57.20 FN	*57.20 FN
24	1		*RH TAIL DOOR HINGE LOWER	Repair	119.90 FN	*- FN
25	1		*RH TAIL DOOR CHECKER	Repair	75.70 FN	*- FN
26	1		*RH TAIL DOOR GLASS	Serviceable	449.50 FN	*- FN
27	1		*LH TAIL DOOR INNER TRIM	Dented	204.80 FN	*204.80 FN
28	1		*RH TAIL DOOR INNER TRIM	Dented	152.80 FN	*152.80 FN
29	17		*TAIL DOOR INNER TRIM CLIP	Necessary	93.50 FN	*93.50 FN
30	1		*TAIL DOOR WEATHERSTRIP	Distorted	96.40 FN	*96.40 FN
31	1		*LH TAIL DOOR OUTER GARNISH WITH HANDLE	Serviceable	336.00 FN	*- FN
32	1		*REAR BUMPER	Bent	624.80 FN	*624.80 FN
33	1		*REAR BUMPER SPONGE	Cracked	133.80 FN	*133.80 FN
34	1		*REAR BUMPER RETAINER	O/s Distorted	70.40 FN	*35.20 FN
35	2		*REAR BUMPER REFLECTOR	Serviceable	133.20 FN	*- FN
36	1		*REAR END PANEL OUTER	Bent	246.20 FN	*246.20 FN
37	1		*REAR END PANEL INNER	Bent	841.00 FN	*841.00 FN
38	1		*REAR END PANEL TOP GARNISH	Dented	85.00 FN	*85.00 FN
39	1		*REAR FLOOR PANEL	Repair	1,848.00 FN	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*SPARE TYRE HANGER	Distorted	198.45 FN	*198.45 FN
41	2		*SPARE TYRE HANGER BRACKET	Bent	164.00 FN	*164.00 FN
42	1		*SPARE TYRE HANGER CLAMP	Repair	98.00 FN	*- FN
43	1		*REAR FLOOR TRIM	Cracked	495.00 FN	*495.00 FN
44	1		*EMBLEM-NV200	Necessary	125.10 FN	*125.10 FN
45	1		*EMBLEM-LOGO	Necessary	66.40 FN	*66.40 FN
46	2		*REAR NUMBER PLATE LAMP	Serviceable	156.80 FN	*- FN
47	1		*RH TAILLAMP	Serviceable	258.76 FN	*- FN
48	1		*REAR RH QUATER PANEL	Repair	264.00 FN	*- FN
49	1		*NUMBER PLATE CASING }	Dented	25.00 FS	*45.00 FS
50	1		*NUMBER PLATE }		20.00 FS	*- FS
51	2		*GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
52	1		*REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
53	1		*REAR FLOOR WOODEN BOARD	Cracked	280.00 FS	*280.00 FS
54	1		*STICKER-70KM/H	Necessary	10.00 FS	*10.00 FS
55	1		*STICKER-6 PAX	Necessary	10.00 FS	*10.00 FS
56	1		*REAR NUMBER PLATE CASING	Bent	25.00 FS	*25.00 FS
57	1		*REAR NUMBER PLATE	Bent	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	16,239.01	10,194.95
- Nett Item Discount on N Items 10.00/10.00% (S\$)	1,548.90	954.50
Total Parts (S\$)	14,690.11	9,240.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND INSTALL TAIL DOORS GLASS	New	200.00	120.00
2	TO SUPPLY PANEL SEALANT AND TO SEAL OFF ALL WELD SEAM AND GAPS	New	90.00	30.00
3	TO SPRAY UNDER COATING	New	120.00	120.00
4	TO CHECK WIRING AND LIGHTING	New	60.00	40.00
5	TO REMOVE AND INSTALL REAR VIEW CAMERA AND REVERSE SENSOR	New	150.00	80.00
6	TO PULL AND REALIGN REAR CHASSIS MEMBER	New	250.00	250.00
7	TO REMOVE AND INSTALL DOOR TRIME AND UPHOLSTERY	New	110.00	60.00
8	TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	1,900.00	1,500.00
9	TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	1,500.00	1,400.00
Gross Labour Cost (\$\$)			4,380.00	3,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >