

ASS. REC. BY:

REF:

CS/MSG18015252/K190302

Special Instruction:

Surveyor's name: meimen

Kalvin

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSIG

Date/Time:

21/8/18 @ 3:56pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 6486G

Insured:

8JT 6222M

at Workshop m/s

Premier taxis

Tel:

6544 6689

of

23 chengi south Ave 2 #03-02

Policy No:

29076690 QMX

Claim No:

567819

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

2018/18

CA / REV / REP. / REV 24 HRS

(cup)

23/08/2018

H.O.D. Endorsement:

Date/Time:

4:15pm @ 21/8/18

Person Contacted:

Gary

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SHC 6486G-X</u>
	<u>8JT 6222M-X</u>
<u>21/8/18 @ 4:43pm</u>	<u>visited to Irene Tan via Meimen.</u>

08/11/13 wef

ASS. REC. BY:

Kahn

REF:

MSG

ASSIGNMENT

From: _____ Date: 23/8/18

Estimated Cost: _____

OD WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHC 6486G

at Workshop m/s: Premier taxis

of 23 Changi South Ave 2 # 03-02

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SHC 6486G Yr Regn: 29 May 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: KIA optima c.c. 1685

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: J 69087 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KN AHM 41 MF 55 93 621

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD Rim or _____

Tyre Size: F: 205 / 65 R16

R: _____

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: ✓ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front 7 mm R/Bal. 7 mm

L/Bal. 7 mm Rear 7 mm

D.O.A. 20/8/18 D.O.I. 23/8/18

Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or Rear o/s

The UIC / Chassis frame / Body Structure affected due to collision.

CA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time | Action / Instruction

10/9/18 | Carved 4/5 \$900 / 2 days. cRed B 407,36, 31% 4s

RECEIVED 13 SEP 2018

[Signature]

12/9/2018

Date/Time, File Pass to? : Preli. Report

11/9/18 typist : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Date/Time, File Return to? _____

Report Format: NET-TP

Lump Sum / I.B.F. (\$) 900

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:	<u>150</u>
Transportation:	_____
Photos	_____
Others	<u>10</u>
TOTAL	<u>160</u>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD Ref : CS/MSG18015252/K1qd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 21-08-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 6222M	Veh. Inspected	SHC 6486G
Policy No.	29076690QMX	Coverage (\$)	0.00
Claim No.	567819	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	21/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/08/2018	Inspection Date	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2018		21 Aug 2018 15:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	FOO CHEE MENG, ID: S6827396Z								
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHC6486G	Date of Loss:	20/08/2018 09:00 - :59 [38 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 567819	Policy/Cover Note No.:	29076690QMX (Comprehensive) Coverage: 22/04/2018 - 21/04/2019						
Vehicle Reg. No. (Insured):	SJT6222M	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02, 486443 Changi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/08/2018]								
Adj Asg. Remarks:	Car in. on WP. Please contact us ASAP if you cannot attend this assignment. w/shop will give estimate when surveyor go down. LIABILITY : NOT CLEAR (NON-REPORTING) Please take notes if IHS cannot survey , Kindly outsource to LKK AUTO to conduct the survey , Kindly contact the workshop directly @ 6544 6676 or 6544 6689 to arrange for survey								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 24 Aug 2018

Preliminary Advice

Insured Vehicle No	: SJT6222M	Accident Date	: 20/08/2018
TP Vehicle No	: SHC6486G	Assignment Date	: 21/08/2018
Make	: KIA OPTIMA	Est. Duration of Repair	: 2.00
Date of Inspection	: 23/08/2018		
Inspection At	: PREMIER TAXIS PTE LTD - CHANGI (HQ) 23 CHANGI SOUTH AVE 2 #03-02 SINGAPORE 486443		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,307.36
Revised Amount	:S\$	1,153.26
Check Items (Estimated)	:S\$	74.10
Total	:S\$	1,227.36

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	29 May 2015 / 09:23:14	Receipt No.:	AACCK001-AX239-150529-000007
Asset Type:	Vehicle	Transaction Amount:	\$65,428.00
Asset ID:	SHC6486G	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150529092314594388		
Vehicle No.:	SHC6486G		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	29 May 2015		
Original Registration Date:	29 May 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5593621		
Engine No.:	D4FDEH313855		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2014		
Open Market Value:	\$21,451.00		
Minimum PARF Benefit:	\$8,719.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	29 May 2015 09:23:14		
COE No.:	2015052901002472H		
COE Expiry Date:	28 May 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$50,756.00		
Lifespan Expiry Date:	28 May 2023		

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2018 12:48
Date Of Accident	20/08/2018 09:00
Exact Location Of Accident	SLIP ROAD OF CTE/PIE INTO ANG MO KIO AVE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC6486G
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880

Vehicle Particulars

Manufacturer	KIA
Model	OPTIMA-1.7 D (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5095103893
Cover Note Number	

Driver

Name of Driver	GOH YOU CHYE
NRIC No	S6833536A
Date Of Birth	04/10/1968
Occupation	OUTDOOR
Date Of Driving Pass	28/12/1989
Driving Experience	28 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96875336
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 786C #08-75
 WOODLANDS DRIVE 60
 Postcode 733786
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? YES
 Foreign Vehicle Registration Number JMH1100 (MOTORCYCLE)
 Number of vehicles involved in the accident 3
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : PAX IN THE REAR SEAT - CHINESE
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

VEH. A - 1 PAX VEH. B - NO PILLION VEH. C - UNKNOWN PAX

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

Details of Witness 1

Name MR WEE LIP - PAX IN VEH. A
 Phone Number
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number JMH1100
 Vehicle Make/Model/Colour MOTORCYCLE
 Details Of Properties VEH. B
 Vehicle Category MOTORCYCLE
 Name of Driver MALE CHINESE RIDER
 NRIC/Passport Number
 Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJT6222M

Vehicle Make/Model/Colour

HONDA FIT/BLACK

Details Of Properties

VEH. C

Vehicle Category

PRIVATE CAR

Name of Driver

MALE DRIVER

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

20 AUG 2019
a 68335361A
x SHC64866

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Describe Circumstance of the Accident.

·CHAIN COLLISION·

ON 20/08/2018 @ 0900HRS, I WAS DRIVING MY TAXI (SHC 6486 G) TRAVELLING ALONG THE SLIP ROAD OF CTE/CITY INTO ANG MO KIO AVE 5 WITH A PASSENGER ONBOARD.

WHEN ONCOMING TRAFFIC WAS CLEAR AND I WAS ABOUT TO MOVE OFF AHEAD, SUDDENLY THE FRONT LEFT PORTION OF MY TAXI ACCIDENTLY COLLIDED ONTO VEHICLE B (JMH 1100 – M/CYCLE) WHICH WAS SQUEEZING ON MY LEFT ABRUTPLY. AS SUCH, THE RIDER FELL ON THE GROUND BUT SUFFERED NO INJURY.

SUBSEQUENTLY WHEN STILL STATIONARY, SUDDENLY I FELT AN IMPACT FROM THE REAR.

I THEN ALIGHTED TO CHECK ON RIDER OF VEHICLE B BUT THEN NOTICED VEHICLE C (SJT 6222 M – HONDA FIT) WHICH WAS COLLIDED ONTO THE REAR OF MY TAXI – DROVE OFF AWAY WITHOUT STOPPING.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE REAR PORTION AND I WAS NOT AWARE OF DAMAGES TO OTHER VEHICLES.


MY PASSENGER – MR WEE LIP WHO WAS IN THE REAR SEAT, WILLING TO BE MY EYE WITNESS.

NO AMBULANCE AT SCENE.
NO PILLION ONBOARD VEHICLE B AND UNKNOWN PASSENGERS ONBOARD VEHICLE C.

*VIDEO FOOTAGE CAPTURED.

CHAIN COLLISION / MULTIPLE VEHICLES



DAMAGES FOUND ON VEHICLE A, B, C, D & E



PREMIER TAXI



VEHICLE B
JMH 1100



THIRD PARTY VEHICLES

[Signature] 68335-36A

Driver's Signature & NRIC Number
Monday, August 20, 2018 @ 1:03:07 PM

Sketch Plan Pg. 4

PREMIER TAXIS	HIRER RELIEF / SUPER RELIEF
VEHICLE NO.	S4C64869
CONTACT NO.	9687 5336
NEW MAILING ADDRESS (if any)	

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6833536A



Name: GOH YOU CHYE
吴佑财
Race: CHINESE
Date of Birth: 04-10-1968 Sex: M
Country of Birth: SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S6833536A
Name: GOH YOU CHYE
Birth Date: 04 Oct 1968
Issue Date: 06 Sep 2003




A0083231



UIC No: S6833536A



Blood Group: B+ Date of issue: 29-11-2001

Address:
APT BLK 786C WOODLANDS DRIVE 60
#08-75
SINGAPORE 733786

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIE

		PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	02 Nov 1985
Class 2A	Motorcycles between 201 cc and 400 cc	15 Dec 1990
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	28 Dec 1989
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	17 Jul 1991
Class 5	Motor Vehicles which are not constructed themselves to carry any load and the weight of which unladen exceeds 7250 kilograms	10 Sep 1991

NP 428A

Licence No: S6833536A



Land Transport Authority

VOCATIONAL LICENCE

Licence No: S6833536A
Name: GOH YOU CHYE
Issue Date: 31/8/2005

Please visit www.lta.gov.sg to check the status of this vocational licence



PREMIER AUTOMOTIVE SERVICES PTE LTD
23 Changi South Ave 2
#01-02, Singapore 486443

Assessment Number: MSIG0031
Version: PREMIERA/1

Assessor Report
Printed: 21/08/2018

Summary Information

Claim

Claim Reference:	SHC6486G	Insured:	
Policy Number:		Third Party:	
Date of Decision:	21/08/2018	Able to Authorise Repairs:	TBA
Repairer:		Repairs Authorised?	TBA
Estimated Repair Time (Working Days):	0.0		

Insured's Liability

Excess:	TBA
Customer Contribution:	\$0.00 (excl GST)

Vehicle Details

Vehicle			
Registration:	SHC6486G	VIN/Chassis Number:	
Manufacturer:	KIA	Model:	Optima
Registration Month:	May	Registration Year:	2015
Odometer:	Not Known	Colour:	
Build Date:			
Model Specs	FROM 05/2015 PREPARE OFF VEHICLE BASECOAT CLEAR		

Vehicle Condition

Vehicle Status

Date of Incident:	20/08/2018	Market Value:	Unknown
Pre-Accident Condition:		Salvage Value:	Unknown
Pre-Accident Damage:		Date of Inspection:	21/08/2018
Steering Rim Ply:		Place of Inspection:	
Brake Pedal Travel:			
Vehicle Status:			
Damage Severity:			

Tyres Condition:

Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:

Repair Information

LABOUR	Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR	
	Price/Dent = \$50.00/HR	
Repair / Guide Number Repair Details	WU	Cost Price (\$)
86520R00 RENEW REAR BUMPER (REMOVED)	11.0	55.00
86621R00) R + R BUMPER ABSORBER	4.0	20.00
LABOUR COST	15.0	
Total Work Units	0.0HRS	0.00
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	1.5HRS	\$75.00
Sub Total	2.9HRS	\$145.00
Paint Labour	4.4HRS	\$220.00
Total Labour		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 Changi South Ave 2
#01-02, Singapore 486443

Assessment Number: MSIG0031
Version: PREMIERA/1

Assessor Report
Printed: 21/08/2018

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- BASECOAT CLEAR		
2583	REAR BUMPER NEW PART PAINT K1R	14.0	
	LABOUR COST - PAINT		
	TIME(PAINT)	14.0	
	Preparation Main Work Plastic	15.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	29.0	
	Total Paintwork Labour	2.9HRS	\$145.00
	MATERIAL COST - PAINT		Cost Price
	New Part Painting - Plastic K1R		\$70.36
	Material-Const Main Work Plastic		\$28.60
	Total Excluding Pearlescent Uplift		\$98.96
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$98.96

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
2583	1	REAR BUMPER	866112T500	<i>Retard</i>	0%	696.00*
2644	1	REAR BUMPER DAMPER	866202T500	<i>Xsu</i>	0%	114.00*
2770	1	REAR BUMPER SPOILER	866122T500	<i>cl</i>	0%	206.00*
f: OEM Parts			Sub Total			\$1,016.00
g: Original			Deduction from RRP (35 %)			-\$355.60
h: Secondhand			Total Parts			\$660.40
p: Parallel						
x: Exchange						

Price Valid: 01/06/2015

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
REAR BUMPER CLIPS SPECIALIST	0% <i>see</i>	\$48.00
REVERSE SENSOR SPECIALIST	<i>skipped</i>	\$280.00 <i>200</i>
Total Extras		\$328.00

Final Calculation

Total Parts		\$660.40
Labour		
Total Panel/Mechanical	55	\$75.00
Total Paintwork		\$145.00 ✓
Total Labour		\$220.00
Additional Costs		
Corr Prot Materials External		\$0.00
Corr Prot Materials Internal		\$0.00
Cost of Specialist		\$328.00
Total of Additional Costs		\$328.00
Total Paint/Material Costs		\$98.96 ✓
Grand Total Excludes GST		\$1,307.36

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 Changi South Ave 2

#01-02, Singapore 486443

Assessment Number: MSIG0031

Version: PREMIERA/1

Assessor Report

Printed: 21/08/2018

GST @ 7 %

Grand Total Includes GST

\$91.52

\$1,398.88

Assessment Notes

Kahr/UCR

23/8/18 09 40 Lm

2 Rsr

4s

After Repair


24/8/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore

408933

Claim Reference: SHC6486G
Assessment Number: MSIG0031
Version: PREMIERA/1
Date Calculated: 10/09/2018 02:51

Full Report - V1
Registration: SHC6486G
Printed: 10/09/2018 09:52

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	20/08/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	SHC6486G	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	KIA
Model:	Optima
Sub Model:	BASE MODEL
Model Sheet Number:	2836 01
Registration:	SHC6486G
Registration Month:	May
Registration Year:	2015
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 05/2015	PREPARE OFF VEHICLE
BASECOAT CLEAR	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	21/08/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	



Addresses

Cost Summary

Total Labour	\$200.00
Total Paint/Material	\$98.96
Total Parts	\$586.30
Total of Additional Costs	\$248.00
Excess:	TBA
Grand Total Exc GST:	\$1,133.26
7 % GST:	\$79.33
Grand Total Inc GST:	\$1,212.59

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
 Price/Dent = \$50.00/HR

Repair /

Guide Number Repair Details
 86520R00 RENEW REAR BUMPER (REMOVED)

LABOUR COST

	WU	Cost Price (\$)
Total Work Units	11.0	55.00
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	1.1HRS	\$55.00
Paint Labour	2.9HRS	\$145.00
Total Labour	4.0HRS	\$200.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number Description

	WU	Cost Price (\$)
2583 - PREPARE OFF VEHICLE		
- BASECOAT CLEAR		
REAR BUMPER NEW PART PAINT K1R	14.0	
LABOUR COST - PAINT	14.0	
TIME(PAINT)	14.0	
Preparation Main Work Plastic	15.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	29.0	
Total Paintwork Labour	2.9HRS	\$145.00
MATERIAL COST - PAINT		Cost Price
New Part Painting - Plastic K1R		\$70.36
Material-Const Main Work Plastic		\$28.60
Total Excluding Pearlescent Uplift		\$98.96
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$98.96

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
2583	1	REAR BUMPER	866112T500		0%	696.00*
2770	1	REAR BUMPER SPOILER	866122T500		0%	206.00*
f: OEM Parts						\$902.00
g: Original						- \$315.70
h: Secondhand						\$586.30
p: Parallel						
x: Exchange						
Sub Total						
Deduction from RRP (35 %)						
Total Parts						

Price Valid: 01/06/2015

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras	Description	Betterment	Price
	REAR BUMPER CLIPS SPECIALIST	0%	\$48.00
	REVERSE SENSOR SPECIALIST		\$200.00
Total Extras			\$248.00

Final Calculation

Total Parts		\$586.30
Labour		
Total Panel/Mechanical	\$55.00	
Total Paintwork	\$145.00	
Total Labour		\$200.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$248.00	
Total of Additional Costs		\$248.00
Total Paint/Material Costs		\$98.96
Grand Total Excludes GST		\$1,133.26
GST @ 7 %		\$79.33
Grand Total Includes GST		\$1,212.59

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Aug 2018		21 Aug 2018 15:56 Edit Adj Rpt	S\$900.00 Edit Estimates	S\$900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	FOO CHEE MENG , ID: S6827396Z								
Main Claimant:	PREMIER TAXIS PTE LTD , Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHC6486G	Date of Loss:	20/08/2018 09:00 - :59 [38 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 567819	Policy/Cover Note No.:	29076690QMX (Comprehensive) Coverage: 22/04/2018 - 21/04/2019						
Vehicle Reg. No. (Insured):	SJT6222M	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02, 486443 Changi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 20/09/2018]								
Adj Asg. Remarks:	Car in. on WP. Please contact us ASAP if you cannot attend this assignment. w/shop will give estimate when surveyor go down. LIABILITY : NOT CLEAR (NON-REPORTING) Please take notes if IHS cannot survey , Kindly outsource to LKK AUTO to conduct the survey , Kindly contact the workshop directly @ 6544 6676 or 6544 6689 to arrange for survey								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All	Search Tasks	Create New Task	Complete		
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC6486G (567819)
 [SJT6222M]
 TP
PREMIER TAXIS PTE LTD
Aug 20 2018 9:00AM
[FOO CHEE MENG]
Premier Taxis Pte Ltd - Changi

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View View in Browser <input type="button" value="v"/>
Letters/Correspondences			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Print
1	21/08/18 09:08	Non Reporting Letter to OI	<input checked="" type="checkbox"/> Load HTM
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	24/08/18 16:43	Adjuster Immediate Advice	<input checked="" type="checkbox"/> Load HTM
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
2	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
3	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
4	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
5	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
6	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
7	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
8	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
9	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
10	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
11	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
12	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
13	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
14	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
15	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
16	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
17	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
18	23/08/18 18:51	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
19	07/09/18 17:22	Reinspection Photo	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
20	07/09/18 17:22	Reinspection Photo	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
21	07/09/18 17:22	Reinspection Photo	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
22	07/09/18 17:22	Reinspection Photo	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Print
1	21/08/18 09:09	TPD SHC6486G - PRI	<input checked="" type="checkbox"/> Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
----------------------------	---

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18015252/K1QD3E2
Date: 14/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 29076690QMX	
Claimant Vehicle No: SHC6486G	Insured Vehicle No: SJT6222M	
Date of Loss: 20/08/2018	Nature of Claim: TP	Claim No: 567819

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC6486G		Engine No: D4FDEH313355
Make & Model: KIA OPTIMA, 1.7 D CRDi (A)		Chassis No: KNAGM414MF5593621
Reg. Date: 29/05/2015 (Man. Year: 2014)		Odometer: 369087 km
Colour: Silver		
Engine Capacity: 1685 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16	Rear Tyre Size: 205/65 R16
Front Left Side: Maxxis 7 mm	Rear Left Side: Maxxis 7 mm
Front Right Side: Maxxis 7 mm	Rear Right Side: Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	988.40	834.30	154.10	15.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	318.96	298.96	20.00	6.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,307.36	1,133.26	174.10	13.32
Approved Total (Overridden) (S\$)		900.00		
(S\$)	1,307.36	900.00	407.36	31.16
+ GST 7.00/7.00% (S\$)	91.52	63.00	28.52	31.16
Nett Amount (S\$)	1,398.88	963.00	435.88	31.16

INSPECTION

Date of Assignment:	21/08/2018	
Date Inspected:	23/08/2018	Inspected At: Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02 Singapore 486443
Estimated Period of Repair:	2.0 days	

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2018)
Parts: 143	KIA OPTIMA 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC6486G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	696.00 FL	*696.00 FL	
2	1		*REAR BUMPER DAMPER	Serviceable	114.00 FL	*- FL	
3	1		*REAR BUMPER SPOILER	Cut	206.00 FL	*206.00 FL	
4	1		*REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS	
5	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS	
					Sub Total (S\$)	1,344.00	1,150.00
					- List Item Discount on L Items 35.00/35.00% (S\$)	355.60	315.70
					Total Parts (S\$)	988.40	834.30

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOTAL PANEL / MECHANICAL	New	75.00	55.00
2	TOTAL PAINTWORK	New	145.00	145.00
3	TOTAL PAINT / MATERIAL COSTS	New	98.96	98.96
Gross Labour Cost (\$\$)			318.96	298.96

Report was unsubmitted during this print-out.

< END OF ESTIMATES >