(08/11/11)

Surveyor

REF: III

ASSIGNMENT

From: Date: 29.08.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJL 7929T

at Workshop m/s K. Kim Hin Auto

of Blk 160 Sin Ming Drive #03-20

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: 8

IDAC Accident Rport: Consistent? : **Yes** or **No**

GIA / PR Seen: Consistent? : **Yes** or **No**

Est. Repairs: 02 days Res.: **Yes** or **No**

Lum Sum: 20 % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS

Vehicle: **IN / OUT**

Date: Person Contacted:

Veh No: SJL 7929T Yr Regn: 12 / 08

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer** or

Make: Hyundai (m) Avante c.c 1591

Colour M. Silver A/C: **Insured / Std / NI / NA**

Sp.Reading 129404 T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: KMHDU41BR946234 56

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi : **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: 205/55R16

R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	8 mm	R/Bal.	8 mm
L/Bal.	8 mm	L/Bal.	8 mm
D.O.A.	19/8/18	D.O.I.	29/8/18

Survey held at ✓

Des. of Damages : **Frt / Rear / O/S / N/S / U/C / Rooftop** or

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
30/8	File pass to Carhome

Date/Time, File Pass to? ☐ : **Preli. Report**

1) ☐ : **Final Report**

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: ___S + RS.___SI

Photos

Others

TOTAL