

PDI TUAS

PDI TUAS

TONG HOR SENG, KENNETH  
@DONG KECHENG  
7 AMBER GARDENS  
#10-17  
Singapore, 439974  
Singapore

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

### Service Quote

Customer No. CV010665  
Quote No. SER/QUO/1801378  
QuoteDate 23/08/18  
Salesperson Delsie Ong  
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 VARIANT 1.4 (DSG) 92KW	17,228	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SLB1981J	WVWZZZAUZGP577312	30/03/16	Delsie Ong
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 085299	BA54HZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	3	UNIT		840 <del>2,820.00</del>
P B&P ALEX PAINT	SPRAY PAINT	3	UNIT		800 <del>1,500.00</del>
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		480.00
P B&P MECH	CHECK WIRE HARNESS, ECU, S Nett	1	Time Un		280.00
	<b>Sum Labor</b>				<b>4,780.00</b>
P 5G9807305A	BUMPER REINFORCEMENT	1	Pieces		? 544.14
P 5G9807375	BUMPER BRACKET LHS	1	Pieces		? 59.73
P 5G9807376	BUMPER BRACKET RHS	1	Pieces		? 52.42
P 5G9807393A	BUMPER RETAINER LHS	1	Pieces		? 52.42
P 5G9807394G	BUMPER RETAINER RHS Predecessor 5G9807394A	1	Pieces		? 52.42
P 5G9807417H GRU	REAR BUMPER	1	Pieces		DE / 1,416.49
P 5G9807568H 041	REAR LOWER RDIFFUSOR	1	Pieces		CRA / 438.09
P 5G9807863A	REAR CENTER STRIP	1	Pieces		? 86.43
P 5G9919491	SENSOR BRACKET	1	Pieces		net / 34.98
P 5G9919491A	SENSOR BRACKET	1	Pieces		net / 34.98
P 5G9919491A	SENSOR BRACKET	1	Pieces		net / 34.98
P 5G9919492	SENSOR BRACKET	1	Pieces		net / 34.98
P 5Q0919133 704	SENSOR O RING	1	Pieces		net / 2.53
P D 180KU2A1	2KADHESIVE	1	Pieces		net / 103.66
P D 822150A1	BONDAGENT	1	Pieces		net / 74.16
	<b>Sum carried forward</b>				<b>7,802.41</b>

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

TONG HOR SENG, KENNETH  
@DONG KECHENG  
7 AMBER GARDENS  
#10-17  
Singapore, 439974  
Singapore

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

### Service Quote

Customer No. CV010665  
Quote No. SER/QUO/1801378  
QuoteDate 23/08/18  
Salesperson Delsie Ong  
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 VARIANT 1.4 (DSG) 92KW	17,228	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SLB1981J	WVWZZZAUZGP577312	30/03/16	Delsie Ong
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 085299	BA54HZ

Continued 7,802.41

Sum Item 3,022.41

Sum Labor 4,780.00  
Sum Item 3,022.41

Total SGD 7,802.41  
7% GST 546.17  
Total SGD Incl. GST 8,348.58

#### Explanations

P = Proportionately Charged

#### Payment Terms

No Credit

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*RASUL*  
*Hp 90010068*  
*3 days*  
*27/08/18 @ 1310*

Payments to: - BBN: - Acc.-No.: