

ASS. REC. BY:

REF: CS3/MSG18015331/G24d3e1 Special Instruction:

Surveyor: Guo Qiang
Meimen

ASSIGNMENT (Office)

From (Person): Acaine Ngui of MSG Date/Time: 23/8/18 @ 9:35am

Estimated Cost: _____ Bill to: _____

OD TP WS TP RES OD RES EVA INV MV CS

To Inspect Vehicle No: SLJ 8181M Insured: SGS 9696A

at Workshop m/s 6 speed Autowerkz Tel: 8533 2934

of 68 Kaki Blk Ave 6 # 02-05

Policy No: A28867776QMX Claim No: 567840

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 18/08/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS (up) H.O.D. Endorsement: _____

Date/Time: 11:07am @ 23/8/18 Person Contacted: Sun Sun Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	SLJ 8181M - NA LPI 8015076/h4 DOA: 18/8/18
	SGS 9696A - NA LPI 8015076/h4 DOA: 18/8/18
<u>24/8/18</u>	<u>2ism angle d.</u>

REF: **MSG**


4249F /

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s **6 speed Autowerkz**
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **SLI8181M** Yr Regn: **08 Nov 2016**
 Type: **C** M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Honda civic** c.c **1498**
 Colour: **black** A/C: Insured / Std / NI / NA
 Sp. Reading: **48179** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **MR & HFC 166097000226**
 Gen. Cond: **C** Good / Fair / Poor / Burnt
 Steering: **C** In order / Jammed / Leaked / Burnt or _____
 Brake: **C** In order / Jammed / Leaked / Burnt or _____
 Modi: **C** Nil / S/Rim / STD A/Rim or _____

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**



Tyre Size: F: **235/40 R18**
 R: **11**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Continental**
 Front: _____ Rear: _____
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. _____ D.O.I. **23-08-18**
 Survey held at **W/S** **1:30pm**
 Des. of Damages: **C** Frt / Rear / O/S / N/S / U/C / Rooftop or _____

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **3** days Res.: Yes or No
 Lum Sum: **20** % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: **IN / OUT**

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$2000 - \$3000
28/9/18	submit PR reply.

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair:

1) _____
 Date/Time, File Return to?
 2) _____

Resurvey No. of Trip: _____

Survey Fee:	120
Transportation:	
____ S + RS. ____ SI	
Photos	
Others	10
TOTAL	130

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Report Format : _____
 Lump Sum / I.B.I. (\$) _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Aug 2018		23 Aug 2018 09:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN TECK SAI , ID: S1711503J, Tel: +6596838885, Email: raymondtan8586@gmail.com								
Main Claimant:	TAN TAI JIA (CHEN TAIJIA) , ID: S8124249F								
Vehicle Reg. No.:	SLJ8181M	Date of Loss:	18/08/2018 13:00 - :59 [21 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 567840	Policy/Cover Note No.:	A28867776QMX (Comprehensive) Coverage: 24/12/2017 - 23/12/2018						
Vehicle Reg. No. (Insured):	SGS9696A	Policy No. (Claimant):							
		Excess:							
Repairer:	6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB, 417896 Kaki Bukit - Tel: 85332934								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/08/2018]								
Driver/Custodian (Insured):	TAN TECK SAI (52 / Male), NRIC: S1711503J, Tel: +6596838885								
Adj Asg. Remarks:	liability: 100%. TP reject SJE -assign LKK Auto Consultants Pte Ltd. contact: Sun Sun (8533 2934)								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18015331/Gz4d3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 23-08-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SGS 9696A	Veh. Inspected	SLJ 8181M
Policy No.	A28867776QMX	Coverage (\$)	0.00
Claim No.	567840	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	23/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/08/2018	Inspection Date	23/08/2018
Survey held at	6 SPEED AUTOWERKZ- 68 KAKI BUKIT AVE 6 #02-05		
Repairer	-		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2018 13:33
Date Of Accident	18/08/2018 13:30
Exact Location Of Accident	TPE TWDS SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ8181M
Insured/Policyholder	
Name Of Registered Owner	TAN TAI JIA (CHEN TAIJIA)
NRIC No	S8124249F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98206310
Alternative Phone No	OFFICE-98206310

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC 1.5 TURBO VTIS SR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD16V15150/VPC2/R00
Cover Note Number	-

Driver

Name of Driver	TAN TAI JIA (CHEN TAIJIA)
NRIC No	S8124249F
Date Of Birth	12/08/1981
Occupation	INDOOR
Date Of Driving Pass	28/03/2001
Driving Experience	17 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98206310
Fax Number	
Contact Number	OFFICE-98206310
EEmail Address	NOEMAIL

Address	BLK 208B COMPASSVALE LANE #10-84
Postcode	542208
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SENGKANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 2 SENKANG SQUARE #01-02 SINGAPORE , POSTCODE: 545025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800 - 3438999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGS9696A
Vehicle Make/Model/Colour	
Details Of Properties	

Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLA6389S
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SHD4504X
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SLM7706R
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan

IMPORTANT NOTICE

IMPORTANT NOTICE

- 1. Please refer carefully the terms and conditions attached to the claim process.
- 2. The claim form to be completed by the Policyholder and the Insured Party.
- 3. Every claimant/proxy must be a party to the accident or involved in the occurrence or withholding of material information in the occurrence submitted to insurance company.
- 4. The signed application of the Policyholder and Insured Party is a contract of insurance between the party of the insurance company.
- 5. Available insurance that is required to pay for the accident.
- 6. The claimant/proxy must be a party to the accident or involved in the occurrence or withholding of material information in the occurrence submitted to insurance company.
- 7. The claimant/proxy must be a party to the accident or involved in the occurrence or withholding of material information in the occurrence submitted to insurance company.
- 8. Consent when the Personal Data Protection Act applies.
- 9. Insured Party/Proxyholder agree and understand:
 - (a) to provide, verify, update and the Special Trade Association of Insurers (STAI) and other relevant organizations, necessary details, particularly personal and personal information (not including financial and other personal information) provided by the or disclosure of the insured/collective the "Personal Information" (name, address and phone number) and other information for all purposes, who may involve vehicles involved in the accident (as insured) who have insured vehicles involved in the accident (not collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the insurers' agents, of Singapore and any relevant government agency/authority (such as the police, for the purposes of the accident).
 - (b) providing, tracking and/or dealing with the claims, including the settlement of the claims and any necessary correspondence relating to the claims.
 - (c) investigating the accident/cause of the claims.
 - (d) being and/or dealing with any correspondence relating to any enquiries and.
 - (e) providing my claims, including the making of an affidavit, statements, written responses/notes to the claims, which may involve disclosure of certain personal data and the tracking about delivery of the claim or whether on the actual cover of the respective insurance policies.
 - (f) dealing with representative, including, tracking and/or dealing with the claims, collectively the "Pursuers".
- 10. If any party would have and/or involved in the accident and the insurers' lawyers/law firms may have permitted to collect use, disclose and/or to access my Personal Information for any purpose of the above Pursuers and.
- 11. Any correspondence may be disclosed by or to any Pursuers and/or any other third party, previous providers or agents including their respective lawyers, which may be disclosed outside of Singapore, for the purpose of the above Pursuers.
- 12. My Personal Information will be collected and used to handle claims for the purpose of these details, investigation, and management in present and in future claims.
- 13. My Personal Information will be collected and used to handle claims for the purpose of these details.
- 14. My Personal Information will be collected and used to handle claims for the purpose of these details, including, tracking and/or dealing with the claims, including the settlement of the claims and any necessary correspondence relating to the claims.
- 15. My Personal Information will be collected and used to handle claims for the purpose of these details, including, tracking and/or dealing with the claims, including the settlement of the claims and any necessary correspondence relating to the claims.


Insured Party's Signature
Date: _____

Driver's Signature
Date: _____

Representative Signature
Date: _____

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS
 PA
 POLICE
 10 POINT

DECLARATION

I hereby declare that the foregoing particulars are true in every respect.

Signature

[Signature]

If more than one declarant

Signatures

[Signature]

Date

Signature

[Signature]

SHC6411Y Silver Kia Taxi

- | | | | | | |
|------|---|-----------|--------------------------|--------------------------------|----------|
| 1D3P | ① | SLJ 881M | Black Civic | Tan Tai Jia
(58124249F) | 98206310 |
| 1D1P | ② | SGS 9696A | Black Bmw
523i | Tan Teck Sai
(51711503J) | 96838885 |
| 1D1P | ③ | SLA 6389S | Black Mercedes
CLA180 | Priscilla Tan
(576017106) | 90686332 |
| 1D2P | ④ | SHD 4504X | Blue Gmfort Taxi | Chong Boon Kiat
(57104795D) | 93886101 |
| 1D4P | ⑤ | SLM 7706R | Black Mazda 3 PHV | Lee Chee Koon
(579154600A) | 91129595 |



Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

CONTINUATION OF REPORT

Name	LEE CHEE KOON		ID No.	S7915460A
Related Vehicle	NIL		Contact No.	91129595
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	CHONG BOON KIAT		ID No.	S7104795D
Related Vehicle	NIL		Contact No.	93886101
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Vehicle Owner				
Name	TAN TAI JIA		ID No.	S8124249F
Related Vehicle	NIL		Contact No.	98206310
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	TAN TECK SAI		ID No.	S1711503J
Related Vehicle	NIL		Contact No.	96838885
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL



Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

CONTINUATION OF REPORT

Driver			
Name	PRISCILLA TAN	ID No.	S7601710G
Related Vehicle	NIL	Contact No.	90686332
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 18/08/2018 at about 1331hrs, I was driving my vehicle (Plate no.: SLJ8181M) on lane 1 along TPE heading towards SLE. The weather and visibility of the road was clear. My wife, daughter and mother-in-law were in the vehicle as well. There was a taxi in front of me (Silver, Kia, plate no.: SHC6411Y) came to a stop. I also followed suit and came to a complete stop. At the next moment, we heard a couple of car collisions that had also occurred. I felt an impact on the rear of my vehicle which caused my vehicle to inch forward. My vehicle did not collide into the taxi, he left after he made a quick check of his vehicle and drove off. Afterwards, I got off my vehicle to make a check and realized a vehicle (Black, BMW, plate no.: SGS9696A) collided into the rear of my vehicle that caused a chain collision of vehicles along the road. We took photos and exchanged our particulars.

There was another car accident that occurred before my car accident. I believe that few seconds earlier, the taxi (Plate no.: SHC6411Y) came to a stop because of that accident. The vehicles that were involved in the accident were a Silver, Toyota Avanza, Plate no.: JJG1656 and a black, BMW, Plate no.: SLW3967C.

The AETOS and SCDF attended to our incident. I understood that someone was sent to the hospital by the ambulance. The traffic police, Mr Azrin took my particulars and the SD memory card of my in-car camera and was issued an acknowledgement form. He advised me to make a traffic accident report within 24hours, I am lodging this report for my insurance claims as well. That is all.

Vehicles involved in the accident as follow in the following sequence:

- 1) SLJ8181M
- 2) SGS9696A
- 3) SLA6389S
- 4) SHD4504X
- 5) SLM7706R



**SINGAPORE
POLICE FORCE**



T/20180819/2008

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

4 of 4

Report No. T/20180819/2008


CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 LEE LI TING, JOLYNE	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 19/08/2018 01:25
Officer In Charge Of Case: TP / GIT / Sgt 2 LIM HONG LEE Contact No.: 65476438	Classification Of Case:
Authentication Stamp NP168  Singapore Police Force	



Liberty Insurance Pte Ltd
Registration no.199002791D
51 Club Street
#03-00 Liberty House
Singapore 069428
Tel: (65) 6221 8611 Fax: (65) 6225 6890
Website: <http://www.libertyinsurance.com.sg>

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No	SD16V15150/VPC2/R00
Form	MX1
Date of Issue	16-NOV-2016
1.Index Mark and Registration No. of Vehicle:	SLJ8181M
2.Chassis number of Vehicle:	MRHFC1660GT000226
3.Name of Policyholder:	TAN TAI JIA (CHEN TAIJIA)
4.Effective date of Commencement of Insurance for the purposes of the Act:	08-NOV-2016 00:00 AM
5.Date of Expiry of Insurance:	07-NOV-2018 23:59 PM
6.Persons or Classes of Persons entitled to drive*:	
A) The Policyholder.	
B) Any other person who is driving on the Policyholder's order or with his permission.	
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.	
7.Limitations as to use*:	
Use only for social, domestic and pleasure purposes and for the Policyholder's business.	
8.The Policy does not cover:	
A) Use for hire or reward.	
B) Use for racing, pace-making, reliability trials or speed-testing.	
C) Use for the carriage of goods (other than samples) in connection with any trade or business.	
D) Use for any purpose in connection with the Motor Trade.	
*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.	
I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).	
For and on behalf of LIBERTY INSURANCE PTE LTD Approved Insurers	
 _____ Authorised Signature	
For Information only:	
COVERAGE :	Comprehensive, Unlimited Windscreen, Ncd Protection
SUM INSURED:	MARKET VALUE AT THE TIME OF LOSS
EXCESS:	Section I S\$800, Additional Excess For Young, Elderly & Inexperienced Drivers S\$3000, Windscreen Excess S\$100
FINANCE COMPANY:	OVERSEA-CHINESE BANKING CORPORATION LTD
PRODUCER NAME:	KAH MOTOR COMPANY SDN BERHAD

PLST/PLST/16-NOV-16

S1_CI_T1_T3_OE_Template2-Ver1.

16-NOV-16

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4249F
Vehicle Details	
Vehicle No.:	SLJ8181M
Vehicle to be Exported:	No
Intended De-registration Date:	24 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.5 TURBO VTIS SR
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	L15B71626355
Chassis No.:	MRHFC1660GT000226
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$26,342.00
Original Registration Date:	08 Nov 2016
First Registration Date:	08 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$23,879.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Nov 2026
PARF Rebate Amount:	\$17,909.00
Intended COE Rebate Details	
COE Expiry Date:	07 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,002.00
COE Rebate Amount:	\$46,769.00
Total Rebate Amount:	\$64,678.00

The information contained herein is correct as at 24 Aug 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Aug 2018		23 Aug 2018 09:35 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TAN TECK SAI, ID: S1711503J, Tel: +6596838885, Email: raymondtan8586@gmail.com								
Main Claimant:	TAN TAI JIA (CHEN TAIJIA), ID: S8124249F								
Vehicle Reg. No.:	SLJ8181M	Date of Loss: 18/08/2018 13:00 - :59 [21 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 567840	Policy/Cover Note No.: A28867776QMX (Comprehensive) Coverage: 24/12/2017 - 23/12/2018							
Vehicle Reg. No. (Insured):	SGS9696A	Policy No. (Claimant):							
		Excess:							
Repairer:	6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB, 417896 Kaki Bukit - Tel: 85332934								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 24/08/2018]								
Driver/Custodian (Insured):	TAN TECK SAI (52 / Male), NRIC: S1711503J, Tel: +6596838885								
Adj Asg. Remarks:	liability: 100%. TP reject SJE -assign LKK Auto Consultants Pte Ltd. contact: Sun Sun (8533 2934)								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLJ8181M (567840)**
[SGS9696A]
TP
TAN TAI JIA (CHEN TAIJIA)
Aug 18 2018 1:00PM
[TAN TECK SAI]
6 Speed Autowerkz Pte Ltd

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>		View <input type="button" value="View in Browser"/>		
Assessment Reports		1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/08/18 10:24	Accident Statement <small>From:SC - Reg. No: SGS9696A, Claimant: TAN TECK SAI</small>	Load HTM	<input type="checkbox"/>
Photos/Images		3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
2	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
3	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
4	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
5	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
6	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
7	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
8	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
9	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
10	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
11	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
12	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
13	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
14	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
15	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
16	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
17	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
18	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
19	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
20	28/08/18 11:45	General View	Load JPG	<input checked="" type="checkbox"/>
21	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
22	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
23	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
24	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
25	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
26	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
27	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
28	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
29	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
30	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
31	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
32	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
33	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
35	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
36	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
37	28/08/18 11:45	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/08/18 10:21	TP PRI NOTICE	Load PDF	
2	21/08/18 10:24	TP REJECT SJE - ASSIGN LKK.	Load PDF	
3	21/08/18 10:24	SLJ8181M e-file report From:SC - Reg. No: SGS9696A, Claimant: TAN TECK SAI	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015331/GZ4D3E2
Date: 29/08/2018REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28867776QMX
Claimant Vehicle No :	SLJ8181M	Insured Vehicle No :	SGS9696A
Date of Loss:	18/08/2018	Nature of Claim:	TP
			Claim No: 567840

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ8181M	Engine No:	L15B71626355
Make & Model:	HONDA CIVIC, 1.5 TURBO VTI-S SR (A)	Chassis No:	MRHFC1660GT000226
Reg. Date:	08/11/2016 (Man. Year: 2016)	Odometer:	48179 km
Colour:	Black		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	23/08/2018	
Date Inspected:	23/08/2018	Inspected At:
		6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB Singapore 417896

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Aug 2018)
Parts: 143	HONDA CIVIC 1.5 TURBO VTI-S SR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ8181M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >