

ASS. REC. BY:

REP:

CS/FCI/8015356/Ard3<sup>n2</sup>

Special Instruction:

Surveyor:

Adnan

ASSIGNMENT (Office)

From (Person):

Gerene Jer

of

FCI

Date/Time:

21/8/18 @ 7:05pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLZ 2364H

Insured:

SH 9859M

at Workshop m/s

Keng Car Repairs

Tel:

677477 636

of

1 Kaki Bkt Ave 6 # 0206 Autokay

Policy No:

Claim No:

D18006125MP3H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/08/2018

CA / REV / REP. / REV 24 HRS

DS

H.O.D. Endorsement:

Date/Time:

10:16am @ 23/8/18

Person Contacted:

Sharon

Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate                       |
|-----------|-------------------------------------------------------|
|           | SLZ 2364H - X                                         |
|           | SH 9859M - CC3 / AIG 10005698 / Fg 202k2 DOA: 17/3/10 |
| 10/9/18   | Sent pending estimate thru email                      |
| 18/10/18  | Sent IA thru email                                    |

ASS. REC. BY: Adrian Ling

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: 522 23644 Yr Regn: 2018 April

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 2067 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: R231269470

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16.

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 07/09/18

Survey held at Kang.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP # 1st Cap.

Adrian confirm \$1504.56, 3 days  
Red: \$330, 18/.

RECEIVED 22 OCT 2018

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2)

Report Format: 7P

Lump Sum / L.B.I. (\$) 1504.56

☐

Preli. Report

☒

Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S. + RS. \$

Photos

Other:

TOTAL


100

50

50

19

219

  
 18/10/2018



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006125MFSH

Date: 18 October 2018

Our Ref: CS/FCI18015356/Ard3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLZ 2364H .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 07.09.2018 at the premises of M/s KANG CAR REPAIRERS PTE LTD and have the following to report:-

|                          |                                     |
|--------------------------|-------------------------------------|
| Workshop Estimate Amount | : S\$ <u>1,834.56</u> .             |
| Revised Estimate Amount  | : S\$ <u>1,504.56</u> .             |
| "Check" Items Amount     | : S\$ <u>                    </u> . |
| Market Value             | : S\$ <u>-</u> .                    |
| LTA Reimbursement Value  | : S\$ <u>-</u> .                    |
| Nett Value               | : S\$ <u>-</u> .                    |

**Description of Damage:**

The vehicle sustained damages at the rear o/s portion.



Yours faithfully

ADRIAN  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

|                    |                                              |                               |
|--------------------|----------------------------------------------|-------------------------------|
| Date               | 15-08-2018                                   | Our Ref No. D18006125MFSH     |
| Accident Date      | 13-08-2018                                   | Claim Type. Third Party       |
| Insured Vehicle    | SH9859M                                      | Third Party Vehicle. SLZ2364H |
| Survey Location    | 1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT |                               |
| Contact Person.    | SHARON                                       |                               |
| Contact No.        | 67477636/ 0                                  | Fax No. 67485071              |
| Survey Type        | DIRECT SETTLEMENT: EST. COR \$1,962.98       |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD                 |                               |
| Contact Person     | NA                                           | Fax No. 68416315              |
| Contact Number.    | NA                                           |                               |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                   |                               |                         |
|-------------------|-------------------------------|-------------------------|
| Cc : Workshop     | KANG CAR REPAIRERS<br>PTE LTD | Attention. NIL          |
| Cc : TP Solicitor | NA                            | TP Solicitor Fax No. NA |
| Officer Incharge  | SERENE                        |                         |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Janice Lee (LKKAuto)

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Monday, September 10, 2018 10:49 AM  
**To:** 'Claim Workflow System'  
**Cc:** SERENELER@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18006125MFSH/1

Dear Sir,

Please be informed that we have inspected the vehicle **SLZ 2364H** on 07/09/2018.

We are still pending estimate from repairer.

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Thursday, August 23, 2018 3:30 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18006125MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Tuesday, 21 August 2018 7:05 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG  
**Subject:** PRI: SURVEY ASSESSMENT - D18006125MFSH/1


Dear Sir/Mdm,

We refer to the above reference.  
Please find attached the necessary documents for survey.  
Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

M/S : MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Estimate No: EST1800263

Date: 21 Aug 2018

Veh Reg No: SLZ2364H

Make/Model: HONDA VEZEL HYBRID  
1.5X AUTO

Chasis No: RU31269470

Reg. Date: 26/04/2018

Your Ref No: SH9859M

Claim Type: Third Party

Accident Date: 13/08/2018

TP Veh Reg No: SH9859M

## Estimate Repair Cost to Vehicle No :SLZ2364H

| Quantity | Description                                                                                                   | List Price | Amount      |
|----------|---------------------------------------------------------------------------------------------------------------|------------|-------------|
|          |                                                                                                               | <u>SS</u>  | <u>SS</u>   |
|          | <b>List Price</b>                                                                                             |            |             |
| 1        | 1 PC REAR SIDE BUMPER RH <i>2nd</i>                                                                           | 1155.70    | 195.00 ✓    |
| 2        | 1 PC REAR BUMPER <i>2nd</i>                                                                                   | 924.56     | 765.70 ✓    |
| 3        | 1 PC REAR FENDER PROTECTOR RH <i>2nd</i>                                                                      |            | 195.00 ✓    |
|          |                                                                                                               | 1,155.70   |             |
|          | Less 20%                                                                                                      | 231.14     | 924.56      |
|          | <b>Special Net</b>                                                                                            |            |             |
| 4        | 1 SET REAR BUMPER CLIPS <i>30</i>                                                                             | 60.00      | 30 ✓        |
|          |                                                                                                               | 60.00      | 60.00       |
|          | <b>Labour</b>                                                                                                 |            |             |
| 5        | 1 TO CHECK WIRING <i>550</i>                                                                                  | 50.00      | x.          |
| 6        | 1 (REAR) TO SPRAY PAINTING                                                                                    | 400.00     | 300         |
| 7        | 1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS. | 400.00     | 200         |
|          | <i>To remove reverse sensor 80 50</i>                                                                         | 850.00     | 850.00      |
|          | <b>Total</b>                                                                                                  |            | SS 1,834.56 |
|          | <b>Add GST @ 7%</b>                                                                                           |            | 128.42      |
|          | <b>Total Amount Payable</b>                                                                                   |            | SS 1,962.98 |

LKK Auto Consultants hence notify the Repairer of the following:

- To reserve before/after repair work.
- To display damaged part(s) during repair.
- Parts prices are subject to confirmation.
- Third party survey is on "Without prejudice" basis.
- No illegal modification(s) is allowed.
- Supplementary item(s) must be reserved and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

TOTAL: SINGAPORE DOLLAR ONE THOUSAND NINE HUNDRED SIXTY TWO AND CENTS NINETY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

total. 1504.56 (P/P) ✓

Adrian Lin  
P/P 07/09/18  
03 Aug



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                                                        |                 |                             |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|-----------------|-----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                                                        |                 | Ref : CS/FCI18015356/Ard3n2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                                                        |                 | Date : 25-10-2018           |  |
|                                                                                                                                                                                        |                                                                                                        |                 | Code : FCI2                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                                                        |                 |                             |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SH 9859M                                                                                               | Veh. Inspected  | SLZ 2364H                   |                                                                                     |
| Policy No.                                                                                                                                                                             |                                                                                                        | Coverage (\$)   | 0.00                        |                                                                                     |
| Claim No.                                                                                                                                                                              | D18006125MFSH                                                                                          | Excess (\$)     | 0.00                        |                                                                                     |
| Assign From                                                                                                                                                                            | SERENE                                                                                                 | Assign Date     | 21/08/2018                  |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                                                        |                 |                             |                                                                                     |
| Make & Model                                                                                                                                                                           | HONDA VEZEL                                                                                            | c.c             | 1496                        |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                                                 | Year of Reg.    | 2018                        |                                                                                     |
| Chassis No.                                                                                                                                                                            | RU31269470                                                                                             | Colour          | BROWN                       |                                                                                     |
| Odometer                                                                                                                                                                               | 2067                                                                                                   | Steering        | IN ORDER                    |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                                               | Modification    | SPORTS RIM                  |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                                                   |                 |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                                                        |                 |                             |                                                                                     |
|                                                                                                                                                                                        | Size                                                                                                   | Make            | Balance                     |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 215/60 R16                                                                                             | DUNLOP          | 6 mm                        |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 215/60 R16                                                                                             | DUNLOP          | 6 mm                        |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 215/60 R16                                                                                             | DUNLOP          | 6 mm                        |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 215/60 R16                                                                                             | DUNLOP          | 6 mm                        |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                                                        |                 |                             |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.<br>DAMAGES SEE DETAILS.                                                                                                         |                                                                                                        |                 |                             |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                                                        |                 |                             |                                                                                     |
| Accident Date                                                                                                                                                                          | 13/08/2018                                                                                             | Inspection Date | 07/09/2018                  |                                                                                     |
| Survey held at                                                                                                                                                                         | KANG CAR REPAIRERS PTE LTD<br>NO.1 KAKI BUKIT AVE 6<br>#02-06 AUTOBAY @ KAKI BUKIT<br>SINGAPORE 417883 |                 |                             |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                                                        |                 |                             |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                        |                 |                             |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                                                        |                 |                             |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                                                        | 3 Working Days  |                             |                                                                                     |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 2364H

| Qty                                | Description of Parts                                                                                      | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-----------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>        |                                                                                                           |               |                           |                   |
| 1                                  | REAR SIDE BUMPER RH                                                                                       | DEFORMED      | 195.00                    | 195.00            |
| 1                                  | REAR BUMPER                                                                                               | DEFORMED      | 765.70                    | 765.70            |
| 1                                  | REAR FENDER PROTECTOR RH                                                                                  | DEFORMED      | 195.00                    | 195.00            |
|                                    | LESS 20% DISCOUNT                                                                                         |               | -231.14                   | -231.14           |
|                                    |                                                                                                           |               | 924.56                    | 924.56            |
| <b>SPECIAL NETT ITEMS</b>          |                                                                                                           |               |                           |                   |
| 1                                  | SET REAR BUMPER CLIPS (SN)                                                                                | NECESSARY     | 60.00                     | 30.00             |
|                                    |                                                                                                           |               | 60.00                     | 30.00             |
| <b>LABOUR</b>                      |                                                                                                           |               |                           |                   |
|                                    | TO CHECK WIRING.                                                                                          | NOT NECESSARY | 50.00                     | -                 |
|                                    | (REAR) TO SPRAY PAINTING.                                                                                 |               | 400.00                    | 300.00            |
|                                    | TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS,AND FOR CUTTING/WELDING WORKS. |               | 400.00                    | 200.00            |
|                                    | TO REMOVE REVERSE SENSOR.                                                                                 |               | 80.00                     | 50.00             |
|                                    |                                                                                                           |               | 930.00                    | 550.00            |
| <b>GRAND TOTAL</b>                 |                                                                                                           |               | <b>1,914.56</b>           | <b>1,504.56</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                                                                                           |               |                           | <b>1,504.56</b>   |

Report Ref No. CS/FCI18015356/Ard3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.