22/03/2002

ASS. REC. BY: | REF: cs/CX18015386/Ksd3 MSG | Special Instruction: n2

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): monica chung of MSIG Date/Time: 23/8/18 @ 4.09pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJK 6365G Insured: SJX7228U

at Workshop m/s Wei Lee Motor Tel: 6456 9830

of Blk 9 Sin Ming Ind. Est #01-32

Policy No: A29057765AVW Claim No: 567743

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 17/08/2018

CA / REV / REP. / REV 24 HRS (up) H.O.D. Endorsement:

Date/Time: 9.00am @ 24/8/18 Person Contacted: Karen Vehicle IN / OUT

Date/Time	Action/Instruction (→ Estimate
	SJK 6365G - CCA/ASM18062592/R/mb3s2 DOA: 1/2/18
	SJX7228U - es/MSG/8010176/R/tbs2 DOA: 24/5/18
18/9	L/Sp & 1800 Confirmed by email
20/09/18	Confirmed L/S $1,800.00 @ 8 days with Kenneth ($4,252.48 Red - 70%)

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Survey held at D.O.I. 23/8/18

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
18	File pass to Catherine

RECEIVED 21 SEP 2018

Date/Time, File Pass to? 1) 20/09/18 Typist

Date/Time, File Return to? 2)

☐ : Prell. Report

☑ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ Tech Invs ($)

☐ Weekend ($)

Report Format :

Lump Sum / I.B.I: ($ 1,800/- L/S)

Survey Fee:

Transportation: $ + RS. SI

Photos

Others

TOTAL 220