

Your Ref: 6301440175SG-003

Date: 31st August 2018

Our Ref: CS1/AIG18015393/Bvd3s2

M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #08-16

Chartis Building

Singapore 079120

(The Motor Claims Department)

Attn : Shawn Wui

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SDZ 6869L****INSURED VEHICLE: GBG 5861M****ACCIDENT DATE: 25/01/2018**

We thank you for your instruction on 24/08/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SDZ 6869L from M/s Sincere Appraisal Services Pte Ltd.
- b) Singapore Accident Statement of Vehicles SDZ 6869L and GBG 5861M.
- c) Colour damaged vehicle photographs of SDZ 6869L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SDZ 6869L
Make & Model	: B.M.W 316I 1.6 AT
Year of Registration	: 2015
Chassis Number	: WBA3A16040NS38358
Engine Capacity	: 1598 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.