



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18015415/R1gb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LYNN KHONG			Date : 30-12-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 8068S	Veh. Inspected	GBE 4683C	
Policy No.	P2028702	Coverage (\$)	0.00	
Claim No.	S8M00ST6	Excess (\$)	0.00	
Assign From	LYNN KHONG	Assign Date	23/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	FIAT DOBLO CARGO MAXI 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	ZFA26300006B30556	Colour	RED	
Odometer	77114	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	NEXEN	6 mm	
L/H Front Tyre	195/60 R16	NEXEN	6 mm	
R/H Rear Tyre	195/60 R16	NEXEN	6 mm	
L/H Rear Tyre	195/60 R16	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/08/2018	Inspection Date	23/08/2018	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		