

23/03/2000

ASS. REC. BY:

REF: CS3/MSG18015415/R/24/3² Special Instruction:

Surveyor:

Rasul
Minimen

ASSIGNMENT (Office)

From (Person):

Home fun

of

MSIG

Date/Time:

24/8/18 @ 2.24pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 9405 T

Insured:

GBD 3211T

at Workshop m/s

Sheng Koon Motor

Tel:

9631 1939

of

393 Woodlands Rd blk D4 Yew Tee Ind.

Policy No:

A28814454MKC

Claim No:

568155

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

Date/Time:

3.17pm @ 24/8/18

Person Contacted:

ERIC

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLD 9405 T - CS / SMG18015097 / Uvb DOA: 15/8/18
	GBD 3211T - X



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18015445/R1z4d3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 24-08-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBD 3211T	Veh. Inspected	SLD 9405T
Policy No.	A28814454MKC	Coverage (\$)	0.00
Claim No.	568155	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	24/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/08/2018	Inspection Date	24/08/2018
Survey held at	393 WOODLANDS RD BLK D4# YEW TEE IND.		
Repairer	SHENG KOON MOTOR		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2018		24 Aug 2018 14:29 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	HOWE CATERING, Co. Reg. No.: 52859640C		
Main Claimant:	ANG KIN MENG, ID: S1150858H		
Vehicle Reg. No.:	SLD9405T	Date of Loss:	18/08/2018 15:00 - :59 [25 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 568155	Policy/Cover Note No.:	A28814454MKC (Comprehensive) Coverage: 03/09/2017 - 02/09/2018
Vehicle Reg. No. (Insured):	GBD3211T	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	Sheng Khoon Motor Service (HQ) 393 WOODLANDS ROAD BLK D4 YEW TEE IND EST, 677972 Woodlands - Tel: 63821939		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pel - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/08/2018]		
Driver/Custodian (Insured):	HE XIAN ZHUANG (38 / Male), NRIC: S8017119F, Tel: +6598247552		
Adj Asg. Remarks:	SJE - DISAGREED LIABILITY : CLEAR Please appoint LKK AUTO to conduct the survey . Kindly contact MR ERIC @ 9631 1939 to arrange for survey .		

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2018 17:09
Date Of Accident	18/08/2018 15:45
Exact Location Of Accident	BKE SLIP ROAD TOWARDS DAIRY FARM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD9405T
Insured/Policyholder	
Name Of Registered Owner	ANG KIN MENG
NRIC No	S1150858H
Email Address	ANG_KIN_MENG@LTA.GOV.SG
Mobile Phone No	(LOCAL) +65-92958426
Alternative Phone No	OFFICE-92958426

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER EX-1.6 LED TAIL LAMP (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01010679
Cover Note Number	30/06/2018-29/06/2019

Driver

Name of Driver	ANG KIN MENG
NRIC No	S1150858H
Date Of Birth	03/05/1956
Occupation	INDOOR
Date Of Driving Pass	26/10/1993
Driving Experience	24 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92958426
Fax Number	
Contact Number	OFFICE-92958426
EMail Address	ANG_KIN_MENG@LTA.GOV.SG

Address	BLK 577 HOUGANG AVE 4 08-664
Postcode	530577
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD3211T
Vehicle Make/Model/Colour	B
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	HE XIAN ZHUANG
NRIC/Passport Number	S8017119F
Contact Number	90689794
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBF5648T
-----------------------------	----------

Vehicle Make/Model/Colour	C
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature 
Date & Time: 20/8/18

Driver's Signature 
(If driver is not the policyholder)
Date & Time: 20/8/18

Reporting Centre Personnel's Signature 
Name: Kenneth
NRIC/IN NL

Sketch Plan Pg. 2

SKETCH PLAN



C - GBF5648T

A - SLD9405T

B - GBD3211T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/08/2018 at about 15:45pm, I turned left to the slip road at BKE towards Dairy Farm Road. I stopped at the junction at the slip / Dairy Farm Road behind a van, GBF 5648T. While waiting for the front van to move, a van GBD 3211T suddenly hit my car from behind. The impact pushed my car forward and hit the front van GBF 5648T.

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

- Reporting Only
- Claim OD
- Claim TP
- Claim OD/TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

Policyholder's signature

Date & Time 20/8/2018
13:55 hrs.

Driver's Signature

(if driver not the policyholder)
Date & Time 20/8/18
13:55 hrs.

Reporting Centre Personnel's Signature

Name:
Nric/Fin No.
Kenneth

> Back to OneMotoring

Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLD9405T		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	MITSUBISHI		
Vehicle Model :	LANCER EX 1.6 AT LED TAIL LAMP		
Chassis No. :	JMYSRCY1AGU004091		
Propellant :	Petrol		
Engine No. :	4A92CG7329		
Engine Capacity :	1590 cc		
Maximum Power Output :	86.0 kW (115 bhp)		
Maximum Laden Weight :	1750 kg		
Unladen Weight :	1284 kg		
Year Of Manufacture :	2015		
Original Registration Date :	30 Jun 2016		
Lifespan Expiry Date :	-		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$55,200.00		
COE Expiry Date :	29 Jun 2026		
Road Tax Expiry Date :	29 Dec 2018		
PARF Eligibility Expiry Date :	29 Jun 2026		
Inspection Due Date :	29 Jun 2019		
Intended Transfer Date :	04 Sep 2018		
CO2 Emission :	171.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0858H
Vehicle Details	
Vehicle No.:	SLD9405T
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER EX 1.6 AT LED TAIL LAMP
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	4A92CG7329
Chassis No.:	JMYSRCY1AGU004091
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$14,138.00
Original Registration Date:	30 Jun 2016
First Registration Date:	30 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$14,138.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2026
PARF Rebate Amount:	\$10,603.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,200.00
COE Rebate Amount:	\$43,163.00
Total Rebate Amount:	\$53,766.00

The information contained herein is correct as at 04 Sep 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2018		24 Aug 2018 14:29 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HOWE CATERING, Co. Reg. No.: 52859640C		
Main Claimant:	ANG KIN MENG, ID: S1150858H		
Vehicle Reg. No.:	SLD9405T	Date of Loss:	18/08/2018 15:00 - :59 [25 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 568155	Policy/Cover Note No.:	A28814454MKC (Comprehensive) Coverage: 03/09/2017 - 02/09/2018
Vehicle Reg. No. (Insured):	GBD3211T	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	Sheng Khoon Motor Service (HQ) 393 WOODLANDS ROAD BLK D4 YEW TEE IND EST, 677972 Woodlands - Tel: 63821939		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 25/08/2018]		
Driver/Custodian (Insured):	HE XIAN ZHUANG (38 / Male), NRIC: S8017119F, Tel: +6598247552		
Adj Asg. Remarks:	SJE - DISAGREED LIABILITY : CLEAR Please appoint LKK AUTO to conduct the survey . Kindly contact MR ERIC @ 9631 1939 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SLD9405T (568155)**

[GBD3211T]

TP

ANG KIN MENG

































Aug 18 2018 3:00PM
















[HOWE CATERING]

Sheng Khoon Motor Service

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
2	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
3	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
4	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
5	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
6	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
7	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
8	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
9	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
10	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
11	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
12	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
13	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
14	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
15	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
16	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
17	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
18	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
19	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
20	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
21	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
22	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
23	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
24	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
25	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
26	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
27	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
28	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
29	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
30	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
31	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
32	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
33	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
34	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
35	29/08/18 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	29/08/18 10:43	General View	 Load JPG	✓
37	29/08/18 10:43	General View	 Load JPG	✓
38	29/08/18 10:43	General View	 Load JPG	✓
39	29/08/18 10:43	General View	 Load JPG	✓
40	29/08/18 10:43	General View	 Load JPG	✓
41	29/08/18 10:43	General View	 Load JPG	✓
42	29/08/18 10:43	General View	 Load JPG	✓
43	29/08/18 10:43	General View	 Load JPG	✓
44	29/08/18 10:43	General View	 Load JPG	✓
45	29/08/18 10:43	General View	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/08/18 11:02	OI GBD3211T GIA REPORT	 Load PDF	
2	23/08/18 11:02	TPD SLD9405T GIA REPORT	 Load PDF	
3	23/08/18 11:02	TPD SLD9405T - PRI	 Load PDF	
4	24/08/18 11:02	Pre-Repair Survey	 Load PDF	
5	24/08/18 11:04	Reject email to TP Lawyer & appoint LKK AUTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015445/R1Z4D3S2
Date: 07/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28814454MKC
Claimant Vehicle No: SLD9405T Insured Vehicle No: GBD3211T
Date of Loss: 18/08/2018 Nature of Claim: TP Claim No: 568155

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD9405T Engine No: 4A92CG7329
Make & Model: MITSUBISHI LANCER, 1.6 1.6AT LED (M) Chassis No: JMYSRCY1AGU004091
Reg. Date: 30/06/2016 (Man. Year: 2015) Odometer: 36034 km
Colour: Grey
Engine Capacity: 1590 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/08/2018
Date Inspected: 24/08/2018 Inspected At: Sheng Khoon Motor Service (HQ)
393 WOODLANDS ROAD BLK D4 YEW TEE IND EST
Singapore 677972
Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000.00 - \$10,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Sep 2018)
Parts:	143	MITSUBISHI LANCER 1.6 1.6AT LED (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD9405T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >