

23/03/2002

ASS. REC. BY:

REF:

CS3/ III 18015455/G24d3dz

Special Instruction:



Surveyor: menmen

GA

ASSIGNMENT (Office)

From (Person):

Gabriel Wee

of

III

Date/Time:

23/8/18 @ 04:41pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

821 G705R

Insured:

SHA 69255

at Workshop m/s

Wee Hpe Auto

Tel:

6858 0019

of

19 Kim Chuan Terrace

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/08/2018

CA / REV / REP. / REV 24 HRS

Comp

H.O.D. Endorsement:

Date/Time:

09am @ 22/8/18

Person Contacted:

Mr. Kiat

Vehicle-IN

OUT

Date/Time	Action/Instruction (X) Estimate
	821 G705R - NS/INC/18015400/K/sd3 DOA: 22/8/18
	SHA 69255 - NS/INC/18015400/K/sd3 DOA: 22/8/18

(08/1713) wef
ASS. REC. BY: Kal.

REF: III

ASSIGNMENT

From: _____ Date: 31/08/18
Estimated Cost: _____
OP / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLJ 6705R
at Workshop m/s Whe Hol Auto
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SLJ 6705R Yr Regn: Dec 1 2016
Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Toyota Altis c.c. 1598
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 128210 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MR053 REH.104555222
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 205/55R16
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Ling long
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 31-08-18
Survey held at IDAC Ubi 9:45 AM
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Rear.
The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS 1up
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S
<input checked="" type="checkbox"/>	

Date / Time	Action / Instruction
	<u>\$500 - \$1000</u> <u>500</u>
<u>4/9/18</u>	<u>submit PRO Report</u>

Date/Time, File Pass to? : Preli. Report
1) : Final Report
Date/Time, File Return to? _____
2) _____
Report Format : _____
Lump Sum / I.B.I: (\$) _____
Days Of Repair: _____
Resurvey No. of Trip: _____
Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)
Survey Fee: 20
Transportation: _____
S + RS, SI _____
Photos _____
Others 10
TOTAL 90

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 23 August 2018 4:41 PM
To: admin@visionlawllc.com; Anna Tan; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Manivel Priyadarshini
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLJ6705R (Accident involving SLJ6705R and SHA6925S on 22.08.2018)
Attachments: 3602_001.pdf; 3602_001.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SLJ6705R
III INSURED VEHICLE NO. : SHA6925S
DATE OF LOSS : 22.08.18

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Priya**.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.
Surveyor kindly upload this assignment to Merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Motor Claim - III
Sent: 23 August, 2018 11:28 AM
To: 'admin@visionlawllc.com' <admin@visionlawllc.com>; 'Anna Tan' <annatan@visionlawllc.com>
Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLJ6705R (Accident involving SLJ6705R and SHA6925S on 22.08.2018)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]

Sent: 23 August, 2018 11:23 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Scan Image

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

Company Registration No. 200721148H

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
ONG BOCK KEE
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YINGXIAN SELWYN

Head Office:

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch:

490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

HEAD OFFICE:

TEL : 65342811 (Hunting)
FAX : 65356802 (General)

E-MAIL: annatan@visionlawllc.com

BRANCH

TEL : 63580703
FAX : 63580448(conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to **HEAD OFFICE** for this matter

OUR REF: AKN-atv-INS-W30-SLJ6705R-2018 - [please reply to: annatan@visionlawllc.com](mailto:annatan@visionlawllc.com)
YOUR REF: SHA6925S

23 August 2018

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street
#04/06-00 IOB Building
Singapore 049711

Attn: Motor Claims Department

BY FAX: 6224 4174 Only
motorclaim@iii.com.sg

Dear Sirs

NAME OF CLAIMANT: QUALITY PTE LTD

VEHICLE NUMBER: SLJ6705R

YOUR INSURED VEHICLE NUMBER: SHA6925S

ACCIDENT ALONG PASIR RIS DR 12 AFTER JUNCTION PASIR RIS DR 1 ON 22 AUGUST 2018 AT ABOUT 0225HOURS

We refer to your email dated 23 August 2018 wherein there is no agreement to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

WEE HOE AUTO SERVICE

19 KIM CHUAN TERRACE
SINGAPORE 537041

Contact Person:

TEL: 6858-0019 (KIAT)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

(Head Office)

cc. **SLJ 6705 R** - By fax 6858-0195 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature) :

Date & Time of Inspection :

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III18015455/Gz4d3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 24-08-2018	
		Code : III2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHA 6925S	Veh. Inspected	SLJ 6705R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	GABRIEL WEE	Assign Date	24/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/08/2018	Inspection Date	31/08/2018
Survey held at	WEE HOE AUTO SERVICE 19 KIM CHUAN TERRACE SINGAPORE 537041		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/08/2018 10:10
Date Of Accident	22/08/2018 02:25
Exact Location Of Accident	ALONG PASIR RIS DR 12 AFTER JUNC PASIR RIS DR 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ6705R
Insured/Policyholder	
Name Of Registered Owner	QUALITY PTE LTD
Co Reg No	201624281H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90088701
Alternative Phone No	OFFICE-90088701

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS CLASSIC 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5084705121-01
Cover Note Number	

Driver

Name of Driver	LAU TIEN CHEN
NRIC No	S8470809G
Date Of Birth	05/02/1984
Occupation	OUTDOOR
Date Of Driving Pass	23/03/2007
Driving Experience	11 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96625314
Fax Number	
Contact Number	OFFICE-96625314
EMail Address	NOEMAIL

Address	BLK 82 BEDOK NORTH ROAD #05-314
Postcode	460082
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, I WAS U-TURN FROM PASIR RIS DR 12. AFTER MAKING U-TURN ALONG THE JUNCTION, I TURN ON MY INDICATOR LIGHT AND CHECK MY MY BLIND SPOT BEFORE PROCEED TO LANE 3. WHEN I CHANGED FROM LANE 2 TO LANE 3 VEHICLE B HIT ONTO MY VEHICLE REAR LEFT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA6925S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TAN PAU SOON
NRIC/Passport Number	S0059168H
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLJ6705R		
Vehicle Type :	Z10 - Private Hire (Chauffeur) Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	COROLLA ALTIS CLASSIC 1.6 CVT		
Chassis No. :	MR053REH104555222		
Propellant :	Petrol		
Engine No. :	1ZRX587607		
Engine Capacity :	1598 cc		
Maximum Power Output :	90.0 kW (120 bhp)		
Maximum Laden Weight :	1640 kg		
Unladen Weight :	1205 kg		
Year Of Manufacture :	2016		
Original Registration Date :	20 Dec 2016		
Lifespan Expiry Date :	-		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$48,000.00		
COE Expiry Date :	19 Dec 2026		
Road Tax Expiry Date :	19 Dec 2018		
PARF Eligibility Expiry Date :	19 Dec 2026		
Inspection Due Date :	19 Dec 2019		
Intended Transfer Date :	04 Sep 2018		
CO2 Emission :	151.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Sep 2018 17:14 Edit Reg		23 Aug 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	-, Co. Reg. No.: -		
Main Claimant:	-		
Vehicle Reg. No.:	SLJ6705R	Date of Loss:	22/08/2018 00:00 - :59 [20 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHA6925S	Policy No. (Claimant):	
		Excess:	
Repairer:	Wee Hoe Auto Service (HQ) 19 Kim Chuan Terrace, Singapore 537041, 537041 Kaki Bukit - Tel: 68580019		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 04/09/2018]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

***SLJ6705R**
[SHA6925S]
TP
-
Aug 22 2018 12:00AM
[-]
Wee Hoe Auto Service

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	04/09/18 10:53	LKKPhotosIn6-1.pdf		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	27/08/18 08:46	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III18015455/GZ4D3E2

Date: 05/09/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SLJ6705R

Insured Vehicle No : SHA6925S

Date of Loss: 22/08/2018

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLJ6705R**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A)

Engine No: 1ZRX587607

Reg. Date: 20/12/2016 (Man. Year: 2016)

Chassis No: MR053REH104555222

Colour: Blue

Odometer: 128210 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Linglong 6 mm

Rear Left Side: Linglong 6 mm

Front Right Side: Linglong 6 mm

Rear Right Side: Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/08/2018

Date Inspected: 31/08/2018 Inspected At:

Wee Hoe Auto Service (HQ)
19 Kim Chuan Terrace, Singapore 537041
Singapore 537041

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG**Manager:** Ho Zhao Tian*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Sep 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ6705R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >