Surveyor From (Perso	Adrian Yee pei hi	ASSIGNME	NT (Office)	Date/Time: 24/8/16/09.22em
Estimated C	ost: VS/TP RES/OD RES		Bill to:	
To Inspect \		3KQ 18722	S <u>1</u> In	sured: GBE 41954
at Workshop		19 solution		Tel: 6243 1373
of	23 Kaki &	stet Ave 4 #	02-03B	12 12 13
Policy No:_	a salah lebi sa	- , , . ,	Claim No: C	BE 41954/81/Pl
Sum Insured	1		Excess:	
there are a second	4+		LAUGO.	
Make of Ve	h,		DATES.	D.O.A. 22 8 18
Make of Ve (Client's Rece	h: ord)	os (up)	LAUCIS.	•
Make of Ve (Client's Reco CA / REV	h: ord) / REP. / REV 24 HI		77/2021/1/202	H,O.D. Endorsement:
Make of Ve (Client's Reco CA / REV Date/Time:	h: ord) / REP. / REV 24 HI 9-30UMB 24 8/1	Person Contacted	Ms. Hong	•
Make of Ve (Client's Reco CA / REV	h: ord) / REP. / REV 24 HI 9-30UMB 24 8/1		Ms. Hong	H.O.D. Endorsement: Vehicl IN / DUT
Make of Ve (Client's Reco CA / REV Date/Time:	Action/Instruction	Person Contacted () Estimate	Ms. Hong	H.O.D. Endorsement: Vehicl IN / DUT
Make of Ve (Client's Reco CA / REV Date/Time:	Action/Instruction	Person Contacted () Estimate - NSI INC 180152	Ms. Hong	H.O.D. Endorsement: Vehicl IN / DUT

(ORTHA) Wef ASS REC. BY:	REF:	EGI		×	7				
-			ASSI	GNME	ENT				
From:	Date:	24/8/1	18	Veh No:	4			gn; 2010 /	Dec
Estimated Cost						3.4	Lorry / Taxi /	Prime Mover /	
OD TP WS / TP RE	S / OD RES / EVA / INV /	MV		Ti	ruck / Trailer			130	
To Inspect Vehicle No	SKO 1	STORS		Make:	Yol	Kswager	Sciro	co c.c 139	2
at Workshop m/s	MG SOL	ution		Colour	wh	ile	A/C:	Insured / Std / I	AI / NA
of 23	caki Bkt Ave	4 #02.	-03	Sp.Read	ling 18	8462	T/Radio	: Insured / Std /	NI / NA
Insured:				Eng/No:					
Policy No.				C/No:	W	VWZZZ13	ZBV001	636	
Claims No.				Gen. Co	ng Good / F	air / Poor / Bur	nt		
Sum Insured:	Excess			Steering	: Inorder I Ja	ammed / Leake	d/Burnt or		
(Client's Record)				Brake:	Moreter / Ja	ammed / Leake	d / Burnt or		
Make of Veh:				Modi :	Nil / SiRin	STD A/Rim			
				Tyre Siz	e: F:	255/3	35R18. 35R18.		
(Policy Condition)					R:	855/3	3SR18.		
Remark: The veh had	I commenced its	N/S	O/S	BS / DU	N / EXNOV	TGY)FS/LIZ	A / MIC / OH	TSU / PIR / SUMI	I
repair at the	time of inspection.			TOYO	/YOKO or				
Bal. or Market Value:		.,,		Front			Rear	,	
IDAC Accident Rport:	Consistent? :	Yes or No		R/Bal.	26	mm	R/Bal.	06	mm
GIA / PR Seen:	Consistent?:	Yes or No		L/Bal.	06	mm	L/Bal.	06	mm
Est. Repairs:	days Res.:	Yes or No		D.O.A.			D.O.I.	24/08/18	? .
Lum Sum:	% 3 Val.:	Yes or No		Survey h	neld at	MG	Solutio	1.	
CA / REV / REF	. 1 24 HRS (Up)	Vehicle:	IN / OUT	Des. of I	Damages : Fr	rt / (Rea) 1 0/5	אני ז S / N/S ו	C / Rooftop or	
Date:	Person Contacted:	, emelos		The	U/C / Chass	sis frame / Bo	dy Strusture	affected due to	collision

Date / Time	Action / Instruction		
	77 Ecgo.		
	0		-10
		RECEIVED 0 7 NOV 2	018
	MV . 36K		
	PV: 24.6K		
	MV . 36K PV : 24.6K Nett: 11.4K		

Date/Time, File Pass to?	: Preli. Report	Day	ys Of Repair:	8	
indali tumpa	: Final Report	Re	survey No. of Trip:	1	Survey Fee:
Date/Time, File Return to?		85 8 2 100			Transportation:
2)		Add Fee:	: Site Insp (\$)	_S+RS,SI
		. [: Interview (\$)	Photos
Report Format :	TP		: Tech. Invs (\$)	Others
Lump Sum / I.B.A: (\$	9,600) [: Weekend (\$	5	
			WAR-1		TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Int	ernationale Des Experts En Auton	nobile			
ERGO INSURANCE P	TE LTD	Ref : CS/EGI180154	56/Aqd3			
5 TEMASEK BOULEVA #04-01 SUNTEC TOW! SINGAPORE 038985		Date: 24-08-2018 Code: EGI				
1.	Policy Partic	ulars :- THIRD PARTY CLA				
Insured Veh.	GBE 4195U	Veh. Inspected	SKQ 1872Z			
Policy No.		Coverage (\$)	0.00			
Claim No.	GBE4195U/SL/pl	Excess (\$)	0.00			
Assign From	YEE PEI LI	Assign Date	24/08/2018			
2.	Vehicle	Particulars & Condition				
Make & Model		c.c	0			
Engine No.	HIDDEN	Year of Reg.				
Chassis No.		Colour				
Odometer	5 ₹ 8	Steering				
Brakes		Modification				
General						
3.		Conditions of Tyres	CARLESTED SAN			
	Size	Make	Balance			
R/H Front Tyre			mm			
L/H Front Tyre			mm			
R/H Rear Tyre			mm			
L/H Rear Tyre			mm			
4.	De	scription of Damages	With the Park of t			
5. Channa No.	THE RESIDENCE OF THE PARTY OF T	General Information	0.1100.100.10			
Accident Date	22/08/2018	Inspection Date	24/08/2018			
Survey held at	MG SOLUTION PTE LT 23 KAKI BUKIT AVE 4	D				

Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

(SOUTH WING) #02-03B VICOM INSPECTION CENTRE,

SINGAPORE 415933

5a.

Nivitha (LKK Auto)

From:

Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>

Sent:

Friday, 24 August 2018 9:22 AM

To:

'admin-d@lkkauto.com'

Cc:

'ASSIGNMENTS@LKKAUTO.COM'

Subject:

OI: GBE4195U / TP: SKQ1872Z/LKK / DOA: 22/08/2018

Attachments:

SKQ1872Z - SAS.pdf; SKQ1872Z - PRS FORM.pdf; SKQ1872Z (Pre Inspection) (562

KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company LKK AUTO CONSULTANTS PTE LTD to be the "Single Joint Expert".

Please assist to conduct this survey from MG SOLUTION PTE LTD,

ADDRESS

23 KAKI BUKIT AVE 4 (SOUTH WING)

#02-03B VICOM INSPECTION CENTRE

SINGAPORE 415933

PERSON TO CONTACT

: MS HENG @ 6243 1373

ERGO OFFICER-IN-CHARGE

STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards, <u>Yee</u> Pei Li Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five Singapore 038985

DID.: +65 6829 9194 Tel.: +65 6829 9199 Fax: +65 6829 9247



www.ergo.com.sg



ate: ur Reference:		18	48	Sent via Fax		*
	GBE 419	5U/SL/pl	20	or		
	SKQ 187	2Z	-	or .		
ur Reference:	3114 201		->	Email	7923	-2Lui
1	MG SO	LUTION PTE LTD	-		m	g3solution@gmail.com
re-Renair Su	Irvey (PRS) Acknowledgement				
ehicle For Insp		SKQ 1872Z				
		GBE 4195U	-			
sured's Vehicl		22.08.2018				
ate Of Accider			-			
		your request for PRS on:	23.08.201			
compliance v	with "State	Courts Practice Directions Am	endment No.1	of 2016", do s	elect an as	sessor from
		your selection in the box mar			*	LKK
AIS	Automobi	le Inspection Services Pte Ltd	LBS	L.B.S Auto Co	onsultants P	rte Ltd
FTA		n Consultancy Pte Ltd	LKK	LKK Auto Co		e Ltd
IAS	Infiniti Ap	praisal Service	PS	Priority Servi	ces	
JPK	JP Knights	Pte Ltd	VAC	Vicom Ltd		
- A 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6		ection does not have your client's				py.
Your req We ackn	uest for inspe owledge you	ection does not have your client's ection does not have your client's r interest for direct settlement, w as not reported the accident to u	GIA report, kind re will assess & re	ly forward a copy	1.	
Your req We ackn	uest for inspe owledge you red's driver h	ection does not have your client's r interest for direct settlement, w	GIA report, kind re will assess & re is todate.	ly forward a copy	1.	
Your req We ackn V Our Insu V Others:	uest for inspe owledge you red's driver h	ection does not have your client's r interest for direct settlement, w as not reported the accident to u	GIA report, kind re will assess & re is todate.	ly forward a copy	receipt of e	stimate.
Your req We ackn V Our Insu V Others:	uest for inspe owledge you red's driver h	ection does not have your client's r interest for direct settlement, w as not reported the accident to u	GIA report, kind re will assess & re is todate.	ly forward a copy	1.	stimate. claims@ergo.com.s
Your req We ackn V Our Insu V Others:	uest for inspe owledge you red's driver h	ection does not have your client's r interest for direct settlement, w as not reported the accident to u	GIA report, kind re will assess & re is todate.	ly forward a copy	receipt of e	stimate.
Your req We ackn V Our Insu V Others: repared by: ignature:	uest for inspe owledge you red's driver h	ection does not have your client's r interest for direct settlement, w as not reported the accident to u	GIA report, kind re will assess & re is todate.	ly forward a copy evert soon upon	receipt of e	stimate. claims@ergo.com.s
Your req We ackn V Our Insu V Others:	uest for inspe owledge you red's driver h	ection does not have your client's r interest for direct settlement, w as not reported the accident to u	GIA report, kind re will assess & re is todate. Pei Li Workshop use	ly forward a copy evert soon upon	9 9194	stimate. claims@ergo.com.s
Your req We ackn V Our Insu V Others: repared by: ignature:	uest for inspe owledge you red's driver h OFFICE	ection does not have your client's r interest for direct settlement, w as not reported the accident to u	Pei Li Workshop use Assessor atte Date:	y forward a copy evert soon upon 682 e only:	9 9194	stimate. claims@ergo.com.s
Your req We ackn V Our Insu V Others: Prepared by: Signature: Assessor use on	owledge you red's driver h OFFICE	ection does not have your client's r interest for direct settlement, w as not reported the accident to u	Pei Li Workshop use Assessor atte Date: Time	y forward a copy evert soon upon 682 e only:	9 9194	stimate. claims@ergo.com.s
Your req We ackn V Our Insu V Others: Prepared by: Signature: Assignment Dat Assignment Tim	owledge you red's driver h OFFICE	ection does not have your client's r interest for direct settlement, w as not reported the accident to u	Pei Li Workshop use Assessor atte Date: Time inspector:	e only:	9 9194 on:	claims@ergo.com.s FAX: 6829 9247
Your req We ackn V Our Insu V Others: Prepared by: Signature: Assessor use on Assignment Dat Assignment Tim	owledge you red's driver h OFFICE	ection does not have your client's r interest for direct settlement, w as not reported the accident to u	Pei Li Workshop use Assessor atte Date: Time inspector: Vehicle not a	e only: nded workshop	9 9194	claims@ergo.com.s FAX: 6829 9247
Your req We ackn V Our Insu	owledge you red's driver h OFFICE	ection does not have your client's r interest for direct settlement, w as not reported the accident to u	Pei Li Workshop use Assessor atte Date: Time inspector: Vehicle not a	e only: nded workshop	9 9194	claims@ergo.com.sg FAX: 6829 9247

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Wednesday, 7 November 2018 1:19 PM

To:

'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments; 'Steve Lim'

Cc:

Subject:

RE: GBE4195U / TP: SKQ1872Z/LKK / DOA: 22/08/2018

Attachments:

CSEGI18015456Aqd3.pdf

Dear Steve,

Enclosed herewith preliminary advice of SKQ 1872Z.

Best Regards,

Shiau Chan (Ms) | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)

Sent: Tuesday, 28 August 2018 4:47 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; 'Survey Report (ERGO Insurance Pte. Ltd.)'

<Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: GBE4195U / TP: SKQ1872Z/LKK / DOA: 22/08/2018

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SKQ 1872Z on 24/8/2018 We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Friday, 24 August 2018 9:32 AM

To: 'Survey Report (ERGO Insurance Pte. Ltd.)' < Survey.Report@ergo.com.sg; assignments

<assignments@lkkauto.com> Cc: SUR < sur@lkkauto.com>

Subject: RE: GBE4195U / TP: SKQ1872Z/LKK / DOA: 22/08/2018

Dear Sir/Mdm,

Thank you for the assignment.



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: GBE 4195U/SL/pl

Date: 07th November 2018

Our Ref: CS/EGI18015456/Aqd3

Without Prejudice

The Motor Claims Department ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SKQ 1872Z .

We thank you for the instruction on 24/08/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 24/08/2018 at the premises of M/s _____MG SOLUTION ____ and have the following to report:-

Workshop Estimate Amount
Revised Estimate Amount
"Check" Items Amount

Market Value

S\$ 21,762.88

9,600.00 (Lump Sum)

S\$ -

Salvage Value : S\$ - ...

Nett Value : S\$ - ...

Description of Damage:

The vehicle sustained damages at the

rear portion.

rear front

nearside

Comments/ Present Status:

Damages consistent.

Days of repair: 8 days.

We have NOT authorise repair.

Yours faithfully

ADRIAN LING WAI PING

B. Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Tuesday, 28 August 2018 4:47 PM

To:

Admin-D (LKKAuto); 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments

Cc:

Subject:

RE: GBE4195U / TP : SKQ1872Z/LKK / DOA : 22/08/2018

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SKQ 1872Z on 24/8/2018 We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Friday, 24 August 2018 9:32 AM

To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments

<assignments@lkkauto.com> Cc: SUR <sur@lkkauto.com>

Subject: RE: GBE4195U / TP: SKQ1872Z/LKK / DOA: 22/08/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]

Sent: Friday, 24 August 2018 9:22 AM

To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>

Cc: 'ASSIGNMENTS@LKKAUTO.COM' < ASSIGNMENTS@LKKAUTO.COM>

Subject: OI: GBE4195U / TP: SKQ1872Z/LKK / DOA: 22/08/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company LKK AUTO CONSULTANTS PTE LTD to be the "Single Joint Expert".

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	Singapore NRIC	
Owner ID Type:	0168H	
Owner ID:	过去的东西的东西的 是1995年 2015年	ME
Vehicle Details	SKQ1872Z	
Vehicle No.:	Yes	
Vehicle to be Exported:	24 Aug 2018	
Intended De-registration Date:	VOLKSWAGEN	
Vehicle Make:	SCIROCCO 1.4 TSI A	
Vehicle Model:	White	
Primary Colour:	2010	
Manufacturing Year:	CAV205612	
Engine No.:	WVWZZZ13ZBV001636	
Chassis No.:		
Maximum Power Output:	118.0 kW (158 bhp)	
Open Market Value:	\$22,768.00	
Original Registration Date:	13 Dec 2010	
First Registration Date:	13 Dec 2010	
Transfer Count:	4	
Actual ARF Paid:	\$22,768.00	(8 <u>1</u> ,90
Intended PARF Repare Details	RESEARCH CONTRACTOR OF THE CON	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	12 Dec 2020	
PARF Rebate Amount:	\$13,660.00	胡果
Intended COE Repare Details	12 Dec 2020	
COE Expiry Date:		
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
QP Paid:	\$47,604.00	
COE Rebate Amount:	\$10,943.00	
Total Rebate Amount:	\$24,603.00	

The information contained herein is correct as at 24 Aug 2018

Das WeltAuto. Used cars you can trust. Guaranteed.







Save up to \$30,000 on VW management units.



Purted: 19-Aug-2018 Taylo 2016 Volkowagen Scrocco, Volk



Well Maintained Interior, Always Parked Under Shelter, Recently Serviced (Aug 2018), Fully Stocked (no Modification). Preferred Weekend Viewings. Sadly, Car Needs To Go Due To Newborn.

Posted: 15-Aug-2018 Tags: 2010 Volkswagen Scirocco, Volkswagen Sciroccu, Volkswagen, Scirocco, Used Volkswagen

Volkswagen Scirocco 1.4A TSI \$36,900

\$10,560 /yr 10-Dec-2010 1,390 cc

Sports

Available

Selling On Behalf Of Private Owner Due To Upgrading, Well Taken Care And Always Serviced And Maintained Regularly Without Fail, Trade In And Up To 80% Loan Arrangeable, Please Call To Arrange Before V...

Posted: 20-Aug-2016 Tags: 2010 Volkswagen Sorocco, Volkswagen Schocco, Volkswagen, Schocco, Used Volkswagen

CESTION OF

☐ Volkswagen Scirocco 1.4A TSI \$38,800 \$11,200 /yr 30-Dec-2010 1,390 cc 69,000 km

Sports

Available

Beautiful Condition, Well Taken Care Unit With No Expenses Spared! All Wear And Tear Done Up, Very Low Mileage Done, New Owner To Drive At Ease! Accident Free Unit. Perfect Please Call Our Sales Consult...

Posted: 04-Aug-2018 Tags: 2010 Volkswagen Schocco, Volkswagen Schocco, Volkswagen, Schocco, Used Volkswagen

Save this search criteria, to get email alerts whenever a match is found.

▼ Model Make

▼ \$\rightarrow\$ Price ▼ \$\rightarrow\$ Depreciation ▼ \$\rightarrow\$ Reg Date ▼ \$\rightarrow\$ Eng Cap ▼ \$\rightarrow\$ Mileage ▼ \$\rightarrow\$ Veh Type ▼ \$\rightarrow\$ Status

For old advertisements, view Expired ads

20 ▼ results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

spCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, lixury cars, sports spCarmant is the number one car classifieds for parallel import cars, Toyota, Honda, Nessan, Mittuibishi & BMW. There are plenty of cars for sale, from yans, trucks, sedan cars, Floury cars, sports cars so stabilities and the properties of the sale of the sa

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or onissions or warrant the accuracy of this information.

Follow sgCarMart.com 🔞 🔘 💟











About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2018 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver. 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies. repudiate policy ability.
- 5. Any false reporting may be referred to the Police for investigation. 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for ring and that copies of this report will, for a fee, be made available upon application by interested parties.

	ACCIDENT STATEMENT
Date Of Report Date Of Accident Exact Location Of Accident	23/08/2018 16:06 22/08/2018 12:10 CTE TOWARDS AYE BEFORE BRADDELL RD EXIT SINGAPORE
Country/State of Loss	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKQ1872Z
Insured/Policyholder Name Of Registered Owner NRIC No Email Address	TSE CHEN LOONG S8930168H CLARENCE.TCL@GMAIL.COM
Mobile Phone No Alternative Phone No	(LOCAL) +65-90023336 OFFICE-88888888
Vehicle Particulars	
Manufacturer	VOLKSWAGEN

SCIROCCO-1.4 (A) Model

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY PRIVATE CAR

Vehicle Category

Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD Name of Insurance Company

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

5084689640-01

Cover Note Number

TSE CHEN LOONG Name of Driver

S8930168H NRIC No 08/09/1989 Date Of Birth INDOOR Occupation 01/09/2011 Date Of Driving Pass

6 YEARS AND 11 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-90023336 Mobile Number

Fax Number

OFFICE-88888888 Contact Number

CLARENCE.TCL@GMAIL.COM EMail Address

BLK 22 JALAN MEMBINA

@28-66

166022 Postcode

Was driver an employee of the Insured's Company NO

OWNER If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Address

Insurance Company of Driver's Own Vehicle

General Information of the Accident

CHAIN COLLISION Type Of Accident

RAINING Weather Conditions WET Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s)

YES NO

soliciting/offering accident claims assistance. Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON 22/08/2018 AT ABOUT 1212HRS AT ALONG CTE TOWARDS AYE BEFORE BRADDELL ROAD EXIT. I WAS TRAVELLING ON THE LANE 2 AND WHEN MY FRONT VEHICLE (C) SLOW DOWN AND STOP DUE TO HEAVY TRAFFIC HENCE I FOLLOW SUIT AND CAME TO A COMPLETE STOP. SUDDENLY I HEARD A LOUD BANG FROM BEHIND AND THE GREAT IMPACT FORCED MY VEHICLE (A) FORWARD TO HIT ONTO THE REAR PORTION OF VEHICLE (C). WHEN I ALIGHTED, I REALISED THAT IT WAS VEHICLE (B) WHO HIT ONTO MY REAR PORTION OF MY VEHICLE (A) CAUSING DAMAGES TO MY VEHICLE. IT WAS A CHAIN COLLISION OF TOTAL 3 VEHICLES INVOLVED. (A) SKQ1872Z (B) GBE4195U (C) SHC8731K

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

PLS GET FROM WS

NO Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBE4195U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHC8731K

Vehicle Make/Model/Colour

Details Of Properties

TAXI

Vehicle Category Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

MPORTANT NOTICE

- Please report sprreatly the details of the accident to speed up the claims product.
- 1. This Form must be completed by the Polinisolder and for the Authorised Driver.
- Information provided must be as truthful and ecourate as possible. Any uniful misrepresentation or withhelding of meterial facts may allow insurance companies to repudiate policy Bability.
- The issue and asseptance of this Form by insurance companies is not an admission of policy liability on the cart of the incurance companies.
- i. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the incurers of the GIA Records (Approximant Canno established by the Tonoral Insurance Association of Singapore (GIA) for archiving and that ropies of this report will for a fee be made qualitable about any list on by interested parties.
- 1. By the lodgment of this report to the laurers, you haraby thready the transfer of this transfer of this transfer of the transfer made available alorgand.
- L. Consent under the Personal Data Protection Act (FDPA)


Lunderstand, orknowledge, agree and someent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to cullest, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monstery Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and for Seeling with my define inducing the artifement of the claims and any necessary Exceptions relating to the similar.
 - (is) Investigating the appliant and/or my dialms:
 - (III) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports of notices to me, which could involve disclasure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); end/or
 - (v) complying with applicable law in edministering, processing, fundling and/or dealing with my deline (collectively the represent)
- (a) all insurer(s) who have incured validate) involved in this accidant and the insurers' iswyers/law firms, may/ere perturbed to gradest, ora, discloss and for process my Personal information for one or many at the above Personal and
- 1) my Percent Internation may from de disclosed by any of the lower wend/or GIA to their their percent providers or eigenst including their lavgers) are firms), which may be a ten outside of Singeborg, for one or more of the choice Purposts.
- (ii) the Terrorial information will also be obtained and used to compile cising history for the purpose of front determined, investigation and management in present and all future elabra.
- Felt report in formation we collected under (c) above may be ansied / d'antecado
 - to additioners end for any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for enmplying with requirements under any regulations, laws or court orders.

Fat cynoleer's Signature Date & Times

Driver's Signature (If driver is not the policyholder) Date & Timet Reporting Contra Personners Signature

Name: NRIC/FIN No.:



MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO

: ERGO

DATE

: 22/08/2018

ATTENTION

: MOTOR CLAIMS DEPT

JOB TYPE : TPCLAIM

ESTIMATE REPORT

VEHICLE DETAILS

VEHICLE NO

: SKQ1872Z

MODEL

: VOLKSWAGEN SCIROCCO R 1.4A

XIGO QIEN.

WVWZZZ13ZBVOO1 636

CHASSIS NO

ACCIDENT DETAILS

DATE : 22-Aug-18 TIME : 12:10HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N DESCRIPTION	QTY	UNIT LIST PRICE		PRICE		
1 BONNET Repair	1	\$	1,350.00	\$	1,350.00	
2 BONNET LOGO Her	1	\$	64.00	\$	64.00	
3 FRONT BUMPER Dehend	1	\$	1,223.00	\$	1,223.00	
4 FRONT BUMPER SIDE RETAINER ALL	2	\$	65.30	\$	130.60	
5 FRONT BUMPER TOP GRILLE COULD	1	\$	290.00	\$	290.00	
6 FRONT BUMPER TOP GRILLE BASE CILCA	1	\$	280.00	\$	280.00	
7 FRONT BUMPER BOTTOM GRILLE	d1	\$	244.00	\$	244.00	
8 FRONT BUMPER REINFORCEMENT FLOR	1	\$	520.00	\$	520.00	
9 FRONT BUMPER SPONGE	1	\$	140.00	\$	140.00	
10 FRONT BUMPER FOG LAMP	2	\$	190.00	\$	380.00	
11 FRONT BUMPER FOGLAMP GRILLE RHOWLA	2	\$	130.00	\$	280.00	
12 FRONT BUMPER NUMBER PLATE GARNISH COLL	d 1	\$	140.00	\$	140.00	
13 FRONT RADIATOR TOP COVER NO	1	\$	101.00	\$	101.00	
14 FRONT SUPPORT PANEL HA	1	\$	880.30	\$	880.30	
15 HEADLAMP RA Code	2	\$	590.60	\$	1,184.20	
16 HEADLAMP LOWER BRACKET New	2	\$	90.00	\$	180.00	
17 TAILGATE Device	1	\$	1,900.60	\$	1,900.60	
18 TAILGATE LOGO	1	\$	80.00	\$	80.00	
19 TAILGATE EMBLEM 'SCIROCCO'	1	\$	60.00	\$	60.00	
20 TAILGATE TOP LOCK Damy	1	\$	122.00	\$	122.00	

21	TAILGATE INNER BOARD XIR M	1	\$	344.80	\$ 344.80
22		1	\$	255.00	\$ 255.00
_	TAILGATE WINDSCREEN MOULDING MA	1	\$	211.60	\$ 211.60
	REAR BUMPER Detorned	1	\$	1,122.30	\$ 1,122.30
	REAR BUMPER SIDE RETAINER	2	s	60.30	\$ 120.60
	BEAD BUMBER BEINEORCEMENT BEAT	1	\$	460.00	\$ 460.00
_	REAR BUMPER CENTRE BEAM	1	\$	230.00	\$ 230.00
	REAR NUMBER PLATE LAMP(SET) and	1	\$	133.00	\$ 133.00
	TAILLAMP Cruleed	2	\$	322.30	\$ 644.60
30	THE PROPERTY AND A	2	\$	78.00	\$ 156.00
3	END PANEL Distorted	1	\$	930.00	\$ 930.00
_	END PANEL TOP GARNISH Could	1	\$	225.50	\$ 225.5
	REAR FLOOR PANEL PLY	1	\$	1,255.80	\$ 1,255.8
	REAR FLOOR PANEL TOP BOARD	1	S	287.30	\$ 287.30

929380

TOTAL PRICE \$ 15,903.20 LESS 10% \$ 1,590.32 SUB TOTAL PRICE \$ 14,312.88

5/N	DESCRIPTION	QTY	UNI	T S/NETT		OTAL S/NETT
1	FRONT NUMBER PLATE CANCC	1	\$	50.00	\$	50.00
	FRONT BUMPER CLIPS(SET)	1	\$	20.00	\$	20.00
	FRONT RADIATOR GRILLE EMBLEM "R"	1	\$	100.00	\$	100.00
	SUPPORT PANEL TOP COVER CLIPS(SET)	1	\$	20.00	\$	20.00
	REAR NUMBER PLATE Dand	1	s	50.00	\$	50.00
6	TAILGATE SEALANT ME M	1	\$	100.00	\$	100.00
_	TAILGATE INNER BOARD CLIPS(SET)	1	\$	20.00	\$	20.00
	TAILGATE EMBLEM "SWCS"	1	\$	100.00	\$	100.00
	TAILGATE EMBLEM 'STICKER"	1	\$	80.00	\$	80.00
	REAR BUUMPER CLIPS(SET) Her	1	\$	20.00	s	20.00
	REAR BUMPER DIFFUSER Pistonted	1	\$	1,200.00	\$	1,200.00
_	REAR BUMPER DIFFUSER CLIPS (SET)	1	\$	20.00	\$	20.00
	REAR WINDSCREEN SEALANT	1	\$	120.00	\$	120.00
	REAR REVERSE SENSOR Domuyed	1	s	220.00	\$	220.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,000,00	200.	

200 1,000.00 2 SPRAY PAINTING TO AFFECTED AREA \$ \$2,000.00 400 TOTAL CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR) 800. PANEL BEATING, REMOVAL AND 1,600.00 \$ 1 REPLACING PARTS 800. 2 TO SPRAY PAINT AFFECTED AREA 1,400,00 \$ 49 . 50.00 \$ 3 TUFF COAT REMOVE, REINSTALL AND REPLACE REAR INNER TRIMS, GARNISHES AND 60. 4 BOARDS TO ASSIST REPAIR S REMOVE AND REFIX REVERSE REAR 100 . \$ 5 WINDSCREEN REMOVE AND REFIX REVERSE 50 7 SENSOR AND DISTANCE SETTING \$ 1850-\$3,330.00 TOTAL ESTIMATE REPORT 16,432.88 TOTAL PARTS COST : \$ 5.330.00 : \$ TOTAL LABOUR COST : S 21,762.88 TOTAL REPAIR COST APPROVED DETAILS **EXCESS** NO. OF WORKING DAYS: RE-SURVEY PART BY PART OR LUMP SUM DATE & TIME OF SURVEY SURVEYED BY CONTACT NUMBER FAX NUMBER total 12044.42

> LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- Parts prices :
 subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

HS: 9.6K.