

ASS. REC. BY:

REF: CS/EGII18015456/Aqds

02

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Yee Pei Li

of EGI

Date/Time: 21/8/18 @ 9.22am

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKQ 1872Z

Insured: GBE 4195U

at Workshop m/s MG Solution

Tel: 6243 1373

of 23 Kaki St Ave 4 # 02-03B

Policy No:

Claim No: GBE4195U / SL / pl

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 22/8/18

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 9.30am @ 21/8/18

Person Contacted: Ms. Heng

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKQ 1872Z - NSLINC18015402 / K1+d3 . D.O.A: 22/8/18

GBE 4195U - x

23/8 - Revert via email preli advise (pending estimate) 02/11/18 @ 1.19pm revised to Steve Lim by email.

us \$9600, 8 days (Red \$1262.88, 56%)

GIA / PR Seen:

Consistent? : Yes or No

L/Bal. 06 mm

L/Bal. 06 mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

D.O.I. 24/08/18

Lum Sum:

%

3 Val.: Yes or No

Survey held at

MG Solution.

CA / REV / REP. / 24 HRS (up)

Des. of Damages (Frt) (Rear) / OIS / NIS / UIC / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Ego.

RECEIVED 07 NOV 2018

MV : 36K

PV : 24.6K

Nett: 11.4K.

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 8

02/11/18 turnia

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Survey Fee:

Transportation:

\_\_\_\_ \$ + RS, \_\_\_\_ SI

Photos

Others

350

TOTAL

Report Format : TP

Lump Sum / I.B.A. (\$) 9600