

(08/11/13)

Surveyor: KalvinREF: NS/INC18015477/K1+d3n2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: _____

at Workshop no/s _____

of _____

Insured: SLK 2650 KPolicy No: 50873 07994-01 (11/11/8-10/11/19)Claims No: M7/100 8414-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of Inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 3331 P Yr Regn: 2 Apr 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/Tr / Prime Mover /

Truck / Trailer or

Make: Hyundai 2x c.c. 1685Colour: Blue A/C: Insu 6 / Std / NI / NASp. Reading: 559532 T/Radio: Insu 0 / Std / NI / NA

Eng/No: _____

No: KMHLD 44AF40 67886

Gen. Cond: Good / F6 / Poor / Burnt

Steering: Inord 6 / Jammed / Leaked / Burnt orBrake: Inord 6 / Jammed / Leaked / Burnt orModi: Nil / S/Rim / SD A/Rim orTyre Size: F: 205 / 60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WenthaFront 7 mm Rear 7 mmR/Bal. 7 mm L/Bal. 7 mmD.O.A. 23/8/16 D.O.I. 24/8/16Survey held at CDHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHC 3331 P - NS/INC16020832/H1th3m2DoA: 30/10/16 IncSLK 2650K - X4x29/8/16 Wentha 4x \$2050 / 3 B. (Red: 1646.30 / 44%)

RECEIVED 30 AUG 2016

Date/Time, File Pass to?

☐ : Prel. Report

1) 30/8 Typist

☒ : Final Report

Date/Time, File Return to?

2)

Report Format: TPLump Sum / L.B.I: (\$ 2050)Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

160



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18015477/K1td3

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 27-08-2018
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 2650K	Veh. Inspected	SHC 3331P
Policy No.	5087307994-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/08/2018	Inspection Date	24/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="23/08/2018 07:58"/>							
Vehicle No.(For Motor)	<input type="text" value="SLK2650K"/>	Certificate Number	<input type="text"/>							
<input type="button" value="Search"/>										
Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5087307994-01		LEE LEE CHOO	S26279111	GPC	drivo CLASSIC	SLK2650K	SLK2650K	11/01/2018	10/01/2019
<input type="button" value="Continue"/>										

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/1009373-001	COMFORT TRANSPORTATION PTE LTD	SHC 3055L	PC 3697P	19/8/2018	\$ 1,623.66	\$ 1,095.46
2	MT/1009185-002	COMFORT TRANSPORTATION PTE LTD	SHC 8825Z	SFE 2060R	28/8/2018	\$ 2,892.18	\$ 800.00
3	MT/1009007-002	COMFORT TRANSPORTATION PTE LTD	SH 8358Z	RD 6187X	27/8/2018	\$ 2,089.88	\$ 814.45
4	MT/1009087-002	COMFORT TRANSPORTATION PTE LTD	SHA 4428Z	SIV 6885P	24/8/2018	\$ 6,595.38	\$ 5,236.10
5	MT/1008717-002	CITYCAB PTE LTD	SHC 7877E	SLA 3866B	24/8/2018	\$ 2,219.36	\$ 950.00
6	MT/1009120-002	COMFORT TRANSPORTATION PTE LTD	SHD 3624P	SJL 6504S	26/8/2018	\$ 6,844.92	\$ 1,510.06
7	MT/1008471-002	COMFORT TRANSPORTATION PTE LTD	SH 7842Z	FBK 6778T	22/8/2018	\$ 1,473.20	\$ 1,273.20
8	MT/1008626-002	COMFORT TRANSPORTATION PTE LTD	SHA 2462L	PC 6244T	23/8/2018	\$ 1,679.16	\$ 300.00
9	MT/1009154-002	CITYCAB PTE LTD	SHA 9452U	SJE 7737S	24/8/2018	\$ 2,731.58	\$ 650.00
10	MT/1008987-002	CITYCAB PTE LTD	SHA 621H	YN 8044B	26/8/2018	\$ 4,685.68	\$ 2,950.00
11	MT/1008975-002	CITYCAB PTE LTD	SHA 881Z	YP 2006R	26/8/2018	\$ 8,248.46	\$ 1,500.00
12	MT/1008414-002	COMFORT TRANSPORTATION PTE LTD	SHC 3331P	SLK 2650K	23/8/2018	\$ 3,696.80	\$ 2,050.00
13	MT/1008095-002	COMFORT TRANSPORTATION PTE LTD	SHA 3850T	FBK 1449B	17/8/2018	\$ 2,745.13	\$ 1,282.00

Claim received from LKK Auto

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/08/2018 16:34
Date Of Accident	23/08/2018 13:40
Exact Location Of Accident	BUKIT BATOK CENTRAL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC3331P
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	TAN KIAN HWEE
NRIC No	S6945530A
Date Of Birth	09/12/1969
Occupation	OUTDOOR
Date Of Driving Pass	19/09/1994
Driving Experience	23 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93696469
Fax Number	
Contact Number	
Email Address	TANKIANHWEE1212@YAHOO.COM

Address	803B 15-124 KEAT HONG CLOSE
Postcode	682803
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK2650K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN JIA WEI
NRIC/Passport Number	S9327340J
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT RHT
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23/8/18 at about 1340hrs while I Veh A was travelling along the right lane, Veh B abruptly exited from the side road and collided on the front left portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE. L.
CC REG. NO 199303821R

Policyholder's Signature

Driver's Signature

Reporting Centre Personnel's Signature

Jan.

[Signature]
23/8/18

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




OMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 19922821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





REPAIR ESTIMATE*

DATE 24/8/2018 10:13

Like

NTUC

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305203616

TOMER

REGN NO.:

SHC3331P

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN

23.08.2018 15:25

YR OF MANU

02.04.2015

TARGET DATE

CHASSIS CODE

KMHLB41UMFU067886

COMPLETION DATE/TIME:

NTUC

COUNT CARD NO.

JOB DESCRIPTION


Accident Date: 23.08.2018

NATURE: 3P 23.08.2018

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wedgement Slip

Exit Pass

No. 1
No. 2

SHC3331P

LKE

Vehicle No.:

SHC3331P

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18015477/K1td3n2			
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			
		Date: 03-09-2018	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLK 2650K	Veh. Inspected	SHC 3331P
Policy No.	5087307994-01	Coverage (\$)	0.00
Claim No.	MT/1008414-002	Excess (\$)	0.00
Assign From		Assign Date	24/08/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMFU067886	Colour	BLUE
Odometer	559532	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	7 mm
L/H Front Tyre	205/60 R16	WEST LAKE	7 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/08/2018	Inspection Date	24/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3331P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER COVER	TO REPAIR SEE LABOUR	562.30	-
1	FRONT BUMPER BRACKET TOP (LH)	SERVICEABLE	22.40	-
1	FRONT BUMPER BRACKET (LH)	SERVICEABLE	24.60	-
1	HEADLAMP (LH)	CUT	1,388.00	1,388.00
1	FRONT FENDER (LH)	DENTED	619.00	619.00
1	FRONT FENDER SHIELD (LH)	SERVICEABLE	169.80	-
1	FRONT FENDER RETAINER	SERVICEABLE	9.20	-
1	FR WHEEL HUB CAP, LH	GRAZED	150.70	150.70
	LESS 20% DISCOUNT		-589.20	-431.54
			2,356.80	1,726.16
<u>SPECIAL NETT ITEMS</u>				
1	FRT FENDER ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
			100.00	100.00
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BUMPER COVER.		560.00	300.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.		50.00	20.00
	FRT WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
			1,240.00	740.00
GRAND TOTAL			3,696.80	2,566.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,050.00

Report Ref No. NS/INC18015477/K1td3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K. LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.