Spark Car Care
ComfortDelgro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

Finalization Form

Bil :	Vehic	cle Number :	PA9465M	
Attn to KENNET	H (LKK) Type	Of Claim :	TP	
A. Spare parts	\$ 24,119.79	F. Total Parts	\$ 26,418.83	
B. Supplementary	\$ 3,777.80	G. Total Labour	\$ 9,040.00	
C. Nett Price	\$ -	H. Total Repair	\$ 35,458.83	
D. Supp Nett Price	\$	I. Excess		
E. S/Nett	\$ 1,311.00	P/P Total	\$ 35,458.83	
Total Spare Parts Price	\$ 27,897.59			
Cost plus / List Down 10 th	\$ 2,789.76 \$ 25,107.83	Lump Sum Less	\$	
Total Nett Price	\$ -			
Nett Price Less	\$ -	Lump Sum Rounding		
Total		Total Finalized	\$ 35,458.83	
N.B. If we DO NOT receive y	our reply within 2 weeks, we shall t	reat the above finalized amount as co	onfirmed L correct.	
Remarks : Please comfirm and revert	by Fax or Email			
Date In :	Total Repair Day			
Date Survey :	LOU/ Day			
Date Out :	Total LOU	LKK Auto Cons	cultants hence notify	
Sat/Sun/Ph. :	Rental/Day	To resurvey before To display damen	The following: **after spray painting	
Authorized Repair Day	Total Rental	Third party survey	is on a "Million	
Submitted By / Date :	Confirmed By / Date :	Supplementary its	m(s) must be resurveyed and poroval from insurance Company	

Spark Car Care
ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

0			D-	-4-
0	рa	re	۲a	rts

Vehicle No	:	PA9465M	Case Owner	:	0
Make & Model	:	SCANIA KUB4X2 9.3L	Year Manufacture	:	2010
Chassis No	:	YS2K4X20001869858	Engine No	:	0
Sales Order	:		Supplier	:	
Order By	:		Type of Claim	:	<u>TP</u>

S/No	Part Description	QTY	Cost Price		List Price	Nett Price		S/N	Disposition By Surveyor
1	FRT WINDSCREEN GLASS	1		s	5,095.11				
2	FRT WINDSCREEN GLASS MOULDING	1		\$	314.76				
3	SEALANT	1					\$	320.00	
4	INNER SEAL	1					\$	160.00	
5	ERP BRACKET	1					\$	26.00	
6	FRT PANEL	1		\$	1,440.00				
7	FRT PANEL STICKER "COMFORTBUS"	1					\$	300.00	
8	FRT PANEL STRUCTURE	1		s	3,850.00	****			
9	WIPER ARM LH	1							X
10	WIPER BLADE LH	1							X
11	HEADLAMP LH	1		s	1,390.81				
12	HEADLAMP RH	1		\$	1,390.81				
13	FRT BUMPER	1		s	2,688.00				
14	FRT BUMPER STRUCTURE	0		\$	2,304.00				
15	FRT BUMPER FOG LAMP LH	0		\$	358.30				
16	FRT NUMBER PLATE	0					s	45.00	
17	STICKER	0				Me	s	460.00	
18	FRT BODY PANEL LOWER	0		s	5,288.00				
19	0	0							
20	0	0							
21	0	0							
22	0	0							
23	0	0							
24	0	0							
25	0	0							
26	0	0					_		
27	0	0					_		
28	0	0					_		
29		0							
30		0							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care
ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax: 62815767

Labour

Vehicle No. :	PA9465M	Case Owner	:	0	
Make & Model:	SCANIA KUB4X2 9.3L	Year of Manufacture	:	2010	

S/No	Labour Description	Esimated Price	1	Adjusted Price
	TO REMOVE AND RENEW FRT WINDSCREEN GLASS	\$800.00	\$	680.00
	TO KNOCK, STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS			
	FRT PANEL, FRT PANEL STRUCTURE, FRT BODY PANEL, FRT			
	BUMPER, FRT BUMPER STRUCTURE, BOTH HEADLAMP AND ETC	\$4,000.00	\$	3,200.00
	TO PUTTY AND RESPRAY ACCIDENT AREA SUCH AS FRT PANEL,	-		
	FRT PANEL STRUCTURE, FRT BODY PANEL, FRT BUMPER, FRT			
	BUMPER STRUCTURE AND ETC	\$2,000.00	\$	1,500.00
	TO CHECK WIRING AND LIGHTING	\$50.00	\$	20.00
	TO REMOVE AND INSTALL DASHBOARD TO FACILITATE REPAIR	\$280.00	\$	280.00
_				
			-	
-				
				, ,
-				

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Spark Car Care

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Labour

Vehicle No. :	PA9465M	Case Owner	:	0	
Make & Model:	SCANIA KUB4X2 9.3L	Year of Manufacture	:	2010	

S/No	Labour Description	Esimated Price	Adjusted Price
33	SUPPLEMENTARY LABOUR		
34	TO KNOCK STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS		
35	FRT FIRE WALL, FRT BODY PANEL FRAME, FRT PANEL FRAME,		
36	FRT PANEL HINGE SYSTEM AND ETC (\$480 PER DAY)	\$4,800.00	\$ 3,380.00
37			
38			
39			
40			
41			
42			
43			
44			
45			
46			
47			
48			
49			
50			
51			
52			
53			
54			
55_			
56			
57			
58			
59			
60			
61			
62			
63		-	
64			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

2400/

Spark Car Care
ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767


Supplementary 1

Vehicle No	: PA9465M	Case Owner	:	0	
Make & Model	: SCANIA KUB4X2 9.3L	Year Manufactur	re:	2010	
Chassis No	: YS2K4X20001869858	Engine No	:	0	
Sales Order	: 0	Supplier	:	0	
Order By	:	Type of Claim	:	<u>TP</u>	

S/No	Part Description	QTY	Cost	List	Nett		Disposition By
			Price	Price	Item	S/N	Surveyor
1	FRT PANEL HINGE SYSTEM	1	121	\$ 1,480.00			_
2	FRT PANEL LOCK	1	Ry	\$ 123.80			_
3	FRT PANEL FRAME	1	R,	\$ 1,788.00			-
4	AIR REGULATOR	1	nl	\$ 386.00			_
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

UEN: 200200864C GST Reg No: 20-0200864-C Date: 04/10/2018



COMFORTDELGRO ENGINEERING PTE LTD 205 Braddell Road, Blk C Ext 1, 2Nd Level 579701 Attn: Mr Ngo Toh Wee

INSERTION ORDER ACKNOWLEDGEMENT

Dear Sir/Madam.

Thank you for your order

This is to acknowledge your order has been received

The details are as follows -

IO No : 1810057

MC No

IO Date : 02/10/2018

Agency :

Advertiser : COMFORTDELGRO ENGINEERING PTE LTD

Product : JTC-One North (PA9465M)Touch Up

Commencement Date : 09/10/2018

Expiry Date : 15/10/2018

Amount (Before GST) : \$ 460.00

Please examine the details in this letter immediately. If no discrepancy is reported within 7 days from the date of this lettler, the insertion order will be considered as in order.

Please call 63837035 or email advertising@moovemedia.com.sg if you have any query.

This is computer generated letter. No signature is required.