## COMFORTDELGRO ENGINEERING PTE LTD

## **REPAIR ESTIMATE\***

MAKE

VEHICLE NO : SHD6763B

: MERCEDES

27. Aug. 2018 DATE:

ODEL	: E220 (E6)	DOA:	25. Aug. 2018	<u>AXA</u>
Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	1 Side Mirror Housing with Signal Lamp – RH /			\$414.00
	1 Side Mirror Motor – RH /			\$860.00
	1 Side Mirror Glass – RH			\$230.00
	1 Side Mirror Cover – RH			\$70.00
	SUB TOTAL LESS 20%			<b>\$1,574.00</b> \$314.80
	DISCOUNTED TOTAL			\$1,259.20
				\$-
	Labour Charge Panel Beating Spray Painting Charge Wiring Charge			\$100.00 \$100.00 \$50.00
	2 7/8/8 13 45 L. TOTAL LABOUR			\$250.00
Larry NG	Refore Pai21 photo . Parts pri	y damaged par ces are subject rty survey is on	(s) during resurvey to confirmation a "Without Prejudice" basis	\$1,509.20
	This is an initial estimate based on a visual inspection of the	e above vel	hicle. The final repair o	
	be prepared after the vehicle is surveyed by a motor Surveyed	yordppoin	ted by the insurance c	ompany.

Signature: Date: