

INSURANCE

INS. CASE OWNER:

Lynthia

CC 4 ASM AXA1801 5516, R1 e639

LKK:

IDAC:

Surveyor:

MEB

DOI:

ASSIGNMENT

2/1/18

Date / Time:

2/1/18

Registered in Merit:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUP 1082E

Name of Insured:

UM PIKE KHON

Insured Tel No.:

HP: 07340747

Excess Sec II :SS

D.O.A: 2/8/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SEMUTATI/65440

Policy No.:

VPA/VIAYU VI

Make / Model:

REUBERT.

Place of Accident:

BEDUK WIRIN RD.

OI GIA REPORT: YES / NO

YES

TP GIA REPORT: YES / NO

YES

Insured Liability:

%

Final ? Yes / No

SUP 7477

SUP 1082E

SKV 547T

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

01

INSRS:
WSP:
Tel:
Liability:
RMKS:SUP
TPINSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

2/8/18
Pike

SUP 1082E - 4

SUP 547T - 2

Kamutalan

29.8.18 & 10.9

CALLED ON (CONTINUED) ACCIDENT. ON INVOLVED IN 3 VEH. CL ON
WAS THE 2ND VEH. INVOLVED TO CLAIM ACCORD TO SEMUT
AND ADVISE ABOUT NCD ISSUE.

EMER WSP LIABILITY CLEAR.

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

EMAIL 13.9.18

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

Confirm by: MEB

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

45 \$51,950.00

(5 days) Reduction:

57

%

Email

Call

FINAL SETTLEMENT

Date/Time: 10.10.18

Confirm with: Supaya

Email

Call

Final Liability:

100%

(Agreed / Assessed) BOLA S/N No.:

28

Repair Cost:

\$51,950.00

3 VEH CL 01 200

Loss of Rental (LOR):

\$5 -

(5 days)

Loss of Use (LOU):

\$5 300.00

(5 60 x 5 days)

Loss of Income (LOI):

\$5 -

(5 x 5 days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search:

\$5 -

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost:

\$5 -

Total:

\$52,250.00

Global Sum \$5:

FINAL PAYMENT

Date/Time: 14.12.18

Confirm with: Supaya

Email

Call

Payee 1:

\$52,250.00

Name 1:

SUP MOTORING SERVICES

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 7350

COPY SENT
14/12/18

Surveyor: *[Signature]*

REF:

e


7899c

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SKV 547T**
 at Workshop n/s: **SLP MOTORING**
 of **ARK Insurance #03-07**
 Insured **AXA / up**
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: **70K**
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **5** days Res: Yes or No
 Lum Sum: **50** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SKV 547T** Yr Regn: **2015 / Aug**
 Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **HONDA MOBILIO 1.5 CVT** C.C. **1497**
 Colour: **WHITE** A/C: Insured / Std / NI / NA
 Sp. Reading: **06 0843** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **MRH004870FP000204**
 Gen. Cond: Good / ☒ Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modl: **NIJ / S/Rim / STD A/Rim** or
 Tyre Size: F: **195/60R15**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **LANH LONG**
 Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A. **24/08/18** D.O.I. **03/09/18**
 Survey held at: **SLP MOTORING**
 Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

45: +1,950 (RED: +2,500.50 57/-)

Date/Time: File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18015516/eb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 27-08-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLP 1082E	Veh. Inspected	SKV 547T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	27/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/08/2018	Inspection Date		
Survey held at	SLP MOTORING SERVICES 102 GERALD DRIVE #04-75 SELETAR SPRINGS CONDOMINIUM SINGAPORE 798593			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SLP Motoring Services

Blk 10 Ang Mo Kio Industrial Park 2A AMK Autopoint #03-08

Singapore 568047 HP 91004390/HP 91254449 Fax 64841482

Email: slpmotoring@gmail.com

M/s AXA Insurance Pte Ltd

DATE

03.09.2018

8 Shenton Way #27-02

CAR NO

SKV 547 T

Singapore 068811

MAKE

Honda Mobilio / MR 480 4870/2015

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SLP 1082 E

Pc	Pcs	Chassis No. : MRHDD4870FP000204	UNIT PRICE	AMOUNT
1	pc	Rear boot lid	886.30	792
1	pc	Rear boot lid "H" logo	27.50	
1	pc	Rear boot lid "Mobilio"	25.00	
1	pc	Rear boot lid rubber	96.70	
1	pc	Rear bumper	463.70	
1	pc	Rear bumper left side reflector	25.00	1427.70
1	pc	Rear end panel	314.70	20%
1	pc	Rear end panel top garnish	60.80	1142.16
1	pc	Rear end panel top garnish clips	22.80	
		Rust-proofing on the rear accident affected portions	60	\$120.00
		Straightening, repairing and realigning onto rear two side mudguard, cutting rear end panel, dismantle and replace the above mentioned parts	500	\$1100.00
		To spray painting on tail gate inner/outer, rear end panel & rear bumper in pearl white.	600	\$1100.00
		To apply silicon onto rear wind screen (2 tube).	60	\$120.00
		To dismantle & refix rear wind screen.	120	\$180.00
		Total		\$4,542.50

LKK Auto Consultants hence notify the Repairer of the following:

- To survey calibrator spray painting
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be recharged and is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer:

Signature:

Date:

SLP Motoring Services

4/5-1,950
5 days

SLP Motoring Services

Blk 10 Ang Mo Kio Industrial Park 2A AMK Autopoint #03-08

Singapore 568047 HP 91004390/HP 91254449 Fax 64841482

Email: slpmotoring@gmail.com

M/s	AXA Insurance Pte Ltd	DATE	03.09.2018
	8 Shenton Way #27-02	CAR NO	SKV 547 T
	Singapore 068811	MAKE	Honda Mobilio

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SLP 1082 E

Pc	Pcs	Chassis No. : MRHDD4870FP000204	UNIT PRICE	AMOUNT
1	pc	Rear boot lid		886.30
1	pc	Rear boot lid "H" logo		27.50
1	pc	Rear boot lid "Mobilio"		25.00
1	pc	Rear boot lid rubber		96.70
1	pc	Rear bumper		463.70
1	pc	Rear bumper left side reflector		25.00
1	pc	Rear end panel		314.70
1	pc	Rear end panel top garnish		60.80
1	pc	Rear end panel top garnish clips	\$3.80	22.80
		Rust-proofing on the rear accident affected portions	60	120.00
		Straightening, repairing and realigning onto rear two side mudguard, cutting rear end panel, dismantle and replace the above mentioned parts	500	1100.00
		To spray painting on tail gate inner/outer, rear end panel & rear bumper in pearl white.	600	1100.00
		To apply silicon onto rear wind screen (2 tube).	60	120.00
		To dismantle & refix rear wind screen.	120	180.00
			Total	\$4,542.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLP Motoring Services



MANDATE REQUEST FOR S8M00TAH

Go To My

Type

🔔 Question

Message

Liability: Insured involved in 3 vehicle chain collision insured was the 2nd vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$1,950.00 Loss of Use : \$300.00 (5days x \$60) Total: \$2,250.00 Immediate Advice with Mandate and revised estimate for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (24/11/2018)

Reply



Re:MANDATE REQUEST FOR S8M00TAH

Type

🔗 Question

Message

MANDATE APPROVED

Reply

SLP Motoring Services

102 Gerald Drive #04-75 Singapore 798593

HP 91004390/HP 91254449 Fax 64841482

Email:slpmotoring@gmail.com

SATISFACTION & DISCHARGE VOUCHER

I, Ho Yin Peng Doreen, owner of vehicle number SKV 547 T declare that my vehicle has been completed to my satisfaction and was discharged from SLP Motoring Services at Block 10 Ang Mo Kio Industrial Park 2A #03-07 AMK Autopoint Singapore 568047 on the 08 day of Sep 2018.

Signature of Assured,


Ho Yin Peng Doreen.

Accident Date : 24.08.2018

Name : Ho Yin Peng Doreen

Address : 848 Tampines Street 82 #09-197 S520848

SLP Motoring Services

102 Gerald Drive #04-75 Singapore 798593

HP 91004390/HP 91254449 Fax 64841482

Email:slpmotoring@gmail.com

25.10.2018.

Our Ref : SKV 547 T

Your Ref : SLP 1082 E

Ho Yin Peng Doreen
C/o SLP Motoring Services

Attn: Motor Claims Department
AXA Insurance Pte Ltd
8 Shenton Way #27-02
Singapore 068877

Dear Sir/Mdm,

RE: ACCIDENT INVOLVING SKV 547 T, SLP 1082 E & SHF 347 Z ON 24.08.2018

We are repairer of vehicle no. SKV 547 T which was involved in an accident with vehicle no. SLP 1082 E which is insured with you.

The accident was clearly caused by your insured's negligence. We are therefore seeking compensation from you for our client's financial losses as itemized below:-

Cost of Repair				\$1,950.00
Loss of Use	5	Days	\$60.00	\$300.00
Total				\$2,250.00

We enclose copies of the relevant documents to support our claim.

Your prompt settlement of our claim would be much appreciated.

You may contact Susan (HP : 91004390) or Fion (HP : 91254449) should you have any queries.

Thank you for your kind attention.

Yours faithfully,


SLP Motoring Services.

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Wednesday, 12 September 2018 3:03 PM
To: 'BICHABD@SINGNET.COM.SG'
Subject: ACCIDENT INVOLVING SLP 1082E AND SKV 547T ALONG BEDOK NORTH ROAD ON 24/08/2018

12 SEPT 2018

LIM PIAK KHOON

Dear Sir/ Mdm

OUR REF : CC4/ASM18015516/R1eb3
YOUR REF : SLP 1082E
ACCIDENT INVOLVING SLP 1082E AND SKV 547T ALONG BEDOK NORTH ROAD ON 24/08/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s SLP MOTORING SERVICES acting on behalf of the owner of SKV 547T against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties, where your vehicle was involved in a three (3) vehicle chain collision and was the 2ND vehicle that rear-ended the Third Party Vehicle SKV 547T and we are of the opinion that we cannot be absolved from liability.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ashersng@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at ashersng@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

SLP Motoring Services

102 Gerald Drive #04-75 Singapore 798593

HP 91004390/HP 91254449 Fax 64841482

Email:slpmotoring@gmail.com

03.09.2018.

Our Ref : SKV 547 T

Your Ref : SLP 1082 E

Ho Yin Peng Doreen
C/O SLP Motoring Services

Attn: Motor Claims Department
AXA Insurance Pte Ltd
8 Shenton Way #27-02
Singapore 068811

Dear Sir/Mdm,

LETTER OF AUTHORITY

RE: ACCIDENT INVOLVING SKV 547 T, SLP 1082 E & SHF 347 Z ON 24.08.2018

I, Ho Yin Peng Doreen, owner of vehicle no. SKV 547 T hereby authorize M/s SLP Motoring Services as my authorized representative to write, negotiate and settle claim on my behalf in my claim against the owner and / or driver of vehicle no. SLP 1082 E in respect of the above mentioned accident.

Kindly make payment directly to SLP Motoring Services.

Kindly contact Susan (HP : 91004390) or Fion (HP: 91254449) should you have any queries regarding the above.

Yours faithfully,


Ho Yin Peng Doreen.



redefining / insurance

CLAIM REF : S8M00TAH
INSURED : LIM PIAK KHOON

DISCHARGE VOUCHER

We/I **[HO YIN PENG DOREEN, NRIC NO. S7527899C]** hereby agree to accept the sum of dollars **[TWO THOUSAND TWO HUNDRED AND FIFTY ONLY.] [S\$2,250.00]** paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. **[SLP 1082E]** as a result of an accident along **[BEDOK NORTH ROAD/MRT STATION]** on **[24/08/2018]** of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. **[SKV 547T]**.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. **[SLP 1082E]** in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. **[SLP 1082E]**.

Dated this 13 day of Dec 2018

Claimant's Signature

[Signature]

NRIC no./ Company Stamp

S7527899C

Occupation/ Business

Indoor

Address

Blk 848 Tampines St 912 #01-197 S520848

Telephone No.

84468449

Witness's Name

Lim Koh Noi

Witness's Signature

[Signature]

Witness's NRIC No.

S0200161 F

AXA Insurance Pte Ltd (Company Reg. No. 199903512M)
8 Shenton Way, #24-01 AXA Tower, Singapore 068811
Customer Centre #B1-01
Tel: +65 6880 4888 Fax: +65 6338 2522 Website: www.axa.com.sg

WITHOUT PREJUDICE to:

- (a) Insurance Subrogated Claim and/or
 - (b) Any Personal Injury Claims
- (Note: This Notice supersedes any inconsistencies found in this Discharge Voucher)

Email:slpmotoring@gmail.com

MAKE Honda Mobilio

SLP Motoring Services.

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLP 1082E (Insd veh)	Model:	HONDA MOBILIO 1.5 CVT
	SKV 547T (TP veh)		
Date of Accident:	24/08/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	4,542.50
Final Repair Cost	:	\$	1,950.00
Loss of Use	:	\$	300.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	2,250.00

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability ____ 100 ____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: ____
BOLA Liability: ____ (%)	Assessed Liability (*): ____ 0 ____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown		
1)	SLP MOTORING SERVICES	\$ 2,250.00

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

26/12/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18015516/R1eb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 26-12-2018



ATTN: CYNTHIA LOH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLP 1082E	Veh. Inspected	SKV 547T
Policy No.	VPA/P1940271	Coverage (\$)	0.00
Claim No.	S8M00TAH	Excess (\$)	0.00
Assign From		Assign Date	27/08/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA MOBILIO 1.5 CVT	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MRHDD4870FP000204	Colour	WHITE
Odometer	060843	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	LING LONG	6 mm
L/H Front Tyre	195/60 R15	LING LONG	6 mm
R/H Rear Tyre	195/60 R15	LING LONG	6 mm
L/H Rear Tyre	195/60 R15	LING LONG	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/08/2018	Inspection Date	03/09/2018
Survey held at	10 AMK IND PARK 2A #03-07		
Repairer	SLP MOTORING SERVICES		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 547T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LID (CONSISTENT)	BENT	886.30	792.00
1	REAR BOOT LID 'H' LOGO (CONSISTENT)	NECESSARY	27.50	27.50
1	REAR BOOT LID 'MOBILIO' (CONSISTENT)	NECESSARY	25.00	25.00
1	REAR BOOT LID RUBBER (CONSISTENT)	NECESSARY	96.70	96.70
1	REAR BUMPER (CONSISTENT)	DEFORMED	463.70	463.70
1	REAR BUMPER LEFT SIDE REFLECTOR (CONSISTENT)	SERVICEABLE	25.00	-
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	314.70	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	SERVICEABLE	60.80	-
1	REAR END PANEL TOP GARNISH CLIPS (CONSISTENT)	NECESSARY	22.80	22.80
	LESS 20% DISCOUNT		-	-285.54
			1,922.50	1,142.16
	<u>LABOUR</u>			
	RUST-PROOFING ON THE REAR ACCIDENT AFFECTED PORTIONS.		120.00	60.00
	STRAIGHTENING,REPAIRING AND REALIGNING ONTO REAR TWO SIDE MUDGUARD,CUTTING REAR END PANEL,DISMANTLE AND REPLACE THE ABOVE MENTIONED PARTS.		1,100.00	500.00
	TO SPRAY PAINTING ON TAIL GATE INNER /OUTER,REAR END PANEL & REAR BUMPER IN PEARL WHITE.		1,100.00	600.00
	TO APPLY SILICON ONTO REAR WIND SCREEN (2 TUBE).		120.00	60.00
	TO DISMANTLE & REFIX REAR WIND SCREEN.		180.00	120.00
			2,620.00	1,340.00
	GRAND TOTAL		4,542.50	2,482.16
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,950.00

Report Ref No. CC4/ASM18015516/R1eb3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SBM007AH
Reference	CCA/ASM18015516/R1reQu2
Loss Date	24 August 2018
Request Date	8 November 2018
Due Date	
Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SKV5477
Make	TPVO HONDA
Model	MOBILIO 1.5 V CVT (A)
Service Address	
...	
Primary Contact/Insured	
LIM PIAK KHOON	
BLK 475 PASIR RIS DRIVE 6, #08-554, S10475, Singapore	
97390247	
RICHARD@singnet.com.sg	
Claim Handler	
LOH Cynthia	
6548104843	
cynthia.loh@axa.com.sg	
















Additional Instructions

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKXInvoice1 (2).pdf	Invoice	Supplier/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	28 December 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 payment breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 LKD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 November 2018
 LKK Survey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 November 2018
 Immediate Advice with Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 November 2018
 To ABS & CST ,Remain to LKK.tif	Letters and Correspondence	Internal	LOH Cynthia	31 August 2018
 TP PRI FROM WORKSHOP.mng	Letters and Correspondence	Workshop	DHAMAL Raghav	27 August 2018
 SI# 3472 GIA REPORT.PDF	Reports & Statement	GIA Report	DHAMAL Raghav	27 August 2018
 SLP1002E INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAMAL Raghav	27 August 2018

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
 SMV5477 TP GSA REPORT PDF	Reports & Statement	GSA Report	DHAMAL Raghav	27 August 2018