



Your Ref: 18.24904 PD-O

Date: 25th Sep 2018

Our Ref : CS3/ASM18013798/Bsbe2-1

M/s AXA Insurance Pte Ltd
C/O: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLD 6115A
INSURED VEHICLE: SLC 5537C
ACCIDENT DATE: 25/07/2018

We thank you for your instruction on 21/08/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLD 6115A from M/s MC-COY Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SLD 6115A and SLC 5537C.
- c) Final Repair Bill of SLD 6115A from M/s Bluwel Automotive Service Pte Ltd.
- d) Colour damaged vehicle photographs of SLD 6115A.

Pre-Repair Inspection Date : 30/07/2018 at M/s Bluwel Automotive Service Pte Ltd, Blk 1 Kaki Bukit Ave 6 #01-55(Main Office) Singapore 417883.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLD 6115A
Make & Model	: B.M.W. 428I GRAN COUPE M SPORT A/T SR HID NAV
Year of Registration	: 2015
Chassis Number	: WBA4A52000GT40746
Engine Capacity	: 1997 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.