

Surveyor

Marcus

ASSIGNMENT (Office)

From (Person):

Muhd Ashik

of

MS19

Date/Time

27/8/18 @ 10:08am

Estimated Cost:

Bill to:

OD / (P) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SJP 7431R

Insured:

SKA 6559E

at Workshop m/s:

Sin Auto

Tel:

6289 8126

of

Blk 14 De Lu Lane 10 # 01-410 / 412

Policy No.

P277 66970DMA

Claim No:

568122

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

11:07am @ 27/8/18

Person Contacted:

Janis

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SJP 7431R - X

SKA 6559E - X

29/8- Report via menimen preli advice.

ASS. REC. BY: Marcus

REF:


ASIG/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJP7431R
 at Workshop m/s J. M. App.
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 11k.
 IDAC Accident Report: Consistent? : Yes or No
 GIA / PR Seen: 1 Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
6/4/2018 Vehicle: IN / OUT

Veh No: SJP7431R Yr Regn: 4, 09
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Kia Cerato Forte C.C. 1591
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 193751 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KN AFH 221395045094
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/452R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Gremax
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 27/8/18 D.O.I. 27/8/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
N/S R.
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L7A7864 Tollyphus Net 3'36
Spore ports should be 10%

31/8/18 confirmed L/S @ 1350 with Jours (Red 807.50, 37)

RECEIVED 03 sept 2018

31/8/2018

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 3Resurvey No. of Trip: -

Survey Fee:

Transportation:

S + RS: SI

Photos:

Others:

TOTAL

150
10

160

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Report Format: TPLump Sum / I.B.I. (\$) 1350



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18015538/Utd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 27-08-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKA 6559E	Veh. Inspected	SJP 7431R	
Policy No.	P27266970DMA	Coverage (\$)	0.00	
Claim No.	568122	Excess (\$)	0.00	
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	27/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/08/2018	Inspection Date	27/08/2018	
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 29 Aug 2018

Preliminary Advice

Insured Vehicle No	: SKA6559E	Accident Date	: 22/08/2018
TP Vehicle No	: SJP7431R	Assignment Date	: 27/08/2018
Make	: KIA CERATO FORTE	Est. Duration of Repair	: 3.00
Date of Inspection	: 27/08/2018		
Inspection At	: JIN AUTO SERVICES PTE LTD (DEFU) BLK 14 DEFU LANE 10, #01-410/412 SINGAPORE 539195		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,157.50
Revised Amount	:S\$	1,732.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,732.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Aug 2018		27 Aug 2018 10:08 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LEE WEE BENG GERRY, ID: S7109859A		
Main Claimant:	AVON LEASING PTE. LTD., Co. Reg. No.: 201728001G		
Vehicle Reg. No.:	SJP7431R	Date of Loss:	22/08/2018 12:00 - :59 [112 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 568122	Policy/Cover Note No.:	P27266970DMA (Comprehensive) Coverage: 22/03/2018 - 21/03/2019
Vehicle Reg. No. (Insured):	SKA6559E	Policy No. (Claimant):	
		Excess:	
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/08/2018]		
Driver/Custodian (Insured):	EVELYNE LAUW (), NRIC: S8072887E, Tel: +6596286618		
Adj Asg. Remarks:	ON WP. Liability 50%, Contact : Jouis Seow at 6289 8126		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Kia Cerato

Price Range ▼

Depreciation ▼

2009 ▼

Vehicle Type ▼

Home » Used Cars » P M Motoring Trading » Kia Cerato Forte 1.6A SX

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing

Kia Cerato Forte 1.6A SX

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price	\$12,888	
Depreciation	\$9,650 /yr View models with similar depreciation	?
Reg Date	13-Mar-2009 (6mths 13days COE left)	
Manufactured	2009	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,591 cc	
Road Tax	\$738 /yr	?
Power	92.7 kW (124 bhp) View specs of the Kia Cerato Forte (2009-2013)	
Curb Weight	1,251 kg	?
Features	Powerful 1.6L DOHC Engine, Responsive Auto Transmission Gearbox, ABS, Airbags, Auto Climatic Aircon Controls, Steering Control, Reverse Sensors.	
Accessories	Built In Audio System With Steering Controls, Auto Retractable Side Mirrors, Reverse Sensors, Fog Lights.	
Description	Very Well Maintained Interior And Exterior, Accident Free. Stylish, Smart Looking Sedan, Good Performance, Fuel Efficiency Known For Kia Best Seller Worldwide! Showroom Condition, Low Depreciation, Original Paintwork.	
COE	\$4,460	?
OMV	\$15,355	?
ARF	\$15,355	?



Seller Infor

Company

Address

Office No

Contact Perso

Useful Servi



Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8001G
Vehicle Details	
Vehicle No.:	SJP7431R
Vehicle to be Exported:	No
Intended De-registration Date:	27 Aug 2018
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE 1.6(A) SX ABS D/AB 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	G4FC9H242480
Chassis No.:	KNAFH221395045094
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$15,185.00
Original Registration Date:	07 Apr 2009
First Registration Date:	07 Apr 2009
Transfer Count:	2
Actual ARF Paid:	\$15,185.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Apr 2019
PARF Rebate Amount:	\$7,592.00
Intended COE Rebate Details	
COE Expiry Date:	06 Apr 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$4,460.00
COE Rebate Amount:	\$272.00
Total Rebate Amount:	\$7,864.00

The information contained herein is correct as at 27 Aug 2018

OK

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Date : 24/8/2018

M/S MSIG

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SJP7431R

TO SUPPLY :

List Items

- | | | | |
|-----|------|------------------------|--------|
| 01) | 1 PC | FRONT BUMPER | Dis |
| 02) | 1 PC | FRONT LH HEADLAMP | scr |
| 03) | 1 PC | FRONT LH FENDER | 3.6500 |
| 04) | 1 PC | FRONT LH SIDE RETAINER | Ref |

\$	510.00	✓
\$	407.00	✓
\$	325.00	✓
\$	28.00	✓

\$ 1,270.00

LESS 25%

\$ (317.50)

\$ 952.50

- | | | |
|-----|------------------------------------|-----|
| 05) | CLIPS | nm |
| 06) | LABOUR CHARGE | ✓ |
| 07) | ADJUST HEADLAMP AIM & CHECK WIRING | 300 |
| 08) | TUFF KOTE | 20 |
| 09) | SPRAY PAINTING | 30 |

\$	30.00	✓
\$	480.00	300
\$	35.00	20
\$	80.00	30
\$	580.00	400
\$	2,157.50	

Not Added

2 hr
n/s \$1350/-
3 hr
27/8/18

29/8/18

1732.5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18015538/UTD3N2

Date: 04/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	P27266970DMA
Claimant Vehicle No :	SJP7431R	Insured Vehicle No :	SKA6559E
Date of Loss:	22/08/2018	Nature of Claim:	TP
		Claim No:	568122

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP7431R	Engine No:	G4FC9H242480
Make & Model:	KIA CERATO FORTE, 1.6 SX (A)	Chassis No:	KNAFH221395045094
Reg. Date:	07/04/2009 (Man. Year: 2009)	Odometer:	193751 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45ZR17	Rear Tyre Size:	215/45ZR17
Front Left Side:	Gremax 6 mm	Rear Left Side:	Gremax 6 mm
Front Right Side:	Gremax 6 mm	Rear Right Side:	Gremax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	982.50	982.50	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,175.00	750.00	425.00	36.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,157.50	1,732.50	425.00	19.70
Approved Total (Overridden) (S\$)		1,350.00		
(S\$)	2,157.50	1,350.00	807.50	37.43
+ GST 7.00/7.00% (S\$)	151.03	94.50	56.53	37.43
Nett Amount (S\$)	2,308.53	1,444.50	864.03	37.43

INSPECTION

Date of Assignment: 27/08/2018

Date Inspected: 27/08/2018 Inspected At:

Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Sep 2018)
Parts: 143	KIA CERATO FORTE 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP7431R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	510.00 FL	*510.00 FL
2	1		*FRONT LH HEADLAMP	Scratched	407.00 FL	*407.00 FL
3	1		*FRONT LH FENDER	Badly Dented	325.00 FL	*325.00 FL
4	1		*FRONT LH SIDE RETAINER	Bent	28.00 FL	*28.00 FL
5	1		*CLIPS	Necessary	30.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					1,300.00	1,300.00
- List Item Discount on L Items 25.00/25.00% (\$\$)					317.50	317.50
Total Parts (\$\$)					982.50	982.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE	New	480.00	300.00
2	ADJUST HEADLAMP AIM & CHECK WIRING	New	35.00	20.00
3	TUFF KOTE	New	80.00	30.00
4	SPRAY PAINTING	New	580.00	400.00
Gross Labour Cost (\$\$)			1,175.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >