

ASS. REC. BY:

REF: CS/EGT/18015540/Uvd3⁷²

Special Instruction:

Surveyor: Marius

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGIDate/Time: 27/8/18 @ 1:34pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBE 3199RInsured: YK 6230Jat Workshop m/s Liu's BrotherTel: 67411730of No.1 Kaki Bkt Ave G #01-01 AutobayPolicy No: _____ Claim No: YK 6230J / RH / PI

Sum Insured: _____ Excess: _____

Make of Veh:

(Client's Record)

D.O.A. 07/08/2018CA / REV / REP. / REV 24 HRS up

H.O.D. Endorsement: _____

Date/Time: 2:03pm @ 27/8/18 Person Contacted: JufenVehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GBE 3199R - CS/FCI 17024576 / Uvbs2 DOA: 9/12/17</u>
	<u>YK 6230J - X</u>
<u>28/8/18</u>	<u>Email preli revised to Pei Li</u>

(08/11/13) wef

ASS. REC. BY: MORIS

REF:

SR1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBC3199Rat Workshop m/s 1125

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBC3199RYr Regn: 10/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)Make: Toyota hiace c.c. 2982Colour: white A/C: Insured / Std / NI / NASp. Reading: 77597 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFH702P30017998

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CST tiresFront 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 7/8/18 D.O.I. 27/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
29/8/18	continued final by 22/9.65 with Susan. (Recd 941.35, 29/8/18) (No LS)

RECEIVED 30 AUG 2018

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 30/8 - typistDays Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

250Report Format: TPLump Sum / I.B.I. (\$) 2219.65



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18015540/Uvd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 27-08-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YK 6230J	Veh. Inspected	GBE 3199R
Policy No.		Coverage (\$)	0.00
Claim No.	YK6230/RH/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	27/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	07/08/2018	Inspection Date	27/08/2018
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: YK 6230J/RH/pl
Our Ref: CS/EGH18015540/Uvd3

Date: 28/8/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. GBE 3199R


We thank you for your instruction on 27/8/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/8/2018 at the premises of M/s LIU'S BROTHER AUTO ENGINEERING WORKSHOP and have the following to report:-

Workshop Estimate Amount	: S\$3,161.00
Revised Estimate Amount	: S\$2,453.50
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 28 August 2018 2:00 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: YK6230J / TP : GBE3199R/LKK / DOA : 07/08/2018
Attachments: GBE 3199R PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle GBE 3199R
Date of survey: 27/8/2018

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 27 August 2018 1:34 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: OI : YK6230J / TP : GBE3199R/LKK / DOA : 07/08/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **LIU'S BROTHER AUTO**,

ADDRESS : NO 1 KAKI BUKIT AVENUE 6
#01-01 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

PERSON TO CONTACT : SUSAN @ 6741 1730

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li (Ms)
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel. : +65 6829 9199
Fax : +65 6829 9247

The logo for ERGO, consisting of the word "ERGO" in a bold, black, sans-serif font.

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 27.08.2018
Our Reference: YK 6230J/RH/pl
Your Reference: GBE 3199R

To: LIU'S BROTHER AUTO

Sent via Fax ☐
or ☐
Email ☐ liusbro@gmail.com

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBE 3199R
Insured's Vehicle: YK 6230J
Date Of Accident: 07.08.2018


We acknowledge receipt of your request for PRS on: 24.08.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☒ Our Insured's driver has not reported the accident to us to date.
☒ Others: OFFICER-IN-CHARGE - ROHAINI

Prepared by:	<u>Pei Li</u>	6829 9194	claims@ergo.com.sg
Signature:			FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .



Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.



Date: 27.08.2018

Our Reference: YK 6230J/RH/pl

Your Reference: GBE 3199R

To: LIU'S BROTHER AUTO

Sent via Fax

or

Email

liusbro@ymail.com

Pre-Repair Survey (PRS) Acknowledgement


Vehicle For Inspection:	GBE 3199R
Insured's Vehicle:	YK 6230J
Date Of Accident:	07.08.2018

We acknowledge receipt of your request for PRS on: **24.08.2018**

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

✓	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
	Your request for inspection does not have your client's GIA report, kindly forward a copy.
	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
✓	Our Insured's driver has not reported the accident to us todate.
✓	Others: OFFICER-IN-CHARGE - ROHAINI

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 27 August 2018 1:34 PM
To: 'admin-d@lkkauto.com'
Subject: OI : YK6230J / TP : GBE3199R/LKK / DOA : 07/08/2018
Attachments: GBE3199R - SAS.pdf; GBE3199R - PRS FORM.pdf; Re: RE: Request for 3rd party claims survey GBE3199R Claims against YK6... (29.1 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **LIU'S BROTHER AUTO**,

ADDRESS : NO 1 KAKI BUKIT AVENUE 6
#01-01 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

PERSON TO CONTACT : SUSAN @ 6741 1730

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li (Ms)
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038965
DID.: +65 6829 9194
Tel.: +65 6829 9199
Fax: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

[> Back to OneMotoring](#)

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 21 Aug 2018 / 12:11:11

Receipt Date/Time : 21 Aug 2018 / 12:11:11

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180821-001046

Previous Receipt No. :

S/N Item Description/
Business Transaction Reference
No.

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - YK6230J

As at 07 Aug 2018/08:40:00

Insurance Co: ERGO INSURANCE PTE. LTD.

1 Insurance Enquiry - YK6230J
Enquiry Fee
20180821120937226230

7.00	0.49	7.49
------	------	------

Sub-Total

7.00	0.49	7.49
------	------	------

Total Before Rounding

7.00	0.49	7.49
------	------	------

Rounding Difference

0.04

Total Amount Payable

7.45

Paid By

xxxxxxxxxxxx4559 Credit Card;
Visa/MasterCard

7.45

Total

7.45

Cash Change

0.00

Tendered Amount

7.45

Excess Refundable Amount

0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

21-Aug-18, 12:11 PM

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1196N
Vehicle Details	
Vehicle No.:	GBE3199R
Vehicle to be Exported:	No
Intended De-registration Date:	27 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	1KD2561451
Chassis No.:	JTFHT02P300179985
Maximum Power Output:	-
Open Market Value:	\$27,741.00
Original Registration Date:	30 Oct 2015
First Registration Date:	30 Oct 2015
Transfer Count:	1
Actual ARF Paid:	\$1,388.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$42,743.00
COE Rebate Amount:	\$30,655.00
Total Rebate Amount:	\$30,655.00

The information contained herein is correct as at 27 Aug 2018

OK

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay 3C Kaki Bukit Singapore 417985

ROB No: 532977931 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liubro@ymail.com

Invoice/Ref No: GBE3199R180807

Estimate

Customer

Name: ERGO Insurance Pte Ltd

Address: Motor Claims Department

5 Temasek Boulevard #04-01

Suntec Tower Five

Singapore 038985

Date:

24-08-18

Vehicle No:

GBE3199R

Model/Make:

Toyota Hiace Van

Turbo 5 DR Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front LHSide Mirror <i>SAD \$45.10</i>	\$ 1,127.30	
2	Head Lamp <i>CM 901.10</i>	\$ 930.70	
3	Head Lamp Clips 1 set	\$ 65.00	SN X
4	Door "ROC" Sticker <i>CM</i>	\$ 48.00	SN 305.N
5	"Corporate" Advertisement & Artwork <i>CM</i>	\$ 250.00	SN 180 S.N
	To check all wiring & electrical component for proper function	\$ 40.00	20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 300.00	280
	To putty & spray painting & including touch up paint on accident affected area	\$ 400.00	✓

Total Parts & Labour of estimate for damaged vehicle

\$ 3,161.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

*Not Authorized**Lian**P/LP \$2219.65**to be photo After up - 347.*

- Liu's Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18015540/Uvd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 03-09-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YK 6230J	Veh. Inspected	GBE 3199R	
Policy No.		Coverage (\$)	0.00	
Claim No.	YK6230/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	27/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTFHT02P300179985	Colour	WHITE	
Odometer	77597	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	CST TIRES	6 mm	
L/H Front Tyre	195 R15	CST TIRES	6 mm	
R/H Rear Tyre	195 R15	CST TIRES	6 mm	
L/H Rear Tyre	195 R15	CST TIRES	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/08/2018	Inspection Date	27/08/2018	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 3199R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT LH SIDE MIRROR	BROKEN	1,127.30	845.10
1	HEAD LAMP	CRACKED	930.70	901.10
	LESS 25% DISCOUNT		-	-436.55
			2,058.00	1,309.65
SPECIAL NETT ITEMS				
1	SET HEAD LAMP CLIPS (SN)	NOT NECESSARY	65.00	-
1	DOOR "ROC" STICKER (SN)	NECESSARY	48.00	30.00
1	"CORPORATE" ADVERTISEMENT & ARTWORK (SN)	NECESSARY	250.00	180.00
			363.00	210.00
LABOUR				
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		40.00	20.00
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS.		300.00	280.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA.		400.00	400.00
			740.00	700.00
GRAND TOTAL			3,161.00	2,219.65
RECOMMENDED COST OF REPAIRS				2,219.65

Report Ref No. CS/EGI18015540/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.