

SS. REC. BY:

REF:

CS/smo18015560 / Ng boi

Special Instruction:

Surveyor:

W92

ASSIGNMENT (Office)

From (Person):

mavin Ye

of

Smo

Date/Time:

20082018 421pm

Estimated Cost:

Bill to:

OD / TH / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

3KK 5952G

Insured:

SJL 7773A

at Workshop m/s

Chng Brothers

Tel:

974 5169.

of

Blk 2 Kaki Bukit Ave 2 #02-32

Policy No:

Claim No:

CMTD1803547 / GPL

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16-082018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Mr Chng

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

3KK 5952G - CS / msh15007727 / Uquok3

DOA: 11/052015

SJL 7773A - CCG / msh12006255 / Aschy

DOA: 29/032012

26/082018

Email estimate to William

16/9/18 @ 7:09pm revised to Anh Pau Loong by email.

Range &amp; Repair day

08/11/18 @ 5:17pm confirmed with Mr Chng is \$7350, 4 days.

Cred \$7595.17, 57%.

Surveyor: Naz REF: SMD

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKK 5952 G Yr Regn: 2 AUG/2013  
 Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make: TOYOTA ALHARD C.C. 2,362  
 Colour: WHITE A/C: Insured / Std / Nil /  
 Sp. Reading: 133, 852 T/Radio: Insured / Std / Nil /  
 Eng/No: \_\_\_\_\_  
 C/No: JTEGD21H408286869

Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In Order / Jammed / Leaked / Burnt or  
 Brake: In Order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 215/55 R17  
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5</u> mm
D.O.A. <u>16/8/18</u>	D.O.I. <u>29/8/18</u>

Survey held at ZERO GRAVITY  
 Des. of Damages: Frt / Rev / O/S / N/S / U/C / Rooftop or  
O/S FRONT.  
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Naz, RECEIVED 09 NOV 2018

Pls see my remarks

SMD L/S

- Give sim  
check marking  
again  
- If ok pls

26/9

Date/Time, File Pass to?

☐ : Pre  
☐ : Final report

Of Repair: 4

1) 08/11/18 Finalise  
 Date/Time, File Return to?

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: 250  
 Transportation:

2)

Add Fee: ☐ : Site Insp (\$ ) S + RS. \$  
☐ : Interview (\$ ) Photos  
☐ : Tech. Invs (\$ ) Others  
☐ : Weekend (\$ )

Report Format: 7P

Lump Sum / I.B.I. (\$) 2350

TOTAL

250



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS3/SMO18015560/Nz4b

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 27-08-2018



Code : SMO

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJL 7773A	Veh. Inspected	SKK 5952G
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1803547	Excess (\$)	0.00
Assign From	MELVIN YE	Assign Date	20/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	16/08/2018	Inspection Date	29/08/2018
Survey held at	CHNG BROTHER MOTOR SERVICE 2 KAKI BUKIT AVENUE 2 #02-32 KAKI BUKIT AUTOHUB SINGAPORE 417921.		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**Catherine Chong (LKK Auto)**

---

**From:** Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>  
**Sent:** Monday, 20 August, 2018 4:21 PM  
**To:** info@chngbrothers.com; assignments@lkkauto.com; 'Nivitha (LKK Auto)'  
**Cc:** Gnoh, Pau Loong; Teo, Grace; ct-admin@visionlawllc.com  
**Subject:** RE: CMTD1803547/GPL - PRI/ SJL7773A & SKK5952G ACC ON 16.08.18  
**Attachments:** 3331\_001.pdf

Our Ref : CMTD1803547

Your Ref : AM.jt.Ins.C136.107709.18(sj)

Dear Sir,

We acknowledged receipt of your claim documents.

Please be informed that Gnoh Pau Loong is the handler of this case.

We have appointed LKK AUTO – Marcus Chua to conduct the survey.

-----

Aside to LKK – Marcus Chua,

Please make arrangement to conduct the survey for SKK5952G.

Please submit with your report to my colleague, Mr Gnoh Pau Loong.

Thank you.

Best Regards

**Melvin Ye**

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG**

Download now @  or 

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** Teo, Grace

**Sent:** Friday, 17 August, 2018 4:11 PM

**To:** ct-admin@visionlawllc.com; info@chngbrothers.com

**Cc:** Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

**Subject:** CMTD1803547/GPL - PRI/ SJL7773A & SKK5952G ACC ON 16.08.18

Our Reference : CMTD1803547/GPL

Your Reference: AM.jt.Ins.C136. SKK5952G.18 (sj)

Date: 17<sup>th</sup> August 2018

**Without Prejudice**  
**EMAIL ONLY**

**Attention:**

**M/S VISION LAW LLC**

Dear Anjalli,

**ACCIDENT INVOLVING SJL7773A & SKK5952G ON 16.08.2018**

We refer to your Notice of Accident dated 17/08/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	<b>Motor Surveyor</b>	<b>Surveyor</b>	<b>Selection (Indicate as tick)</b>
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	

		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG

Download now @



or



<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** [ct-admin@visionlawllc.com](mailto:ct-admin@visionlawllc.com) [<mailto:ct-admin@visionlawllc.com>]

**Sent:** Friday, August 17, 2018 2:40 PM

**To:** Claims - Motor Survey; [info@chngbrothers.com](mailto:info@chngbrothers.com)

**Subject:** Scan Image

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 26 September 2018 2:09 PM  
**To:** Gnoh, Pau Loong; 'Ye, Yong Kang Melvin'  
**Cc:** assignments; SUR; 'Teo, Grace'  
**Subject:** RE: CMTD1803547/GPL - PRI/ SJL7773A & SKK5952G ACC ON 16.08.18  
**Attachments:** CSSMO18015560Nqb.pdf

Dear Mr Gnoh,

Enclosed herewith preliminary advice of SKK 5952G.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]  
**Sent:** Monday, 20 August, 2018 4:21 PM  
**To:** [info@chngbrothers.com](mailto:info@chngbrothers.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com); 'Nivitha (LKK Auto)' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** Gnoh, Pau Loong <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>; Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; [ct-admin@visionlawllc.com](mailto:ct-admin@visionlawllc.com)  
**Subject:** RE: CMTD1803547/GPL - PRI/ SJL7773A & SKK5952G ACC ON 16.08.18

Our Ref : CMTD1803547

Your Ref : AM.jt.Ins.C136.107709.18(sj)

Dear Sir,

We acknowledged receipt of your claim documents.

Please be informed that Gnoh Pau Loong is the handler of this case.

We have appointed LKK AUTO – Marcus Chua to conduct the survey.

-----

Aside to LKK – Marcus Chua,

Please make arrangement to conduct the survey for SKK5952G.

Please submit with your report to my colleague, Mr Gnoh Pau Loong.

Thank you.

Best Regards

**Melvin Ye**

Claims Division



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1803547/GPL

Date: 26<sup>th</sup> September 2018

Our Ref: CS/SMO18015560/Nqb

Without Prejudice

The Motor Claims Department  
Sompo Insurance

Attn: Melvin

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. SKK 5952G .**


We thank you for the instruction on 20/08/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/08/2018 at the premises of M/s CHNG BROTHERS and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 4,945.17</u> .
Revised Estimate Amount	: <u>S\$ 2,727.45</u> .
"Check" Items Amount	: <u>S\$ 537.39</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:

The vehicle sustained damages at the n/s front portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 4 days.

We have not authorized repair.

Yours faithfully

Naz

Automobile Assessor



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/08/2018 09:46
Date Of Accident	16/08/2018 14:30
Exact Location Of Accident	TANJONG KATONG ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK5952G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIN DENG LI
NRIC No	S2002895E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-85686777
Alternative Phone No	OFFICE-85686777

### Vehicle Particulars

Manufacturer	TOYOTA
Model	ALPHARD-2.4 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	8-V0013519-MVA-R002
Cover Note Number	

### Driver

Name of Driver	CHNG CHEE HIN
NRIC No	S0233187Z
Date Of Birth	18/01/1948
Occupation	OUTDOOR
Date Of Driving Pass	25/07/1966
Driving Experience	52 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85288511
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 314 SERANGOON AVE 2 #03-200
Postcode	550314
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

MY CAR WAS PARK STATIONARY AT THE ROAD SIDE. VEHICLE B(SJL 7773 A) FAST THRU AND COLLIDED ONTO MY FRONT RIGHT DOOR.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Is there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL7773A
Vehicle Make/Model/Colour	
Details Of Properties	CAR B
Vehicle Category	PRIVATE CAR
Name of Driver	LIM BAN LEE (LI WAN LI)
NRIC/Passport Number	S8408138H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 2. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 16/08/18 6pm

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**SKETCH PLAN**



**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

My car was park stationary at the road side. Vehicle B (SJL 7773 A) fast thru and collided onto my front right door.

**DECLARATION**

I declare the foregoing particulars are true in every respect.

Policyholder's Signature  
& Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 16/08/18 6pm



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# CHNG BROTHERS MOTOR SERVICES

2 Kaki Bukit Avenue 2, #02-32 Kaki Bukit Autohub, Singapore 417921  
Tel: +65 67470407 Fax: +65 67426933  
E-mail: info@chngbrothers.com

## QUOTATION

SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE  
#05-01/06 SINGAPORE LAND TOWER  
SINGAPORE 048623  
Attn: Motor Claims Department  
Tel: +65 67470407 Fax: +65 67426933

Your Ref. : SJL7773A  
Vehicle No. : 8115952G 9KK5952h  
Make & model : TOYOTA ALPHARD  
Chassis No. : JTEGD21H408286869  
Engine No. : 2AZJ011568  
Accident Date : 16-08-2018  
Policy No. : 8-V0013519-MVA-R002  
Date : 23-08-2018  
Page : 1 of 1

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/Price S\$	Amount S\$
1	DOOR (R/H/F)	1.0 PCS	1,796.60	1,796.60
2	SIDE MIRROR (R/H)	1.0 PCS	1,126.51	1,126.51
3	DOOR INNER LOCK (R/H/F)	1.0 PCS	583.84	583.84
4	DOOR OUTER LOCK (R/H/F)	1.0 PCS	186.50	186.50
5	DOOR HANDLE (OUTER) (R/H/F)	1.0 PCS	309.31	309.31
6	DOOR HANDLE (OUTER) (BASE)	1.0 PCS	386.76	386.76
7	DOOR WEATHER STRIP (R/H/F)	1.0 PCS	154.18	154.18
8	DOOR STOPPER RUBBER	2.0 PCS	18.97	37.94
9	DOOR INNER TRIM BOARD CLIP	10.0 PCS	5.39	53.90
10	DOOR ANTI SPLASH PLASTIC SEAL	1.0 PCS	196.55	196.55
11	DOOR HINGE (R/H LOWER)	1.0 PCS	75.78	75.78
12	DOOR HINGE (R/H UPPER)	1.0 PCS	75.78	75.78
13	DOOR CHECKER (R/H/F)	1.0 PCS	174.17	174.17
14	DOOR CHANNEL BRACKET	1.0 PCS	102.40	102.40
15	Discount 25%			-1,315.05
16	SubTotal (L)			3,945.17
17	PANEL BEATING & REPLACING OF THE ABOVE	1.0 X		400.00
18	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0 X		400.00
19	TO REMOVE, TRANSFER & INSTALL RELATED COMPONENT	1.0 X		120.00
20	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0 X		80.00
21	SubTotal (LABOUR)			1,000.00

SINGAPORE DOLLAR FIVE THOUSAND TWO HUNDRED THIRTEEN AND CENTS SIXTY TWO ONLY

E. & O. E

Total S\$ 4,945.17  
Discount S\$  
Net Total S\$ 4,945.17

Customer's Signature/Co. Stamp

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.

### LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Particulars free of cost of such work, no claim for loss consequential or otherwise being admissible.
- Third party survey to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Terms: C.O.D

NAZ LKK

14/9/18

4 DAYS

15/10/18

BEFORE PAINT PHOTO




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18015560/Nqbe2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 19-11-2018		
		Code : SMO		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJL 7773A	Veh. Inspected	SKK 5952G	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1803547/GPL	Excess (\$)	0.00	
Assign From	MELVIN YE	Assign Date	20/08/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA ALPHARD	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JTEGD21H408286869	Colour	WHITE	
Odometer	133852	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	5 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	5 mm	
R/H Rear Tyre	215/55 R17	YOKOHAMA	5 mm	
L/H Rear Tyre	215/55 R17	YOKOHAMA	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	16/08/2018	Inspection Date	29/08/2018	
Survey held at	CHNG BROTHER MOTOR SERVICE 2 KAKI BUKIT AVENUE 2 #02-32 KAKI BUKIT AUTOHUB SINGAPORE 417921.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 5952G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	DOOR (R/H/F)	DENTED	1,796.60	1,796.60
1	SIDE MIRROR (R/H)	TO REPAIR SEE LABOUR	1,126.51	-
1	DOOR INNER LOCK (R/H/F)	BENT	583.84	583.84
1	DOOR OUTER LOCK (R/H/F)	DEFORMED	186.50	186.50
1	DOOR HANDLE (OUTER) (R/H/F)	BENT	309.31	309.31
1	DOOR HANDLE (OUTER) (BASE)	DEFORMED	386.76	386.76
1	DOOR WEATHER STRIP (R/H/F)	SERVICEABLE	154.18	-
2	DOOR STOPPER RUBBER @\$18.97	SERVICEABLE	37.94	-
10	DOOR INNER TRIM BOARD CLIP @\$5.39	SERVICEABLE	53.90	-
1	DOOR ANTI SPLASH PLASTIC SEAL	SERVICEABLE	196.55	-
1	DOOR HINGE (R/H LOWER)	SERVICEABLE	75.78	-
1	DOOR HINGE (R/H UPPER)	SERVICEABLE	75.78	-
1	DOOR CHECKER (R/H/F)	SERVICEABLE	174.17	-
1	DOOR CHANNEL BRACKET	SERVICEABLE	102.40	-
	LESS 25% DISCOUNT		-1,315.06	-815.75
			3,945.16	2,447.26
	<b><u>LABOUR</u></b>			
	PANEL BEATING & REPLACING OF THE ABOVE. INCLUSIVE OF THE REPAIR OF SIDE MIRROR (R/H).		400.00	200.00
	TO PUTTY AND RE-SPRAY AFFECTED PORTION.		400.00	200.00
	TO REMOVE, TRANSFER & INSTALL RELATED COMPONENT.		120.00	50.00
	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT.		80.00	30.00
			1,000.00	480.00
	<b>GRAND TOTAL</b>		<b>4,945.16</b>	<b>2,927.26</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,350.00</b>

Report Ref No. CS/SMO18015560/Nqbe2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.