

ASS. REC. BY

REF

CS3/CT118015561/12403<sup>52</sup>

Special Instruction

Surveyor

Munirah

Guo Qiang

ASSIGNMENT (Office)

From (Person)

Elaine Cheong

of

CT1

Date/Time

24/8/18 @ 4:34pm

Estimated Cost

Bill to

OD ☒ WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SFN 1812Y

Insured:

GBF 2828K

at Workshop m/s

Motor Intel

Tel:

62810087

of

13 Keki St Rd 4 #01-20

Policy No:

DMCVSN3051391802

Claim No:

8NM18D04106C02

Sum Insured

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19/08/2018

28/8/18 @ 11am - 11:30am

H.O.D. Endorsement

CA / REV / REP. / REV 24 HRS

cup?

Date/Time:

10:55am @ 27/8/18

Person Contacted:

Tinnie

Vehicle IN

☒ OUT

Date/Time	Action/Instruction (X) Estimate
	SFN 1812Y - N/A / LIP08C0911G/B
	GBF 2828K - X
28/8/18	Dismantled.

BOA: 17/3/08

PRG  
Summit

REF: CTL

6211B -

# ASSIGNMENT

From: Date: 28/08/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFN 1812Y  
at Workshop m/s: Motor Intel  
of: 13 Kaki Bukit Rd #01-20

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

11am - 11:30am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SFN 1812Y Yr Regn: 13 Oct 2004 (-2004)

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda MX5 1.6 c.c 1598

Colour: Grey A/C: Insured / Std / NI / NA

Sp Reading: 221846 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: IMZNB 186200 413028

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 / 55 R/15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 28-08-18

Survey held at

w/s

11:40AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
\$ 5000 - \$ 6000

29/8/18 submit PRS Report.

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ )

Add Fee: ☐ : Site Insp (\$ )

☐ : Interview (\$ )

☐ : Tech. Invs (\$ )

☐ : Weekend (\$ )



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18015582/Gz4d3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 27-08-2018



Code : AIG

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLX 3301T	Veh. Inspected	SLQ 8546H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	27/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	21/08/2018	Inspection Date	28/08/2018
Survey held at	LUSH AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-47 PREMIER @ KAKI BUKIT SINGAPORE 415875		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Aug 2018		24 Aug 2018 16:34 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	NGAI KHAI HING		
Vehicle Reg. No.:	SFN1812Y	Date of Loss:	19/08/2018 00:00 - :59
Claim Type:	TP / SNM18D04106C02	Policy/Cover Note No.:	DMCVSN3051391802
Vehicle Reg. No. (Insured):	GBF2828K	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/09/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Date of Accident : 19-Aug-2018 Accident Time: 0030hrs (24-HR-Format)  
Accident Place : Sam Leong Road (from Jalan Besar)  
Vehicle No. (Car Plate No.) : SFN 18127 Make/Model: mazda mx5  
Insurance Company : Tenet Comp Policy No: D18MTPV01066561  
Owner or Company Name / IC No. : Ngai Khai Hing 57106211B  
Owner or Company Contact No. : 9747 2727 Owner's Hp : - Company Tel : -  
DRIVER'S Name / IC No. : as above  
DRIVER'S Date Of Birth : 25-02-1971 DRIVER'S License Pass Date 20 Aug 1991  
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: Owner  
DRIVER'S Address : BUC 404B Fernvale Lane #09-143 S(792404)  
DRIVER'S Contact No / Alt No. : 1) 9747 2727 2) -  
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)  
Email Address : Sales@wia.com.sg  
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET  
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance  
Number of Passengers (including Driver): 01 - Driver  
Was there any video Captured by car camera? YES \ NO  
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose  
Any Injury (If YES, Pls state): NIL

**Other Party Driver's Particular (if any)**

Vehicle No: <u>GBF 2828 F</u>	Vehicle No: _____
Vehicle Make/Model: <u>toyota Hiace</u>	Vehicle Make/Model: _____
Name Driver: <u>Ajijul (G6582120L)</u>	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

\* NEW - Passenger's name & gender:



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN

Sam Leong Road (from Jalan Besar).



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Jalan Besar towards Mustafa center. After turning into Sam Leong Rd, a single lane one-way road, I was driving straight and in my lane when I suddenly felt a strong impact from the rear portion of my vehicle. After the accident, I alighted to see that vehicle B front left portion collided into the rear right portion of my vehicle when he was turning out from the car park lot. Hence I was involve in an accident of 2 vehicles.

Vehicle A STN 1812Y  
vehicle B. GBF 2828K

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Aug 2018		24 Aug 2018 16:34 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	NGAI KHAI HING		
Vehicle Reg. No.:	SFN1812Y	Date of Loss:	19/08/2018 00:00 - :59 [166 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04106C02	Policy/Cover Note No.:	DMCVSN3051391802
Vehicle Reg. No. (Insured):	GBF2828K	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 04/09/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





## Claim Documents

**\*SFN1812Y (SNM18D04106C02)**  
**[GBF2828K]**

**TP**

**NGAI KHAI HING**

**Aug 19 2018 12:00AM**

**[-]**




**Motor Intel Automo Pte Ltd - Kaki Bukit**

[Upload Documents](#)[Upload Photos](#)[Compose New Letter](#)**View**[View in Browser ▼](#)

### Documentation

1 per page ▼



No	Finalized On		Thumbnail	Print
1	24/08/18 16:33	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) <b>PRS</b>	 Load PDF	
No	Relabel/Reorder		Thumbnail	Print
1	29/08/18 19:20	LKK Auto Consultants Pte Ltd (HQ) <b>LKKPhotosIn6-1.pdf</b>	 Load PDF	
2	29/08/18 19:20	<b>LKKPhotosIn6-2.pdf</b>	 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118015561/GZ4D3S2

Date: 30/08/2018

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3051391802

Claimant Vehicle No: SFN1812Y Insured Vehicle No: GBF2828K

Date of Loss: 19/08/2018 Nature of Claim: TP Claim No: SNM18D04106C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SFN1812Y

Make & Model: MAZDA MX-5, 1.6 (M) Engine No: B6698539

Reg. Date: 13/10/2004 (Man. Year: 2004) Chassis No: JMZN186200413028

Colour: Grey Odometer: 221846 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/55R15 Rear Tyre Size: 195/55R15

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 24/08/2018

Date Inspected: 28/08/2018 Inspected At: Motor Intel Automo Pte Ltd - Kaki Bukit (HQ)  
13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre  
Singapore 417807

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 30 Aug 2018)	
<b>Parts:</b>	N/A	MAZDA MX-5 1.6 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFN1812Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >