

2003/2004

SS. REC. BY:

REP:

cs/MSG180/SS62/Tirdzel

Special Instruction:

Surveyor  
menimen

Taufik

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time:

27/8/10 @ 10:23am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJF 5864S

Insured:

SGJ 2597X

at Workshop m/s:

FDK Automobik

Tel:

9191 6590

of

39 Woodlands Close Mega #05-12

Policy No:

A28982118@MX

Claim No:

568018

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/8/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:40am 27/8/18

Person Contacted:

Fubian

Vehicle ☒ IN / ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SJF 5864S - X
	SGJ 2597X - CCG/ALG/6007628 / Klyb 39.2 DOA: 24/4/2016
	Report from menimen
	Confirm with Hazel \$489.00 @ 6 days (Red: \$6692.96, 62%).

Cityville

Tanji

REF:

MS16

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLF5864S Yr Regn: 2010 May  
 Type: 60 M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Volkswagen Polo C.C. 1390  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 185433 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WVW 222 6R244 04 2078  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 185/60 R15  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 27/8/18  
 Survey held at FDK Automobile  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7869R

. 37 WL close Maya #05-12

RECEIVED 12 OCT 2018

Date/Time. File Pass to?

1) typist

Date/Time. File Return to?

2)

Report Format: TP

Lump Sum / I.B.I: (\$) 4189.00

☐ : Preli. Report  
☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:

☐ Site Insp (\$)   
☐ Interview (\$)   
☐ Tech. Invs (\$)   
☐ Weekend (\$)

Survey Fee:

Transportation:

☐ S + PS. ☐ SI

☐ Photos

☐ Other

TOTAL

200

10

210

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Aug 2018		27 Aug 2018 10:23 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN AIK LEE ALAN, ID: S1221447B		
Main Claimant:	WONG CHOR CHAN, ID: F0337869K		
Vehicle Reg. No.:	SLF5864S	Date of Loss:	19/08/2018 13:00 - :59 [98 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 568018	Policy/Cover Note No.:	A28982118QMX (Comprehensive) Coverage: 05/07/2018 - 04/07/2019
Vehicle Reg. No. (Insured):	SGJ2597X	Policy No. (Claimant):	
		Excess:	
Repairer:	Fdk Automobile & Leasing Services Pte Ltd (HQ) 39 WOODLANDS CLOSE MEGA @ WOODLANDS, #05-12, 737856 Woodlands - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/08/2018]		
Driver/Custodian (Insured):	SANTHI D/O NAGAPAN (), NRIC: S7316379Z, Tel: +6591814515		
Adj Asg. Remarks:	Liability unclear. TP agree to use Kenneth Kong frm LKK. Contact Person: Mr Fabian 9191 6590 / Ms Hazel 8101 6895		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18015562/T1rd3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 27-08-2018



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGJ 2597X	Veh. Inspected	SLF 5864S
Policy No.	A28982118QMX	Coverage (\$)	0.00
Claim No.	568018	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	27/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	19/08/2018	Inspection Date	27/08/2018
Survey held at	FDK AUTOMOBILE- 39 WOODLANDS CLOSE MEGA #05-12		
Repairer	-		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIR

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 03 Sep 2018

## Preliminary Advice

Insured Vehicle No	: SGJ2597X	Accident Date	: 19/08/2018
TP Vehicle No	: SLF5864S	Assignment Date	: 27/08/2018
Make	: VOLKSWAGEN POLO	Est. Duration of Repair	: 6.00
Date of Inspection	: 27/08/2018		
Inspection At	: FDK AUTOMOBILE & LEASING SERVICES PTE LTD (HQ) 39 WOODLANDS CLOSE MEGA @ WOODLANDS, #05-12 SINGAPORE 737856		

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,005.00
Revised Amount	:S\$	4,650.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,650.00

Lump Sum Repair	:S\$
-----------------	------

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

## Remarks

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/08/2018 09:30
Date Of Accident	19/08/2018 13:10
Exact Location Of Accident	ALONG YISHUN ST.22
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF5864S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WONG CHOR CHAN
NRIC No	F0337869K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91916590
Alternative Phone No	OTHERS-91916590

### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	POLO 1.4 AT 6R 13E7
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MOMVP000001118-01-000
Cover Note Number	01/12/17 - 30/11/18

### Driver

Name of Driver	WONG JUN JIE, FABIAN(HUANG JUNJIE)
NRIC No	S8837882B
Date Of Birth	10/10/1988
Occupation	INDOOR
Date Of Driving Pass	07/01/2008
Driving Experience	10 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91916590
Fax Number	
Contact Number	
Email Address	ELITEWONG111@GMAIL.COM

Address	BLK 270 YISHUN ST.22 #10-48
Postcode	760270
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH. \* THIRD PARTY CLAIM BY FDK AUTOMOBILE & LEASING SERVICES PTE LTD \*

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGJ2597X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SANTHI D/O NAGAPAN
NRIC/Passport Number	
Contact Number	91814515
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan


### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information"); and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:




Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
20/8/18  
Reporting Centre Personnel's Signature  
Name: (YS)  
NRIC/FIN No.:

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Yishun Street 22 and iam driving in the right of way with the traffic flow. All of a sudden, A red vehicle SGJ2597X came out of the carpark from my right and hit into me.

The red car came towards my lane when my car was still traveling and there was also a car in front of me. I have always been traveling and ~~driving~~ with great care and conform to the road safety rules and regulations.

The red vehicle banged onto the back of my vehicle so hard that it drags from the back of my vehicle to the front of the driver side door.

Type: Third Party Claim (by FDK Automobile & Leasing Services Pte Ltd)

*[Signature]*

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*

Policyholder's Signature  
Date & Time:

*[Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]* 20/8/18

Reporting Centre Personnel's Signature  
Name: (YS)  
NRIC/FIN No.:

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S8837882B



Name

WONG JUN JIE, FABIAN  
(HUANG JUNJIE)

黄俊杰

Race

CHINESE

Date of birth

10-10-1988

Sex

M

Country of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S8837882B

Name

WONG JUN JIE, FABIAN  
(HUANG JUNJIE)

Birth Date 10 Oct 1988

Issue Date 07 Jan 2008



001558340D

3425348



NRIC No. S8837882B



Date of issue

03-11-2003

NRIC No: S8837882B

Date: 08/03/2011

No: 6747049

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 2B Motorcycle <= 200 CC  
Class 3 Motor cars <= 3500 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg

22 Oct 2009  
07 Jan 2008

S / No. 9000115008

S8837882B



Licence No: S8837882B

RP 428A

OWNER IC

REPUBLIC OF SINGAPORE  
FIN F0337869K



Name  
WONG CHOR CHAN

Date of Birth 10-05-1954 Sex M  
Nationality MALAYSIAN

F0337869K

KAD PENGENALAN  
MALAYSIA  
IDENTITY CARD  
640510-05-5075



WONG CHOR CHAN

NO 12  
JALAN KEBANGSAAN 6  
TAMAN UNIVERSITI  
81300 SKUDAI  
JOHOR

WARGANEGARA  
LELAK



# FDK AUTOMOBILE & LEASING SERVICES PTE LTD

UEN: 201611065K

39 WOODLANDS CLOSE MEGA @ WOODLANDS

#05-12 S (737856)

Fabian Wong: 9191 6590

Daryl Wong: 9772 9698

Kenneth Wong: 9755 3198

Date: 27 August 2018

51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
SINGAPORE 408933

ATTN: TAUFIQ/ MOTOR CLAIM DEPT  
TEL: 6256 3561  
FAX: 6256 4315

YOUR REF NO:  
CLAIM TYPE: THIRD PARTY CLAIM  
ACCIDENT DATE: 19/08/2018 13:10

NO	QUOTATION: 2018/0004
DATE	27/ 08/ 2018
POICY NO	MOMVP000001118-R01
VEHICLE REG NO	SLF5864S
MAKE/ MODEL	VOLKSWAGEN POLO 1.4 AT 6R 13E7
CHASSIS NO	WVWZZZ6RZAU042078
ENGINE NO	CGG333817
REG. DATE	31 MAY 2010

## Estimate Repair Cost to Vehicle NO.: SLF5864S

	Description	Quantity	Unit Price (\$)	Amount (\$)
<b>WORKSHOP 1 - REPAIR</b>				
1	Right Front Door (Driver's side)	1	1200.00	1200.00 Rx
2	Right Rear Door (Driver's side)	1	1400.00	1400.00 bt ✓
3	Rear Bumper	1	185.00	185.00 Rx
4	Panel Beating Rear Bumper	1	370.00	370.00 un
5	Panel Beating Side Skirt <i>Rear fender</i>	1	400.00	400.00 un
6	Fitting Labour <i>door</i>	1	120.00	120.00 60 L
7	Volkswagen Polo Original Rim	21	1100.00	1100.00 SN 300 cut ✓
8	Tyres 185/60/15	21	450.00	450.00 X nn
9	Labour	6 days	<del>160.00</del> \$200	640.00 <del>\$1200</del>

Labour \$800 ✓ L

1

\$2580

WORKSHOP 2 - SPRAY PAINTING					spray paint fender - \$200.	
10	Spray Paint Right Front Door (Driver's side)	1	700.00	700.00	250	
11	Spray Paint Right Rear Door (Driver's side)	1	700.00	700.00	250	
12	Spray Paint Rear Bumper	1	500.00	500.00	200	
13	Labour	3 days	160.00	480.00	Xm	
TOTAL:				\$8,245.00	10,881.96	

MAKE ALL CHEQUE PAYABLE TO FDK AUTOMOBILE & LEASING SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Authorized Signature

62563561/  
Taufik 97495749  
WP

27/8/18 @ 1745

6 days

Sur @ lkkauto.com

Resurvey before paint.

Parts ————— 2110

10% ————— 1899

Spray ————— 900

Labour ————— 1090

9N - 300

\$4189

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

**FDK AUTOMOBILE & LEASING SERVICES PTE LTD**

UEN: 201611065K

39 WOODLANDS CLOSE MEGA @ WOODLANDS

#05-12 S (737856)

Fahlan Wong: 9191 6590

Daryl Wong: 9772 9698

Kenneth Wong: 9755 3198

Date: 17 September 2018

51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
SINGAPORE 408933

ATTN: TAUFIQ MOTOR CLAIM DEPT  
TEL: 6256 3561  
FAX: 6256 4315

YOUR REF NO:  
CLAIM TYPE: THIRD PARTY CLAIM  
ACCIDENT DATE: 19/08/2018 13:10

NO	QUOTATION: 2018/0009
DATE	17/ 09/ 2018
POICY NO	MOMVP000001118-R01
VEHICLE REG NO	SLF5864S
MAKE/ MODEL	VOLKSWAGEN POLO 1.4 AT 6R 13E7
CHASSIS NO	WVWZZZ6RZAU042078
ENGINE NO	CGG333817
REG. DATE	31 MAY 2010

**Supplementary Estimate Repair Cost to Vehicle NO.: SLF5864S**

	Description	Quantity	Unit Price (S\$)	Amount (S\$)
	<b>WORKSHOP 1 - REPAIR</b>			
1	Rear Door Hinge Lower Left	1	70.00	70.00 <i>bt</i>
2	Weather Strip	1	189.30	189.30 <i>not</i>
3	Wiring Check	1	30.00	30.00 <i>L</i>
4	Window Glass Run Channel	1	90.00	90.00 <i>X m</i>
5	Right Door Inner Trim Clips	1 set	30.00	30.00 <i>not</i>
6	Right Rear Bearing	1	420.70	420.70 <i>bt</i>
7	Right Rear Wheel Hub	1	105.20	105.20 <i>X m</i>
8	Right Rear Absorber	1	390.40	390.40 <i>X m</i>
9	Right Rear Absorber Mounting	1	68.00	68.00 <i>X m</i>

R000277  
4.9.18 12:34  
SLF5864S

HAO



SLF5864S  
Odometer:185594

AL TYRES PTE LTD  
39 WOODLANDS CLOSE  
#01-01/02/03 MEGA@WOODLANDS  
SINGAPORE 737856  
TEL : 65-84186000

Volkswagen : Polo : 2010-15 (6R) : Standard Suspension (G09 G10 G31 G32 G51) (Modified Specification)  
Thrust Line Alignment

Front : Left

Actual	Before	Specified Range
1°01'		-0°58' 0°02'
		4°24' 5°24'
-0°15'		0°00' 0°10'
		-1°39' -0°59'

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-2°23'		-0°58' 0°02'
		4°24' 5°24'
-0°01'		0°00' 0°10'
		-1°39' -0°59'

Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

Actual	Before	Specified Range
3°24'		-0°30' 0°30'
		-0°30' 0°30'
-0°17'		0°00' 0°20'

Rear : Left

Actual	Before	Specified Range
-0°57'		-1°40' -1°20'
-0°06'		-0°09' 0°30'

Camber  
Toe

Rear : Right

Actual	Before	Specified Range
-2°12'		-1°40' -1°20'
0°14'		-0°09' 0°30'

Rear

Cross Camber  
Total Toe  
Thrust Angle

Actual	Before	Specified Range
1°15'		-0°30' 0°30'
0°08'		0°11' 0°31'
-0°10'		-0°20' 0°20'

**FDK AUTOMOBILE & LEASING SERVICES PTE LTD**

UEN: 201611065K

39 WOODLANDS CLOSE MEGA @ WOODLANDS

#05-12 S (737856)

Fabian Wong: 9191 6590

Daryl Wong: 9772 9698

Kenneth Wong: 9755 3198

Date: 27 August 2018

51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
SINGAPORE 408933

ATTN: TAUFIQ/ MOTOR CLAIM DEPT  
TEL: 6256 3561  
FAX: 6256 4315

YOUR REF NO:  
CLAIM TYPE: THIRD PARTY CLAIM  
ACCIDENT DATE: 19/08/2018 13:10

NO	QUOTATION: 2018/0004
DATE	27/ 08/ 2018
POICY NO	MOMVP000001118-R01
VEHICLE REG NO	SLF5864S
MAKE/ MODEL	VOLKSWAGEN POLO 1.4 AT 6R 13E7
CHASSIS NO	WVWZZZ6RZAU042078
ENGINE NO	CGG333817
REG. DATE	31 MAY 2010

**Estimate Repair Cost to Vehicle NO.: SLF5864S**

	Description	Quantity	Unit Price (S\$)	Amount (S\$)
<b>WORKSHOP 1 - REPAIR</b>				
1	Right Front Door (Driver's side)	1	1200.00	1200.00 Rx
2	Right Rear Door (Driver's side)	1	1400.00	1400.00 bt ✓
3	Rear Bumper	1	185.00	185.00 Rx
4	Panel Beating Rear Bumper	1	370.00	370.00 nh
5	Panel Beating Side Skirt <i>Rear fender</i>	1	400.00	400.00 nh ✓
6	Fitting Labour <i>door</i>	1	120.00	120.00 80
7	Volkswagen Polo Original Rim	21	1100.00	1100.00 Rx
8	Tyres 185/60/15	21	450.00	300 450.00 out ✓ 80%.
9	Labour	6 1/2 days	<del>160.00</del> \$250	640.00 \$1200

Labour \$800

1

\$2580

WORKSHOP 2 - SPRAY PAINTING				
spray paint fender - \$200				
10	Spray Paint Right Front Door (Driver's side)	1	700.00	700.00 250
11	Spray Paint Right Rear Door (Driver's side)	1	700.00	700.00 250
12	Spray Paint Rear Bumper	1	500.00	500.00 200
13	Labour	3 days	160.00	480.00
TOTAL:				\$8,245.00

MAKE ALL CHEQUE PAYABLE TO FDK AUTOMOBILE & LEASING SERVICES PTE LTD

Spray: \$900

9005

Authorized Signature

62563561/  
Taufik 97495749  
WP

27/8/18 @ 1745

6 days

suu@lkkauto.com

Resurvey before paint

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices on "without prejudice" basis
- No ill-effects
- Supply of parts to be surveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Janice Lee (LKKAUTO)

---

**From:** Hazellea Bong <hazelleabong@gmail.com>  
**Sent:** Friday, October 12, 2018 1:27 PM  
**To:** Janice Lee (LKKAUTO)  
**Subject:** Re: SLF 5864S

Dear Janice,

Noted with thanks. Please proceed with confirmation of \$4,189.00 @ 6 days.

Warmest Regards,  
Hazel Bong

On Thu, Oct 11, 2018 at 9:57 AM Janice Lee (LKKAUTO) <[JaniceLee@lkkauto.com](mailto:JaniceLee@lkkauto.com)> wrote:

Dear Hazel,

Parts less 10% for vehicle model Volkswagen is market practice (pls refer to SAAA guidelines).

\*For any query, please drop me call

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hazellea Bong [<mailto:hazelleabong@gmail.com>]  
**Sent:** Wednesday, October 10, 2018 6:53 PM

**To:** Janice Lee (LKKAuto) <[JaniceLee@lkkauto.com](mailto:JaniceLee@lkkauto.com)>  
**Subject:** Re: SLF 5864S

Hi janice,

My apologise, I meant 10% in my earlier email. Please advise.

On 10 Oct 2018, at 4:43 PM, Janice Lee (LKKAuto) <[JaniceLee@lkkauto.com](mailto:JaniceLee@lkkauto.com)> wrote:

Dear Hazel,

Kindly confirm \$4,189.00 @ 6 days

\*For any enquiry, you may reach me at 6256 3561

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<SLF 5864S EST.pdf>

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Aug 2018		27 Aug 2018 10:23 <a href="#">Edit Adj Rpt</a>	<b>S\$4,189.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,189.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	TAN AIK LEE ALAN, ID: S1221447B	
Main Claimant:	WONG CHOR CHAN, ID: F0337869K	
Vehicle Reg. No.:	SLF5864S	Date of Loss: 19/08/2018 13:00 - :59 [98 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 568018	Policy/Cover Note No.: A28982118QMX (Comprehensive) Coverage: 05/07/2018 - 04/07/2019
Vehicle Reg. No. (Insured):	SGJ2597X	Policy No. (Claimant):
		Excess:
Repairer:	Fdk Automobile & Leasing Services Pte Ltd (HQ) 39 WOODLANDS CLOSE MEGA @ WOODLANDS, #05-12, 737856 Woodlands - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/09/2018]	
Driver/Custodian (Insured):	SANTHI D/O NAGAPAN (), NRIC: S7316379Z, Tel: +6591814515	
Adj Asg. Remarks:	Liability unclear. TP agree to use Kenneth Kong frm LKK. Contact Person: Mr Fabian 9191 6590 / Ms Hazel 8101 6895	

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

\*SLF5864S (568018)  
[SGJ2597X]  
TP  
WONG CHOR CHAN  
Aug 19 2018 1:00PM  
[TAN AIK LEE ALAN]  
Fdk Automobile & Leasing Services Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports
















































1 per page




No	Finalized On		Thumbnail	Print
1	23/08/18 12:01	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> <b>Accident Statement</b> From: SC - Reg. No: SGJ2597X, Claimant: TAN AIK LEE ALAN	Load HTM	
No	Finalized On	<b>LKK Auto Consultants Pte Ltd (HQ)</b>	Thumbnail	Print
1	03/09/18 15:09	<b>Adjuster Immediate Advice</b>	Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder		Thumbnail	Print
1	12/10/18 13:58	<b>LKK Auto Consultants Pte Ltd (HQ)</b> <b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
25	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
26	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
27	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
28	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
29	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
30	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
31	12/10/18 13:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
32	12/10/18 13:58	<b>General View</b>	Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	12/10/18 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
34	12/10/18 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	12/10/18 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	12/10/18 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	12/10/18 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	12/10/18 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	12/10/18 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	12/10/18 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	12/10/18 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	12/10/18 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	12/10/18 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	12/10/18 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	12/10/18 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	12/10/18 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	12/10/18 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	12/10/18 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	12/10/18 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	12/10/18 14:13	Reinspection Photo 2	 Load JPG	<input checked="" type="checkbox"/>
77	12/10/18 14:13	Reinspection Photo 2	 Load JPG	<input checked="" type="checkbox"/>
78	12/10/18 14:13	Reinspection Photo 2	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/08/18 12:01	SLF5864S GIA Rpt	Load PDF	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
		MSIG Insurance (Singapore) Pte. Ltd. (HQ)			
		From: SC - Reg. No: SGJ2597X, Claimant: TAN AIK LEE ALAN			
2	23/08/18 12:01	Email frm TP - PRI			Load PDF
No	Relabel/Reorder			Thumbnail	Print
1	18/10/18 15:47	LKK Auto Consultants Pte Ltd (HQ)			Load PDF
		Supplementary			

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18015562/T1RD3E2

Date: 18/10/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28982118QMX

Claimant Vehicle No : SLF5864S

Insured Vehicle No : SGJ2597X

Date of Loss: 19/08/2018

Nature of Claim: TP

Claim No: 568018

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLF5864S

Make &amp; Model: VOLKSWAGEN POLO, 1.4 (A)

Engine No: CGG333817

Reg. Date: 31/05/2010 (Man. Year: 2010)

Chassis No: WWZZZ6RZAU042078

Colour: Black

Odometer: 185433 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,098.60	2,199.00	3,899.60	63.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,343.36	1,990.00	3,353.36	62.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>11,441.96</b>	<b>4,189.00</b>	<b>7,252.96</b>	<b>63.39</b>

## INSPECTION

Date of Assignment: 27/08/2018

Date Inspected: 27/08/2018 Inspected At:

Fdk Automobile & Leasing Services Pte Ltd (HQ)  
39 WOODLANDS CLOSE MEGA @  
WOODLANDS, #05-12  
Singapore 737856

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

<https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen...> 18/10/2018



REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2018)
Parts:	144	VOLKSWAGEN POLO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF5864S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT FRONT DOOR (DRIVERS SIDE)	Repair	1,200.00 F	*- FL
2	1		*RIGHT REAR DOOR (DRIVERS SIDE)	Bent	1,400.00 F	*1,400.00 FL
3	1		*REAR BUMPER	Repair	185.00 F	*- FL
4	1		*VOLKSWAGEN POLO ORIGINAL RIM (2PCS)	Cut-1pc only	1,100.00 FS	*300.00 FS
5	2		*TYRES 185/60/15	Not Necessary	450.00 F	*- FL
6	1		*REAR DOOR HINGE LOWER LEFT	Bent	70.00 F	*70.00 FL
7	1		*WEATHER STRIP	Necessary	189.30 F	*189.30 FL
8	1		*WINDOW GLASS RUN CHANNEL	Not Necessary	90.00 F	*- FL
9	1		*SET RIGHT DOOR INNER TRIM CLIPS	Necessary	30.00 F	*30.00 FL
10	1		*RIGHT REAR BEARING	Bent	420.70 F	*420.70 FL
11	1		*RIGHT REAR WHEEL HUB	Not Necessary	105.20 F	*- FL
12	1		*RIGHT REAR ABSORBER	Not Necessary	390.40 F	*- FL
13	1		*RIGHT REAR ABSORBER MOUNTING	Not Necessary	68.00 F	*- FL
14	1		*RIGHT REAR BRAKE PUMP WITH CALIBER	Not Necessary	300.00 F	*- FL
15	2		*BRAKE FLUID	Not Necessary	100.00 F	*- FL
					Sub Total (S\$)	6,098.60 2,410.00
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 211.00
					Total Parts (S\$)	6,098.60 2,199.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING REAR BUMPER	New	370.00	0.00
2	PANEL BEATING SIDE SKIRT	New	400.00	0.00
3	FITTING LABOUR	New	120.00	60.00
4	LABOUR	New	1,200.00	800.00
5	LABOUR	New	480.00	0.00
6	WIRING CHECK	New	30.00	30.00
7	ALIGNMENT REPORT }	New	110.00	80.00
8	WHEEL ALIGNMENT }	New	80.00	0.00
9	REFILL & REPLACE UNDERCARRIAGE ITEMS	New	120.00	120.00
10	SPRAY	New	1,900.00	900.00
11	LABOUR	New	533.36	0.00
Gross Labour Cost (S\$)			5,343.36	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >