

ASS. REC. BY:

REF: CS/CT118015565 / Urdzel

Special Instruction:

Surveyor
Mehmen

Marcus

ASSIGNMENT (Office)

From (Person):

Irene Fey

of

CTI

Date/Time:

21/8/18 @ 5:33pm

Estimated Cost:

Bill to:

OT / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SD218P

Insured:

SKL 3746T

at Workshop m/s

Trans Eurokars

Tel:

63457874

of

5 ubi close

Policy No:

DMPCSNI405801804

Claim No:

SNM18D04112C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/08/2018

CA / REV / REP. / REV 24 HRS

(up)

21/8/18 @ 4:30pm ow

H.O.D. Endorsement:

Date/Time:

11:22am @ 27/8/18

Person Contacted:

Jess

Vehicle IN (OUT)

Date/Time

Action/Instruction (-> Estimate

SD218P-X

SKL 3746T-X

REF: **CTL**

ASSIGNMENT

From: _____ Date: **29.08.2018**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SDL 1SP**
at Workshop m/s: **TRAB Eunkars**
of: **5 ubi nose**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

4:30pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GVA / PR Seen: **u** Consistent?: Yes or No

Est. Repairs: **3** days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SDL 1SP** Yr Regn: **5-16**

Type: **M. Car** / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or **(C)**

Make: **mazda cx-5** c.c. **1998**

Colour: **black** A/C: Insured / Std / NI / NA

Sp Reading: **43102** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JM6KE107260351819**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: **225/65-R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. **7** mm R/Bal. **7** mm

L/Bal. **7** mm L/Bal. **7** mm

D.O.A. **7/8/18** D.O.I. **29/8/18**

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S. Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27.8.18

1 st. of 18 vehicle hasn't sent in for repair

19/12/18 Submit preli report. - \$ 3207.32

RECEIVED 19 DEC 2018

Date/Time: File Pass to? : Preli. Report

: Final Report

Days Of Repair: **3**

Resurvey No. of Trip: **-**

Survey Fee: **970**

Date/Time: File Return to?

19/12 - typist

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Transportation: _____

) \$ + PS. SI

) Photos

) Others

TOTAL

970

Report Format: **merimen**

Lump Sum / I.B.I: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18015565/Uvd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 27-08-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKL 3746T	Veh. Inspected	SDL 18P
Policy No.	DMPCSN1405801804	Coverage (\$)	0.00
Claim No.	SNM18D04112C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	27/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/08/2018	Inspection Date	29/08/2018
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Aug 2018		24 Aug 2018 17:33 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)
CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	FONG FATT WENG		
Vehicle Reg. No.:	SDL18P	Date of Loss:	07/08/2018 00:00 - :59
Claim Type:	TP / SNM18D04112C02	Policy/Cover Note No.:	DMPCSN1405801804
Vehicle Reg. No. (Insured):	SKL3746T	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	Trans Eurokars Pte Ltd (HQ) 5 Ubi Close, 408605 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/09/2018]		
Adj Asg. Remarks:	EST \$7328.03, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED
[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0362C
Vehicle Details	
Vehicle No.:	SDL18P
Vehicle to be Exported:	No
Intended De-registration Date:	30 Aug 2018
Vehicle Make:	MAZDA
Vehicle Model:	CX-5 5-DOOR WAGON 2.0L SP.6EAT
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	PE10295319
Chassis No.:	JM6KE1072G0351819
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$23,891.00
Original Registration Date:	31 May 2016
First Registration Date:	31 May 2016
Transfer Count:	0
Actual ARF Paid:	\$25,448.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2026
PARF Rebate Amount:	\$19,086.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$49,700.00
COE Rebate Amount:	\$38,095.00
Total Rebate Amount:	\$57,181.00

The information contained herein is correct as at 30 Aug 2018


OK

10 Sin Ming Drive Singapore 575701
www.lta.gov.sg

12 Jul 2018

Our ref 1207180203N057019247

FONG FATT WENG
23 CORONATION DRIVE
SINGAPORE 269577



Dear Sir/Madam

NOTIFICATION ON SUCCESSFUL REPLACEMENT OF VEHICLE REGISTRATION NO. SMC6129D WITH VEHICLE REGISTRATION NO. SDL18P

You may be pleased to know that your application of 12 Jul 2018 for replacement of registration number is approved.

2. The details of the vehicle after the transaction are as follows:

Vehicle Registration No. : SDL18P (Previously SMC6129D)
Vehicle Make : MAZDA
Vehicle Model : CX-5 5-DOOR WAGON 2.0L SP.6EAT
Chassis No. : JM6KE1072G0351819
Engine No./ Motor No. : PE10295319 / -

3. Please change the number plates on your existing vehicle (ie. Chassis No. : JM6KE1072G0351819, Engine No./ Motor No. : PE10295319 / -) to display the new/ replacement registration number, SDL18P by 15 Jul 2018. It is an offence to keep or use a vehicle without displaying the correct vehicle registration number assigned. The penalty for first offence is a fine not more than \$1,000 or imprisonment of not more than 3 months. For second or subsequent offence, the fine is not more than \$2,000 or imprisonment of not more than 6 months.

4. Please contact our customer service officers on tel: 1800-CALL LTA (1800-2255 582) if you have any questions. You can either quote the Business Transaction Reference No. 20180712135404284947 or the vehicle registration number when making your enquiry.



CERTIFICATE OF INSURANCE

MAZDA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Fong Fatt Weng (Kuang Farong)
Period of Insurance : 31 May 2018 To 30 May 2019
Engine No. : PE10295319
Chassis No. : JM6KE1072G0351819

Vehicle No. : SBL2323T
Policy No. : 2100473106-02
Endorsement No. :
Issued Date : 28 May 2018

ABOUT THE COVER

Make/Model : MAZDA CX5 2.0 SKYACTIV
Engine Capacity/Tonnage : 1,998.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 - b) Any other person who is driving on the Policyholder's order or with his/her permission.
- This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Fong Fatt Weng (Kuang Farong) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Trans Eurokars Pte Ltd Add: 5 Ubi Close, Singapore 408605 63958899

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0503599190

ARF (AP) PTE LTD - MAZDA
 7 MAXWELL ROAD #01-100 ANNEX B MND COMPLEX
 SINGAPORE 069111

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSPLLC

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7220362C



Name
**FONG FATT WENG
(KUANG FARONG)**
序发荣
Race
CHINESE
Date of Birth Sex
30-03-1972 M
Country of Birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S7220362C**

Name

**FONG FATT WENG
(KUANG FARONG)**

Birth Date: **30 Mar 1972**

Issue Date: **11 Feb 2016**



002535240F

2854962



NRIC No. **S7220362C**



Blood Group Date of issue
A+ 18-07-1996

**23 CORONATION DRIVE
SINGAPORE 269577**

NRIC No: **S7220362C**

Date: **16/12/2008**

No: **6093810**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles with unladen weight \leq 2500kg 28 Aug 1996



Licence No: S7220362C

NP 426A



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
 6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-121214
 Date of Request: 07/08/2018

Your Ref No: Online Purchase

Trans Eurokars Pte Ltd
 12 Sungei Kadut Ave
 Singapore 729648

Dear Sir/Madam,

Enquiry Date 07/08/2018
 Enquiry By Catherine Chua Siew Quek
 TP Vehicle No. SKL3746T
 Accident Date 07/08/2018

Enquiry Result SDL 18P

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKL3746T	China Taiping Insurance (Singapore) Pte. Ltd.	24/06/2018-23/06/2019	6389 6111

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/08/2018 14:42
Date Of Accident	07/08/2018 09:05
Exact Location Of Accident	NEWTON ROAD @JUNCTION WITH THOMSON & MOULMEIN RDS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDL18P
Insured/Policyholder	
Name Of Registered Owner	FONG FATT WENG
NRIC No	S7220362C
Email Address	WENGFONG24@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94550572
Alternative Phone No	OTHERS-94550572
Vehicle Particulars	
Manufacturer	MAZDA
Model	MAZDA CX5 2.0L
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100473106
Cover Note Number	
Driver	
Name of Driver	FONG FATT WENG
NRIC No	S7220362C
Date Of Birth	30/03/1972
Occupation	INDOOR
Date Of Driving Pass	28/08/1996
Driving Experience	21 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94550572
Fax Number	
Contact Number	OTHERS-94550572
EMail Address	WENGFONG24@GMAIL.COM

Address 23 CORONATION DRIVE
 Postcode 269577
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : TAN YEOW KOON
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name KAMPONG JAVA NEIGHBOURHOOD POLICE CENTRE
 Police Station Address **ROAD:** 21 KAMPONG JAVA ROAD , **POSTCODE:** 228892 , **COUNTRY:** SINGAPORE
 Police Station Contact **TEL NO:** 1800-2959999 - **FAX NO:** 63918499
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN AND POLICE REPORT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKL3746T
 Vehicle Make/Model/Colour WHITE
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode

Insurance Company Name

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 7/8/18 2:10pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Catherine Chua
NRIC/FIN No.: S1449251H

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report Attached.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


7/8/18

Policyholder's Signature
Date & Time: 2.10 PM

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Catherine Chua
NRIC/FIN No.: S14492511



Police Station Of Origin:
Kampong Java N.P.C
21 Kampong Java Road SINGAPORE
228892
Tel No: 1800-2959999

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SDL18P	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2100473106-02	31/05/2018	30/05/2019

Brief Details.

On the 7/8/2018 at about 0905hrs, I was driving my vehicle (SDL18P) along Newton Road towards Moulmein Road at the third lane on the left. When I was driving towards the junction between Newton, Thomson Road and Moulmein Road, a white vehicle (SKL3746T) from the 2nd middle lane drove past my lane knocked the rear of my vehicle. I stopped my vehicle and horned at the white vehicle as he slowed down while trying to enter into the filter lane on my left, as I was getting out of my vehicle the white car drove off towards Thomson road.

I managed to take some pictures of the white vehicle that hit my vehicle's rear before he drove out of my sight. I am lodging this report for police assistance.



SINGAPORE
POLICE FORCE



T/20180807/2017

Police Station Of Origin:
Kampong Java N.P.C
21 Kampong Java Road SINGAPORE
228892
Tel No: 1800-2959999

3 of 3

Report No. T/20180807/2017

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: E / Staff Sgt LEE CHONG TAT, TIMOTHY 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 07/08/2018 09:50
Officer In Charge Of Case: TP / HRT / SSI GOH GEOK LYE Contact No.: 65476148	Classification Of Case: <div data-bbox="540 1858 1081 2035" style="border: 1px solid black; padding: 5px; display: inline-block;">  SINGAPORE POLICE FORCE SN 167 </div>
Authentication Stamp NP168 	



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



to Jimmy
APPROVAL

Aug 21, 2018 @ 4:30PM
KKK PHOTO.

DOA: 07-8-2018
SKL 37467

(LK)

CHINA TAIPING INSURANCE P/L		NAME : Mr Fong Fatt Weng	WIP : 18425
3 ANSON ROAD		ADDRESS : 23 Coronation Drive	EXCESS :
#16-00 SPRINGLEAF TOWER		Singapore 269577	DATE : 7-Aug-18
SINGAPORE 079909		TEL : 94550572	<i>3 dy. not authorized a letter received 29/8/18 take photo before party.</i>
ATTN. :	MOTOR CLAIMS		
FAX :			
VEH NO :	SDL18P	DATE IN :	CONTACT PERSON : Jess 63957874
CHASSIS NO :	JM6KE1072G0351819	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	CX5	DATE REG.: 31-May-16	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	REAR BUMPER	1	MKDY7-50-22XDBB \$ 1,218.00
2	RETAINER RHS	1	MKD53-50-2H1A \$ 32.40
3	REFLECTOR RHS	1	MKD31-51-5L0 \$ 101.20
4	CLIP, REAR BUMPER	2	MC274-50-133 \$ 7.00
5	RIVET, REAR BUMPER	4	ML33X-13-209 \$ 11.20
6	GROMMET, REAR BUMPER	6	MBHN1-50-0Z1A \$ 15.00
7	FASTENER, REAR BUMPER	2	MB45A-56-146A \$ 5.60
8	GARNISH RHS, REAR FENDER	1	MKD53-51-W50C \$ 209.60
9	BRACKET RHS, GARNISH	1	MKD53-51-U30 \$ 10.70
10	RIVET, BRACKET	2	ML33X-13-209 \$ 5.60
11	GASKET LHS, TAILLAMP	1	MKD54-51-163A \$ 35.20
12	GASKET RHS, TAILLAMP	1	MKD54-51-153A \$ 35.20
TOTAL PARTS			\$ 1,686.70
LESS 10%			\$ 168.67
TOTAL PARTS COST			\$ 1,518.03

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660 \$ 1,980.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	630 \$ 1,890.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	200 \$ 990.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	11X \$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120 \$ 250.00

6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	net 30	\$ 100.00
TOTAL LABOUR				\$ - \$ 5,810.00
TOTAL PARTS				\$ - \$ 1,518.03
TOTAL				\$ - \$ 7,328.03
LESS EXCESS				\$ - \$ -
TOTAL AFTER EXCESS				\$ -
GST 7%				\$ - \$ -
GRAND TOTAL				\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

 Authorised Signature

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplemental item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Aug 2018		24 Aug 2018 17:33 Edit Adj Rpt	S\$3,207.32 Edit Estimates	S\$3,207.32 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	-, Co. Reg. No.: -		
Main Claimant:	FONG FATT WENG		
Vehicle Reg. No.:	SDL18P	Date of Loss:	07/08/2018 00:00 - :59 [26 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04112C02	Policy/Cover Note No.:	DMPCSN1405801804
Vehicle Reg. No. (Insured):	SKL3746T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Trans Eurokars Pte Ltd (HQ) 5 Ubi Close, 408605 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 04/09/2018]		
Adj Asg. Remarks:	EST \$7328.03, CASE WITH SJE.		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

***SDL18P (SNM18D04112C02)**
[SKL3746T]
TP
FONG FATT WENG
Aug 7 2018 12:00AM
[-]
Trans Eurokars Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser		
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print	
1	19/12/18 10:13	General View				Load PDF		
Documentation							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail	Print	
1	24/08/18 17:32	EMAIL FM TRNAS				Load PDF		
2	24/08/18 17:32	REPAIR EST WITH TP GIA				Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18015565/UVD3E2

Date: 20/12/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN1405801804	
Claimant Vehicle No: SDL18P	Insured Vehicle No: SKL3746T	
Date of Loss: 07/08/2018	Nature of Claim: TP	Claim No: SNM18D04112C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDL18P	Engine No: PE10295319
Make & Model: MAZDA CX-5, 2.0 (A)	Chassis No: JM6KE1072G0351819
Reg. Date: 31/05/2016 (Man. Year: 2015)	Odometer: 43102 km
Colour: Black	
Engine Capacity: 1998 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 225/65 R17	Rear Tyre Size: 225/65 R17
Front Left Side: Yokohama 7 mm	Rear Left Side: Yokohama 7 mm
Front Right Side: Yokohama 7 mm	Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,618.03	1,447.32	170.71	10.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,710.00	1,760.00	3,950.00	69.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,328.03	3,207.32	4,120.71	56.23
+ GST 7.00/7.00% (S\$)	512.96	224.51	288.45	56.23
Nett Amount (S\$)	7,840.99	3,431.83	4,409.16	56.23

INSPECTION

Date of Assignment: 24/08/2018		
Date Inspected: 29/08/2018	Inspected At:	Trans Eurokars Pte Ltd (HQ) 5 Ubi Close Singapore 408605
Estimated Period of Repair: 3.0 days		

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2018)
Parts: M1-SUV	MAZDA CX-5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDL18P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,218.00 FL	*1,218.00 FL
2	1		*RETAINER RHS	Bent	32.40 FL	*32.40 FL
3	1		*REFLECTOR RHS	Not Necessary	101.20 FL	*- FL
4	2		*CLIP, REAR BUMPER	Necessary	7.00 FL	*7.00 FL
5	4		*RIVET, REAR BUMPER	Necessary	11.20 FL	*11.20 FL
6	6		*GROMMET, REAR BUMPER	Necessary	15.00 FL	*15.00 FL
7	2		*FASTENER, REAR BUMPER	Necessary	5.60 FL	*5.60 FL
8	1		*GARNISH RHS, REAR FENDER	Grazed	209.60 FL	*209.60 FL
9	1		*BRACKET RHS, GARNISH	Not Necessary	10.70 FL	*- FL
10	2		*RIVET, BRACKET	Necessary	5.60 FL	*5.60 FL
11	1		*GASKET LHS, TAILLAMP	Necessary	35.20 FL	*35.20 FL
12	1		*GASKET RHS, TAILLAMP	Necessary	35.20 FL	*35.20 FL
13	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
Sub Total (S\$)					1,786.70	1,604.80
- List Item Discount on L Items 10.00/10.00% (S\$)					168.67	157.48
Total Parts (S\$)					1,618.03	1,447.32

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,980.00	660.00
2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT	New	1,890.00	630.00
3	TO TRANSFER REVERSE SENSORS	New	990.00	200.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	0.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	150.00
Gross Labour Cost (S\$)			5,710.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >