

ASS. REC. BY:

REF: cs/ASM/8015586 / RHD3<sup>42</sup>

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Yvonne Ang

of

ASM (AXA)

Date/Time:

24/08/2018

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGY 71E

Insured:

at Workshop m/s

K. Kim Hin

Tel:

6452 7018 / 97176861

of

160 Sin Ming Drive # 02-20

Policy No:

Claim No:

SBM00376

Sum Insured:

Excess:

NIL

Make of Veh:

D.O.A.

14/8/18

(Client's Record)

28/8/2018 @ 4pm

☒ CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:53am @ 28/8/18

Person Contacted:

Sundra

Vehicle IN ☒ OUT

Date/Time:

Action/Instruction (✓) Estimate

SGY 71E - X

Part by Part \$4997.49 (Red: 0:0%)

✓ 20/12/18





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18015586/R1td3

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 27-08-2018



Code : ASM

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SGY 71E
Policy No.	Coverage (\$)	0.00
Claim No. S8M00S76	Excess (\$)	0.00
Assign From SMARTCLAIM (YVONNE ANG)	Assign Date	27/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date 14/08/2018	Inspection Date 28/08/2018
Survey held at K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722	

## 5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.




## Service Request Details

Claim

S8M00S76

Reference

None 

Loss Date

August 14, 2018

Request Date

August 24, 2018

Due Date

August 31, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SGY71E

Make

BMW

Model

328 I

Service Address

---

...

Primary Contact/Insured

---

LEE KHENG BOON MARK  
SINGAPORE, 631 EAST COAST ROAD, 459017, Singapore

EVECHONG\_23@HOTMAIL.COM

Claim Handler

---

ANG Yvonne  
6568804461  
yvonne.ang@axa.com.sg

Additional Instructions  
EXCESS NIL REPAIRER K KIM HIN

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

Date: 29/8/2018

To : AXA Insurance Pte Ltd

### Survey details

Date of loss	27-Aug-18
Date of appointment	27-Aug-18
Date of survey	28-Aug-18
Location of survey	K Kim Hin

### Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SGY 71E
Make and Model	B.M.W
Date of registration	11/5/2018
Excess	nil
Market Value	\$75,000
Parf Rebate	\$61,547
Nett Loss	\$13,453

### Repair details

Initial Estimate	\$2,017
------------------	---------

#### Proposed/Revised repair cost:

Parts	\$1,172
Check item	\$143
Labour	\$663
Total	\$1,977
Lump Sum(if applicable)	\$0

Number of days of repair	3
--------------------------	---

#### Remarks:

We have authorise repair  
Repair cost economical

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/08/2018 17:35
Date Of Accident	14/08/2018 17:30
Exact Location Of Accident	SLE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGY71E
-----------------------------	--------

### Insured/Policyholder

Name Of Registered Owner	MARK LEE KHENG BOON
NRIC No	S7104659A
Email Address	MARKLCZ@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96892361
Alternative Phone No	OTHERS-96892361

### Vehicle Particulars

Manufacturer	BMW
Model	328

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA194962
Cover Note Number	

### Driver

Name of Driver	MARK LEE KHENG BOON
NRIC No	S7104659A
Date Of Birth	01/02/1971
Occupation	INDOOR
Date Of Driving Pass	16/01/1989
Driving Experience	29 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96892361
Fax Number	
Contact Number	OTHERS-96892361
Email Address	MARKLCZ@HOTMAIL.COM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4659A
<b>Vehicle Details</b>	
Vehicle No.:	SGY71E
Vehicle to be Exported:	No
Intended De-registration Date:	24 Aug 2018
Vehicle Make:	B.M.W.
Vehicle Model:	328i 2.0 AT D/AB 4DR ABS HID NAV
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	A1630125N20B20A
Chassis No.:	WBA3A52040F253711
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$44,084.00
Original Registration Date:	11 May 2012
First Registration Date:	11 May 2012
Transfer Count:	1
Actual ARF Paid:	\$44,084.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 May 2022
PARF Rebate Amount:	\$28,654.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	10 May 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$88,990.00
COE Rebate Amount:	\$33,017.00
<b>Total Rebate Amount:</b>	<b>\$61,671.00</b>

The information contained herein is correct as at 24 Aug 2018

OK

## CHEAPEST CAR INSURANCE RENEWAL



Free roadside  
assistance

Free claims  
support

**GET A CHEAPER QUOTE NOW!**

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

2017 BMW 218i Convertible At \$135000.



Sell Under PML Servicing And  
Warranty. Best Condition In The  
Market.  
Direct Owner - StarAd

**AutoInn**  
An Inspiration For Car Buyers

click here to view  
our **PRISTINE USED CARS**  
at **GREAT PRICES**

Browse by Category

Sort by Date Posted  20 results/page

2 vehicles

bmw 328

Advanced Search  Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	bmw 328		Any	Any	2012	Any	Any	Any	Available



**BMW 3 Series 328i Luxury** \$84,000 \$15,460 /yr 28-Sep-2012 1,997 cc 102,000 km Luxury Available  
1 Meticulous Owner, Car Is In Excellent Condition, Well Maintained And Serviced Meticulously. PML Unit. New Tyres And Suspensions (Original From BMW) For Both Front And Rear. Sticky Handles Just Repla...

Posted: 26-Aug-2018 Tags: 2012 BMW 328i, BMW 328i, BMW, 328i, Used BMW



**BMW 3 Series 328i Luxury** \$77,800 \$14,850 /yr 13-Jun-2012 1,997 cc 51,000 km Luxury Available  
PML Unit, Low Mileage Done, Full Service Record. High ARF, Guaranteed Lowest Depreciation And Best Condition In Market! In House Loan With Low Down Payment Avail, Call For Appointment To View Right No...

Posted: 04-Aug-2018 Tags: 2012 BMW 328i, BMW 328i, BMW, 328i, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
--	------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

[Home](#) [New Cars](#) [Used Cars](#) [Sell My Car](#) [Directory](#) [Products](#) [Insurance](#) [Article](#) [Forum](#) [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used bmw 328, bmw 328 Singapore, used bmw 328 Singapore, used bmw 328, used vehicles Singapore or even buy used bmw 328 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**

[About Us](#) [Careers](#) [Contact Us](#) [Sitemap](#) [Terms of Service](#) [Privacy Policy](#) [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

[Compare](#)

**K.KIM HIN AUTO PTE LTD**  
**160 Sin Ming Drive**  
**#02-20 Sin Ming AutoCity**  
**Singapore 575722**

**Claim Reference:**

**Assessment Number: KKHA0023**

**Version: K.KIMHIN/1**

**Date Calculated: 24/08/2018 05:01**

**Full Report - V1**

**Registration: SGY71E**

**Printed: 24/08/2018 12:02**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SANDRA KHONG	Date of Incident:	14/08/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	GA194962/1	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

**Vehicle Details**

**Vehicle**

Manufacturer:	BMW
Model:	3 Series
Sub Model:	328I
Model Sheet Number:	1AC 02
Registration:	SGY71E
Registration Month:	
Registration Year:	
VIN Number:	WBA3A52040F253711
Odometer:	Not Known
Colour:	Blue
Engine Number:	A1630125N20B20A
Fuel Level:	%

**Model Specs**

FR PRODUCTION START	LUXURY LINE
THROUGH LOAD SYSTEM	AIR CON AUTO 2-ZONES
WINDSCREEN RAIN SENS	COMFORT ACCESS SYST
BLUETOOTH/USB	DIP REAR VIEW MIRROR
NAVIG-SYST PROFESS	HI-FI SPEAKER SYSTEM
XENON HEADLAMPS	FOG LAMPS
LIGHT PACKAGE	HEADLAMP WASHERS
DAKOTA LEATHER TRIM	ELEC/SEAT ADJ MEMORY
INSTR CLUSTER EXTEND	SHELF PACKAGE
FRT SLIDING ARMREST	CRUISE CONTROL
DIP REAR VIEW MIRROR	RR PARK DIST CONTROL
2.0 LTR 180KW	SPORT S-WHEEL LEATH
MULTI FUNC S-WHEEL	8-GEAR AUTOMATIC
SERVOTRONIC	TYRES 225/45 YR 18
WHEELS 8J X 18 ALLOY	NOBLE WOOD FINELINE
PEARL CHROM STRIPS	VERSION HOT COUNTRY
TYRE W/FLAT RUNNING	TWO COAT PEARL/MICA

**Vehicle Condition**

**Vehicle Status**

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on
	Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	24/08/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

# K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHA0023

Version: K.KIMHIN/1

Date Calculated: 24/08/2018 05:01

Full Report - V1

Registration: SGY71E

Printed: 24/08/2018 12:02

TIME(PAINT)	46.0	
Preparation Main Work Metal	11.0	
Preparation Comp. Work Plastic	5.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	62.0	
Total Paintwork Labour	6.2HRS	\$279.00
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$100.10
New Part Painting - Plastic K1R		\$56.58
Surface-/Blend Paint		\$8.96
Material-Const Main Work Metal		\$18.10
Material-Const Comp. Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$192.74
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$192.74

## PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
257	1	FRONT NUMBER PLATE	KNPL6		0%	0.00
258	1	FRT NO PLATE REINF	KNPL6		0%	60.00
283	1	FRONT BUMPER	51 11 7 293 022		0%	760.00
340	1	FRT UPP IMPACT DAMP	51 11 7 255 364		0%	55.00
371	1	FRT UPPER AIR GUIDE	51 74 7 255 413		0%	75.00
415	1	L/F GRILLE	51 13 7 263 481		0%	85.00
416	1	R/F GRILLE	51 13 7 263 482		0%	85.00
431	1	GRILLE BADGE	51 76 7 288 752		0%	75.00
f: OEM Parts			Sub Total			\$1,195.00
g: Original			Mark Up From Cost	(10 %)		\$119.50
h: Secondhand			Sundry Parts	(Fixed)		\$0.00
p: Parallel			Total Parts			\$1,314.50
x: Exchange						

Price Valid: 01/05/2018

THIS ASSESSMENT CONTAINS UNPRICED PARTS  
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Extras

Description	Betterment	Price
FRT NUMBER PLATE SPECIALIST	0%	\$40.00
Total Extras		\$40.00

## Final Calculation

Total Parts	\$1,314.50
Labour	
Total Panel/Mechanical	\$191.25
Total Paintwork	\$279.00
Total Labour	\$470.25
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$40.00
Total of Additional Costs	\$40.00
Total Paint/Material Costs	\$192.74
Grand Total Excludes GST	\$2,017.49
GST @ 7 %	\$141.22

4242.49

**K.KIM HIN AUTO PTE LTD**  
**160 Sin Ming Drive**  
**#02-20 Sin Ming AutoCity**  
**Singapore 575722**

**Claim Reference:**  
**Assessment Number: KKHA0023**  
**Version: K.KIMHIN/2**  
**Date Calculated: 12/11/2018 02:56**

**Full Report - V1**  
**Registration: SGY71E**  
**Printed: 22/11/2018 14:32**

### Summary Information

#### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SANDRA KHONG	Date of Incident:	14/08/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	GA194962/1	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

#### Vehicle Details

##### Vehicle

Manufacturer:	BMW
Model:	3 Series
Sub Model:	328I
Model Sheet Number:	1AC 02
Registration:	SGY71E
Registration Month:	
Registration Year:	
VIN Number:	WBA3A52040F253711
Odometer:	Not Known
Colour:	Blue
Engine Number:	A1630125N20B20A
Fuel Level:	%

##### Model Specs

FR PRODUCTION START	LUXURY LINE
THROUGH LOAD SYSTEM	AIR CON AUTO 2-ZONES
WINDSCREEN RAIN SENS	COMFORT ACCESS SYST
BLUETOOTH/USB	DIP REAR VIEW MIRROR
NAVIG-SYST PROFESS	HI-FI SPEAKER SYSTEM
XENON HEADLAMPS	FOG LAMPS
LIGHT PACKAGE	HEADLAMP WASHERS
DAKOTA LEATHER TRIM	ELEC/SEAT ADJ MEMORY
INSTR CLUSTER EXTEND	SHELF PACKAGE
FRT SLIDING ARMREST	CRUISE CONTROL
DIP REAR VIEW MIRROR	RR PARK DIST CONTROL
2.0 LTR 180KW	SPORT S-WHEEL LEATH
MULTI FUNC S-WHEEL	8-GEAR AUTOMATIC
SERVOTRONIC	TYRES 225/45 YR 18
WHEELS 8J X 18 ALLOY	NOBLE WOOD FINELINE
PEARL CHROM STRIPS	VERSION HOT COUNTRY
TYRE W/FLAT RUNNING	TWO COAT PEARL/MICA

### Vehicle Condition

#### Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	24/08/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

Claim Reference:

Assessment Number: KKHA0023



Version: K.KIMHIN/2

Date Calculated: 12/11/2018 02:56

Full Report - V1

Registration: SGY71E

Printed: 22/11/2018 14:32

**Addresses****Cost Summary**

Total Labour	\$500.25
Total Paint/Material	\$192.74
Total Parts	\$4,064.50
Total of Additional Costs	\$40.00
Excess:	TBA
Grand Total Exc GST:	\$4,797.49
7 % GST:	\$335.82
Grand Total Inc GST:	\$5,133.31

**Repair Information****LABOUR**

Time Basis 12 WU = 1 HR. Price/CL 1 = \$45.00/HR

Price/Dent = \$45.00/HR

**Repair /****Guide Number Repair Details**

		WU	Cost Price (\$)
NO NUMBER	ADD/TIME FOR MAIN WORK	2.0	7.50
51 11 656	R + R FRONT BUMPER COVER	9.0	33.75
51 11 566	R + R BOTH FRONT BUMPER CARRIERS (BUMPER COVER REMOVED)	11.0	41.25
51 11 592	RENEW FRONT BUMPER TRIM (BUMPER TRIM REMOVED)	12.0	45.00
61 67 803	HEADLIGHT WASHER UNIT - SUPPLEMENTARY OPERATION	3.0	11.25
	INCLUDES: REMOVE/REFIT WASHER NOZZLES		
51 71 600)	R + R RADIATOR AIR GUIDE	6.0	22.50
63 12 826)	R + R BOTH HEADLAMPS	8.0	30.00
63 12 524	RENEW L/HEADLAMP (REMOVED)	4.0	15.00
63 12 524	RENEW R/HEADLAMP (REMOVED)	4.0	15.00

**LABOUR COST**

Total Work Units	59.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	4.9HRS	\$221.25
Paint Labour	6.2HRS	\$279.00
Total Labour	11.1HRS	\$500.25

\*NOTE TIME BASIS = 12 WU / HOUR\*

**PAINT WORK**

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT PEARL/MICA		
471	BONNET NEW PART PAINTING	29.0	
283	FRONT BUMPER NEW PART PAINT K1R	12.0	

**K.KIM HIN AUTO PTE LTD**

**Claim Reference:**

**Assessment Number: KKHA0023**

**Version: K.KIMHIN/2**

**Date Calculated: 12/11/2018 02:56**

**Full Report - V1**

**Registration: SGY71E**

**Printed: 22/11/2018 14:32**

741	L/F WING SURFACE PAINT	5.0	
	<b>LABOUR COST - PAINT</b>		
	<b>TIME(PAINT)</b>	<b>46.0</b>	
	Preparation Main Work Metal	11.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	62.0	
	Total Paintwork Labour	6.2HRS	\$279.00
	<b>MATERIAL COST - PAINT</b>		<b>Cost Price</b>
	New Part Painting		\$100.10
	New Part Painting - Plastic K1R		\$56.58
	Surface-/Blend Paint		\$8.96
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$192.74
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$192.74

**PARTS**

				Price Valid: 01/05/2018	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
257	1	FRONT NUMBER PLATE	KNPL6		0% 0.00
258	1	FRT NO PLATE REINF	KNPL6		0% 60.00*
283	1	FRONT BUMPER	51 11 7 293 022		0% 760.00*
340	1	FRT UPP IMPACT DAMP	51 11 7 255 364		0% 55.00*
371	1	FRT UPPER AIR GUIDE	51 74 7 255 413		0% 75.00*
415	1	L/F GRILLE	51 13 7 263 481		0% 85.00*
416	1	R/F GRILLE	51 13 7 263 482		0% 85.00*
431	1	GRILLE BADGE	51 76 7 288 752		0% 75.00*
561	1	LEFT HEADLAMP ASSY	63 11 7 338 699		0% 1,250.00*
562	1	RIGHT HEADLAMP ASSY	63 11 7 338 700		0% 1,250.00* (A)
f: OEM Parts			Sub Total		\$3,695.00
g: Original			Mark Up From Cost	(10 %)	\$369.50
h: Secondhand			Sundry Parts	(Fixed)	\$0.00
p: Parallel			<b>Total Parts</b>		<b>\$4,064.50</b>
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS  
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Extras**

Description	Betterment	Price
FRT NUMBER PLATE SPECIALIST	0%	\$40.00
	<b>Total Extras</b>	<b>\$40.00</b>

**Final Calculation**

<b>Total Parts</b>	<b>\$4,064.50</b>
<b>Labour</b>	
Total Panel/Mechanical	\$221.25
Total Paintwork	\$279.00
<b>Total Labour</b>	<b>\$500.25</b>
<b>Additional Costs</b>	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$40.00
<b>Total of Additional Costs</b>	<b>\$40.00</b>

# K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHA0023

Version: K.KIMHIN/2

Date Calculated: 12/11/2018 02:56

Full Report - V1

Registration: SGY71E

Printed: 22/11/2018 14:32

Total Paint/Material Costs	\$192.74
Grand Total Excludes GST	\$4,797.49
GST @ 7 %	\$335.82
Grand Total Includes GST	\$5,133.31

## Assessment Notes

KK  
28/8  
SGK  
KPM

**K.KIM HIN AUTO PTE LTD**  
160 Sin Ming Drive  
#02-20 Sin Ming AutoCity  
Singapore 575722

**Claim Reference:**  
**Assessment Number: KKHA0023**  
**Version: K.KIMHIN/1**  
**Date Calculated: 24/08/2018 05:01**

**Full Report - V1**  
**Registration: SGY71E**  
**Printed: 24/08/2018 12:02**

### Summary Information

#### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SANDRA KHONG	Date of Incident:	14/08/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA

Claim Reference:		Estimated Repair Time:	
Policy Number:	GA194962/1	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

#### Vehicle Details

##### Vehicle

Manufacturer:	BMW
Model:	3 Series
Sub Model:	328I
Model Sheet Number:	1AC 02
Registration:	SGY71E
Registration Month:	
Registration Year:	
VIN Number:	WBA3A52040F253711
Odometer:	Not Known
Colour:	Blue
Engine Number:	A1630125N20B20A
Fuel Level:	%

##### Model Specs

FR PRODUCTION START	LUXURY LINE
THROUGH LOAD SYSTEM	AIR CON AUTO 2-ZONES
WINDSCREEN RAIN SENS	COMFORT ACCESS SYST
BLUETOOTH/USB	DIP REAR VIEW MIRROR
NAVIG-SYST PROFESS	HI-FI SPEAKER SYSTEM
XENON HEADLAMPS	FOG LAMPS
LIGHT PACKAGE	HEADLAMP WASHERS
DAKOTA LEATHER TRIM	ELEC/SEAT ADJ MEMORY
INSTR CLUSTER EXTEND	SHELF PACKAGE
FRT SLIDING ARMREST	CRUISE CONTROL
DIP REAR VIEW MIRROR	RR PARK DIST CONTROL
2.0 LTR 180KW	SPORT S-WHEEL LEATH
MULTI FUNC S-WHEEL	8-GEAR AUTOMATIC
SERVOTRONIC	TYRES 225/45 YR 18
WHEELS 8J X 18 ALLOY	NOBLE WOOD FINELINE
PEARL CHROM STRIPS	VERSION HOT COUNTRY
TYRE W/FLAT RUNNING	TWO COAT PEARL/MICA

### Vehicle Condition

#### Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on
	Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	24/08/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

**K.KIM HIN AUTO PTE LTD**

Claim Reference:

Assessment Number: KKHA0023



Version: K.KIMHIN/1

Date Calculated: 24/08/2018 05:01

Full Report - V1

Registration: SGY71E

Printed: 24/08/2018 12:02

**Addresses****Cost Summary**

Total Labour	\$470.25
Total Paint/Material	\$192.74
Total Parts	\$1,314.50
Total of Additional Costs	\$40.00
Excess:	TBA
Grand Total Exc GST:	\$2,017.49
7 % GST:	\$141.22
Grand Total Inc GST:	\$2,158.71

**Repair Information****LABOUR**

Time Basis 12 WU = 1 HR. Price/CL 1 = \$45.00/HR

Price/Dent = \$45.00/HR

**Repair /**

Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	ADD/TIME FOR MAIN WORK	2.0	7.50
51 11 656	R + R FRONT BUMPER COVER	9.0	33.75
51 11 566	R + R BOTH FRONT BUMPER CARRIERS (BUMPER COVER REMOVED)	11.0	41.25
51 11 592	RENEW FRONT BUMPER TRIM (BUMPER TRIM REMOVED)	12.0	45.00
61 67 803	HEADLIGHT WASHER UNIT - SUPPLEMENTARY OPERATION INCLUDES: REMOVE/REFIT WASHER NOZZLES	3.0	11.25
51 71 600)	R + R RADIATOR AIR GUIDE	6.0	22.50
63 12 826)	R + R BOTH HEADLAMPS	8.0	30.00

**LABOUR COST**

Total Work Units	51.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	4.3HRS	\$191.25
Paint Labour	6.2HRS	\$279.00
Total Labour	10.5HRS	\$470.25

\*NOTE TIME BASIS = 12 WU / HOUR\*

**PAINT WORK**

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

**Guide Number Description**

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT PEARL/MICA		
471	BONNET NEW PART PAINTING	29.0	
283	FRONT BUMPER NEW PART PAINT K1R	12.0	
741	L/F WING SURFACE PAINT	5.0	

**LABOUR COST - PAINT**

**K.KIM HIN AUTO PTE LTD**

**Claim Reference:**

**Assessment Number: KKHA0023**

**Version: K.KIMHIN/1**

**Date Calculated: 24/08/2018 05:01**

**Full Report - V1**

**Registration: SGY71E**

**Printed: 24/08/2018 12:02**

**Grand Total Includes GST**

**\$2,158.71**

**Assessment Notes**

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>
--

Rasul  
Hp 90010068  
3 days  
P/P  
28/08/18 @ 1615  
EXCESS: NIL  
Authorized  
Resurvey by paint

# K.KIM HIN AUTO PTE LTD

Claim Reference:  
Assessment Number: KKHA0023  
Version: K.KIMHIN/1  
Date Calculated: 24/08/2018 05:01

Full Report - V1  
Registration: SGY71E  
Printed: 24/08/2018 12:02

TIME(PAINT)	46.0	
Preparation Main Work Metal	11.0	
Preparation Comp. Work Plastic	5.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	62.0	
Total Paintwork Labour	6.2HRS	\$279.00
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$100.10
New Part Painting - Plastic K1R		\$56.58
Surface-/Blend Paint		\$8.96
Material-Const Main Work Metal		\$18.10
Material-Const Comp. Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$192.74
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$192.74

## PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
257	1	FRONT NUMBER PLATE	KNPL6		0%	0.00
258	1	FRT NO PLATE REINF	KNPL6		0%	60.00*
283	1	FRONT BUMPER	51 11 7 293 022		0%	760.00*
340	1	FRT UPP IMPACT DAMP	51 11 7 255 364		0%	55.00*
371	1	FRT UPPER AIR GUIDE	51 74 7 255 413		0%	75.00*
415	1	L/F GRILLE	51 13 7 263 481		0%	85.00*
416	1	R/F GRILLE	51 13 7 263 482		0%	85.00*
431	1	GRILLE BADGE	51 76 7 288 752		0%	75.00*
f: OEM Parts			Sub Total			\$1,195.00
g: Original			Mark Up From Cost	(10 %)		\$119.50
h: Secondhand			Sundry Parts	(Fixed)		\$0.00
p: Parallel			Total Parts			\$1,314.50
x: Exchange						

THIS ASSESSMENT CONTAINS UNPRICED PARTS  
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Extras

Description	Betterment	Price
FRT NUMBER PLATE SPECIALIST	0%	\$40.00
Total Extras		\$40.00

## Final Calculation

Total Parts		\$1,314.50
Labour		
Total Panel/Mechanical		\$191.25
Total Paintwork		\$279.00
Total Labour		\$470.25
Additional Costs		
Corr Prot Materials External		\$0.00
Corr Prot Materials Internal		\$0.00
Cost of Specialist		\$40.00
Total of Additional Costs		\$40.00
Total Paint/Material Costs		\$192.74
Grand Total Excludes GST		\$2,017.49
GST @ 7 %		\$141.22

51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
Singapore  
408933

Claim Reference:  
Assessment Number: KKHA0023  
Version: LKKAUTOC/3  
Date Calculated: 12/12/2018 07:55

Full Report - V1  
Registration: SGY71E  
Printed: 12/12/2018 15:58

## Summary Information

### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	14/08/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	GA194962/1	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

### Vehicle Details

#### Vehicle

Manufacturer:	BMW
Model:	3 Series
Sub Model:	328I
Model Sheet Number:	1AC 02
Registration:	SGY71E
Registration Month:	
Registration Year:	
VIN Number:	WBA3A52040F253711
Odometer:	Not Known
Colour:	Blue
Engine Number:	A1630125N20B20A
Fuel Level:	%

#### Model Specs

FR PRODUCTION START	LUXURY LINE
THROUGH LOAD SYSTEM	AIR CON AUTO 2-ZONES
WINDSCREEN RAIN SENS	COMFORT ACCESS SYST
BLUETOOTH/USB	DIP REAR VIEW MIRROR
NAVIG-SYST PROFESS	HI-FI SPEAKER SYSTEM
XENON HEADLAMPS	FOG LAMPS
LIGHT PACKAGE	HEADLAMP WASHERS
DAKOTA LEATHER TRIM	ELEC/SEAT ADJ MEMORY
INSTR CLUSTER EXTEND	SHELF PACKAGE
FRT SLIDING ARMREST	CRUISE CONTROL
DIP REAR VIEW MIRROR	RR PARK DIST CONTROL
2.0 LTR 180KW	SPORT S-WHEEL LEATH
MULTI FUNC S-WHEEL	8-GEAR AUTOMATIC
SERVOTRONIC	TYRES 225/45 YR 18
WHEELS 8J X 18 ALLOY	NOBLE WOOD FINELINE
PEARL CHROM STRIPS	VERSION HOT COUNTRY
TYRE W/FLAT RUNNING	TWO COAT PEARL/MICA

## Vehicle Condition

### Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	24/08/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

Claim Reference:

Full Report - V1



Assessment Number: KKHA0023

Registration: SGY71E

Version: LKKAUTOC/3

Printed: 12/12/2018 15:58

Date Calculated: 12/12/2018 07:55



## Addresses

## Cost Summary

Total Labour	\$500.25
Total Paint/Material	\$192.74
Total Parts	\$4,064.50
Total of Additional Costs	\$40.00
Excess:	TBA
Grand Total Exc GST:	\$4,797.49
7 % GST:	\$335.82
Grand Total Inc GST:	\$5,133.31

## Repair Information

### LABOUR

Time Basis 12 WU = 1 HR. Price/CL 1 = \$45.00/HR

Price/Dent = \$45.00/HR

### Repair /

### Guide Number Repair Details

NO NUMBER	ADD/TIME FOR MAIN WORK	WU	Cost Price (\$)
51 11 656	R + R FRONT BUMPER COVER	2.0	7.50
51 11 566	R + R BOTH FRONT BUMPER CARRIERS (BUMPER COVER REMOVED)	9.0	33.75
		11.0	41.25
51 11 592	RENEW FRONT BUMPER TRIM (BUMPER TRIM REMOVED)	12.0	45.00
61 67 803	HEADLIGHT WASHER UNIT - SUPPLEMENTARY OPERATION	3.0	11.25
	INCLUDES: REMOVE/REFIT WASHER NOZZLES		
51 71 600)	R + R RADIATOR AIR GUIDE	6.0	22.50
63 12 826)	R + R BOTH HEADLAMPS	8.0	30.00
63 12 524	RENEW L/HEADLAMP (REMOVED)	4.0	15.00
63 12 524	RENEW R/HEADLAMP (REMOVED)	4.0	15.00

### LABOUR COST

Total Work Units	59.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	4.9HRS	\$221.25
Paint Labour	6.2HRS	\$279.00
Total Labour	11.1HRS	\$500.25

\*NOTE TIME BASIS = 12 WU / HOUR\*

### PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT PEARL/MICA		
471	BONNET NEW PART PAINTING	29.0	
283	FRONT BUMPER NEW PART PAINT K1R	12.0	

741	L/F WING SURFACE PAINT	5.0	
	<b>LABOUR COST - PAINT</b>		
	TIME(PAINT)	46.0	
	Preparation Main Work Metal	11.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	62.0	
	Total Paintwork Labour	6.2HRS	\$279.00
	<b>MATERIAL COST - PAINT</b>		Cost Price
	New Part Painting		\$100.10
	New Part Painting - Plastic K1R		\$56.58
	Surface-/Blend Paint		\$8.96
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$192.74
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$192.74

**PARTS**

					Price Valid: 01/05/2018	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
283	1	FRONT BUMPER	51 11 7 293 022		0%	760.00*
257	1	FRONT NUMBER PLATE	KNPL6		0%	0.00
258	1	FRT NO PLATE REINF	KNPL6		0%	60.00*
340	1	FRT UPP IMPACT DAMP	51 11 7 255 364		0%	55.00*
371	1	FRT UPPER AIR GUIDE	51 74 7 255 413		0%	75.00*
431	1	GRILLE BADGE	51 76 7 288 752		0%	75.00*
415	1	L/F GRILLE	51 13 7 263 481		0%	85.00*
561	1	LEFT HEADLAMP ASSY	63 11 7 338 699		0%	1,250.00*
416	1	R/F GRILLE	51 13 7 263 482		0%	85.00*
562	1	RIGHT HEADLAMP ASSY	63 11 7 338 700		0%	1,250.00*
f: OEM Parts		Sub Total				\$3,695.00
g: Original		Mark Up From Cost		(10 %)		\$369.50
h: Secondhand		Sundry Parts		(Fixed)		\$0.00
p: Parallel		<b>Total Parts</b>				<b>\$4,064.50</b>
x: Exchange						

THIS ASSESSMENT CONTAINS UNPRICED PARTS  
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Extras**

Description	Betterment	Price
FRT NUMBER PLATE SPECIALIST	0%	\$40.00
<b>Total Extras</b>		<b>\$40.00</b>

**Final Calculation**

<b>Total Parts</b>	<b>\$4,064.50</b>
<b>Labour</b>	
Total Panel/Mechanical	\$221.25
Total Paintwork	\$279.00
<b>Total Labour</b>	<b>\$500.25</b>
<b>Additional Costs</b>	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$40.00
<b>Total of Additional Costs</b>	<b>\$40.00</b>

Claim Reference:

Full Report - V1

Assessment Number: KKHA0023

Registration: SGY71E

Version: LKKAUTOC/3

Printed: 12/12/2018 15:58

Date Calculated: 12/12/2018 07:55

---

Total Paint/Material Costs	\$192.74
Grand Total Excludes GST	\$4,797.49
GST @ 7 %	\$335.82
Grand Total Includes GST	\$5,133.31

---

#### Assessment Notes

---



# 友興汽車零件私人有限公司 YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708

TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858

Email: yewheng@yewhengauto.sg

Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

## TAX INVOICE

M/S: K.KIM HIN AUTO PTE LTD

160 SIN MING DRIVE #02-18/19/20/21  
SIN MING AUTOCITY  
SINGAPORE 575722

NO: YLI1211076  
PAGE: 1  
DATE: 29/08/2018  
A/C CODE: LYKKH001  
TERMS: 60 DAYS  
P/O NO: SGY71E

YHAP  
A/C 1200

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 5113 7 279 708	NUMBER PLATE GARNISH	YDS	1	60.00	60.00
2 5111 7 293 022	FRT BUMPER TRIM	2N-1A	1	760.00	760.00
3 5176 7 288 752	FRONT LOGO	1N-43B1	1	75.00	75.00
4 5111 7 255 364	FRT BUMPER SPONGE	YDS	1	55.00	55.00
5 5113 7 263 481	FRT GRILLE LH	1N-16A	1	85.00	85.00
6 5113 7 263 482	FRT GRILLE RH	1N-16A	1	85.00	85.00
7 5174 7 255 413	AIR DUCT TOP	YDS	1	75.00	75.00
8 6311 7 338 699	HEAD LAMP LH	2OS-1A	1	1,250.00	1,250.00
9 6311 7 338 700	HEAD LAMP RH	2OS-1A	1	1,250.00	1,250.00
TOTAL QUANTITY:			9	TOTAL	SIN 3,695.00
				ADD GST @ 7%	258.65
				GRAND TOTAL	<u>SIN 3,953.65</u>

DELIVERY  
TTN:MR SIMON

case 180536  
quote 29984

14.8.18 AXA

Print / KXM / 29/08/2018 9:14:17 AM

SALESMAN: KXM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18015586/R1td3s2

8 SHENTON WAY #24-01  
AXA TOWERS SINGAPORE 068811  
ATTN: YVONNE ANG

Date : 21-12-2018



Code : ASM

#### 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SGY 71E
Policy No.	GA194962	Coverage (\$)	0.00
Claim No.	S8M00S76	Excess (\$)	0.00
Assign From	YVONNE ANG	Assign Date	24/08/2018

#### 2. Vehicle Particulars & Condition

Make & Model	B.M.W. 328i 2.0A	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WBA3A52040F253711	Colour	BLUE
Odometer	145256	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45R18	PIRELLI	6 mm
L/H Front Tyre	225/45R18	PIRELLI	6 mm
R/H Rear Tyre	225/45R18	PIRELLI	6 mm
L/H Rear Tyre	225/45R18	PIRELLI	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.
---

#### 5. General Information

Accident Date	14/08/2018	Inspection Date	28/08/2018
Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722		

#### 5a. Remarks

A) THE MARKET VALUE IS S\$75,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 71E**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRT NO PLATE REINF (WCP) (CONSISTENT)	DEFORMED	60.00	60.00
1	FRONT BUMPER (WCP) (CONSISTENT)	DEFORMED	760.00	760.00
1	FRT UPP IMPACT DAMP (WCP) (CONSISTENT)	DEFORMED	55.00	55.00
1	FRT UPPER AIR GUIDE (WCP) (CONSISTENT)	CRACKED	75.00	75.00
1	L/F GRILLE (WCP) (CONSISTENT)	SCRATCHED	85.00	85.00
1	R/F GRILLE (WCP) (CONSISTENT)	CRACKED	85.00	85.00
1	GRILLE BADGE (WCP) (CONSISTENT)	NECESSARY	75.00	75.00
1	LEFT HEADLAMP ASSY (WCP) (CONSISTENT) (ADDITIONAL)	SCRATCHED	1,250.00	1,250.00
1	RIGHT HEADLAMP ASSY (WCP) (CONSISTENT) (ADDITIONAL)	SCRATCHED	1,250.00	1,250.00
	COST PLUS 10%		369.50	369.50
			4,064.50	4,064.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRT NUMBER PLATE (SN) (CONSISTENT)	BENT	40.00	40.00
			40.00	40.00
	<b><u>LABOUR</u></b>			
	TOTAL PANEL / MECHANICAL		221.25	221.25
	TOTAL PAINTWORK		279.00	279.00
	TOTAL PAINT / MATERIAL COSTS		192.74	192.74
			692.99	692.99
	<b>GRAND TOTAL</b>		<b>4,797.49</b>	<b>4,797.49</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>4,797.49</b>

Report Ref No. CS/ASM18015586/R1td3s2

**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

**ADRIAN LING WAI PING**

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.