

ASS. REC. BY:

REF:

CS3/LPC/8015547/Gqd3 02

Special Instruction:

Surveyor:

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Gerold poh

of

LPC

Date/Time:

27/8/18 @ 9:54am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN1582P

Insured:

SLN725A

at Workshop m/s

Precise Auto

Tel:

6745 7367

of

1 Kaki Bkt Ave 6 # 02-33/36

Policy No:

Claim No:

18/18/18/VPO5/020853

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/08/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time:

12:30pm 27/8/18

Person Contacted:

Aine

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLN1582P-X
	SLN725A-X
07/10/18	Submit PRS.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS3/LPC18015597/Gqd3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 27-08-2018		
		Code : LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SJN 725A	Veh. Inspected	SLN 1582P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	27/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date		Inspection Date	27/08/2018	
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 27 August 2018 9:54 AM
To: Precise Auto Service
Cc: MT_Claim_SG; Catherine Chong (LKK Auto)
Subject: RE: Pre-repair Inspection for SLN 1582P. Your Insured Vehicle no : SJN 725A

WITHOUT PREJUDICE

Dear Arine,

We are not agreeable to your lists of Single Joint Experts and shall proceed to appoint LKK Auto Consultants Pte Ltd for the pre-repair survey.

Aside to LKK-Attn:Catherine
Kindly proceed with the pre-repair survey.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Precise Auto Service [mailto:support@preciseauto.sg]
Sent: Monday, 27 August, 2018 9:44 AM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: Re: Pre-repair Inspection for SLN 1582P. Your Insured Vehicle no : SJN 725A

Dear Mr. Gerald,

We refer to your email dated 27-08-2018. Kindly be informed that we're unable to accept your surveyors. Herewith enclosed our nominator surveyor list for your attention.

Thank You.

Best Regards
Arine

On 27 August 2018 at 09:24, GERALD POH WEE BIN <geraldpoh@lonpac.com> wrote:

Dear Arine,

Please see attached

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Precise Auto Service [mailto:support@preciseauto.sg]

Sent: Monday, 27 August, 2018 9:19 AM

To: MT_Claim_SG

Cc: GERALD POH WEE BIN

Subject: Fwd: Pre-repair Inspection for SLN 1582P. Your Insured Vehicle no : SJN 725A

First Reminder

Dear Sir,

We refer to the above mentioned matter, herewith enclosed a 2 days notice for your attention.

Please arrange to do pre-repair inspection for **SLN 1582P** in our workshop ASAP.

Thank You!

Best Regards

Arine

T : 6745 7367 | F : 6841 3390

E : support@preciseauto.sg

W: www.preciseauto.sg

A : 1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



PRECISE AUTO SERVICE

準 確 汽 車 服 務

Follow us on social media:



T : 6745 7367 | F : 6841 3390

E : support@preciseauto.sg

W: www.preciseauto.sg

A : 1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



PRECISE AUTO SERVICE

準 確 汽 車 服 務

Follow us on social media:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1605B
Vehicle Details	
Vehicle No.:	SLN1582P
Vehicle to be Exported:	No
Intended De-registration Date:	28 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5G CVT
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	2NR8698457
Chassis No.:	NSP1707064342
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$21,247.00
Original Registration Date:	25 Apr 2017
First Registration Date:	25 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$11,746.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Apr 2027
PARF Rebate Amount:	\$8,809.00
Intended COE Rebate Details	
COE Expiry Date:	24 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$45,021.00
Total Rebate Amount:	\$53,830.00

The information contained herein is correct as at 28 Aug 2018

OK



PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC18015597/Gqd3n2 Date: 08-10-2018 Code: LPC2	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SJN 725A	Veh. Inspected	SLN 1582P	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020853	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	27/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	NSP1707064342	Colour	BROWN	
Odometer	28863 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	TOYO	6 mm	
L/H Front Tyre	185/60 R15	TOYO	6 mm	
R/H Rear Tyre	185/60 R15	TOYO	6 mm	
L/H Rear Tyre	185/60 R15	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	23/08/2018	Inspect Date / Time	27/08/2018 (04:00 PM)	
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC18015597/Gqd3n2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAAE,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.