



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

LEE MAY YIN
81 JURONG WEST CENTRAL 3 #07-37
THE CENTRIS SINGAPORE 648340

Attention : THE OWNER
Contact : 97805493

Estimate : ES006433

Date : 27/08/2018
Vehicle Num. : SLZ1747T
Make/Model : VOLKSWAGEN TIGUAN COMFORTLI
Chassis/Eng# : WVGZZZ5NZJW379331/CZE381885
Accident Date : 21/08/2018
Claim No. :
Reference :
Policy No. :

*Not Withheld
1.B.1
Pursuing B6 repair*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	REAR BUMPER		1,368.10 ✓
3.	1	REAR BUMPER SPONGE		261.00 ✓
4.	1	REAR BUMPER REINFORCEMENT		559.72 ✓
5.	1	REAR BUMPER CENTRE INNER GARNISH		389.70 ✓
6.	1	REAR BUMPER LOWER PAD		362.58 ✓
6.	8	REAR BUMPER CLIP	10.80	86.40 ✓
List Total S\$:				3,027.50
10.00% Discount S\$:				302.75
				2,724.75
1.	2	SPECIAL NETT ITEMS :		
		REVERSE SENSOR	233.13	466.26 X
Special Nett Total S\$:				466.26
LABOUR :				
RUST PROOFING TREATMENT				100.00 X
SPRAY PAINT DAMAGED AREA AFFECTED				900.00
TO KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE				
ALL NECESSARY PARTS				
Labour Total S\$:				1,950.00

SingDollars : Five Thousand One Hundred Forty-One & Cents One Only

Total S\$: 5,141.01
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: