

INSURANCE

INS. CASE OWNER:

slany

CC 4 ASM 5677, T1 P167/

LKK

IDAC

Surveyor:

TAWAKH

DOI:

ASSIGNMENT

12/9/18

Date / Time:

20/8/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SEL 7462L

Name of Insured:

UM KWEE SIE

Insured Tel No.:

HP: 96655710

Excess Sec II (S\$)

D.O.A: 15/8/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) (YES / NO)

Claim No.:

S8M10TIE / 65771

Policy No.:

BA007785 / 1

Make / Model:

BMW

Place of Accident:

WESTLAKE ME

OI GIA REPORT:

(YES / NO)

TP GIA REPORT: (YES / NO)

Insured Liability:

% Final? Yes / No

Summary



INSRS:
WSP:
Tel:
Liability:
RMKS:

Kah motor



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

21/8/18

UNT

Summary - 4

Summary - 4

STAGE

DATE / PIC

Non-Reporting Itr (1st)

Non-Reporting Itr (2nd)

Non-Reporting Itr (Final)

Notification Itr (if non-pickup)

Call Of:

After call Itr to Of:

21/8/18

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to Of:

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA

Medical Bill

PIR

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

14/1/19

Confirm with:

Demurel

Email

Call

Final Liability:

%

100

(Assessed / Assessed) BOLA S/N No. 22.

If NO or B 28. Ass. Lia:

Repair Cost: w/h

S\$

3200.56

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

2000.00

(5 x 4 days)

Loss of Income (LOI):

S\$

15 x 4 days

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/Independent)

Legal Cost:

S\$

1) Claim status: Non-Report/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

3200.56

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3200.56

Name 1:

Kah motor (v. soln. Bhd.

Payee 2 (Strike if N.A.)

S\$

Name 2:

Payee 3 (Strike if N.A.)

S\$

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18015637/pb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 28-08-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKL 3462L	Veh. Inspected	SLM 8919L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	28/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/08/2018	Inspection Date		
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

QUANTITY

Tamper

REF: ASM(UAXA)

ASSIGNMENT

From: Date: 17092018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLM 8919L
at Workshop m/s: Kah motor
of: 255 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Sin Hai

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$70K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLM 8919L Yr Regn: 2017 April

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda J335 C.C. 1318

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 4098 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHM GK 3850 H X 20017

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175 / 65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 17/1/18 Q1020

Survey held at Kah motor

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear o/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PIP \$2804.26 (Reel # 7302.50 / 724.)

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

\$ + RS 31

Photos

Other

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811
 Registration No : SLM8919L
 Chassis No : JHMGK3850HX200447
 Model : JAZZ 1.3LXR CVT 17YM
 Owner's Name : OOI SU ZAN
 Ins Policy No. :
 Date of Accident : 25/8/2018

Document No. : SQT18003775 Page 1
 Date : 7. Sep 2018
 Customer No. : WZA006
 Svc Advisor :
 Engine No : L13B11020302
 Date | Time : 7. Sep 2018 9:16:36 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.20	25	8.40	0.59	8.99
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.30	25	9.45	0.66	10.11
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
68100-TAR-U10ZZ	TAILGATE COMP	1	716.30	25	537.22	37.61	574.83
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
74801-T5A-013	LOCK ASSYTAILGATE	1	173.20	25	129.90	9.09	138.99
74813-T5A-003	STRIKER ASSYTAILGATE	1	24.70	25	18.52	1.30	19.82
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER	1	52.10	25	39.07	2.73	41.80
84441-T5A-003ZB	POCKETTAILGATE LINING PULL	1	5.00	25	3.75	0.26	4.01
75722-T5L-T01	EMBLEMRR.	1	10.50	25	7.87	0.55	8.42
33500-T5A-J02	TAILLIGHT ASSY.R.	1	235.10	25	176.32	12.34	188.66
04715-T5A-000ZZ	FACERR.BUMPER	1	492.70	25	369.52	25.87	395.39
71502-T5A-000	GARNISHR.RR.BUMPER	1	14.00	25	10.50	0.74	11.24
71507-T5A-000	GARNISHL.RR.BUMPER	1	14.00	25	10.50	0.74	11.24
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	5	2.00	25	7.50	0.53	8.03
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	60.80	25	45.60	3.19	48.79
Sum Item					1586.80	111.09	1,697.89



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 96203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLM8919L
Chassis No : JHMGK3850HX200447
Model : JAZZ 1.3LXR CVT 17YM
Owner's Name : OOI SU ZAN
Ins Policy No. :
Date of Accident : 25/8/2018

Document No. : SQT18003775
Date : 7. Sep 2018
Customer No. : WZA006
Svc Advisor :
Engine No : L13B11020302
Date | Time : 7. Sep 2018 9:16:36 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES <i>APL</i>	1 <i>30</i>	100.00	✓	100.00	7.00	107.00
BML02J	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1 ✓	180.00	✓	180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1 ✓	180.00	✓	180.00	12.60	192.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1 X	560.00		560.00	39.20	599.20
BOMISC1	REMOVE, INSTALL & RESET REAR VIEW CAMERA.(N)	1 X	380.00		380.00	25.60	406.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1 X	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1 X	560.00		560.00	39.20	599.20
BKBU02R	REPLACE RR BUMPER, REPAIR RR PANEL & OTHER DAMAGE	1 <i>1120</i>	3000.00	✓	3000.00	210.00	3210.00
BP03R	SPRAY PAINTING ON TAILGATE, RR BUMPER & RR PANEL	1 <i>900</i>	3000.00	✓	3000.00	210.00	3210.00
Sum Labor					8520.00	596.40	9,116.40

Survey By *Tan JH 92495749*
Date & Time *12/9/18 @ 1030*
Excess *WP*
Status *WP*
Signature *[Signature]* *4 days*
Resurvey after before print
sur@lkkauto.com

Total Amount 10,106.80 707.49 10,814.29
Total (Inclusive of GST) **10,814.29**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 7/9/2018 9:21:08 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
Chassis No: JHMGK3850HX200447
License No: SLM8919L
Mileage: 2347
Engine No: L13B11020302

Document No: SVO18054621
Printed By: SHNG
Order Date: 17. September 2018
Order Time: 12:22:08 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:OOI SU ZAN OWNER INSURER:TOKIO ACC DATE:25/08/2018 SURVEYED BY:TAUFIKH DATE:17/09/2018 REF NO: TP INSURER:AXA TP VEH:SKL3462L						
04715-T5A-000ZZ	FACERR.BUMPER	1	492.70	25	369.52	25.87	395.39
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	5	2.00	25	7.50	0.53	8.03
	SUM PARTS:				394.26	27.60	421.86
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BML02I	0669 INSPECT RR LIGHTING MECHANISMS, PERFORM WATER TEST.(N)	1	180.00		180.00	12.60	192.60
BA02R	0669 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BKBU02R	0669 REPLACE RR BUMPER, REPAIR RR PANEL & OTHER DAMAGE PARTS.	1	1,120.00		1,120.00	78.40	1,198.40
BP03R	1610 SPRAY PAINTING ON TAILGATE, RR BUMPER & RR PANEL	1	900.00		900.00	63.00	963.00
	SUM LABOUR:				2,410.00	168.70	2,578.70
	TOTAL SGD				2,804.26	196.30	3,000.56

Total Payable (SGD)

3,000.56

GST Amount is calculated from individual line(s)

Hsiao Tong (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 20 September 2018 12:52 PM
To: Hsiao Tong (LKKAUTO); CS A Team; Admin A; Ng Sin Hai (shng@kahmotor.onmicrosoft.com)
Cc: SUR
Subject: FW: Submission Pre-Invoice for vehicle SLM8919L
Attachments: 4637_001.pdf; DSCF9852.jpg; DSCF9849.jpg; DSCF9850.jpg; DSCF9851.jpg

Dear Sin Hai,

For future on direct settlement Third party cases, you may email to cs-a@lkkauto.com & admin-a@lkkauto.com

Dear Hsiao Tong,

FYNA-CC4/ASM18015637/T1pb3

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent: Thursday, 20 September 2018 12:48 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FW: Submission Pre-Invoice for vehicle SLM8919L

Dear Mr Taufikh,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair : S\$2,804.26 (before GST)

No of working days : 04 days. (LOU)

We will proceed for closing after 1 week of submission to you.

Kindly contact me if there is any discrepancy

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page

Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Ng Sin Hai

Sent: Tuesday, 19 June, 2018 9:54 AM

To: Taufikh@lkkauto.com; 'SUR' <sur@lkkauto.com>

Subject: RE: Submission Pre-Invoice for vehicle SLK1294R

Thank you and have a nice day, ☺

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page



CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

<< <Request for DS> - S8M00TIE [ACCIDENT INVOLVING SKL 3462L(OI) & SLM 8919L(TP) ON 25/08/2018]

Type

 Question

Message

Liability: 100%. Insured driver collided onto third party parked vehicle. Informed OI about third party claim. Agreed to settle and aware NCD issue. Kindly advise if we may proceed DS with third party repairer.

***Third party will arrange survey after liability clear/ AXA agreed to do DS. Thank you. Hsiao Tong - 30 Aug 2018

Reply

<< **Re:RE: <Request for DS> - S8M00TIE [ACCIDENT INVOLVING SKL 3462L(OI) & SLM 8919L(TP) ON 25/08/2018]**

Type

🔔 Question

Message

Pls proceed DS Kindly provide IA.

Reply

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Tuesday, 11 September 2018 11:04 AM
To: 'shng@kahmotor.onmicrosoft.com'
Cc: Admin A; assignments
Subject: RE: 3rd party direct settlement for SLM8919L/ & your insured SKL3462L /DOA:25/08/2018/Est \$

Without Prejudice

Hi Sirs,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject to insurer's approval.

****Kindly arrange for survey.**

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAUTO)
Sent: Monday, 10 September 2018 8:56 AM
To: shng@kahmotor.onmicrosoft.com
Cc: Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: 3rd party direct settlement for SLM8919L/ & your insured SKL3462L /DOA:25/08/2018/Est \$

Without Prejudice

Hi Sin Hai,

Thank you for your email.

We are pending Direct Settlement instruction from AXA and we will get back to you asap.

Kindly bear with us for time being.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 10 September 2018 7:58 AM

To: shng@kahmotor.onmicrosoft.com; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: FW: 3rd party direct settlement for SLM8919L/ & your insured SKL3462L /DOA:25/08/2018/Est \$

Dear Sir/Mdm,

Thank you for the email.

Dear Hsiao Tong,

Kindly assist

FYNA Our Ref : CC4/ASM18015637/pb3

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai [<mailto:shng@kahmotor.onmicrosoft.com>]

Sent: Friday, 7 September 2018 9:16 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: FW: 3rd party direct settlement for SLM8919L/ & your insured SKL3462L /DOA:25/08/2018/Est \$

Dear Catherine,

Please check for me on the liability for this case.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg



Visit our
Facebook page

 Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Ng Sin Hai
Sent: Monday, 27 August, 2018 8:38 PM
To: axa t/p (motor_survey@axa.com.sg) <motor_survey@axa.com.sg>
Subject: RE: 3rd party direct settlement for SLM8919L/ & your insured SKL3462L /DOA:25/08/2018/Est \$

Dear MotorClaims,

Please refer to the attached pdf, we are assisting our insured vehicle **SLM8919L** to file a 3rd party claim against your insured vehicle **SKL3462L**.

Kindly assist and expedite to check the claim liability soonest and to request for direct settlement.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com



<SEEK MANDATE> -S8M00TIE [ACCIDENT INVOLVING SKL 3462L(OI) & SLM 8919L(TP) ON 25/08/2018]

Type

🔔 Question

Message

Liability: 100%. Insured collided onto third party parked vehicle. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate up to \$3,248.01(all-in). IA with mandate had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 22 Oct 2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 22/10/2018

Survey Details:

Date of loss	25-Aug-18
Date of appointment	28-Aug-18
Date of survey	17-Sep-18
Location of survey	KAH MOTOR CO SDN BERHAD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLM 8919L
Make and Model	HONDA JAZZ 1.3 CVT ABS D/AIRBAG
Date of registration	17/4/2017
Excess	NIL
Market Value	\$70,000
Parf Rebate	\$52,206
Nett Loss	\$17,794

Repair details:

Initial Estimate	\$ 10,106.80
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 394.26
Check items (estimate)	
Labour	\$ 2,410.00
Total	\$ 2,804.26
Lump Sum(if applicable)	\$ -

Number of days for repair	4
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%
Proposed repair cost (w/GST)	\$	3,000.56
Loss of use	\$	240.00 (4days x 60.00)
Loss of rental		NIL
Loss of income		NIL
LTA search fees	\$	7.45
Others		NIL
Proposed Total	\$	3,248.01

Hsiao Tong (LKKAuto)

From: Shu Pei (LKKAuto)
Sent: Monday, 5 November 2018 2:01 PM
To: Hsiao Tong (LKKAuto)
Subject: RE: New message for service request 65771, vehicle number SLM8919L

11/4/18 11:39 PM

NG Stacey

Re:RE: <SEEK MANDATE> -S8M00TIE (ACCIDENT INVOLVING SKL 3462L(OI) & SLM 8919L(TP) ON 25/08/2018]

pls proceed

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)
Sent: Monday, 5 November 2018 9:44 AM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 65771, vehicle number SLM8919L

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: stacey.ng@axa.com.sg [mailto:stacey.ng@axa.com.sg]
Sent: Sunday, 4 November, 2018 11:40 PM
To: admin-d@lkkauto.com
Subject: New message for service request 65771, vehicle number SLM8919L

AXA Insurance has sent you a message for claim number S8M00TIE.

Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

<< **Re:RE: <SEEK MANDATE> -S8M00TIE [ACCIDENT INVOLVING SKL 3462L(OI) & SLM 8919L(TP) ON 25/08/2018]**

Type

🔍 Question

Message

pls proceed

Show

Hsiao Tong (LKKAuto)

From: Desmond Toh <desmondtoh@honda.com.sg>
Sent: Tuesday, 11 December 2018 5:37 PM
To: Hsiao Tong (LKKAuto)
Cc: Jerome Tan; Sum Wai Teck; Winson Chow
Subject: FW: LOD Submission of TPDS - Accident Involving SLM8919L and SKL3462L on 25.08.2018
Attachments: 0713_001.pdf

Your Ref: SKL3462L

Our Ref: SLM8919L

M/s: AXA Insurance Singapore Pte Ltd
C/o: LKK Auto Consultants Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Attn: Hsiao Tong / Case Handler

Dear All,

Above is the attached document for third party direct settlement claim.

Kindly provide us your finalized settlement & payment as your soonest.

Will appreciate your response after receiving this email.

Best Regards
Desmond Toh
Kah Motor Co Sdn Bhd
Website : www.honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended

recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Kah Motor Co. Sdn. Bhd.
A Member of Oriental Holdings Berhad
Body Repair & Paint Centre
6A, Mandai Estate
Singapore 729903
Tel : +65 6841 3838
Fax : +65 6362 5015
www.honda.com.sg

M/s: AXA Insurance Singapore Pte Ltd

Date : 6/12/2018

8 Shenton Way
#27-01
Singapore 068811

Attn: Motor Claims Department

Your ref : SKL3462L

Our ref : SLM8919L

Dear All,

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SLM8919L AND SKL3462L ON 25/08/2018.

We refer to the item(s) marked (✓) below:

- (✓) We refer to your email dated 11/09/2018
- (✓) We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.
- () Kindly forward the discharge voucher for our client's signature within **2 weeks** via email to : desmondtoh@honda.com.sg
- (✓) We return your discharge voucher duly completed.
- (✓) Kindly expedite settlement the following :-
 - Repair Cost **S\$3,000.56 payable to Kah Motor Co. Sdn. Bhd.**
 - Loss of RENTAL

Loss of Use **S\$50.00 X 04days=S\$200.00 payable to OOI SU ZAN**

LTA Search

- (✓) Kindly let us have your cheque made in favour of the above mentioned name(s) for our transmission as soon as possible.
- (✓) Letter of Authority

Thank you.

Yours faithfully,



Ng Sin Hai



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563563 FAX : (065) 62564315

04 SEPT 2018

LIM HWEE SIE
7 WESTLAKE AVENUE
SINGAPORE 574218

Dear Sir/ Mdm

OUR REF : CC4/ASM18015637/pb3
YOUR REF : GA003385/1 (SKL 3462L)
ACCIDENT INVOLVING SKL 3462L AND SLM 8919L ALONG/AT WESTLAKE AVE ON
25/08/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from KAH MOTOR CO SDN BERHAD acting on behalf of the owner of SLM 8919L against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in our favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to chewht@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely


Chew Hsiao Tong
Case Handler
DID: 6742 3197
FAX: 6741 4108
EMAIL: chewht@lkkauto.com

Cc *AXA Insurance Pte Ltd*
(Motor Claims Dept)

LETTER OF AUTHORITY

TO WHOM IT MAY CONCERN

ACCIDENT INVOLVING (OWNER'S VEHICLE NO.) SLM 8919 L &
(THIRD PARTY'S VEHICLE NO.) SKL 3462 L ON 25/8/18
ALONG Westlake Avenue

I hereby authorize Kah Motor Co. Sdn Bhd (Kah Motor) and its agents or any person authorized by Kah Motor to do all or any of the following:

- To submit, resolve and make any claim(s) which I may have against the 3rd party insurers.
- To execute, sign discharge voucher/indemnity forms and all necessary documents in connection with and arising out of the above claim.
- Any payment should be made in favour of my name / Kah Motor Co. Sdn. Bhd.

Suzan
Owner Signature
(Co stamp & authorized signature if is Co registered vehicle)

Name : Ooi Su Zan

NRIC No : S 2511993 B

Vehicle No : SLM 8919 L

Date : 20/9/18



redefining / insurance

CLAIM REF : S8M00TIE
INSURED : LIM HWEE SIE

WITHOUT PREJUDICE

DISCHARGE VOUCHER

We/I, OOI SU ZAN, NRIC NO. S2511993B hereby agree to accept the sum of dollars THREE THOUSAND TWO HUNDRED AND CENTS FIFTY SIX ONLY (\$\$3,200.56) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. SKL 3462L as a result of an accident along WESTLAKE AVENUE on 25/08/2018 which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SLM 8919L.

We/I hereby declare that the said Insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SKL 3462L in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SKL 3462L.

Dated this 18 day of JANUARY 2019

Claimant's Signature : DES

NRIC no./ Company Stamp : KAH MOTOR CO. SDN. BHD.

Occupation/ Business : BODY REPAIR & PAINT CENTRE

Address : 8 MANDAI ESTATE

Telephone No. : SINGAPORE 729905

Witness's Name : DES

Witness's Signature : KAH MOTOR CO. SDN. BHD.

Witness's NRIC No. : BODY REPAIR & PAINT CENTRE

AXA Insurance Pte Ltd (Company Reg. No. 199903512M)
8 Shenton Way, #24-01 AXA Tower, Singapore 068811
Customer Centre #B1-01
Tel: +65 6880 4888 Fax: +65 6338 2522 Website: www.axa.com.sg

**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

6A Mandai Estate, SINGAPORE 729903

Mandai Parts Centre

Phone No. : +65 6841 3838 Fax No. :

AXA INSURANCE S'PORE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer No. : WZA006

Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S80FC1360G

Invoice No. : SINV-BM18001442
Invoice Date : 17/11/18
Order No. : SVO18054621
Reference :
Job Card No. : 09293
Date/Time Received : 07/09/18 / 9:16:36 PM
Licence No. : SLM8919L
Model : JAZZ 1.3LXR CVT 17YM
Car Chassis No. : JHMGK3850HX200447
Car Engine No. : L13B11020302
Mileage : 2347
Service Advisor : NG SIN HAI 1596
Served By : SHNG
Page : 1

No.	Description	Qty.	UoM	U. Price	Disc %	Amount	7% GST Amount	Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:OOI SU ZAN OWNER INSURER:TOKIO ACC DATE:25/08/2018 SURVEYED BY:TAUFIKH DATE:17/09/2018 REF NO: TP INSURER:AXA TP VEH:SKL3462L							
BOSUN	0701 SUNDRIES	1	Hours	30.00		30.00	2.10	32.10
BML02I	0669 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	Hours	180.00		180.00	12.60	192.60
BA02R	0669 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	Hours	180.00		180.00	12.60	192.60
BKBU02R	0669 REPLACE RR BUMPER, REPAIR RR PANEL & OTHER DAMAGE PARTS.	1	Hours	1,120.00		1,120.00	78.40	1,198.40
BP03R	1610 SPRAY PAINTING ON TAILGATE, RR BUMPER & RR PANEL	1	Hours	900.00		900.00	63.00	963.00
04715-T5A-000ZZ	FACERR.BUMPER	1	Each	492.70	25	369.52	25.87	395.39
71593-T5A-000	SPACERR.RR.BUMPER	1	Each	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	Each	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	5	Each	2.00	25	7.50	0.53	8.03

Sum Labor	2,410.00	168.70	2,578.70
Sum Item	394.26	27.60	421.86
Total SGD	2,804.26	196.30	3,000.56
Total Payable (SGD)			3,000.56

Printed by SHNG on 17 Nov 2018 at 8:23:25 AM

This is a computer generated invoice. No signature is required.

Please review your bill and advise us of any errors or omissions.

Kah Motor reserves the right to deliver a subsequent bill for any charge omitted.

GST Amount is calculated from individual line(s)

Please give us your
feedback by scanning
the QR Code using
mobile device.



THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKL 3462L ✓ (Insd veh)	Model:	HONDA JAZZ
	SLM 8919L (TP veh)		
Date of Accident:	25/08/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	10,814.28
Final Repair Cost	:	\$	3,000.56
Loss of Use	:	\$	200.00
Rental (if any)	:	\$	
LTA / GIA Search Fee	:	\$	0.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	3,200.56

Is Third Party Workshop GIA Registered?		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
		22		
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	KAH MOTOR CO.SDN.BHD.	:	\$ 3,200.56

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

28/01/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18015637/T1pb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG		Date : 28-01-2019 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKL 3462L	Veh. Inspected	SLM 8919L
Policy No.	GA003385/1	Coverage (\$)	0.00
Claim No.	S8M00TIE	Excess (\$)	0.00
Assign From		Assign Date	28/08/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA JAZZ	c.c	1318
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMGK3850HX200447	Colour	GREY
Odometer	4098	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/65 R15	GOODYEAR	6 mm
L/H Front Tyre	175/65 R15	GOODYEAR	6 mm
R/H Rear Tyre	175/65 R15	GOODYEAR	6 mm
L/H Rear Tyre	175/65 R15	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR Q/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/08/2018	Inspection Date	17/09/2018
Survey held at	255 ALEXANDRA RD		
Repairer	KAH MOTOR CO SDN BERHAD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 8919L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RUBBER CWINDSHIELD DAMPER (SN) (CONSISTENT)	NOT NECESSARY	8.40	-
2	RUBBERWIDSHIELD DAMPER (SN) (CONSISTENT)	NOT NECESSARY	9.45	-
1	DAMPERSTD 5X5 (SN) (CONSISTENT)	NOT NECESSARY	6.22	-
2	WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
1	TAILGATE COMP (SN) (CONSISTENT)	NOT NECESSARY	537.22	-
1	WEATHERSTRIPTAILGATE (SN) (CONSISTENT)	NOT NECESSARY	69.22	-
1	LOCK ASSYTAILGATE (SN) (CONSISTENT)	NOT NECESSARY	129.90	-
1	STRIKER ASSYTAILGATE (SN) (CONSISTENT)	NOT NECESSARY	18.52	-
1	LINING ASSYTAILGATE LOWER (SN) (CONSISTENT)	NOT NECESSARY	39.07	-
1	POCKETTAILGATE LINING PULL (SN) (CONSISTENT)	NOT NECESSARY	3.75	-
1	EMBLEMRR (SN) (CONSISTENT)	NOT NECESSARY	7.87	-
1	TAILLIGHT ASSY.R. (SN) (CONSISTENT)	NOT NECESSARY	176.32	-
1	FACERR.BUMPER (SN) (CONSISTENT)	DEFORMED	369.52	369.52
1	GARNISHR.RR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	GARNISHL.RR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	SPACERR.RR.BUMPER (SN) (CONSISTENT)	NECESSARY	8.62	8.62
1	SPACERL.RR.BUMPER (SN) (CONSISTENT)	NECESSARY	8.62	8.62
5	CLIPBUMPER (SN) (CONSISTENT)	NECESSARY	7.50	7.50
1	LINING ASSYRR.PANEL (SN) (CONSISTENT)	NOT NECESSARY	45.60	-
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	30.00
			1,686.80	424.26
LABOUR				
INSPECT RR LIGHTING MECHANISMS.PERFORM WATER.			180.00	180.00
REMOVE & RENEW REVERSE SENSORS.			180.00	180.00
REMOVE & INSTALL RR.WINDSCREEN.		NOT NECESSARY	560.00	-
REMOVE .INSTALL & RESET REAR VIEW CAMERA.		NOT NECESSARY	380.00	-
REMOVE & INSTALL REAR COMPARTMENT LININGS.		NOT NECESSARY	560.00	-
REMOVE & TRANSFER ITEMS TO NEW TAILGATE.ADJUST &.		NOT NECESSARY	560.00	-
REPLACE RR BUMPER ,REPAIR RR PANEL & OTHER DA			3,000.00	1,120.00

Report Ref No. CC4/ASM18015637/T1pb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING ON TAILGATE ,RR BUMPER & RR PANEL		3,000.00	900.00
			8,420.00	2,380.00
GRAND TOTAL			10,106.80	2,804.26
RECOMMENDED COST OF REPAIRS				2,804.26

Report Ref No. CC4/ASM18015637/T1pb3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SUMOOTIE
Reference	CC4/AS0418015637/TP0342
Loss Date	25 August 2018
Request Date	28 August 2018
Due Date	
Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next StepWait for Approve Invoice

Auto Progress

Vehicle Information	
Incident Vehicle Registration #	SLM8919L
Make	TPVD HONDA
Model	JAZZ-1.3 (A)
Service Address	
...	
Primary Contact/Insured	
LIM HWEE SIE 19 #02-02, JALAN KILANG BARAT, 159361, Singapore 96655710	
Claim Handler	
NG Stacey 6568804351 stacey.ng@axa.com.sg	





Additional Instructions

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKXInvoice1.pdf	Invoice	Surveyor / Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	28 January 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED:
 payment breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 LKK Inspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 LKK Adjustment 1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 AUTHORIZATION TO ACT FORIM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 WORKSHOP INVOICE.pdf	Invoice	Regular	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2019
 TF ESTIMATE_MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	22 October 2018
 FARE_COE Rebutal.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 October 2018
 LKK Recovery Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 October 2018
 LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 October 2018
 IA with mandated dtd 221018.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 October 2018
 GIA REPORT OF SLMB919L (TP).PDF	Reports & Statement	GIA Report	KADRI Maizeen	28 August 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 GIA REPORT OF SKL3462L (174328).PDF	Reports & Statement	GIA Report	KADRI Muteen	29 August 2018
 EMAIL.jpg	Letters and Correspondence	Others	KADRI Muteen	29 August 2018