

REF:

CS3 | MSG | 8015662 / G240302

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Elaine Ngan

of

MSIG

Date/Time:

28/8/18 @ 10.09 am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FB1354C

Insured:

SKJ 1460R

at Workshop m/s

360 Motor City

Tel:

62626246

of

280 woodlands rd. ES # 04-22

Policy No:

27A 67976 SMP

Claim No:

568258

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17108	2018
-------	------

CA / REV / REP. / REV 24 HRS

(wp)

29/08/2018

H.O.D. Endorsement:

Date/Time:

10.37um @ 28/8/18

Person Contacted:

Erni⁶Vehicle ~~IN~~ OUT[illegible]

PRS

REF: mslh

ASSIGNMENT

From: Date: 29/08/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBJ 354C

at Workshop m/s

of 280 Woodlands Ind Est #04-22

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: FBJ354C Yr Regn: 12 Dec 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha YZF-R15 c.c 150

Colour: white & red A/C: Insured / Std / NI / NA

Sp.Reading: - T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ME11CK044D2006570

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/70-17

R: 140/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or METZELER

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. mm

L/Bal. mm

D.O.A.

D.O.I. 29-08-18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$1500 - \$2500

31/8/18	submit PRS Report -
---------	---------------------

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Aug 2018		28 Aug 2018 10:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SHAHRUDIN BIN CHE' ZAINAL, ID: S6909522D, Tel: +6587775996, Email: SHAH1@SINGNET.COM.SG		
Main Claimant:	TOK JING EN, ID: S9747014F		
Vehicle Reg. No.:	FBJ354C	Date of Loss:	17/08/2018 13:00 - :59 [56 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 568258	Policy/Cover Note No.:	27467976SMP (Comprehensive) Coverage: 22/02/2018 - 21/02/2019
Vehicle Reg. No. (Insured):	SKJ1460R	Policy No. (Claimant):	
		Excess:	
Repairer:	360 Motorcity Pte Ltd (HQ) 280 Woodlands Industrial E5, #04-22 Woodlands @harvest, 757322 Woodlands - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/08/2018]		
Driver/Custodian (Insured):	SHAHRUDIN BIN CHE' ZAINAL (49 / Male), NRIC: S6909522D, Tel: +6587775996		
Adj Asg. Remarks:	LIABILITY: 50%, TP REJECT SJE - ASSIGN LKK AUTO CONSULTANTS PTE LTD CONTACT: 6262 6246/ 98133997 (Ms Reen/Mr Sif) Hp:9844 4411		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18015662/Gz4d3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 28-08-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKJ 1460R	Veh. Inspected	FBJ 354C
Policy No.	27467976SMP	Coverage (\$)	0.00
Claim No.	568258	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	28/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	17/08/2018	Inspection Date	28/08/2018
Survey held at	360 MOTORCITY-280WOODLANDS IND.E5 # 04-22		
Repairer	-		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2018 09:36
Date Of Accident	17/08/2018 13:00
Exact Location Of Accident	WOODLANDS CHECKPOINT TOWARDS JOHOR CHECKPOINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBJ354C
Insured/Policyholder	
Name Of Registered Owner	TOK JING EN
NRIC No	S9747014F
Email Address	LUK_QWERTYN006@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-84289097
Alternative Phone No	OTHERS-84289097

Vehicle Particulars

Manufacturer	YAMAHA
Model	YZF-R15-150CC (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5098812844
Cover Note Number	

Driver

Name of Driver	TOK JING EN
NRIC No	S9747014F
Date Of Birth	13/12/1997
Occupation	INDOOR
Date Of Driving Pass	08/03/2018
Driving Experience	0 YEAR AND 5 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84289097
Fax Number	
Contact Number	OTHERS-84289097
Email Address	LUK_QWERTYN006@HOTMAIL.COM

Address	BLK. 296A COMPASSVALE CRESCENT #15-285
Postcode	541296
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SEMBANWANG NPC
Police Station Address	ROAD: 4 SEMBAWANG CRESCENT , POSTCODE: 757633 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER NOTICE OF COMPLIANCE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ1460R
Vehicle Make/Model/Colour	BMW
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SHAHRUDIN BIN CHE' ZAINAL
NRIC/Passport Number	S6909522D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Y E CYS Automobile Services Pte Ltd
38 Woodlands Industrial Park East
Reporting Centre
Name: Tel: 6219 2098 (Lines) Fax: 6219 2098
NRIC/FIN No.: 58465443

Sketch Plan #2

SKETCH PLAN

A - FB3354C

B - SEJ 146012



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Notice of Compliance

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:



連友威汽車服務私人有限公司
CYS Automobile Services Pte Ltd

38 Woodlands Industrial Park East 1
#07-17 Admiralty Industrial Park

Reporting Centre Personnel's Signature: _____

Name: _____

NRIC/FIN No.:

CONFIDENTIAL

Annex E

NOTICE OF COMPLIANCE

This is to confirm that **Tok Jing En, NRIC/FIN S9747014F**, has reported to the Police a non-injury traffic accident which occurred **Along Woodlands Checkpoint towards Johore Checkpoint**, on **17/08/2018** at **1300hrs**

involving the following vehicles:

- **FBJ354C (COMPLAINANT)**
Name: TOK JING EN, S9747014F, Tel: 84289097
- **SKJ1460R**
Name: SHHRUDIN BIN CHE' ZAINAL, S6909522D, Tel: 87775996

Complainant was riding on the left of the lane most when one vehicle SKJ1460R made a sudden change of lane from the first lane to the third lane. As complainant could not avoid the said vehicle, a collision occurred. Complainant's motorcycle hit onto the front left bumper of the vehicle. The driver told complainant that he was instructed by the ICA officer as to change lane as he was driving on the bus lane. No one was injured and no government property was damaged. Lodging for insurance purposes.

If this accident was reported to the Police within 24 hours of its occurrence,

Then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer **Sgt T140191 Tan Jun Quan**

Date: **18/08/2018** Time: **1210hrs**

S/D Ref: 8

Police Post/Unit: **Sembawang NPC** SEMBAWANG NPC
4 Sembawang Crescent
Singapore 757633
Original – to be issued to informant
Duplicate – to be submitted to Traffic Police
Tel: 1800-6549999
Fax: 68522499

CONFIDENTIAL

Version as of 15 Jan 2002

	SN 085
Signature: _____	
Singapore Police Force	

Tok Jing En
S9747014F
JOK

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S9747014F

Name: TOK JING EN

Birth Date: 13 Dec 1997

Issue Date: 08 Mar 2018

002780894E



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S9747014F

Name: TOK JING EN

卓敬恩

Race: CHINESE

Date of birth: 13-12-1997

Sex: M

Country of birth: SINGAPORE



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2B Motorcycles =< 200 cc

EFFECTIVE DATE

08 Mar 2018

NP 428A



4836146



NRIC No. S9747014F



Date of issue: 02-03-2012

Address: APT BLK 296A COMPASSVALE CRESCENT #15-285 SINGAPORE 541296

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7014F
Vehicle Details	
Vehicle No.:	FBJ354C
Vehicle to be Exported:	No
Intended De-registration Date:	30 Aug 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YZF-R15 MANUAL
Primary Colour:	Red
Secondary Colour:	White
Manufacturing Year:	2013
Engine No.:	1CK4006549
Chassis No.:	ME11CK044D2006570
Maximum Power Output:	-
Open Market Value:	\$2,884.00
Original Registration Date:	12 Dec 2013
First Registration Date:	12 Dec 2013
Transfer Count:	3
Actual ARF Paid:	\$433.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,712.00
COE Rebate Amount:	\$903.00
Total Rebate Amount:	\$903.00

The information contained herein is correct as at 30 Aug 2018

OK



































...CLAIM SUBFOLDER...(Pending for Survey Report)


















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Aug 2018		28 Aug 2018 10:09 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SHAHNURDIN BIN CHE' ZAINAL , ID: S6909522D, Tel: +6587775996, Email: SHAH1@SINGNET.COM.SG									
Main Claimant: TOK JING EN , ID: S9747014F									
Vehicle Reg. No.: FBJ354C		Date of Loss: 17/08/2018 13:00 - :59 [56 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 568258		Policy/Cover Note No.: 27467976SMP (Comprehensive) Coverage: 22/02/2018 - 21/02/2019							
Vehicle Reg. No. (Insured): SKJ1460R		Policy No. (Claimant):							
		Excess:							
Repairer: 360 Motorcity Pte Ltd (HQ) 280 Woodlands Industrial E5, #04-22 Woodlands @harvest, 757322 Woodlands - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 29/08/2018]									
Driver/Custodian (Insured): SHAHRUDIN BIN CHE' ZAINAL (49 / Male), NRIC: S6909522D, Tel: +6587775996									
Adj Asg. Remarks: LIABILITY: 50%. TP REJECT SJE - ASSIGN LKK AUTO CONSULTANTS PTE LTD CONTACT: 6262 6246/ 98133997 (Ms Reen/Mr Sif) Hp:9844 4411									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBJ354C (568258)**
[SKJ1460R]
TP
TOK JING EN
Aug 17 2018 1:00PM
[SHAHKUDIN BIN CHE' ZAINAL]
360 Motorcity Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/08/18 11:42	Accident Statement From: SC - Reg. No: SKJ1460R, Claimant: SHAHRUDIN BIN CHE' ZAINAL	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
2	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
3	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
4	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
5	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
6	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
7	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
8	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
9	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
10	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
11	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
12	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
13	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
14	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
15	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
16	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
17	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
18	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
19	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
20	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
21	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
22	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
23	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
24	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
25	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
26	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
27	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
28	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
29	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
30	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
31	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
32	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
33	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
35	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
36	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
37	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
38	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
39	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
40	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
41	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
42	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
43	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
44	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
45	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
46	31/08/18 12:37	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/08/18 11:42	FBJ354C E-FILE REPORT From: SC - Reg. No: SKJ1460R, Claimant: SHAHRUDIN BIN CHE' ZAINAL	 Load PDF	
2	27/08/18 11:42	TP PRI NOTICE	 Load PDF	
3	27/08/18 11:43	TP PRI REQUEST EMAIL	 Load PDF	
4	27/08/18 11:48	TP REJECT SJE - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015662/GZ4D3E2

Date: 04/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27467976SMP

Claimant Vehicle
No : FBJ354C

Insured Vehicle No : SKJ1460R

Date of Loss: 17/08/2018

Nature of Claim: TP

Claim No: 568258

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBJ354C

Make & Model: YAMAHA YZF-R15, 150cc (M)

Engine No: 1CK4006549

Reg. Date: 12/12/2013 (Man. Year: 2013)

Chassis No: ME11CK044D2006570

Colour: White/Red

Odometer: 0 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70-17

Rear Tyre Size: 140/70-17

Front Left Side: Metzeler 5 mm

Rear Left Side: Metzeler 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/08/2018

Date Inspected: 29/08/2018 Inspected At:

360 Motorcity Pte Ltd (HQ)
280 Woodlands Industrial E5, #04-22
Woodlands @harvest
Singapore 757322

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500.00 -\$2,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 Sep 2018)

Parts: N/A YAMAHA YZF-R15 150cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBJ354C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >