

ASS. REC. BY:

REF:

CS3/FCI18015681/G2403

Special Instruction:

Surveyor
CW/S

GQ

ASSIGNMENT (Office)

From (Person):

griffen

of

FCI

Date/Time:

27/8/18 @ 7:40pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PNN 2564

Insured:

8HA 452D

at Workshop m/s

MS Car Auto

Tel:

97254442

of

8 Kuki Bkt Ave 4 # 01-07

Policy No:

Claim No:

D18006294MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/08/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9:50am @ 28/8/18

Person Contacted:

Desmond

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

PNN 2564-X

SHA 452D-CC3/AIGI 3002040/H/g293y

DOA: 28/11/2013

(08/11/13) wef

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From:

Date: 28/08/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

PNN2564

at Workshop m/s

MS Car Auto

of

8 kaki Bkt Ave 4 # 01-07 premier

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

R2 \$2300

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PNN2564

Yr Regn:

2018 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha

BSLC

c.c

134

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

879

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70/90-17

R:

80/90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

mm

D.O.A.

D.O.I.

28-08-18

Survey held at

w/s

3pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/8/18

Submit PRS Report.

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS3/FCI18015681/Gz4d3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 28-08-2018



Code : FCI2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHA 452D	Veh. Inspected	PNN 2564
Policy No.		Coverage (\$)	0.00
Claim No.	D18006294MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	28/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	21/08/2018	Inspection Date	28/08/2018
Survey held at	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

MOTOR SURVEY ASSIGNMENT

Date	23-08-2018	Our Ref No. D18006294MFSH
Accident Date	21-08-2018	Claim Type. Third Party
Insured Vehicle	SHA0452D	Third Party Vehicle. PNN2564
Survey Location	8 KAKI BUKIT AVE 4#01-07 PREMIER @ KAKI BUKIT	
Contact Person.	MR DESMOND NG	
Contact No.	63851838/ 97254442	Fax No. 63861838
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MS CAR AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	ROY & PARTNERS	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



SINGAPORE POLICE FORCE



T/20180821/7011

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180821/7011

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/08/2018 17:40		Vide Report No.: E/20180821/0052		Station Diary No.:	
Informant's Particulars					
Name of Informant: VIJAYAKUMARI A/P KATHAN			Address: 3 COLEMAN STREET # 04 22 PENI SINGAPORE 179804		
ID Type / ID No.: FIN NO / G6617689X			Contact No.: Home/Office: Mobile: 83547026		
Nationality: MALAYSIAN			Email: raj@volantra.com.sg		
Sex: Female	Age: 40	Date of Birth: 24/01/1978	Type of Informant: Pillion		
Race: Indian			Language: English		Institution / School Name:
Occupation: PRIVATE SECURITY OFFICER			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 21/08/2018 08:15	Type of Location: T-Junction
Location: THOMSON ROAD				
Weather: Sunny		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PNN2564	Motorcycle	YAMAHA	135lc	Blue	Slightly Damaged	2

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180821/7011

2 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180821/7011


CONTINUATION OF REPORT

Pillion			
Name	Saravanan	ID No.	NIL
Related Vehicle	PNN2564 (Motorcycle)	Contact No.	83547026
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	21/08/2018	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious
Pillion			
Name	VIJAYAKUMARI A/P KATHAN	ID No.	G6617689X
Related Vehicle	NIL	Contact No.	83547026
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

We were to go on a straight road a oncoming taxi which wanted to make a right turn came straight and hit onto my motorcycle. The accident area I can remember it's Thomson road but cannot remember the exact location

**SINGAPORE
POLICE FORCE**



T/20180821/7011

3 of 3

Report No. T/20180821/7011

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
MOHAMED HUSNUL TAUFIQ BIN MD YUSOF
Contact No.: 65476358


Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
21/08/2018 17:40

Classification Of Case:



PRE-REPAIR INSPECTION REPORT			
FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CS3/FCI18015681/Gz4d3s2 Date: 30-08-2018	
		Code: FCI2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHA 452D	Veh. Inspected	PNN 2564
Policy No.		Coverage (\$)	0.00
Claim No.	D18006294MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	27/08/2018
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA 135CC	c.c	134
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.		Colour	BLUE
Odometer	879 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	70/90-17	MICHELIN	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	MICHELIN	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.			
5. General Information			
Accident Date	21/08/2018	Inspect Date / Time	28/08/2018 (03:00 PM)
Survey held at	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) MARKET VALUE \$2,300.00			

Report Ref No. CS3/FCI18015681/Gz4d3s2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.