

ASS. REC. HY

REF

CS3/AIG/8015690/1124032

Total Instruction

Surveyor

From Person

Estimated Cost

OD / TP

To Inspect Vehicle No.

at Workshop only

of

Policy No.

Sum Insured

Make of Veh.

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time

Person Contacted

R.O.D. Endorsement

Vehicle IN OUT

Date/Time

Action/Instruction (X) Estimate

Repairer arranged on 29/8/18 as tdy her wheel is full of
vehicle and difficult to sunny.

SKX76A-X

EE71J-X

ASSIGNMENT (Office)

AIG

Date/Time

28/8/18 @ 12:11pm

Bill to

WS / TP RES / OD RES / EVA / INV / MV / CS

SKX 76A

Insured

EE71J

Apex motoring

Tel

90064184

25 Kelki Bkt Rd # 01-55

Claim No.

Excess

D.O.A

02/06/2018

29/08/2018 @ Before 12pm

(up)

Shirley

ASS. REC. BY: Tan

REF: ALG

ASSIGNMENT

From: 29/8/18

Estimated Cost

On: TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: 8KX76A

at Workshop m/s Apex Motoring
of 25 Kaki Bkt Rd 4 # 01-55

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Before 12pm

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Est. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ups

Vehicle: IN / OUT

Date: 12/9/18 Person Contacted: PRS

Veh No: 8KX76A Yr Regn: Jun / 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz CC 1991

Colour: White A/C: Insured / Std / NI / NA

Sp Reading: 3958 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDC2533462F.442770

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R19

R: 235/55R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

R/Bal: 6 mm

L/Bal: 6 mm

D.O.A.

Rear

R/Bal: 6 mm

L/Bal: 6 mm

D.O.I: 24/8/18 @ 2330pm

Survey held at Apex Motoring

Des. of Damages: Frt / Rear / O/S / N/S / D/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction NO GLA

12/9/18 Submit DAR Report

Repair days 3

Torion

12/9/18

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

180

20

200

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 28/8/2018 12:11:37 PM
Attachments:  tmp5ADE.TIF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



27 August 2018

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120
Fax : 6415 3727

Dear Sirs

ACCIDENT BETWEEN VEHICLE NO. SKX 76 A AND VEHICLE NO. EE 71 J ON
02/06/2018 @ 1700 Hrs

We are the appointed repair workshop of vehicle no. SKX 76 A

We understand that you are the insurer of vehicle no. EE 71 J

The owner of vehicle number SKX 76 A has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

The vehicle is now at our workshop awaiting for your inspection at the following address: 25 Kaki Bukit Road 4 #01-55 Synergy@KB Singapore 417800
Mobile No. 9006 4184 / peijie@expresscar.com.sg. Ms Shirley

Yours faithfully





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18015690/T1z4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 28-08-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	EE 71J	Veh. Inspected	SKX 76A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	28/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/06/2018	Inspection Date	29/08/2018
Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the G/A Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 25/08/2018 11:05
Date Of Accident 23/08/2018 17:55
Exact Location Of Accident AYE(TUAS) AT PORTSDOWN ROAD EXIT
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKX76A
Insured/Policyholder LIM CHEE WEE
Name Of Registered Owner S7623590B
NRIC No LCW076@YAHOO COM SG
Email Address (LOCAL) +65-96194055
Mobile Phone No Office-96194055
Alternative Phone No

Vehicle Particulars

Manufacturer MERCEDES-BENZ
Model GLC250

Exact Purpose for which vehicle was being used at time of accident PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken

Vehicle Category THIRD PARTY
PRIVATE CAR

Insurance Company

Name of Insurance Company AVIVA LTD
Type Of Coverage COMPREHENSIVE

Fleet Policy	NO
Policy Number	10844826
Cover Note Number	
Driver	
Name of Driver	LIM CHEE WEE
NRIC No	S7623590B
Date Of Birth	01/08/1976
Occupation	INDOOR
Date Of Driving Pass	25/05/1995
Driving Experience	23 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96194055
Fax Number	
Contact Number	OFFICE-96194055
EMail Address	LCW076@YAHOO.COM SG
Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
	-
	-
	-
Insurance Company of Driver's Own Vehicle	
General Information of the Accident	
Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY
Other Information	
Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Police Station Name

Police Station Address

Police Station Contact

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO: (D/2018024/7008) ON 23/08/2018 I WAS DRIVING MY VEHICLE SKX76A ALONG AYE TOWARDS CLEMENTI DIRECTION. AT ABOUT 5.55PM, A VEHICLE BEARING EE71J SWERVE IN TO MY LANE FROM THE ROAD DIVIDER. THE VEHICLE HIT ON TO THE LEFT SIDE OF MY CAR. I SOUNDED MY HORN TO ASK THE VEHICLE TO STOP, HOWEVER HE SPEED OFF WITHOUT STOPPING. AFTER THE ACCIDENT, MY CAR IS PULLING TO THE RIGHT AND THERE IS A KNOCKING SOUND. THE INCIDENT WAS RECORDED ON MY DASH CAM. I AM LODGING THIS REPORT TO ASK THE POLICE TO INVESTIGATE THE CASE AND ALSO FOR INSURANCE CLAIM PURPOSES.

Attachment(s)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Remarks/ Reasons:

Was there any audio recorded?

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

NO

1

YES

CLEMENTI POLICE DIVISIONAL HQ (D DIVISION)

ROAD, 20 CLEMENTI AVENUE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE

TEL NO: 1800-7740000 - FAX NO: 67741705

NO

YES

YES

WILL UPLOAD TO FILEZILA ONCE INSURED SEND

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

EE71J

MERCEDES BENZ/A45

PRIVATE CAR

UNKNOWN DRIVER



POLICE REPORT



SINGAPORE POLICE FORCE

POLICE REPORT (NP299)

Police Station Of Origin
Clementi Police Divisional HQ
20 Clementi Avenue 5 SINGAPORE 129858
Tel No 1600-7740000



Report No. D/2018/0824/7008

1 of 2

Date/Time Report Made 24/08/2018 11:53	Video Report No.	Station Diary No.
Name Of Informant LIM CHEE WEE	Address APT BLK 28 JALAN LEMPENG #12-06 SINGAPORE 128807	
ID Type / ID No. NRIC NO / S7623590B	Contact No. Home/Office	Mobile 98194055
Nationality SINGAPORE CITIZEN	Email Address jcw076@vodafone.com.sg	
Occupation COMPANY DIRECTOR	Sex Male	Age 42
Institution/School Name	Date of Birth 29/07/1976	Race Chinese
Date/Time Of Incident 23/08/2018 17:55 - 23/08/2018 18:00	Language English	
	Location Of Incident APT BLK 28 JALAN LEMPENG #12-06 SINGAPORE 128807	

Brief details.

On 23/08/2018 I was driving my vehicle SKX76A along AYE towards Clementi direction. At about 5.55PM, a vehicle bearing EE71J swerve in to my lane from the road divider. The vehicle hit onto the left side of my car. I sounded my horn to ask the vehicle to stop, however he speed off without stopping. After the accident, my car is pulling to the right and there is a knocking sound. The incident was recorded on my dash cam. I am lodging this report to ask the police to investigate the cause and also for

Insurance claim purposes.

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:


The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:

24/08/2018 11:53

Classification Of Case:


POLICE REPORT



POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. D201808247008



2 of 2

Subjects Involved

Victim:


Person Name	LIM CHEE WEE	ID No	57623590B
ID Type	NRIC NO	Age	42
Gender	Male	Language	English
Race	Chinese	Address Type	
Occupation	COMPANY DIRECTOR	Mobile No	96194055
Address	APT BLK 2b JALAN LEMPENG		
	#12-06 SINGAPORE 128807		
Is Informant A	Yes		
Victim?			
Person Name	LIM CHEE WEE (Informant)		

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 24/08/2018 11:53
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Driving License

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: S7623590B

LIM CHEE WEE
(LIN ZHRWEI)

Birth Date: 01 Aug 1978
Valid Date: 21 Apr 2003

000412028D



Driving License

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

PASS DATE:

16 Apr 1990
06 Oct 1990
25 May 1990
20 Jun 1990

Class 2B Motorcycles not exceeding 200 cc
Class 2A Motor cycles between 201 cc and 400 cc
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms
Class 4 Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms

License No: S76235308



NP 4284

Identification Card

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7623590B



Name
LIM CHEE WEE
(LIN ZHIWEI)
林志伟

Race
CHINESE

Date of birth
01-08-1976

Sex
M

Country of birth
SINGAPORE





Identification Card



[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3590B
Vehicle Details	
Vehicle No.:	SKX76A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	05 Sep 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLC250 4MATIC COUPE AUTO
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	27492031465910
Chassis No.:	WDC2533462F442770
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$51,815.00
Original Registration Date:	18 Jun 2018
First Registration Date:	18 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$65,267.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jun 2028
PARF Rebate Amount:	\$48,950.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jun 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,000.00
COE Rebate Amount:	\$28,800.00
Total Rebate Amount:	\$77,750.00

The information contained herein is correct as at 05 Sep 2018

OK

MOTOR CAR (LE)

Left Portion

Vehicle No: SKX 76A

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	SCR	✓	
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper LH	SCR	✓	
1006	991325	Frt Bumper Bracket LH	DL	✓	
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender	SCR	✓	
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
		Frt LH wheel arch	DL	✓	
		Frt LH wheel	SCR	✓	

[illegible]

No of Items: 6 Assessor: _____

TỔNG

Una

12/9/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Aug 2018 Edit Reg		28 Aug 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Jeremy Lee Seow Poh (Jeremy Li XiaoBao) , ID: S7145510F, Tel: +6596817989									
Main Claimant: *									
Vehicle Reg. No.: SKX76A		Date of Loss: 23/08/2018 00:00 - :59 [2 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 4096127207SG		Policy/Cover Note No.: 2100448631							
Vehicle Reg. No. (Insured): EE71J		Policy No. (Claimant):							
		Excess:							
Repairer: Apex Motoring () 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 06/09/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (30/08/2018): Request To Upload TP GIA Report - AIG_SG (30/08/2018): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKX76A (4096127207SG)
[EE71J]

TP

-

Aug 23 2018 12:00AM
[Jeremy Lee Seow Poh (Jeremy Li XiaoBao)]
Apex Motoring

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	04/09/18 16:54	General View														Load JPG	☒			
2	04/09/18 16:54	General View														Load JPG	☒			
3	04/09/18 16:54	General View														Load JPG	☒			
4	04/09/18 16:54	General View														Load JPG	☒			
5	04/09/18 16:54	General View														Load JPG	☒			
6	04/09/18 16:54	General View														Load JPG	☒			
7	04/09/18 16:54	General View														Load JPG	☒			
8	04/09/18 16:54	General View														Load JPG	☒			
9	04/09/18 16:54	General View														Load JPG	☒			
10	04/09/18 16:54	General View														Load JPG	☒			
11	04/09/18 16:54	General View														Load JPG	☒			
12	04/09/18 16:54	General View														Load JPG	☒			
13	04/09/18 16:54	General View														Load JPG	☒			
14	04/09/18 16:54	General View														Load JPG	☒			
15	04/09/18 16:54	General View														Load JPG	☒			
16	04/09/18 16:54	General View														Load JPG	☒			
17	04/09/18 16:54	General View														Load JPG	☒			
18	04/09/18 16:54	General View														Load JPG	☒			
19	04/09/18 16:54	General View														Load JPG	☒			
20	04/09/18 16:54	General View														Load JPG	☒			
21	04/09/18 16:54	General View														Load JPG	☒			
22	04/09/18 16:54	General View														Load JPG	☒			
23	04/09/18 16:54	General View														Load JPG	☒			
24	04/09/18 16:54	General View														Load JPG	☒			
25	04/09/18 16:54	General View														Load JPG	☒			
26	04/09/18 16:54	General View														Load JPG	☒			
27	04/09/18 16:54	General View														Load JPG	☒			
28	04/09/18 16:54	General View														Load JPG	☒			
29	04/09/18 16:54	General View														Load JPG	☒			
30	04/09/18 16:54	General View														Load JPG	☒			
31	04/09/18 16:54	General View														Load JPG	☒			
32	04/09/18 16:54	General View														Load JPG	☒			
33	04/09/18 16:54	General View														Load JPG	☒			
34	04/09/18 16:54	General View														Load JPG	☒			
															1 per page		☒			
Documentation																				
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)														Thumbnail	Print			

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 10:09	TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18015690/T1Z4D3E2

Date: 17/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100448631

Claimant Vehicle No: SKX76A

Insured Vehicle No: EE71J

Date of Loss: 23/08/2018

Nature of Claim: TP

Claim No: 4096127207SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX76A

Make & Model: MERCEDES-BENZ GLC250, 2.0 4MATIC COUPE (A)

Engine No: 27492031465910

Reg. Date: 18/06/2018 (Man. Year: 2018)

Chassis No: WDC2533462F442770

Colour: White

Odometer: 3958 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19

Rear Tyre Size: 235/55 R19

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/08/2018

Date Inspected: 29/08/2018 Inspected At:

Apex Motoring

25 Kaki Bukit Road 4, #01-55 Synergy @

KB

Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Scratched	0.00 F	*- F
2	1		*FRT BUMPER LH	Scratched	0.00 F	*- F
3	1		*FRT BUMPER BRACKET LH	Dislodged	0.00 F	*- F
4	1		*FRT LH FENDER	Scratched	0.00 F	*- F
5	1		*FRT LH WHEEL ARCH	Dislodged	0.00 F	*- F
6	1		*FRT LH WHEEL	Scratched	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >