

(08/11/13) wof
ASS. REC. BY: Rose

REF: LER

15702/11 wa3


W
8762B

ASSIGNMENT

From: _____ Date: 30/09/18
Estimated Cost: _____
OP / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SDP 9118D
at Workshop m/s: Performance Motor
of: 303 Alexandra Rd
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record) Before 12pm
Make of Veh: Inthirun

Veh No: SDP 9118D Yr Regn: 2016 / APR
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: B.M.W 528I c.c 1997
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 21943 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WBA 5AS 2000 4390082
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 245/45R8
R: 2

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____
Front: R/Bal. 6 mm L/Bal. 6 mm
Rear: R/Bal. 6 mm L/Bal. 6 mm
D.O.A. 23/08/18 D.O.I. 10/09/18
Survey held at PERFORMANCE
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS (up)
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction

Date/Time, File Pass to? : Preli. Report
1) : Final Report
Date/Time, File Return to?
2) _____
Report Format : _____
Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____
Resurvey No. of Trip: _____
Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	
_____ S + RS, _____ SI	
Photos	
Others	
TOTAL	