INS. CASE OWNER	CL CC4, Asm, 180	15/10/1	1 WA39 1000	6564
Surveyor.	LARM DOI: ASSIGNA		Date / Time: 28	18/18
Pre-assign / CCU	FTE		Registered in Merimen:	-
Insured Vehicle No	tral 427	22000	50m	ro TIN X
# #	No.	Claim No.	- 8	The live
Name of Insured	Lee Sie Kong	Policy No.		
Insured Tel No.	HP:	Make / Model		
Excess Sec II :SS	D.O.A: 26 8 2018	Place of Acciden	1: tu 77	NVU
Is driver the owner	(YES / NO) Nature of Accident :			
If NO, Driver Nan Driver Tel 1		Of GIA REPORT	T: YES / NO : TP GIA REPO	4
5HD 2319	№			
INSRS: WSP. WML Tel: Liability: RMKS:	INSRS: WSP: Tel: Limbility: RMKS:	INSRS: WSP- Tel: Linbility: RMKS:	WS Tel Lini	
Date! Time				
34/6 4	1407318E.Y: EW 477 X		STAGE	DATE/PIC
My wife,			Non-Reporting ltr (1st): Non-Reporting ltr (2sd):	
	BIRP. sont out let letter		Non-Reporting ltr (Final):	
N 10	0 . L. 20. 1 Bect At 00/10.		Notification ltr (if non-pickup) Call Ot	110
	need to get video		3.0	(1/2
selv110			Documentation Check List:	Handler Typist
2119111	RECEIVE IF VIDED . GAD to AXLA		Notification Itr (If non-pickup)	
21/9/18	Seet mardeli VIQ SMART.		After call itr to OE: Authorisation To Act:	2
18/10/8	madel approve no SMART		Raicese Voucher	
10110/19	INSTITUTE ADDITION AND DIMPER		Final Repair Bill Car Rental Invoice:	
			Towing Invoice	
			LTA / GIA	
			Medical Bill	
			PIRC	
			Mandate/Reject Instruction:	
			LOD Payment Breakdown Form:	
PRELIMINARY ADVICE	Date Time: Sent By: \		Post-Repair Photos:	
	20/8 Mu		Others:	
FINALIZATION Parada Conti	Date/Time: Confirm with:		Confirm by:	
Repair Cost: FINAL SETTLEMENT	Date/Time: 23 10 W Confirm with PAlea	- 56	Email	Call
Final Lisbility:	% 100 (Agreed / Assessed) BOLA 5/N No.: 13		Email Call	
Repair Cost:	85 Uppl-00	3	If NO or B 28, Ass. Lin:	
Loss of Rental (LOR):	58 7840.00 (5 days) KH6156.80			
Loss of Use (LOU):	SS (S x days)			IGIVI TILI
Loss of Income (LOI):	55 (\$ x days)		77	18 10
LOR only LOU only GIA/LTA Search	LOR+LOU LOR+LOI Tick only one		1.7	-4 10
Medical:	55		1) Claim status: Normal/Reje	ot/Deisste Canta
Disbursement:	55 (e.g. Tow/ Independent		Report Format:	AN ATTAING DELINE
Legal Cost	SS		3) Survey for	
Total:	68 5387 00 Global Sum SS: 53 50 00			
FINAL PAYMENT	Date/Time: Confirm with:		Email Call	
Payer 1:	53 5350.00 Name 1: Prime Auto	Claims So	ervice the uto	
Payee 2: (Strike if N.A.) Payee 3: (Strike if N.A.)	55 Name 2: 55 Name 3:			
E-179-CALIBRETT N.A.J.	5\$ Nume 3;			

ASSIGNMENT Veh No. SHO 23 18E Yr Regn: 2014 APPL Type: Marr IM-Cycle! Bus I Van I Lorry (Felly Prime Mover! Type: Marr IM-Cycle! Bus I Van I Lorry (Felly Prime Mover! Truck! Trailer or Truck! Trai	SINYRUUT: REF:	62932
Type: M.Car M.Cycle Bus Van Lory Caby Prime Mover Truck Trailer or M.Workshop m's		ASSIGNMENT
Truck/Trailer or Make: Truck/Trailer or Make: Truck/Trailer or Make: Toyota Vettface Make: Toyota Make: Toyot	A PARTY	
Make: DNET VELLFIRE HERE LIVE 25 LE Colour White ACC Insured Std NI NA Sp. Reading TiRadic: Insured Std NI SRIP State Tiradic: Insured Std NI NA Sp. Reading Tiradic: Insured Std NI SRIP State Sta		
Verbrace Source		THE THE PARTY OF THE PROPERTY OF THE PARTY O
Verbrace Source		Make: 104017 VELLYIKE HAPPY C.C. 2566
Eng/No: Collor No. Latins No. Latins No. Latins No. Latins No. Latins No. Gen. Cond: Good 60 Poor / Burnt Steering / Norder Jammed Leaked Burnt or Brake: Increte Jammed Leaked Burnt or Brake: Increte Jammed Leaked Burnt or Brake: Increte Jammed Leaked Burnt or Modi: Nil SRin STD ArRim or Tyre Size: F:	de la constantina de	Colour WKITE NO Insured / Std / NI / NA
Cinc. Arth 208 o 346 o 3 decided Steering Arth 208 o 3 decided	of	
Gen. Cond: Good God Fail Poor Burnt Steering; Afordar Jammed Leaked Burnt or Steering; Afordar Jammed Leaked Burnt or Mod Nill SRM STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tyre Size: F: 24 SR 6 R: A STO Alrim or Tovo / Yoko or A Good Part of All		15 A COVA
Steering Mortal Jammed Leaked / Burnt or Brake. (Client's Record) take of Veh: (Folicy Condition) temank: The veh had commenced its repair at the time of inspection. al. or Market Value: AA / PR Seen: Consistent?: Yes or No Ital / PR Seen: Consistent?: Yes or No St. Repairs: days Res: Yes or No AA / REV / REP. / 24 HRS Vehicle: IN / OUT Date / Time Action / Instruction Action / Instruction Date / Time Action / Instruction Date / Time Action / Instruction Days Of Repair: Resurvey No. of Trip: Transportation: Add Fee: Site Insp / State / Jammed / Leaked / Burnt or Brake / Burnt or Brake / Burnt or Modil: NII / STD AlRim or Tyre Size: F: 2/5 SR L. R: ABS / DUNI / EXNOVA / GY / FS / L. IZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Acre OF HILL R: ABS / DUNI / EXNOVA / GY / FS / L. IZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Acre OF HILL R: BS / DUNI / EXNOVA / GY / FS / L. IZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Acre OF HILL R: BS / DUNI / EXNOVA / GY / FS / L. IZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Acre OF HILL R: ABS / DUNI / EXNOVA / GY / FS / L. IZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Acre OF HILL R: BS / DUNI / EXNOVA / GY / FS / L. IZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Acre OF HILL R: ABS / DUNI / EXNOVA / GY / FS / L. IZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Acre OF HILL R: ABS / DUNI / EXNOVA / GY / FS / L. IZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Acre OF HILL R: ABS / DUNI / EXNOVA / GY / FS / L. IZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Acre OF HILL R: ABS / DUNI / EXNOVA / GY / FS / L. IZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Acre OF HILL R: ABS / DUNI / EXNOVA / GY / FS / L. IZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Acre OF HILL R: ABS / DUNI / EXNOVA / GY / FS / L. IZA / MIC / OHTSU / TOYO / YOK / TO	2	
Brake:	Claims No.	
Mod NII	North Albert Town	
Tyre Size: F: 2/5 SR		
Remark: The veh had commenced its repair at the time of inspection. N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or GOFO P. IDC	Make of Veh:	
Semark: The veh had commenced its repair at the time of inspection. Semark: The veh had commenced its repair at the time of inspection. Semark: The veh had commenced its repair at the time of inspection. Semark: The veh had commenced its repair at the time of inspection. Semark: Toyo / YOKO or		Tyre Size: F: 215/6 SR 16
repair at the time of inspection. TOYO YOKO or A OF OF INTERNATION	(Policy Condition)	R: A
al or Market Value: DAC Accident Rport: DAC A Repairs: DAC Accident Rport: DAC A Repairs: DAC A Repairs: Person Contacted: Date / Time		O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
DAC Accident Rport: Consistent?: Yes or No Ida / PR Seen: Consistent?: Yes or No Ida / Rev / Rep. / 24 HRS Ida / Rev / Rep. / 24 HRS Vehicle: IN / OUT Ida / Time Action / Instruction Ida / Rep Pass to? Preli. Report Days Of Repair: Ida / Report Preli. Report Days Of Repair: Ida / Report Preli. Report Survey Fee: Ida / Re	repair at the time of inspection.	TOYO/YOKO OF GOODRIDE
LBal. D.O.A. 26 ps lt D.O.I. 28 ps lt D.O.I. 2	Bal. or Market Value:	Front Rear
st. Repairs: days Res.: Yes or No sum Sum: % 3 Val.: Yes or No A / REV / REP. / 24 HRS The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction The U/C / Chassis frame / Body Structure affected due to collision. Date / Time File Pass to? Prelii. Report	DAC Accident Rport: Consistent? : Yes or No	R/Bal. R/Bal. 6 mm
Survey held at PRINE AND Des. of Damages : Frt / Rear / O/S / O/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision Date / Time Action / Instruction Survey held at PRINE AND Des. of Damages : Frt / Rear / O/S / O/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision CROSSING AND Des. of Damages : Frt / Rear / O/S / O/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision Date / Time Action / Instruction Date / Time Action / Instruction CROSSING AND Des. of Damages : Frt / Rear / O/S / O/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision CROSSING AND Date / Time File Pass to? Days Of Repair: Survey Fee: Transportation: Transportation: Transportation: Seport Format : Interview (\$) Photos Days Of Repair: Site Insp (\$) S+RS_SI Interview (\$) Photos Days Of Repair: Site Insp (\$) S+RS_SI Difference Site Insp (\$) Photos Days Of Repair: Site Insp (\$) Photos Deport Format : Deport Forma	GIA / PR Seen: Consistent?: Yes or No	L/Bai. 6 mm L/Bai. 6 mm
Survey held at PRINE AND Des. of Damages : Frt / Rear / O/S / O/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision Date / Time Action / Instruction Survey held at PRINE AND Des. of Damages : Frt / Rear / O/S / O/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision CROSSING AND Des. of Damages : Frt / Rear / O/S / O/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision Date / Time Action / Instruction Date / Time Action / Instruction CROSSING AND Des. of Damages : Frt / Rear / O/S / O/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision CROSSING AND Date / Time File Pass to? Days Of Repair: Survey Fee: Transportation: Transportation: Transportation: Seport Format : Interview (\$) Photos Days Of Repair: Site Insp (\$) S+RS_SI Interview (\$) Photos Days Of Repair: Site Insp (\$) S+RS_SI Difference Site Insp (\$) Photos Days Of Repair: Site Insp (\$) Photos Deport Format : Deport Forma	est Repairs: days Res.: Yes or No	D.O.A. 26/88/18 D.O.I. 28/08/18
Des. of Damages: Frt / Rear / O/S / 1/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision. The U/C / Chassis frame / Body Structure affected due to collision. The U/C / Chassis frame / Body Structure affected due to collision. Clouds: The U/C / Chassis frame / Body Structure affected due to collision. Clouds: The U/C / Chassis frame / Body Structure affected due to collision. Clouds:	.um Sum: % 3 Val.: Yes or No	
Action / Instruction The U/C / Chassis frame / Body Structure affected due to collision. The U/C / Chassis frame / Body Structure affected due to collision. The U/C / Chassis frame / Body Structure affected due to collision. Color of the Color of t	A / REV / RED / 24 HRS	Des. of Damages : Frt / Rear / O/S / A/S / U/C / Rooftop or
Date / Time Action / Instruction Instruction Action / Instruction Action / Instruction Instru	Vehicle:	IN / OUT
te/Time, File Pass to? Preli. Report Days Of Repair:	Date / Time Action / Instruction	•
the/Time, File Pass to? Preli. Report Days Of Repair:	21/9/14 Confirm US \$4300-0	to with I worldgdays
the/Time, File Pass to? Preli. Report Days Of Repair:		
: Final Report Resurvey No. of Trip: Survey Fee: Startime, File Return to? Survey Fee:		(20)-\$ (146)
: Final Report Resurvey No. of Trip: Survey Fee: Startime, File Return to? Survey Fee:		184.17
: Final Report Resurvey No. of Trip: Survey Fee: Startime, File Return to? Survey Fee:		
: Final Report Resurvey No. of Trip: Survey Fee: Startime, File Return to? Survey Fee:		
### Resurvey No. of Trip: Survey Fee:	late/Time, File Pass to? : Prell. Report	Days Of Repair:
Add Fee: : Site Insp (\$)S+RS,Si Interview (\$) Photos Photos	: Final Report	
: Interview (\$) Photos	sate/Time, File Return to?	Section of the second section of the second section of the second
eport Format : : Tech. Invs (\$) Others ump Sum / I.B.I: (\$) : Weekend (\$)	Ad	tile and the second sec
ump Sum / I.B.I: (\$)		: Interview (\$) Photos
7 17734310 15	eport Format :	: Tech. Invs (\$) Others
	ump Sum / I.B.I: (\$: Weekend (\$
		TOTAL



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M 6 Benoi Place Singapore 629927 Tel: 6861 0908 Fax: 6515 2948

Date: 27.08.2018

AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01/02 AXA Tower Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO SHD2318E TOYOTA VELLFIRE (2013)

To Supply

1)	1 set	left side mirror assy	S	726.40
2)	1pc	left side mirror outer cover	\$	85.60ML)
3)	1pc	left front triangle glass	\$	290.00 BRO
4)	1pc	left front door	S	1,747.20 requir
5)	1pc	left front door protector	\$	536.005
6)	1pc	left front fender	S	420.00 repair
7)	1pc	left front fender "Hybrid" emblem	S	69.00 men
8)	1pc	front bumper	\$	1,785.00 DE
9)	1pc	front bumper left side retainer	S	92.40 Mer
10)	1set	front bumper clip	S	30.00pe
11)	1pc	left head lamp	\$	920.00 \$ 4

Sub total parts Less: 25% discount	\$ 6,701.60
Less: 25% discount	\$ (1,675.40)
ALLOCATION OF THE PARTY OF THE	\$ 5,026.20

To supply S.Nett Parts

1)	1pc	Prime Royal Limousine' sticker	\$ 80.00
2)	Itube	glass sealant	\$ 35.00
			\$ 115.00

L/charges

1)	Towing charges (use king trolley)	\$	85.00
2)	To remove left front door glass, weatherstrip & mechanism parts	\$	129.00 60
3)	To tuff kote	\$	190.0060
4)	To remove & replace left front fender, left front door, front bumper, knock & repair left rear fender & rear bumper	\$	1,200.00700
5)	To putty, respray painting left front fender, left front door inlet & outer, left rear fender, left rear tail lamp lower panel & rear bumper in pearl white	s	1,890.00 1000

Sub total L/charges \$ 3,305.00 Estimated grand total \$ 8,446.20

LKK Auto Consultants homee notify the Repairer of the following:

- . To resurvey before latter spray pointing
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Wilmout Projudica" basis
- No illegal medification(s) is allowed. Supplementary item(x) must be resurreyed and is subject to final approval from trigutation Company

Acknowledged by Repairer

Signatule:

Para lays 28/08/18 @ 1010
Ray after requir



ISLAND RECUVERY SERVICES
Blk 3026, Ubi Road 1 #04-146 Singapore 408719

Facsimile: 6844 7233 GST Reg.No M90370499P

Telephone: 6747 7400 Email: islandrecovery@ymail.com Web: www.islandrecovery.com.sg Co. Reg. 53120055L

Cash Sales/ Work Order

M/S:	Frank remo	41		
1		odel :	Toyota velta	c
		ne Start:		
To: 6 Pend	ŢTin	ne End:	17 Yo	
Remarks:				
☐ Change Tyres /Jump Start ☐ Basement / Multi Carpark	. D Accident	☐ Use Car (,
Using King Dolley	☐ Crane Up / Winch Out ☐ Dismantle Shaft / Brak		AMOUNT S\$	5.60
• 6	OPY him	APP	TOTAL S\$	85.60
	DIC	FAFE,		75/3.
Received By	mponi	ant Note:	Island Reco	overy Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R) 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

FWD Singapore Pte. Ltd. To:

6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Clara Li Zi Rong Attn:

Date: 30 Aug 2018

Preliminary Advice

Insured Vehicle No : SDQ8898L

TP Vehicle No

: SLZ5222P

Accident Date

25/08/2018

Make

: HYUNDAI ELANTRA

Assignment Date

28/08/2018

Date of Inspection : 29/08/2018

: 3 - 5 days

Est. Duration of Repair

Inspection At

: BH Auto Services Pte Ltd (Sin Ming)

Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117

Singapore 575636

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...rear O/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,097.60
Revised Amount	:S\$	2,939.60
Check Items (Estimated)	:S\$	2,786.40
Total	:S\$	5,726.00

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:5\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

)	The vehicle is repairable at our ad		t. We have	e also c	onfirmed	excess a	and policy	coverage
	Kindly let us have your authorisati	on.						

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: We have not authorized repairs.

LKK AUTO CONSULTANTS PTE LTD (TP) -

Menu



Re:RE: PROCEED DS

Type

Question

Message

Mandate approved

Reply



Prime Auto Claims Service Pte Ltd

Without prejudice

GST Reg. No : 201606560M 6 Benoi Place Singapore 629927 Tel: 6861 0908 Fax: 6515 2948

Date: 10.09.2018

Our Ref: SHD2318E

LKK ref: CC4/ASM18015710/R1wa3

AXA Insurance (S) Pte Ltd No. 8 Shenton Way #27-01 AXA Tower Singapore 068819

Attn: Motor Claims Dept

Dear Sir.

ACCIDENT ON 15.07.2018 INVOLVING VEHICLE NO. SHD2318E & EW42Z

We are on behalf of M/S Prime Car Rental & Taxi Services Pte Ltd owner of SHD318E in their third party claim against your insured / driver of vehicle EW42Z

Appended below our client's claim:-

1.	Cost of repair		\$	4,601.00
2.	Loss of rental @\$156.80 x 5 days		S	784.00
3.	GIA search		S	2.00
		Total	S	5,387.00

We enclosed herewith copy of our Invoice 2462, GIA search, Authorization to Act & Letter of Certification for your retention.

For an amicable direct settlement, please let us have your reply the soonest.

Regards

Yours faithfully.

Ms. Alice Leong

E-mail: aliceleong@primeautoclaims.com

Encl.



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

24 September 2018

LEE SIEW KONG BLK 58 MARINE TERRACE, #05-69, Singapore 440058,

Dear Sir/ Mdm

OUR REF

: CC4/ASM18015710/R1wa3

YOUR REF

: EW 42Z

ACCIDENT INVOLVING EW 42Z & SHD 2318E ALONG ECP ON 26/08/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Prime Auto Claims Service Pte Ltd acting on behalf of the owner of SHD 2318E against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. You intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to Vivianlau@Ikkauto.com within 7 days if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- · Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us 6841 8625 or email us at Vivianlau@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vivian Lau Case Handler DID: 6841 8625

FAX: 6741 4108

EMAIL: Vivianlau@lkkauto.com

c.c. AXA Insurance Pte Ltd (Motor Claims Dept)

AUTHORISATION TO ACT

In the matters of an	accident invo	lving my/o	our motor vi	ehicle	SHO	23186	۶		
And others	EW427							11///	
on 26.08.2018			towards	Town			4		
1/We Prime Car	Rental & T	bui sen	icer Ale.	dd. D/Birth	NA	1000	Sex _	NA	0
Occupation	NA	sing of si	*	Tel No:	'	NI	9		_
Occupation	appoint Pri	me Aut	o Claims	Service	Pto.	Ltd.	to ac	t for me/	us fo
the purpose of makin									
				(2)					
I / We further authori	ze the worksh	op to sett	le my/ our a	bove ment	ioned	claim i	n a ma	anner that	they
deem fit and the wo	rkshop is also	authorize	ed to receive	e any payn	ent f	urther	to set	tiement o	f my
claim with payment c	heque being n	nade in fa	vour of the	workshop o	n my	behalf.			
I / We also knowledge	that any settle	ement the	workshop n	nay reach o	n my,	our be	half is	on a "Witi	hout
Prejudice and without	admission of	liability" t	oasis insofar	as the driv	er/ o	wner/ i	nsure	rs of the o	ther
vehicle is concerned.									
Date	the	day o	of Augus	<u>∤</u> mor	nth of	2018			
201600	SERVER PER				2	()	Total Bally	
nterpreted and witnes	sed by				Sig	nature	or Th	umb Print	
lame:					Na	me:			





CLAIM REF

: 58M00TIW

INSURED

: Lee Siew Kong

DISCHARGE VOUCHER

We/I Prime Car Rental & Taxi Services Pte Ltd hereby agree to accept the sum of dollars Five Thousand Three Hundred Fifty only (SS 5,350,00) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. EW 42Z as a result of an accident along ECP TEDS TOWN on 26/08/2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SHD 2318E.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said insurer, owner and/or driver of vehicle no. <u>EW 42Z</u> in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. EW 42Z.

Dated this 33 No. 2018

Claimant's Signature

NRIC no./ Company Stamp

Occupation/ Business

Address

Telephone No.

Witness's Name

Witness's Signature

Witness's NRIC No.

Dated this 33 No. 2018

CHAN KONG LOONG

STESSOIDEI WORKSHOP MANAGER
NO. 8 BENOL PLACE
BINGAPORE 829926

Witness's Name

Witness's NRIC No.

AXA Insurance Pte Ltd (Company Reg. No. 199903512M) 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 Customer Centre #B1-01

Tel: +65 6880 4888 Fax: +65 6338 2522 Website: www.axa.com.sg

"The contents of this document apply to vehicles damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document"

TAX INVOICE

No: 2462



Prime Auto Claims Service Pte Ltd

6 Benoi Place Singapore 629927 Tel: 6861 0908 Fax: 6515 2948 GST Reg. No: 201606560M Reg No. 201606560M

MESSRS

AXA Insurance (S) Pte Ltd

5/9/2018

Date:_

2421

8 Shenton Way #24-01 AXA Tower Singapore 068811

Vehicle No:

Works Order No:

SHD2318E

	Singapore 068811	Vehicle No:	3H07310F
ITEM	DESCRIPTION	UNIT PRICE	AMOUNT
	Make/Model : Toyota Velifire Repair Date : 26/8/2018 Terms of Payment COD		
	Third Party Claims		
1.	Being lump sum repair to the above vehicle.		5 4,300.00

* Compound interests at the rate of 1% per month will be charged on late payment.

SUB TOTAL

5 4,300.00

GST7%

5 301.00

TOTAL

\$ 4,601.00

Prepared by

Prime Auto Claims Service Pte Ltd

Manager



Prime Taxi Office 5, Benoi Place 5, Benoi Place Singapore 629926 Tel: 6898 2000 Fax: 6862 2628

Email: primetaxi@singnet.com.sg Website: www.primetaxi.com.sg

Co. Cert. No: 199606293Z Gst Reg. No: 19-9606293-Z

Your Ref: Please advise

Our Ref: SHD2318E

Date

: 30.08.2018

To

: Whom It May Concern

From

: Prime Car Rental & Taxi Services Pte Ltd

RE: LETTER OF CERTIFICATION FOR MR. LIM JINGXIANG LORENZO

This letter serves to confirm that Mr. Lim Jingxiang Lorenzo, Nric Number S8012156C is a Taxi Master for Prime Car Rental & Taxi Services Pte Ltd hiring the Vehicle Registration Number SHD2318E for Singapore Dollar One Hundred and Fifty Six and Cents Eighty (\$156.80) Only.

Should clarification require I can be contacted at 94524182.

Thank you with Best Regards

Yours Sincerely

CHAN KONG LOONG 876301061

WORKSHOP MANAGER NO. 5 BENOL PLACE SINGAPORE 629926

Mr Chan Kong Loong Workshop Manager



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No:

GR-18-131527

Date of Request:

27/08/2018

Your Ref No:

Online Purchase

Prime Auto Claims Service Pte Ltd

6 Benoi Place Singapore 629927

Dear Sir/Madam,

Enquiry Date

27/08/2018

Enquiry By

Chrissy Teo Ye En

TP Vehicle No.

EW42Z

ccident Date

26/08/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Inc. Total
EW42Z	AXA Insurance Pte Ltd	20/01/2018-19/01/2019	Insurer Tel. No.
		20/01/2010-13/01/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-18-131527

Date of Request:

27/08/2018

Your Ref No:

Online Purchase

Prime Auto Claims Service Pte Ltd

6 Benoi Place Singapore 629927

Dear Sir/Madam,

Enquiry Date

27/08/2018

Enquiry By

Chrissy Teo Ye En

TP Vehicle No.

EW42Z

cident Date

26/08/2018

DESCRIPTION	
TP Insurer Enquiry	AMOUNT (S\$)
GST Amount	1.87
Total Amount Due (GST Inclusive)	0.13
(Solit Ede (Solit Hiddsive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	EW 42Z (I	nsd veh)	Model:	TOYOTA	A VELLFIRE
	SHD 2318E	(TP veh)		HYBRID	2.4X A
Date of Accider	nt: 26/08/2018				15.
Global Sum Set	tlement : [X] Yes	1] No	1	
Repair Estimate		: \$	9,037.4	3	
inal Repair Cos	st	: \$	4,601.0	0	
oss of Token S	um	: \$		day	s at \$0.00 per day
Rental (if any)		: \$	784.0	5 days	3
TA / GIA Searc	h Fee	: \$	2.00	o	
Others:		: \$	0.00		
		\$		1	
inal Settlement	Sum (Global Sum)	: \$	5,350.00		
s Third Party V elow)	Vorkshop GIA Registere	d? [] YES	[X] NO	(Kindly indicate
A) For Non GI	A Registered Workshop	:	Agreed Liability	/100	(%)
B) For GIA Re	gistered Workshop:		BOLA Applicat	ole: Yes/ No B	OLA Scenario No:
BOLA Liabil	lity:(%)		Assessed Liabi	ility (*):	(%)
* Assessed	Liability to be filled only fo	or chain co	illisions and for	cases where BO	OLA does not apply.
Remarks					
ayment Instru	ction: Payee's Breakdov	vn			
THE RESERVE OF THE PARTY OF THE	O CLAIMS SERVICE PT		: \$		5,350.0
JOANN	E LEE KHANG MIN		14/11/2018		
	Consultante Die Ltd		Date		

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internati		
AXA INSURANCE PT	E LTD	Ref : CC4/ASM1801	5710/R1wa3q2
8 SHENTON WAY #2 AXA TOWERSINGAP ATTN:CYNTHIA LOH	ORE 068811	Date: 14-11-2018	
1.		:- THIRD PARTY CLAI	M
Insured Veh.	EW 42Z	Veh. Inspected	SHD 2318E
Policy No.	GA008098	Coverage (\$)	0.00
Claim No.	S8M00TIW	Excess (\$)	0.00
Assign From	100	Assign Date	28/08/2018
2.	Vehicle Part	iculars & Condition	Li de la constitución de
Make & Model	TOYOTA VELLFIRE HYBRID 2.4X A	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	ATH208034603	Colour	WHITE
Odometer	150	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3.	Condit	tions of Tyres	
	Size	Make	Balance
R/H Front Tyre	215/65 R16	GOODRIDE	6 mm
L/H Front Tyre	215/65 R16	GOODRIDE	6 mm
R/H Rear Tyre	215/65 R16	GOODRIDE	6 mm
L/H Rear Tyre	215/65 R16	GOODRIDE	6 mm
	Descript	ion of Damages	
THE VEHICLE SU DAMAGES SEE D	JSTAINED DAMAGES AT THE NA DETAILS.	S BODY.	
5.	Genera	al Information	A PROPERTY OF STREET
Accident Date	26/08/2018	Inspection Date	28/08/2018
Survey held at	PRIME AUTO CLAIMS SERVICE	E PTE LTD	
	6 BENOI PLACE SINGAPORE 629927	<	
Sa.		lemarks	
A)THE INSPECTION B)IN ACCORDAN	ON WAS CONDUCTED ON A"WI" CE TO YOUR INSTRUCTIONS, V	THOUT PREJUDICE" BAS VE HAVE NOT AUTHORIS	IS. ED REPAIRS.
5b.		Days of Repair	
	MAL PERIOD FOR REPAIR:	7 Working Day	5



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 2318E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SET LEFT SIDE MIRROR ASSY (CONSISTENT)	BROKEN	726.40	726.40
1	LEFT SIDE MIRROR OUTER COVER (CONSISTENT)	MISSING	85.60	85.60
1	LEFT DOOR TRIANGLE GLASS (CONSISTENT)	BROKEN	290.00	290.00
1	LEFT FRONT DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	1,747.20	19
1	LEFT FRONT DOOR PROTECTOR (CONSISTENT)	SCRATCHED	536.00	536.00
1	LEFT FRONT FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	420.00	ğ
1	LEFT FRONT FENDER -'HYBRID' EMBLEM (CONSISTENT)	NECESSARY	69.00	69.00
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,785.00	1,785.00
1	FRONT BUMPER LEFT SIDE RETAINER (CONSISTENT)	NECESSARY	92.40	92.40
1	SET FRONT BUMPER CLIP (CONSISTENT)	NECESSARY	30.00	30.00
1	LEFT HEAD LAMP (CONSISTENT)	SCRATCHED	920.00	920.00
	LESS 25% DISCOUNT		-1,675.40	-1,133.60
			5,026.20	3,400.80
	SPECIAL NETT ITEMS			
1	PRIME ROYAL LIMOUSINE STICKER (SN) (CONSISTENT)	NECESSARY	80.00	80.00
1	TUBE GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	35.00	35:00
		The second secon	115.00	115.00
	LABOUR			
	TOWING CHARGES (USE KING TROLLEY).		85.00	85.00
	TO REMOVE LEFT FRONT DOOR GLASS ,WEATHERSTRIP & MECHANISM PARTS.		120.00	60.00
	TO TUFF KOTE.		100.00	60.00
	TO REMOVE & REPLACE LEFT FRONT FENDER , LEFT FRONT DOOR , FRONT BUMPER , KNOCK & REPAIR LEFT REAR FENDER & REAR BUMPER . INCLUSIVE OF THE REPAIR OF LEFT FRONT DOOR AND LEFT FRONT FENDER .		1,200.00	700.00

Report Ref No. CC4/ASM18015710/R1wa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PUTTY, RESPRAY PAINTING LEFT FRONT FENDER , LEFT FRONT DOOR INLET & OUTER , LEFT REAR FENDER , LEFT REAR TAIL LAMP LOWER PANEL & REAR BUMPER IN PEARL WHITE.		1,800.00	1,000.00
	AS ASSAULT OF THE CONTROL OF THE PROPERTY OF THE CONTROL OF THE CO		3,305.00	1,905.00
	GRAND TOTAL		8,446.20	5,420.80

RECOMMENDED COST OF LUMP SUM REPAIRS	4,300.00
(TO ITS PRE-ACCIDENT CONDITION)	10.52A72.032

Report Ref No. CC4/ASM18015710/R1wa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatacever, in contact or turt, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

SERVICE REQUESTS

*

MESSAGES

CLABMS

Service Request Details



cynthia.loh@axa.com.sg. NON-REPORTED

Notes

Metrics

Assessment

Documents

History

Bryoices

Messages

Additional Instructions

Claim Handler

6568804843 LOH Cynthia

			SAB-TYPE.
Document SubType			THE
Document Type	•	4 Uthrod Documenty	HADAE

UNCADED

AUTHOR

LICK AUTO CONSULTANTS PTE. LTD ITP!

Surveyor/ Assessor expense

psycice

Liddinyoler1 (9).pdf

20
10
8
8
E
III.
굎
푠
22
20
æ.
炽
T
*
ã
E
2
ž
10
3
0
2
ď.
Ö
5
ĕ
in
S
類
10
3
0
2
T.
ō
5
ä
jā.
蓷
E
Ħ
10
sts.
ests.
dnests.
equests.
-requests.
ce-requests.
vice-requests.
ervice-requests.
service-requests.
r-service-requests.
for-service-requests.
ndor-service-
ndor-service-
ndor-service-
ex-vendor-service-requests.
ndor-service-
idex-vendor-service-
ndor-service-
idex-vendor-service-
tml/index-vendor-service-
idex-vendor-service-
tml/index-vendor-service-
tml/index-vendor-service-
tml/index-vendor-service-
-portal/html/index-vendor-service-
tml/index-vendor-service-
aim-portal/html/index-vendor-service-
g/claim-portal/html/index-vendor-service-
sg/claim-portal/html/index-vendor-service-
sg/claim-portal/html/index-vendor-service-
om.sg/claim-portal/html/index-vendor-service-
.com.sg/claim-portal/html/index-vendor-service-
a.com.sg/claim-portal/html/index-vendor-service-
axa.com.sg/claim-portal/html/index-vendor-service-
axa.com.sg/claim-portal/html/index-vendor-service-
s.axa.com.sg/claim-portal/html/index-vendor-service-
ims.axa.com.sg/claim-portal/html/index-vendor-service-
s.axa.com.sg/claim-portal/html/index-vendor-service-
claims.axa.com.sg/claim-portal/html/index-vendor-service-
artdaims.axa.com.sg/claim-portal/html/index-vendor-service-
martclaims.axa.com.sg/claim-portal/html/index-vendor-service-
smartclaims.axa.com.sg/claim-portal/html/index-vendor-service-
rp.smartclaims.axa.com.sg/claim-portal/html/index-vendor-service-
martclaims.axa.com.sg/claim-portal/html/index-vendor-service-

3446	201	SUB-TITE	млюя	UNCADED
RENTAL RECEIPT pull	Forms / Claim Documents	Open	LKK AUTO CONSULTANTS PTE LTD (TP)	15 November 2018
payment breakdown.pdf	Forms / Claim Documents	Others	LICK AUTO CONSULTANTS PTE LTD (TP)	15 November 2018
■LOD pell	Forms / Claim Documents	Others	LISK AUTO CONSULTANTS PTE LTD (TP)	15 November 2018
LiOchrapection CD pair	Forms / Claim Decuments	Others	LKK AUTO CONGULTANTS PTE LTD (TP)	15 November 2018
LXXAdjutmentta (6).pdf	Forms / Claim Documents	Offers	LICK AUTO CONSULTANTS PTE LTD (TP)	15 November 2018
LIOK PHOTO-2 polf	Forms / Claim Documents	Others	LICK AUTO CONSULTANTS PTE LTD (TP)	15 November 2018
GIA SEARCH pitt	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 November 2018
DISCHARICE VOUCHER pair	Forms / Claim Documents	Satisfaction / Discharge Vaucher	LICK AUTO CONSULTANTS PTE LTD (TP)	15 November 2018
AUTHORISATION TO ALT FORMupel	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	15 Nivember 2018
WORKHOP INVOICE pat	Propice	Repairer	LICK AUTO CONSULTANTS PTE LTD (TP)	15 November 2018
LETTER TO OLD OF	Letters and Correspondence	Palicy Holders / Insured	LICK AUTO CONSULTANTS PTE LTD (TP)	15 November 2018
LICK Inspection Photos.pdf	Forms / Claim Documents	Others	LIKE AUTO CONSULTANTS PTE LTD (TP)	21 September 2018
AXA Mandate, SHD 2318E petr	Reports & Statement	Others	LICK AUTO CONSULTANTS PTE LTD (TP)	21 September 2018
SHD 2318EMP4	Evidence	Videos	LICK AUTO CONSULTANTS PTE LTD (TP)	21 September 2018

w	
8	
ö	
5	
H	
Ī	
-5	
99	
10	
E	
ber=6	
E	
₹	
10	
Sedue	
Redu	
1	
200	
99	
Ps C	
sts/	
Sa	
3	
8	
Ŕ	
Σ	
98	
á	
E	
- 75	
-	
sts.	
uests.h	
dues	
-requests.h	
ce-redues	
dues	
service-reques	
rvice-redues	
ndor-service-reques	
vendor-service-reques	
ex-vendor-service-reques	
vendor-service-reques	
ex-vendor-service-reques	
tml/index-vendor-service-reques	
html/index-vendor-service-reques	
html/index-vendor-service-reques	
oortal/html/index-vendor-service-reques	
oortal/html/index-vendor-service-reques	
laim-portal/html/index-vendor-service-reques	
laim-portal/html/index-vendor-service-reques	
laim-portal/html/index-vendor-service-reques	
om.sq/claim-portal/html/index-vendor-service-regues	
.com.sq/claim-portal/html/index-vendor-service-regues	
om.sq/claim-portal/html/index-vendor-service-regues	
.axa.com.sq/claim-portal/html/index-vendor-service-reques	
ms.axa.com.sq/claim-portal/html/index-vendor-service-reques	
laims.axa.com.sq/claim-portal/html/index-vendor-service-reques	
laims.axa.com.sq/claim-portal/html/index-vendor-service-reques	
martclaims.axa.com.sq/claim-portal/html/index-vendor-service-reques	
artolaims.axa.com.sq/claim-portal/html/index-vendor-service-reques	
martclaims.axa.com.sq/claim-portal/html/index-vendor-service-reques	

	E	348-7795	млноя	UNIONOED
GIA REPORT, SLK729G PDF	Reports & Statement	GIA Report	LOH Cynthia	21 September 2018
TP GA_SHD2318E.PDF	Reports & Statement	GIA Report	LOH Cynthia	21 September 2018
OLGIA HEPORT POF	Reports & Statement	GIA Report	LICK AUTO CONSULTANTS PTE LTD (TP)	5 September 2018
TP ESTINATE + TOWING adt	Reports & Statement	Estimate / Quotation	LICK AUTO CONSULTANTS PTE	31 August 2018
PRI CMAIL FROM WORKSHIOP WITH TP CIA. SHDZJIBE mig	Forms / Claim Documents	Others	KUMAR Skallendra	26 August 2018
thr to insured mon regulating pull	Letters and Correspondence	Policy Holders / Imazed	LIKE AUTO CONSULTANTS PTE. LTD (TP)	ZB August 2018