

ASS. REC. BY:

REF:

CS/FCI 18015719/Nqd3

Special Instruction:

SC

Surveyor:

Nq2

ASSIGNMENT (Office)

From (Person):

Lemene Jw

of

PEI

Date/Time:

21/8/18 5.42pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJA 536Y

Insured:

SHA 8104G

at Workshop m/s

Zhong Cheng

Tel:

9338 2859

/ 9206 777 Vincent

of

31k 6 woodlands rd Yew Tee Ind. Est 399J

Policy No:

Claim No:

D18006214 MP8H

Sum Insured:

Excess:

Make of Veh:

D.O.A. 17/08/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

up)

H.O.D. Endorsement:

Date/Time:

10.27am @ 23/8/18

Person Contacted:

Ms. Sini

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJA 536Y-X
	SHA 8104G-CC3/AIG/6023947/H/yg392 DOA: 12/12/16
23/8/18 @ 2.41pm	Informed Wayne, we are pending estimate from repairer.
08/10/18 @ 5.50pm	checked with Vincent, the estimate not yet ready;
21/1/19 @ 3.06pm	revised to Fci by email.
	MV: # 606644; UTA: # 46405(24); NV: # 13535

(08/1/13) wof

ASS. REC. BY:

NAZ

REF:

FCI

SC

ASSIGNMENT

From:

Date:

23/8/18

Estimated Cost:

OP ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJA 536Y

at Workshop m/s

zhong cheng

of

81K 6 woodlands Rd Yew Tee Ind.

Insured:

399J

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Ms. Sini @ 9338 2859

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

cup

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJA 536Y

Yr Regn:

27 NOV 2017

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

MERCE C180

c.c 1,796

Colour

BLACK

A/C:

☒ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading

113,307

T/Radio:

☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No:

C/No:

WDD2040462 A075313

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / S/Rim / ☒ STD / ☐ Rim or

Tyre Size:

F:

225/40 R18

R:

225/35 R18

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

17/8/18

D.O.I.

23/8/18

Survey held at

ZHONG CHENG

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/1/19

FINALIZED LUMP SUM REPAIR \$6350.00 / 4 DAY.
(Red @ 10757.30, 63%)

RECEIVED 22 JAN 2019

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

4

1) 20/1/19

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

6350

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

7x15=105

170+105

50

20

345

PIF

[Signature]

21/1/2019



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015719/Nqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 8104G	Veh. Inspected	SJA 536Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18006214MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	29/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/08/2018	Inspection Date	23/08/2018
Survey held at	ZHONG CHENG ENTERPRISE BLK 4 YEW TEE IND 393-H WOODLANDS ROAD SINGAPORE 677969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	20-08-2018	Our Ref No. D18006214MFSH
Accident Date	17-08-2018	Claim Type. Third Party
Insured Vehicle	SHA8104G	Third Party Vehicle. SJA536Y
Survey Location	BLK 6 WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE 399J	
Contact Person.	MR TAN	
Contact No.	98264959/ 98264959	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ZHONG CHENG ENTERPRISE	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 21 January 2019 3:06 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006214MFSH/1
Attachments: CSFCI18015719Nqd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SJA 536Y.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 29 August 2018 2:41 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006214MFSH/1

Dear Lurene,

Please be informed that we have inspected the vehicle SJA 536Y on 23/08/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 23 August 2018 10:28 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006214MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006214MFSH

Date: 21 January 2019

Our Ref: CS/FCI18015719/Nqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJA 536Y .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 23/08/2018 at the premises of M/s ZHONG CHENG. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>17,107.30</u> .
Revised Estimate Amount	: S\$ <u>6,350.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the o/s front portion.



Yours faithfully

Taufikh
Automotive Assessor

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 29 August 2018 2:41 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006214MFSH/1

Dear Lurene,

Please be informed that we have inspected the vehicle SJA 536Y on 23/08/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 23 August 2018 10:28 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006214MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 21 August 2018 5:42 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006214MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team

> Back to OneMotoring

D.O.A. 17/8/2018
Bal : 9 yrs 3.3 mths.
M.V. \$60K

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7170F
Vehicle Details	
Vehicle No.:	SJA536Y
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180K
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	27195230977564
Chassis No.:	WDD2040462A075313
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$36,777.00
Original Registration Date:	27 Nov 2007
First Registration Date:	27 Nov 2007
Transfer Count:	1
Actual ARF Paid:	\$40,455.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Nov 2027
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$50,168.00
COE Rebate Amount:	\$44,370.00
Total Rebate Amount:	\$44,370.00

The information contained herein is correct as at 22 Jan 2019

OK

$$\begin{aligned} \text{PARF} &= \text{NIL} \\ \text{COE} &= \text{OP} \times \frac{\text{bal mths}}{10 \text{ yrs}} \\ &= 50168 \times \frac{111}{120} \\ &= 46405.40 \\ \text{LTA} &= \text{PARF} + \text{COE} \\ &= 46405.40 \end{aligned}$$

$\approx \text{LTA} = 46405$

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/08/2018 11:21
Date Of Accident	17/08/2018 21:35
Exact Location Of Accident	PIE B4 PAYA LEBAR EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJA536Y
Insured/Policyholder	
Name Of Registered Owner	GOH HAN LANG
NRIC No	S1217170F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-85881481
Alternative Phone No	OFFICE-85881481

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5082373185-01(CLASSIC)
Cover Note Number	

Driver

Name of Driver	GOH TIAN YAN
NRIC No	S9510448G
Date Of Birth	23/03/1995
Occupation	INDOOR
Date Of Driving Pass	18/07/2014
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85881481
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 419 CHOA CHU KANG AVE 4 #09-310
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ---
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA8104G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg




Policyholder's Signature
Date & Time:

 18/08/18
11:57am

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The Accident happened on 17/08/18, 21:37 at PIE towards Changi, Exact location is at before exit of paya lebar. I, Goh TIAN YUAN was sending off my girlfriend back home from CHOA CHU KANG to Bedok. I was at the second lane of the expressway driving around 70km/h, during that time a taxi number plate (SHA8104G), came out from lane one from right side, it turn into ~~my~~ the lane I'm driving in a very fast pace, and both of our car got clash. The impact was quite big, it caused my hands slipped off from the steering wheel and hit the car key that is insert into the car. My vehicle has a dent above right side of the wheel, ~~there~~ there are scratched at the below the head light and the right side rim been scratched as well. I took the third party information & both vehicle condition. I told the driver to wait for a moment ^{cause} ~~because~~ I was making a call, But the moment I turn ~~I~~ around the taxi just drove off. Then I noticed I had a injuries on my right ~~arms~~ arms caused by the impact and the car key was broken in half. Half of the key is inserted in the car, until I ~~reached~~ reached the destination that I supposed to go, I turn off the engine and noticed can't be turn back on again. ~~So~~ So I called for ~~the~~ help & the tow truck came on 12:13am at Chai chee drive Block 55.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

18/08/18

11:37 am

IDAC BUKIT BATOK (VAC)

511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SJA536Y

Estimate - Parts(s)

S/N	Qty	Descriptions	Amount
-----	-----	--------------	--------

LIST ITEMS:-

1	1	FR fender RH ✓	\$ 842.15 /DD
2	1	FR fender innershield ✓	\$ 175.50 ?/TN
3	1set	FR fender innershield clips	\$ 56.00 ?XSVL
4	1	side mirror RH	\$ 288.00 ?XSVL
5	1	side mirror cover RH	\$ 206.90 ?XSVL
6	1	side mirror signal lamp	\$ 193.90 ?XSVL
7	1	side mirror assy	\$ 1,270.00 ?XSVL
8	1	seal mirror	\$ 75.00 ?XSV
9	1	FR bumper ✓	\$ 1,488.50 XR/CR
10	1	FR bumper retainer ✓	\$ 45.00 ?/CRK
11	1set	Fr bumper clips ✓	\$ 36.00 ?/NE
12	1	Fr bumper bracket ✓	\$ 87.50 ?/BT
13	1	Fr bumper reinforcement	\$ 625.90 ?XSVL
14	1	Fr bumper sponge ✓	\$ 185.50 ?/DL
15	1	FR bumper logo	\$ 112.50 ?/NE
16	1	Headlamp ✓	\$ 2,875.50 /CRK
17	1set	Headlamp fasteners	\$ 321.85 ?/NE
18	1	Headlamp bracket ✓	\$ 155.50 ?/BT
19	1	Fog lamp ✓	\$ 395.80 ?/CR
20	1	Fog lamp cover ✓	\$ 95.50 ?/CR
21	1	Lower arm RH	\$ 578.50 ?XSVL
22	1	Knuckle arm RH	\$ 469.50 ?XSVL
23	1	Disc rotor RH	\$ 335.00 ?XSVL
24	1	Suspension RH	\$ 525.60 ?XSVL
25	1	Fr support panel	\$ 635.90 ?XSVL
26	1	Bonnet	\$ 1,420.00 ?X R
			\$ 13,497.00

\$6319 45

Less 10%

\$ 1,349.70

\$5687.50

\$ 12,147.30

Special Nett Item

1 FR rim

350

\$

450.00 / cut

2 FR tyre

\$

350.00 xsv

3 Car Key

\$

680.00 ? BR

\$1,030

Estimate - Labour(s)

S/N	Qty	Descriptions	Amount
-----	-----	--------------	--------

B/F

LABOUR & OTHER CHARGES:-

1		To panel beat and renewal of all necessary damaged body parts	\$ 1,100.00 500
2		To check wiring and rewire	\$ 120.00 50
3		To remove & refix radiator/condenser for checking	\$ 240.00 X NN
4		Towing	\$ X ^{not towed} 200.00 ? show receipt
5		To anti-rust	\$ 140.00 50
6		To putty and spray-paint of affected areas	\$ 1,400.00 600
7		To reset fault code	\$ 180.00 50
8		To perform wheel alignment	\$ 100.00 ? X NN
			1250
			<hr/>
			\$ 3,480.00

NAZ LKK
23/8/18
PIP
4 DAYS
CHECK ITEM PHOTO
BEFORE PAINT PHOTO


14/1/19

PARTS \$6319.45
LESS 10% \$5687.50
SINNET \$1030.00
LABOUR \$1250.00
TOTAL \$7967.50
LESS L/S 20% \$6374.00
L/S TOTAL \$6350.00 / 4 DAY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Grand - Total \$ -

17102-30




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015719/Nqd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8104G	Veh. Inspected	SJA 536Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006214MFSH	Excess (\$)	0.00	
Assign From	LURENE JAW	Assign Date	21/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180K	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	WDD2040462A075313	Colour	BLACK	
Odometer	113307	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
L/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
R/H Rear Tyre	225/35 R18	GOODYEAR	6 mm	
L/H Rear Tyre	225/35 R18	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/08/2018	Inspection Date	23/08/2018	
Survey held at	ZHONG CHENG ENTERPRISE BLK 4 YEW TEE IND 393-H WOODLANDS ROAD SINGAPORE 677969			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 536Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FR FENDER RH	DENTED	842.15	842.15
1	FR FENDER INNERSHIELD	TORN	175.50	175.50
1	SET FR FENDER INNERSHIELD CLIPS	SERVICEABLE	56.00	-
1	SIDE MIRROR RH	SERVICEABLE	288.00	-
1	SIDE MIRROR COVER RH	SERVICEABLE	206.90	-
1	SIDE MIRROR SIGNAL LAMP	SERVICEABLE	193.90	-
1	SIDE MIRROR ASSY	SERVICEABLE	1,270.00	-
1	SEAL MIRROR	SERVICEABLE	75.00	-
1	FR BUMPER	CRACKED	1,488.50	1,488.50
1	FR BUMPER RETAINER	CRACKED	45.00	45.00
1	SET FR BUMPER CLIPS	NECESSARY	36.00	36.00
1	FR BUMPER BRACKET	BENT	87.50	87.50
1	FR BUMPER REINFORCEMENT	SERVICEABLE	625.90	-
1	FR BUMPER SPONGE	DISTORTED	185.50	185.50
1	FR BUMPER LOGO	NECESSARY	112.50	112.50
1	HEADLAMP	CRACKED	2,875.50	2,500.00
1	SET HEADLAMP FASTENERS	NECESSARY	321.85	200.00
1	HEADLAMP BRACKET	BENT	155.50	155.50
1	FOG LAMP	CRACKED	395.80	395.80
1	FOG LAMP COVER	CRACKED	95.50	95.50
1	LOWER ARM RH	SERVICEABLE	578.50	-
1	KNUCKLE ARM RH	SERVICEABLE	469.50	-
1	DISC ROTOR RH	SERVICEABLE	335.00	-
1	SUSPENSION RH	SERVICEABLE	525.60	-
1	FR SUPPORT PANEL	SERVICEABLE	635.90	-
1	BONNET	TO REPAIR SEE LABOUR	1,420.00	-
	LESS 10% DISCOUNT		-1,349.70	-631.95
			12,147.30	5,687.50
<u>SPECIAL NETT ITEMS</u>				
1	FR RIM (SN)	CUT	450.00	350.00

Report Ref No. CS/FCI18015719/Nqd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FR TYRE (SN)	SERVICEABLE	350.00	-
1	CAR KEY (SN)	BROKEN	680.00	680.00
			1,480.00	1,030.00
	LABOUR			
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS. INCLUSIVE OF THE REPAIR OF BONNET.		1,100.00	500.00
	TO CHECK WIRING AND REWIRE.		120.00	50.00
	TO REMOVE & REFIX RADIATOR / CONDENSER FOR CHECKING.	NOT NECESSARY	240.00	-
	TOWING.	NOT NECESSARY	200.00	-
	TO ANTI-RUST.		140.00	50.00
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		1,400.00	600.00
	TO RESET FAULT CODE.		180.00	50.00
	TO PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
			3,480.00	1,250.00
	GRAND TOTAL		17,107.30	7,967.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,350.00

Report Ref No. CS/FCI18015719/Nqd3e2

MARKET VALUE: \$60,000.00(EST)-LTA REIMBURSEMENT VALUE: \$46,405.00=NETT VALUE: \$13,595.00

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.