

(08/11/13) wef

ASS. REC. BY: Morley

REF:

CCS/MSA/1001/2155/UPD112

MSA/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLJ6797A

at Workshop n/s Pl.

of _____

Insured: SLH6732

Policy No. B288435212mx

Claims No 569517

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 45

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: 9 Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ6797A Yr Regn: 7 11

Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A1

Make: Volkswagen passat cc 1798

Colour Silver A/C: Insured / Std / NI / NA

Sp. Reading 112260 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZXX3C2BE759592

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 235/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / RIR / SUMI /

TOYO / YOKO or Michelin

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 29/8/18

D.O.I. 29/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21A 3543 / 2703 11ale.

30/8/18 Spmt GIA thru email

9/18 4/5 6550 confirmed with Alu.

Red: 8 18,578.94, 741.

RECEIVED 17 SEP 2018

Date/Time, File Pass to?

☐ : Prel. Report

☒ : Final Report

Date/Time, File Return to?

1) typist

2) _____

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL

200
10
210

Report Format: TP

Lump Sum H.B.I.: (\$ 6550.00)

Survey Department Check List (Case Handler)

Reference No. : 663/MSG18015733 /urb

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler Janice Typist

Admin (Catherine): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	/			
C	Customer Code				
N	Assign From				
C	Assign Date				
C	Veh No (Inspected)	/			
C	Veh No (Insured)	/			
C	D.O.A	/			
C	Policy No				
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	/			
C	Weekend Charges				
N	Survey held at/Repairer	/			
C	Excess				

Surveyor (Marius)

: Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	/			
C	Regn Month/Year	/			
N	Vehicle Type	/			
N	Make & Model	/			
C	Engine Capacity. (C.C)	/			
N	Colour	/			
C	Odometer. (Sp.Reading)	/			
C	Chassis No	/			
N	General Condition	/			
N	Steering	/			
N	Brake	/			
N	Modification (Modi)	/			
C	Tyre Size	/			
N	Tyre Make	/			
C	Tyre Balance	/			
C	Date of Inspection	/			
N	Survey held	/			
N	Des.of Damages	/			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	/			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	/			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	/			
C	Finalised Amount	/			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By:
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/08/2018 10:55
Date Of Accident	29/08/2018 07:35
Exact Location Of Accident	BKE TWDS PIE AT KJE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ6797A
Insured/Policyholder	
Name Of Registered Owner	YOGESWARAN S/O RANJEN
NRIC No	S8214645H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84441432
Alternative Phone No	OFFICE-84441432

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	PASSAT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	HL ASSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MP305883
Cover Note Number	

Driver

Name of Driver	YOGESWARAN S/O RANJEN
NRIC No	S8214645H
Date Of Birth	11/05/1982
Occupation	INDOOR
Date Of Driving Pass	07/08/2009
Driving Experience	9 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84441432
Fax Number	
Contact Number	OFFICE-84441432
Email Address	NOEMAIL

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

UNKNOWN

Approximate Age

Injuries Sustain

Injured person in which vehicle?


Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DUE TO HEAVY TRAFFIC AHEAD, THE FRONT VEHICLE SLOWED DOWN AND STOPPED. AND I FOLLOWED SUIT. SUDDENLY, I FELT A GREAT IMPACT FROM MY REAR. AND I GOT OUT OF MY VEHICLE AND I REALIZED VEHICLE B HAD HIT THE REAR OF MY RACK AND IT WAS A CHAIN COLLISION OF 3 VEHICLES INVOLVED.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

Date of Accident : 27/08/2018 Accident Time: 0335HRS (24-HR-Format)
 Accident Place : RUE TOWARDS PIE AT KUE EXIT
 Vehicle No. (Car Plate No.) : SJ3 497A Make/Model: VOLKSWAGEN PASSAT
 Insurance Company : HL Assurance Policy No: MP 306883
 Owner or Company Name / IC No. : Yogeswaran s/o Rajen / 58214645H
 Owner or Company Contact No. : 8444432 Owner's Hp _____ Company Tel _____
 DRIVER'S Name / IC No. : as above
 DRIVER'S Date Of Birth : 11/5/1982 DRIVER'S License Pass Date 7/8/2009
 Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: owner
 DRIVER'S Address : Blk 266B Punggol way #09-378
 DRIVER'S Contact No./ Alt No. : 1) _____ 2) 5822266
 DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
 Email Address : _____
 Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
 Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
 Number of Passengers (Including Driver): 01
 Was there any video Captured by car camera: YES \ NO
 Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
 Any Injury (If YES, Pls state): YES

Other Party Driver's Particular (if any)

Vehicle No: (B) SLH 632
 Vehicle Make/Model: HYUNDAI ELANTRA
 Name Driver: _____
 IC No. Driver/Contact: _____

Vehicle No: (C) SJE 2773X
 Vehicle Make/Model: MITSUBISHI OUTLANDER
 Name Driver: _____
 IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

① S1J6797A
② S1H675Z
③ S1E2773X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DUE TO HEAVY TRAFFIC AHEAD, THE FRONT VEHICLE SLOWED DOWN AND STOPPED. AND I FOLLOWED SUIT. SUDDENLY, I FELT A GREAT IMPACT FROM MY REAR. AND I GOT OUT OF MY VEHICLE AND I REALISED VEHICLE B HAD HIT THE REAR OF MY BACK AND IT WAS A CHAIN COLLISION OF 3 VEHICLES INVOLVED.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4645H

Vehicle Details

Vehicle No.: SLJ6797A
Vehicle to be Exported: No
Intended De-registration Date: 29 Aug 2018
Vehicle Make: VOLKSWAGEN
Vehicle Model: PASSAT CC 1.8T AT 3574H7
Primary Colour: Gold
Manufacturing Year: 2011
Engine No.: CDA215950
Chassis No.: WVVZZZ3CZBE759592
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$31,811.00
Original Registration Date: 26 Jul 2011
First Registration Date: 26 Jul 2011
Transfer Count: 3
Actual ARF Paid: \$31,811.00 15,928

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Jul 2021
PARF Rebate Amount: \$19,086.00

Intended COE Rebate Details

COE Expiry Date: 25 Jul 2021
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$56,300.00
COE Rebate Amount: \$16,345.00
Total Rebate Amount: \$35,431.00

The information contained herein is correct as at 29 Aug 2018

OK



Engineered to save you time.



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Wish 1.8A



\$2800 Downpayment Monthly
From \$668 Onwards. Lowest
3.68%PA @GV Cars Financing
GV Credit Pte Ltd Star4d

PRIME MOTOR & LEASING

LEASING FROM CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES

With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

5 vehicles

Volkswagen Passat

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Volkswagen Passat		Any	Any	2011	Any	Any	Any	Available
	Volkswagen	Passat CC 1.8T	\$45,000	\$11,550 /yr	23-Mar-2011	1,798 cc	130,000 km	Luxury	Available
Well Maintained By Previous Owner. 100% Accident Free. View To Believe! Schedule A Test Drive Today. Viewing Is Strictly By Appointment Only.									
Carro									
Posted: 27-Aug-2018 Tags: 2011 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen									
	Volkswagen	Passat 1.8A TSI	\$44,800	\$9,880 /yr	16-Sep-2011	1,798 cc	88,800 km	Luxury	Available
Safe Buy! Paper Plus Body Value \$43k, Only \$750/Mth! No Repair Needed! Smooth Ride! Your Best Choice Selection With Us! 1 Stop Services, 90% Loan Financing. Lowest Interest Rate, 100% Accident Free, N...									
GD Motoring									
Posted: 20-Aug-2018 Tags: 2011 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen									
	Volkswagen	Passat CC 1.8T	\$50,800	\$12,420 /yr	21-Jun-2011	1,798 cc	114,000 km	Luxury	Available
1 Owner. 5 Seater Passat CC, Low Mileage, Pristine Black Exterior With Perfect Brown Leather Interior.Call For Viewing Appointment.									
Faster Auto Trading									
Posted: 19-Aug-2018 Tags: 2011 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen									
	Volkswagen	Passat 1.8A TSI	\$41,500	\$10,490 /yr	21-Mar-2011	1,798 cc	-	Luxury	Available
Road Tax Paid. Lady Owner Who Uses The Car To Drive To Work And Back Home. MU Unit Just Changed 1 Month Ago With Original Agent Parts. Warranty On MU. Buy With Confident. Service Every 5,000km. No Exp...									
Posted: 18-Aug-2018 Tags: 2011 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen									
Car Buying Car Selling Car Ownership Buying a pre-owned car, but Unsure of its Condition? Get, STA Car Evaluation									
Car Aftermarket On The Move Lifestyle									
	Volkswagen	Passat 1.8A TSI	\$39,000	\$8,700 /yr	17-Jun-2011	1,798 cc	100,000 km	Luxury	Available
Cheapest In Market! Powerful And Responsive Car, Good Choice Of Car For Daily Drive. Fully Stock! Excellent Fuel Consumption! Spacious Leg Room! Perfect For Families! Trade In Available. Call Now To Vi...									
1 Accurate Auto									
Posted: 18-Aug-2018 Tags: 2011 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

not Authorized
to take
4/5 \$6500
50g.

FASTECH AUTO PTE LTD

1 Kakit Bukit Ave 6
#01-46,48,50 Autobay
SINGAPORE 417883

VEHICLE NO: SLJ 6797A

QTY	PARTICULAR			
1 PCS	BOOTLID	1615.00	But/sec	\$2,255.32
1 PCS	BOOTLID REAR LOGO		11	\$105.00 X
1 PCS	BOOTLID 'TSI' EMBLEM	42.00	ren	\$48.00
2 PCS	BOOTLID REFLECTORS @\$650.00		11	\$1,300.00 X
1 PCS	BOOTLID INNER LOCK	392.30	shut/h	\$655.00
1 PCS	BOOTLID WEATHERSTRIP	288.50	twi	\$399.00
1 PCS	REAR BUMPER	1692.70	012e	\$2,018.00
1 PCS	REAR BUMPER CHROME MOULDING CENTRE	211.62	1re	\$366.50
2 PCS	REAR BUMPER CHROME SIDE MOULDINGS @\$325.00		11	\$650.00 X
1 PCS	REAR BUMPER REINFORCEMENT	450.37	03	\$849.12
1 PCS	REAR BUMPER TOP RETAINER	119.00	twi/cr	\$305.00
1 PCS	REAR BUMPER LICENCE PLATE LAMP	60.00	1re	\$185.00
1 PCS	REAR BUMPER LOWER GARNISH	266.30	2e	\$485.00
1 PCS	REAR BUMPER TOP PROTECTOR	150	ren	\$211.00
2 PCS	REAR BUMPER SIDE RETAINERS @\$115.00		11	\$230.00 X
1 SET	REAR BUMPER CLIPS		ren	\$60.00
2 PCS	REAR BUMPER REFLECTORS @\$80.00		11	\$160.00 X
2 PCS	TAILLAMPS @\$825.00	601	nl/scr	\$1,650.00 X
1 PCS	REAR END PANEL	612.00	03	\$1,210.00
1 PCS	REAR END PANEL TOP GARNISH	241.30	twi	\$366.00
1 PCS	REAR FLOOR PANEL		R	\$1,410.00 X
1 PCS	REAR FLOOR PANEL TOP BOARD		11	\$688.00 X
2 PCS	REAR FENDER INNER TRIMS @\$466.50		11	\$933.00 X
2 PCS	REAR FENDERS @\$1100.00		11	\$2,200.00 X
1 PCS	REAR EXHAUST ASSY		11	\$1,650.00 X
				\$20,388.94
	S.NETT			
1 PCS	REAR LICENCE PLATE W/HOLDER		1re	\$50.00
1 PCS	REAR END PANEL SEALANT		ren	\$50.00
1 PCS	REAR WINDSCREEN SEALANT		11	\$80.00 X
1 SET	REAR FLOOR PANEL INSULATOR		11	\$300.00 X

LABOUR CHARGES:

TO CHECK WIRING	\$80.00	30
TO DISMENTLE & REPLACING REVERSE SENSOR	\$80.00	50
TO DISMENTLE & REFIX REAR WINDSCREEN	\$150.00	X
TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTREY	\$120.00	80

6802-09
6461-58

TO DISMENTLE & REFIX REAR EXHAUST	1 1	\$180.00	X
TO DISMENTLE & REFIX BOOTLID MECHANISM		\$150.00	60
TO MOUNT VEHICLE ON CAR O-LINER	1 1	\$380.00	X
TO SPRAY RUST PROOFING		\$120.00	50
LABOUR FOR PANEL BEATING & REPLACING PARTS		\$1,500.00	600
TO PUTTY & SPRAY PAINTING		\$1,500.00	200
TOTAL		\$25,128.94	

1221.88

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18015733/URBN2

Date: 18/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B28843521QMX (COMP)
Claimant Vehicle No :	SLJ6797A	Insured Vehicle No :	SLH673Z
Date of Loss:	29/08/2018	Nature of Claim:	TP
		Claim No:	569517

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ6797A	Engine No:	CDA215950
Make & Model:	VOLKSWAGEN PASSAT, 1.8 T (B5) (A)	Chassis No:	WVWZZZ3CZBE759592
Reg. Date:	26/07/2011 (Man. Year: 2011)	Odometer:	112260 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45R17	Rear Tyre Size:	235/45R17
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	20,868.94	6,551.99	14,316.95	68.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,260.00	1,670.00	2,590.00	60.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,128.94	8,221.99	16,906.95	67.28
Approved Total (Overridden) (S\$)		6,550.00		
(S\$)	25,128.94	6,550.00	18,578.94	73.93
+ GST 7.00/7.00% (S\$)	1,759.03	458.50	1,300.53	73.93
Nett Amount (S\$)	26,887.97	7,008.50	19,879.47	73.93

INSPECTION

Date of Assignment:	13/09/2018	
Date Inspected:	29/08/2018 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Sep 2018)
Parts:	143	VOLKSWAGEN PASSAT 1.8 T (B5) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ6797A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent/Buckled	2,255.32 F	*1,615.00 FL
2	1		*BOOTLID REAR LOGO	Not Necessary	105.00 F	*- FL
3	1		*BOOTLID TSI EMBLEM	Necessary	48.00 F	*42.00 FL
4	2		*BOOTLID REFLECTORS	Not Necessary	1,300.00 F	*- FL
5	1		*BOOTLID INNER LOCK	Shorted	655.00 F	*392.30 FL
6	1		*BOOTLID WEATHERSTRIP	Twisted	399.00 F	*288.50 FL
7	1		*REAR BUMPER	Dented/Deformed	2,018.00 F	*1,692.70 FL
8	1		*REAR BUMPER CHROME MOULDING CENTRE	Cracked	366.50 F	*211.62 FL
9	2		*REAR BUMPER CHROME SIDE MOULDINGS	Not Necessary	650.00 F	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Dented	849.12 F	*450.37 FL
11	1		*REAR BUMPER TOP RETAINER	Cracked/Twisted	305.00 F	*119.00 FL
12	1		*REAR BUMPER LICENCE PLATE LAMP	Cracked	185.00 F	*60.00 FL
13	1		*REAR BUMPER LOWER GARNISH	Deformed	485.00 F	*266.30 FL
14	1		*REAR BUMPER TOP PROTECTOR	Necessary	211.00 F	*150.00 FL
15	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	230.00 F	*- FL
16	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
17	2		*REAR BUMPER REFLECTORS	Not Necessary	160.00 F	*- FL
18	1		*TAILLAMPS	N/s Cracked	1,650.00 F	*601.00 FL
19	1		*REAR END PANEL	Dented	1,210.00 F	*612.00 FL
20	1		*REAR END PANEL TOP GARNISH	Twisted	366.00 F	*241.30 FL
21	1		*REAR FLOOR PANEL	Repair	1,410.00 F	*- FL
22	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	688.00 F	*- FL
23	2		*REAR FENDER INNER TRIMS	Not Necessary	933.00 F	*- FL
24	2		*REAR FENDERS	Not Necessary	2,200.00 F	*- FL
25	1		*REAR EXHAUST ASSY	Not Necessary	1,650.00 F	*- FL
26	1		*REAR LICENCE PLATE W/HOLDER	Cracked	50.00 FS	*40.00 FS
27	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
28	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
29	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	20,868.94	6,892.09
- List Item Discount on L Items 0.00/5.00% (S\$)	0.00	340.10
Total Parts (S\$)	20,868.94	6,551.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMENTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMENTLE & REFIX REAR WINDSCREEN	New	150.00	-
4	TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMENTLE & REFIX REAR EXHAUST	New	180.00	-
6	TO DISMENTLE & REFIX BOOTLID MECHANISM	New	150.00	60.00
7	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	-
8	TO SPRAY RUST PROOFING	New	120.00	50.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,500.00	600.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
Gross Labour Cost (S\$)			4,260.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >