## COMFORTDELGRO ENGINEERING PTE LTD

## **REPAIR ESTIMATE\***

VEHICLE NO : SHA1851D

DATE:

28. Aug. 2018

MAKE

: TOYOTA

DEL	: PRIUS	DOA:	21. Aug. 2018	AXA
Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	1 Side Mirror Assy – LH			\$1,374.00
	1 Side Mirror Cover – LH 🗶			\$107.40
	1 Front Door – LH			\$1,227.00
	1 Rocker Panel - LH XMA			\$500.00
	Front Feeler (CH) -			
	Front Feeder (CH)			
	Found Feeder Enden (W)			
	100			
	SUB TOTA	կ		\$3,208.40
	LESS 259	6		\$883.53
	DISCOUNTED TOTAL	L		\$2,324.87
	1 Front Door Logo – Comfort			\$75.00
				100
				\$75.00
	Labour Charge			300
	1 Panel Beating			\$400.00
	1 Spray Painting Charge			\$590.00
	1 Transfer of Door			\$180.00
	1 Tuff Kote		actify	\$100.00
	1 Wiring Charge	consultants he	ing:	\$100.00
	the Report	ternintter Spie	Volum	
	• To results	nart(S)	during resurvey	
	TOTAL LABOU	R are subject in	nafirmation Vithout Prejudice" basis	\$1,280.00
	Calum 1 (1CK) Third pa	it modification(s)	st the resurveyed and	\
	ESTIMATE TOTA	Lintary tomes m	ist the resurveyed and insurance Company	\$3,679.87
	1 2 4/8/18 10 tohr is subj	SCHO III III III III III III III III III I	T.	\
	TOTAL LABOUR TOTAL LABOUR Third part of the state of the	ledged by Repaire		1
Larry N	Signal	TLE:		-
	Before Poil plate			
	This is an initial estimate based on a visual inspection of	the above ve	hicle. The final repair	guantum will