

INS. CASE OWNER:

Winnic Ho. CC 4, ASM 180 15769, K pa3

LKK: 65854
IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

29/8/18

Date / Time:

28/08/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SJX 496H

Claim No. :

Name of Insured :

LA CASA CUBANA P/L

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :SS

D.O.A.:

28/8/2018

Place of Accident :

Pinnacul Rd

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : %

Final ? Yes / No

SL6 2230K



INSRS:

WSP:

Tel :

Liability :

RMKS:

WSP: 106E (B).




INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time		STAGE	DATE / PIC
	SL6 2230K, X;	Non-Reporting ltr (1st):	
	SJX 496H - 04/11/15 016399 / Kug/92; DOA: 26/09/15	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
29/18	ONE. to sent let letter	Call OI:	
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
		After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
		Authorisation To Act:	<input type="checkbox"/> <input type="checkbox"/>
		Release Voucher:	<input type="checkbox"/> <input type="checkbox"/>
		Final Repair Bill:	<input type="checkbox"/> <input type="checkbox"/>
		Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
		Towing Invoice	<input type="checkbox"/> <input type="checkbox"/>
		LTA / GIA :	<input type="checkbox"/> <input type="checkbox"/>
		Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
		PIR:	<input type="checkbox"/> <input type="checkbox"/>
		Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
		LOD	<input type="checkbox"/> <input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S\$	(days) Reduction: %	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time:	Confirm with	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost:	S\$		
Loss of Rental (LOR):	S\$	(days)	
Loss of Use (LOU):	S\$	(\$ x days)	
Loss of Income (LOI):	S\$	(\$ x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]		
GIA/LTA Search	S\$		
Medical:	S\$		
Disbursement:	S\$	(e.g. Tow/ Independent)	1) Claim status: Normal/Reject/Private Settle
Legal Cost	S\$		2) Report Format:
Total:	S\$	Global Sum S\$:	3) Survey fee:
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	S\$	Name 1:	
Payee 2: (Strike if N.A.)	S\$	Name 2:	
Payee 3: (Strike if N.A.)	S\$	Name 3:	

Surveyor

ASSIGNMENT

From: _____ Date: 29/08/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 2230K

at Workshop m/s Comfort Delgro

of 205 Braddell Rd

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SLG 2230K Yr Regn: 09, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon

Make: Honda Shuttle c.c. 1496

Colour: M. D. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 142275 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP7 1040385


Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: Raventi 185/60R15



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Rovelo R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value: 8736

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 0.5 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Front	Rear
R/Bal. <u>9</u> mm	R/Bal. <u>9</u> mm
L/Bal. <u>9</u> mm	L/Bal. <u>9</u> mm
D.O.A. <u>28/8/18</u>	D.O.I. <u>29/8/18</u>

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>18</u>	<u>File pass to Customer</u>

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

_____ S + RS. _____ St

Photos _____

Others _____

TOTAL _____