

ASS. REC. BY

REF

CS/CTI18015772/R1s d3

Special Instruction:

Surveyor

meimen

ASSIGNMENT (Office)

From (Person):

Chong Eoun Sen

of

CTI

Date/Time:

29/8/18 @ 2:04pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 9495L

Insured:

GBD 4202M

at Workshop m/s:

Mova Automotive

Tel:

6272 3892

of

Blk 1008, Blk Merak Lane 3 #01-04

Policy No:

DMCVSN 143610703

Claim No:

SNM18D04089C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22/08/2018

Insp: IS Fen Yang Rd

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

2:47pm 29/8/18

Person Contacted:

Nidhan

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SLH 9495L-x

GBD 4202M-CS/CAI14021639/R/H/bk3

DOA: 13/11/19

05/11/18

Confirmed P/P \$ 8,278.68 @ 9 days with Taufik.

(\$ 3,054.00 Red - 27%)

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

WP

Date:

Person Contacted:

Vehicle: IN / OUT

D.O.A.

D.O.I.

36/8/18 @ 1430-

Survey held at

Mova Fan Yang

Des. of Damages: F/H (Rear) O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

RECEIVED 00 NOV 2018

Date/Time, File Pass to?

08/11/18

1)

Typest

Date/Time, File Return to?

2)

Report Format:

Lump Sum / LB L/C

8,278.68 P/P

Days Of Repair:

9

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp \$

☐

Interpaw \$

☐

Tech Insp \$

☐

Wagon \$

Survey Fee

Transportation

TOTAL \$

TOTAL \$

TOTAL \$

TOTAL \$

TOTAL \$

220

220