

ASS. REC. BY:

REF: CS/CPI18015774/Kvd3n2

Special Instruction:

Surveyor  
Meinen

Kenneth  
Irene Jay

ASSIGNMENT (Office)

From (Person):

of

CPI

Date/Time:

4:33pm 28/8/18

Estimated Cost:

Bill to:

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 9608 X

Insured:

GBC 4006 T

at Workshop m/s

Optima Werkz

Tel:

6484 9919

of

9A Strongman Ave S

Policy No:

DMCVSN 3012251500

Claim No:

SNM18D04174002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03/08/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

9:34am 29/8/18

Person Contacted:

Lily

Vehicle  IN  OUT

Date/Time

Action/Instruction (✓) Estimate

SKZ 9608X-X

GBC 4006T-X

29/8/18

@3:44pm Lily said vehicle has not repair yet. Pending liability

REF: CTI

ASSIGNMENT

From: \_\_\_\_\_ Date: 29/08/2018

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKZ 9608T

at Workshop m/s: Optima Werkz

of: 9A Serampang Nuth Ave 5

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition) 11.45am  
owner waiting

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 04 days Res: Yes or No

Lum Sum: 1.B.1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKZ 9608T Yr Regn: 02 / 18

Type: M Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Honda <sup>VA</sup> Vatel c.c. 1896

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 83971 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RUI 1107814

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD / ARM or \_\_\_\_\_

Tyre Size: F: 215/60R16  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or \_\_\_\_\_

Front	Rear
R/Bal. 3 mm	R/Bal. 2 mm
L/Bal. 3 mm	L/Bal. 2 mm
D.O.A. 23/8/18	D.O.I. 29/8/18

Survey held at: \_\_\_\_\_ ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
30/8	File pass to Catherine

19/11 @ 5pm @ 4075.72 email confirmed with Lily (Red 1420.72, 2670)

RECEIVED 20 NOV 2018

*[Signature]*  
20/11/2018

Date/Time, File Pass to?  Preli. Report

1)  Final Report

Date/Time, File Return to? 2) 20/11 - typist

Report Format: merimen

Lump Sum / I.B.I. (\$) 4075.72

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\_\_\_\_ \$ + RS \_\_\_\_\_ \$

Photos \_\_\_\_\_

Others \_\_\_\_\_

220

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18015774/Kvd3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 29-08-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 4006T	Veh. Inspected	SKZ 9605X
Policy No.	DMCVSN3012251800	Coverage (\$)	0.00
Claim No.	SNM18D04174C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	29/08/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	23/08/2018	Inspection Date	29/08/2018
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Aug 2018		28 Aug 2018 16:53 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	OPTIMA WERKZ PTE LTD		
Vehicle Reg. No.:	SKZ9608X	Date of Loss:	23/08/2018 00:00 - :59
Claim Type:	TP / SNM18D04174C02	Policy/Cover Note No.:	DMCVSN3012251800
Vehicle Reg. No. (Insured):	GBC4006T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5, 554500 Serangoon - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/09/2018]		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2455W
Vehicle Details	
Vehicle No.:	SKZ9608X
Vehicle to be Exported:	Yes
Intended De-registration Date:	25 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	L15B4027817
Chassis No.:	RU11107814
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$18,751.00
Original Registration Date:	17 Feb 2016
First Registration Date:	17 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$8,751.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Feb 2026
PARF Rebate Amount:	\$6,563.00
Intended COE Rebate Details	
COE Expiry Date:	16 Feb 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,651.00
COE Rebate Amount:	\$34,896.00
<b>Total Rebate Amount:</b>	<b>\$41,459.00</b>

The information contained herein is correct as at 25 Aug 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/08/2018 11:22
Date Of Accident	23/08/2018 11:00
Exact Location Of Accident	BLK 138 TAMPINES ST 11 (OPEN SPACE CARPARK)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ9608X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	OPTIMA WERKZ PTE LTD
Co Reg No	201212455W
Email Address	LILY.LOI@OW.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64849919

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD18V07597/VPZ/R01
Cover Note Number	

### Driver

Name of Driver	TAN BOON KIAT
NRIC No	S1472716G
Date Of Birth	11/01/1961
Occupation	OUTDOOR
Date Of Driving Pass	25/05/1992
Driving Experience	26 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	+65-93858411
Fax Number	
Contact Number	
Email Address	MIKETAN@FLYLABEL.COM.SG

Address	BLK 127 TAMPINES ST 11 #05-440
Postcode	521127
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - PRIVATE HIRE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO POLICE REPORT NO.: T/20180823/2123

#### Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	
Phone Number	91879633
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC4006T
Vehicle Make/Model/Colour	WHITE TRUCK
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	



## Accident Sketch Plan Pg. 1

PRELIMINARY

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180823/2123

Police Station Of Origin:  
Changkat NPP  
109 Tampines Street 11 #01-261  
SINGAPORE 521109  
Tel No: 1800-7819999

1 of 3  
Report No. T/20180823/2123

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 23/08/2018 17:07	Vide Report No.:	Station Diary No.: 43
--	------------------	--------------------------

**Informants Particulars**

Name of Informant: TAN BOON KIAT		Address: APT BLK 127 TAMPINES STREET 11 #05-440 SINGAPORE 521127	
ID Type / ID No.: NRIC NO / S1472716G		Contact No.: Home/Office: Mobile: 93858411	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 57	Date of Birth: 11/01/1961	Type of Informant: Vehicle Owner
Race: Chinese		Language:	Institution / School Name:
Occupation: SALES		Driving Licence Information: Class: 3 Date of Expiry:	

**General Information of the Accident**

Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 23/08/2018 13:00	Type of Location: Car Park
Location: Along Road 1 TAMPINES STREET 11  BLOCK 138 TAMPINES STREET 11 OPEN SPACE CARPARK			
Weather: Clear		Road Surface: Dry	Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume:
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
GBC4006T	Van					0
SKZ9608X	Car					0



**SINGAPORE  
POLICE FORCE**



T/20180823/2123

2 of 3

Report No. T/20180823/2123

Police Station Of Origin:  
Changkat NPP  
109 Tampines Street 11 #01-261  
SINGAPORE 521109  
Tel No: 1800-7819999

**CONTINUATION OF REPORT**

**Brief Details.**

On 23rd August 2018 at about 11am, I parked my car with everything intact at the open space carpark of Block 138 Tampines Street 11. I do not remember which lot I parked at.

At about 1pm when I returned to my vehicle, I discovered a note on my windscreen, the note stated: 'Hi For info, we saw a white truck GBC4006 (Supreme Meat Co.) reverse and heard a loud sound. not sure if its related to the dent on your car. FYI. (Tel: 91879633)' I then made a check on my car and discovered a dent on the bumper and bonnet.

I called the number on the telephone and the person told me that he witnessed the above-mentioned truck hit my car earlier.

My dashboard camera was not recording at the time of the accident.

# OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 24 AUGUST 2018

Third Party Insurer: CHINA TAIPING

Vehicle No: SKZ9608X

Third Party Veh No: GBC4006T

Model: HONDA VEZEL 1.5X

Date of Accident: 23 AUGUST 2018

Chassis: RU11107814 - 2015

## ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	FRONT BONNET <i>950-40</i>		<i>RM</i> \$1,224.00
2	FRONT BONNET SEAL RH/LH	\$25.80	<i>RM</i> \$51.60
<del>1</del>	FRONT HEADLAMP RH	<i>RM</i> <del>CM</del>	<del>\$1,895.45</del>
2	FRONT HEADLAMP CLIPS	\$6.50	<i>RM</i> \$13.00
<del>1</del>	FRONT HEADLAMP LOWER BRACKET RH		<del>CM</del> \$196.50
1	FRONT GRILLE	<i>CM</i>	<del>CM</del> \$398.30
6	FRONT GRILLE CLIPS	\$6.50	<i>RM</i> \$39.00
1	FRONT GRILLE EMBLEM 'LOGO'		<i>RM</i> \$29.30
1	FRONT GRILLE GARNISH		<i>CM</i> \$275.20
1	FRONT GRILLE CHROME MOULDING RH		<i>CM</i> \$75.30
1	FRONT GRILLE TOP BRACKET 'CENTRE'		<i>CM</i> \$98.50
1	FRONT GRILLE TOP BRACKET RH		<i>CM</i> \$36.20
1	FRONT SUPPORT PANEL TOP GARNISH		<i>RM</i> \$98.20
10	FRONT SUPPORT PANEL TOP GARNISH CLIPS	\$6.50	<i>RM</i> \$65.00
SUB TOTAL			\$4,495.55
Less 20%			-\$899.11
PARTS TOTAL			\$3,596.44

### LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,000.00	<i>8501</i>
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$600.00	<i>4001</i>
TO CHECK WIRING, LIGHTING & WATER LEAKAGE	\$60.00	<i>201</i>
TO FOCUS HEADLAMP ADJUSTMENT	\$60.00	
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	<i>RM</i> \$180.00	<i>X</i>

LABOUR TOTAL \$1,900.00

PUI THENG

*Not Notified  
1.3.1  
Survey by paint*

*84075.72*

*4 days*

LKK Auto Consultants hence notify the Repairer of the following: **TOTAL \$5,496.44**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18015774/KVD3N2  
Date: 26/11/2018

#### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3012251800
Claimant Vehicle No :	SKZ9608X	Insured Vehicle No :	GBC4006T
Date of Loss:	23/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D04174C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ9608X	Engine No:	L15B4027817
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11107814
Reg. Date:	17/02/2016 (Man. Year: 2015)	Odometer:	83971 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Dunlop 2 mm
Front Right Side:	Dunlop 3 mm	Rear Right Side:	Dunlop 2 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,596.44	3,205.72	390.72	10.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	870.00	1,030.00	54.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,496.44</b>	<b>4,075.72</b>	<b>1,420.72</b>	<b>25.85</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>384.75</b>	<b>285.30</b>	<b>99.45</b>	<b>25.85</b>
<b>Nett Amount (S\$)</b>	<b>5,881.19</b>	<b>4,361.02</b>	<b>1,520.17</b>	<b>25.85</b>

#### INSPECTION

Date of Assignment:	28/08/2018		
Date Inspected:	29/08/2018	Inspected At:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5 Singapore 554500
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2018)	
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SKZ9608X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *		

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BONNET	Bent	1,224.00 FL	*950.40 FL	
2	2		*FRONT BONNET SEAL RH/LH	Serviceable	51.60 FL	*- FL	
3	1		*FRONT HEADLAMP RH	Mtg Cracked	1,895.45 FL	*1,895.45 FL	
4	2		*FRONT HEADLAMP CLIPS	Necessary	13.00 FL	*13.00 FL	
5	1		*FRONT HEADLAMP LOWER BRACKET RH	Cracked	196.50 FL	*196.50 FL	
6	1		*FRONT GRILLE	Cracked	398.30 FL	*398.30 FL	
7	6		*FRONT GRILLE CLIPS	Necessary	39.00 FL	*39.00 FL	
8	1		*FRONT GRILLE EMBLEM LOGO	Necessary	29.30 FL	*29.30 FL	
9	1		*FRONT GRILLE GARNISH	Cracked	275.20 FL	*275.20 FL	
10	1		*FRONT GRILLE CHROME MOULDING RH	Cracked	75.30 FL	*75.30 FL	
11	1		*FRONT GRILLE TOP BRACKET CENTRE	Cracked	98.50 FL	*98.50 FL	
12	1		*FRONT GRILLE TOP BRACKET RH	Cracked	36.20 FL	*36.20 FL	
13	1		*FRONT SUPPORT PANEL TOP GARNISH	Serviceable	98.20 FL	*- FL	
14	10		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	65.00 FL	*- FL	
					<b>Sub Total (S\$)</b>	<b>4,495.55</b>	<b>4,007.15</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>899.11</b>	<b>801.43</b>
					<b>Total Parts (S\$)</b>	<b>3,596.44</b>	<b>3,205.72</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	New	1,000.00	450.00
2	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	New	600.00	400.00
3	TO CHECK WIRING,LIGHTING & WATER LEAKAGE }	New	60.00	20.00
4	TO FOCUS HEADLAMP ADJUSTMENT }	New	60.00	-
5	TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	New	180.00	-
<b>Gross Labour Cost (\$\$)</b>			<b>1,900.00</b>	<b>870.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >