

23/03/2007

A&S. REC. BY:

REF: CS3/MSG18015777/N240367 Special Instruction:

Surveyor
menmen

N92

ASSIGNMENT (Office)

From (Person):

Chhia Nyuk Pui

of

MS16

Date/Time: 28/8/18 @ 4.28pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 4989R

Insured:

SKK 1115H

at Workshop m/s

H.S. Automotive

Tel:

6747 2755

of

2 Kaki Bkt Ave 2 # 02-25

Policy No:

B27487632SMP

Claim No:

568202

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

9:36am @ 29/8/18

Person Contacted:

Connie

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate	
	GBF 4989R - NA / FCF 1805373/24	DOA: 21/08/18
	SKK 1115H - NA / FCF 18015373/24	DOA: 21/08/18
	After repair: 5/9/2018	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18015777/Nz4d3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 29-08-2018	
		Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SKK 1115H	Veh. Inspected	GBF 4989R
Policy No.	B27487632SMP	Coverage (\$)	0.00
Claim No.	568202	Excess (\$)	0.00
Assign From	MERIMEN (CHHIA NYUK PUI)	Assign Date	29/08/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/08/2018	Inspection Date	29/08/2018
Survey held at	H S AUTOMOTIVE SERVICES 2 KAKI BUKIT AVE 2 #01-15 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Aug 2018		28 Aug 2018 16:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MOHANA DASS S/O BALAKRISHNAN NAIR, ID: S1618463B, Tel: +6596609207, Email: MNAIRDAS@GMAIL.COM		
Main Claimant:	ROBINSON CAR RENTAL PTE LTD, Co. Reg. No.: 200414041W		
Vehicle Reg. No.:	GBF4989R	Date of Loss:	21/08/2018 19:00 - :59 [20 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 568202	Policy/Cover Note No.:	B27487632SMP (Comprehensive) Coverage: 30/03/2018 - 29/03/2019
Vehicle Reg. No. (Insured):	SKK1115H	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	H S Automotive Services (Kaki Bukit) BLK 2 KAKI BUKIT, AVENUE 2, # 01-15, KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 67472755		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/08/2018]		
Driver/Custodian (Insured):	MOHANA DASS S/O BALAKRISHNAN NAIR (54 / Male), NRIC: S1618463B, Tel: +6596609207		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK LIABILITY: 100% CONTACT: MR ALEX 6538 1368 UNIT NO: #02-25		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	GBF4989R		
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	NISSAN		
Vehicle Model :	NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC		
Chassis No. :	VSKYBAM20Z0131466		
Propellant :	Diesel		
Engine No. :	K9KC400D055941		
Engine Capacity :	1461 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	2000 kg		
Unladen Weight :	1260 kg		
Year Of Manufacture :	2016		
Original Registration Date :	28 Nov 2016		
Lifespan Expiry Date :	27 Nov 2036		
COE Category :	C - Goods Vehicle & Bus		
PQP Paid :	\$45,470.00		
COE Expiry Date :	27 Nov 2026		
Road Tax Expiry Date :	27 Nov 2018		
Inspection Due Date :	27 Nov 2019		
Intended Transfer Date :	28 Sep 2018		
CO2 Emission :	138.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 27 Nov 2018. You may renew the road tax from 28 Aug 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 27 Nov 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 28 Nov 2018 to 27 May 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	0.00	-	0.00
Total Amount Payable :			25.00
Amount Payable (From 28 Nov 2018 to 27 Nov 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4041W
Vehicle Details	
Vehicle No.:	GBF4989R
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Sep 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	K9KC400D055941
Chassis No.:	VSKYBAM20Z0131466
Maximum Power Output:	-
Open Market Value:	\$20,226.00
Original Registration Date:	28 Nov 2016
First Registration Date:	28 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$1,012.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$45,470.00
COE Rebate Amount:	\$37,132.00
Total Rebate Amount:	\$37,132.00

The information contained herein is correct as at 28 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/08/2018 19:13
 Date Of Accident 21/08/2018 19:45
 Exact Location Of Accident ALONG WEST COAST HWY
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBF4989R
Insured/Policyholder
 Name Of Registered Owner ROBINSON CAR RENTAL PTE LTD
 Co Reg No 200414041W
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-89999999
Vehicle Particulars
 Manufacturer NISSAN
 Model NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy YES
 Policy Number D-18090225MFCV/12
 Cover Note Number

Driver

Name of Driver PEH HAN YONG (BAI HANRONG)
 NRIC No S9041203E
 Date Of Birth 28/10/1990
 Occupation OUTDOOR
 Date Of Driving Pass 16/05/2014
 Driving Experience 4 YEARS AND 3 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-96708751
 Fax Number
 Contact Number OFFICE-96708751
 EMail Address NOEMAIL

Address	BLK 518 WEST COAST ROAD #04-577
Postcode	120518
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKK1115H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MOHANA DASS NAIR
NRIC/Passport Number	S1618463B
Contact Number	96609207
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form, and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and/or medical investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the issuing of correspondence, statements, invoices, reports or notices to me) which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared or disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
 - (ii) regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) for complying with requirements under any regulations, laws or court orders;




Policyholder
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Person's Signature
Name
NRIC/IN No.

Accident Sketch Plan

SKETCH PLAN



A: GDFV959R

B: JKE 1115H

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement.

DECLARATION

We declare the foregoing particulars are true in every respect



Date & Time

Driver's signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's signature
Name
NIC No.

Accident Sketch Plan

ON STATED DATE AND TIME, I WAS TRAVELLING ALONG LANE 1 WEST COAST HWY. VEHICLE INFRONT OF ME BRAKE HIS VEHICLE. I BRAKE MY VEHICLE ACCORDINGLY. SUDDENLY I FELT AN IMPACT OF MY VEHICLE, I ALIGHT FROM MY VEHICLE AND REALIZE THAT VEHICLE B HIT ONTO MY VEHICLE REAR PORTION.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Aug 2018		28 Aug 2018 16:28 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: MOHANA DASS S/O BALAKRISHNAN NAIR , ID: S1618463B, Tel: +6596609207, Email: MNAIRDAS@GMAIL.COM									
Main Claimant: ROBINSON CAR RENTAL PTE LTD , Co. Reg. No.: 200414041W									
Vehicle Reg. No.: GBF4989R		Date of Loss: 21/08/2018 19:00 - :59 [20 Months and 24 Days From LTA Reg Date (Man Yr)]	Policy/Cover Note No.: B27487632SMP (Comprehensive) Coverage: 30/03/2018 - 29/03/2019						
Claim Type: TP / 568202		Policy No. (Claimant):							
Vehicle Reg. No. (Insured): SKK1115H		Excess:	S\$1,000.00						
Repairer: H S Automotive Services (Kaki Bukit) BLK 2 KAKI BUKIT, AVENUE 2, # 01-15, KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 67472755									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Imm.Advice due 29/08/2018]									
Driver/Custodian (Insured): MOHANA DASS S/O BALAKRISHNAN NAIR (54 / Male), NRIC: S1618463B, Tel: +6596609207									
Adj Asg. Remarks: SURVEY DISAGREE ON SJE - ASSIGN LKK LIABILITY: 100% CONTACT: MR ALEX 6538 1368 UNIT NO: #02-25									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBF4989R (568202)

[SKK1115H]

TP

ROBINSON CAR RENTAL PTE LTD

Aug 21 2018 7:00PM

[MOHANA DASS S/O BALAKRISHNAN NAIR]

H S Automotive Services

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	28/08/18 13:44	Accident Statement From:OD - Reg. No: SKK1115H, Claimant: MOHANA DASS S/O BALAKRISHNAN NAIR	Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
2	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
3	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
4	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
5	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
6	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
7	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
8	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
9	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
10	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
11	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
12	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
13	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
14	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
15	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
16	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
17	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
18	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
19	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
20	29/08/18 18:26	General View	Load JPG	<input checked="" type="checkbox"/>	
21	08/10/18 10:02	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>	
22	08/10/18 10:02	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>	
23	08/10/18 10:02	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>	
24	08/10/18 10:02	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>	
25	08/10/18 10:02	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>	
26	08/10/18 10:02	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>	

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	28/08/18 13:44	TP GBF4989R GIA Report From:OD - Reg. No: SKK1115H, Claimant: MOHANA DASS S/O BALAKRISHNAN NAIR	Load PDF		
2	28/08/18 13:47	PRI - JUSEQUITY LAW CORPORATION	Load PDF		
3	28/08/18 15:17	SURVEY DISAGREE ON SJE - ASSIGN LKK	Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015777/NZ4D3E2

Date: 10/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B27487632SMP

Claimant Vehicle No : GBF4989R

Insured Vehicle No : SKK1115H

Date of Loss: 21/08/2018

Nature of Claim: TP

Claim No: 568202

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF4989R**

Make & Model: NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A)

Engine No: K9KC400D055941

Reg. Date: 28/11/2016 (Man. Year: 2016)

Chassis No: VSKYBAM20Z0131466

Colour: Silver

Odometer: 33975 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14C	Rear Tyre Size:	175/70 R14C
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/08/2018

Date Inspected: 29/08/2018 Inspected At:

H S Automotive Services (Kaki Bukit)
BLK 2 KAKI BUKIT, AVENUE 2, # 01-15,
KAKI BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Oct 2018)	
Parts:	N/A	NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF4989R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >