

ASS. REC. BY:

REF:

CS3 / C7118015785 / GZ2730T

Special Instruction:

✓

Surveyor

Mennen

ASSIGNMENT (Office)

From (Person):

Chong Sun Sen

of

C71

Date/Time:

28/8/18 @ 3.54pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GZ2730T

Insured:

GBD 21324

at Workshop m/s

McWell Ventures

Tel:

9389 3004

of

Slubi Ave 1 #01-05

Policy No:

DMCVSN/642681802

Claim No:

SNM18D04127C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/08/2018

CA / REV / REP. / REV 24 HRS

Inp

Insp: 8 Kelci Bkt Ave 4 # 01-4/48

H.O.D. Endorsement:

Date/Time:

9.51am @ 29/8/18

Person Contacted:

Alan

Vehicle IN/OUT

OUT

Date/Time	Action/Instruction (X) Estimate
	GZ2730T- X
	ABD 21324- CC6 / AIG 16009875 / Kzb3q1 DOA: 26/5/2016
31/9/18	Dummified.

(08/11/13) wef  
ASS. REC. BY:

PR5  
XAL.

REF: CTI

C 0478H /

(-2021)

### ASSIGNMENT

From: Date: 31/08/18

Estimated Cost:

OP: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GZ2730T  
at Workshop m/s: McWell Ventures  
of: 8 kaki Bkt Ave 4 #01-47/48

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \$18K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>sup</sup>

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 082730T Yr Regn: 20 Feb 2006

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace c.c. 2494

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 34873 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 5TFH 502P 7000 38730

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ S/Rim / STD A/Rim or

Tyre Size: F: 195R15

R: 11 (CT)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Sumitomo - (Rear)

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. D.O.I. 31-08-18

Survey held at w/s 12:25pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
\$ 3000 - \$ 4000

4/9/18 Submit PRS Report

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ )

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$ )

☐ : Interview (\$ )

☐ : Tech. Invs (\$ )

☐ : Weekend (\$ )

Survey Fee:

Transportation:

☐ S + RS, ☐ SI

☐ Photos

☐ Others

TOTAL

150

150

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Aug 2018		28 Aug 2018 15:54 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	STANDARD ROLLING SHUTTERS (PTE) LTD, Co. Reg. No.: 197802872C		
Main Claimant:	COSY-ACE ENGINEERING PTE LTD, Co. Reg. No.: 200510478H		
Vehicle Reg. No.:	GZ2730T	Date of Loss:	24/08/2018 09:00 - :59
Claim Type:	TP / SNM18D04127C02	Policy/Cover Note No.:	DMCVSN1642681802 (Comprehensive)
Vehicle Reg. No. (Insured):	GBD2132U	Policy No. (Claimant):	5097549002 COMP
		Excess:	S\$0.00
Repairer:	Mcwell Ventures Pte Ltd (HQ) 51 Ubi Ave 1, #01-05 Paya Ubi Industrial Park, 408933 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/09/2018]		
Driver/Custodian (Insured):	TAN BENG NOAN (52 / Male), NRIC: F0293235X, Tel: +6582847337		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date   Priority   Type   Task Group   Subject   Handler   Assigned By   Completed On   Created On   Done?

No results.




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS3/CTI18015785/Gz4d3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 29-08-2018		
		Code : CTI		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	GBD 2132U	Veh. Inspected	GZ 2730T	
Policy No.	DMCVSN1642681802	Coverage (\$)	0.00	
Claim No.	SNM18D04127C02	Excess (\$)	0.00	
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	29/08/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	24/08/2018	Inspection Date	31/08/2018	
Survey held at	MCWELL VENTURES PTE LTD 51 UBI AVE 1 #01-05/06 PAYA UBI IND. PARK SINGAPORE 408933			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/08/2018 11:36
Date Of Accident	24/08/2018 09:00
Exact Location Of Accident	PAYA LEBAR ROAD TOWARDS KPE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GZ2730T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COSY-ACE ENGINEERING PTE LTD
Co Reg No	200510478H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93598017

### Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE MANUAL
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097549002 COMP
Cover Note Number	

### Driver

Name of Driver	TAMIZHAZHAGAN AYYAPPAN
Passport No/FIN	G2356751U
Date Of Birth	07/03/1992
Occupation	OUTDOOR
Date Of Driving Pass	09/03/2015
Driving Experience	3 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93598017
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	65 UBI CRESCENT #03-08 HOLA CENTRE
Postcode	408559
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : SHUVO GENDER: : MALE
Passenger 2	NAME: : NAZRUL GENDER: : MALE
Passenger 3	NAME: : SHOFIQUUL GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD2132U
Vehicle Make/Model/Colour	TOYOTA DYNA 150 MANUAL
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time

*A. Nappay*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

24 AUG 2018

**IDAC KAKI BUKIT (VAC)**  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [vac@idac.com.sg](mailto:vac@idac.com.sg)  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle is ~~is~~ stationary when the lorry behind me  
bring onto it.

DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

24 AUG 2018

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No:



**REPUBLIC OF SINGAPORE DRIVING LICENCE**

**G2356751U**

**TAMIZHAZHAGAN AYYAPPAN**

Birth Date: 07 Mar 1992  
Issue Date: 09 Mar 2015  
Valid Till 08 Mar 2020

002402830A

**WORK PERMIT**  
Employment of Foreign Manpower Act (Chapter 91A)  
Republic of Singapore

Employer: COSY-ACE ENGINEERING PTE. LTD.

Sector: CONSTRUCTION

Name: TAMIZHAZHAGAN AYYAPPAN  
Occupation: CONSTRUCTION WORKER

Work Permit No. 036205369  
Date of Application: 22-09-2016  
Date of Issue: 13-09-2017  
Date of Expiry: 22-09-2018

L8306462

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

**EFFECTIVE DATE**

Class 2B Motorcycles <= 200 cc 09 Mar 2015  
Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 09 Mar 2015

NP 428A



**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Licence Number: **G2356751U**

Name: **TAMIZHAZHAGAN AYYAPPAN**

Birth Date: 07 Mar 1992  
Issue Date: 09 Mar 2015  
Valid Till 08 Mar 2020

002402830A

**VISIT PASS**  
Immigration Regulations

Name: TAMIZHAZHAGAN AYYAPPAN

Date of Birth: 07-03-1992  
Sex: M  
Nationality: INDIAN  
FIN: G2356751U  
Date of Issue: 13-09-2017  
Date of Expiry: 22-09-2018

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

**WORK PERMIT**  
Employment of Foreign Manpower Act (Chapter 91A)  
Republic of Singapore

Employer: COSY-ACE ENGINEERING PTE. LTD.

Sector: CONSTRUCTION

Name: TAMIZHAZHAGAN AYYAPPAN  
Occupation: CONSTRUCTION WORKER

Work Permit No. 036205369  
Date of Application: 22-09-2016  
Date of Issue: 13-09-2017  
Date of Expiry: 22-09-2018

L8306462

## Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number :** 5097549002

**Cover :** Comprehensive

- |  |                                |
|--|--------------------------------|
| 1. Index mark and Registration Number of Vehicle   | : <b>GZ2730T</b>               |
| Chassis Number   | : JTFHS02P700038730            |
| 2. Name of Policyholder  | : COSY-ACE ENGINEERING PTE LTD |
| 3. Effective Date of Insurance   | : 20 Feb 2018                  |
| 4. Expiry Date of Insurance  | : 19 Feb 2019                  |
| 5. Persons or Classes of Persons entitled to drive#  |                                |
| (a) The Policyholder.  |                                |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission.<br>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. |                                |
| 6. Limitations as to Use#  |                                |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.  |                                |
| (b) Use for the carriage of passengers or goods in connection with the Policyholder's business.  |                                |

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
INSURE WITH COE	: YES
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : DICKSON AUTO AGENCY (00000614645)  
Date of Issue : 25 Jan 2018 11:22 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

\_\_\_\_\_  
Authorised Officer



\_\_\_\_\_  
Chief Executive

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0478H
Vehicle Details	
Vehicle No.:	GZ2730T
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	2KD1416734
Chassis No.:	JTFHS02P700038730
Maximum Power Output:	-
Open Market Value:	\$23,810.00
Original Registration Date:	20 Feb 2006
First Registration Date:	20 Feb 2006
Transfer Count:	0
Actual ARF Paid:	\$1,191.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Feb 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,695.00
COE Rebate Amount:	\$11,185.00
<b>Total Rebate Amount:</b>	<b>\$11,185.00</b>
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 03 Sep 2018

OK

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Aug 2018		28 Aug 2018 15:54 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>STANDARD ROLLING SHUTTERS (PTE) LTD,</b> Co. Reg. No.: 197802872C								
Main Claimant:	<b>COSY-ACE ENGINEERING PTE LTD,</b> Co. Reg. No.: 200510478H								
Vehicle Reg. No.:	<b>GZ2730T</b>	Date of Loss:	24/08/2018 09:00 - :59 [150 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D04127C02</b>	Policy/Cover Note No.:	DMCVSN1642681802 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>GBD2132U</b>	Policy No. (Claimant):	5097549002 COMP						
		Excess:	S\$0.00						
Repairer:	<b>Mcwell Ventures Pte Ltd (HQ)</b> 8 Kakui Bukit Ave 4, #01-47/48 Premier@Kaki Bukit, 415875 Kaki Bukit - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 06/09/2018]								
Driver/Custodian (Insured):	TAN BENG NOAN (52 / Male), NRIC: F0293235X, Tel: +6582847337								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GZ2730T (SNM18D04127C02)  
[GBD2132U]  
TP  
COSY-ACE ENGINEERING PTE LTD  
Aug 24 2018 9:00AM  
[STANDARD ROLLING SHUTTERS (PTE) LTD]  
Mcwell Ventures Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	24/08/18 11:46	Accident Statement	Load HTM	

Photos/Images

3 per page

No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	24/08/18 11:45	Driving License [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	24/08/18 11:45	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	24/08/18 11:45	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	24/08/18 11:45	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	24/08/18 11:45	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	24/08/18 11:45	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page


No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/08/18 15:53	PRS	Load PDF	
2	28/08/18 15:53	OI GIA	Load PDF	

No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	24/08/18 11:46	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	24/08/18 11:46	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/18 11:03	LKKPhotosIn6-1.pdf	Load PDF	
2	04/09/18 11:03	LKKPhotosIn6-2.pdf	Load PDF	

## Linked Accident Report Documents

					View <div>View in Browser</div>	
Assessment Reports					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print	
1	24/08/18 11:46	Accident Statement		Load HTM		
Photos/Images					3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print	
1	24/08/18 11:45	Driving License		Load JPG	<input checked="" type="checkbox"/>	
2	24/08/18 11:45	Accident Photo		Load JPG	<input checked="" type="checkbox"/>	
3	24/08/18 11:45	Accident Photo		Load JPG	<input checked="" type="checkbox"/>	
4	24/08/18 11:45	Accident Photo		Load JPG	<input checked="" type="checkbox"/>	
5	24/08/18 11:45	Accident Photo		Load JPG	<input checked="" type="checkbox"/>	
6	24/08/18 11:45	Accident Photo		Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	24/08/18 11:46	Sketch Plan		Load TIF	
2	24/08/18 11:46	Sketch Plan #2		Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18015785/GZ4D3E2

Date: 05/09/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN1642681802

Claimant Vehicle  
No: GZ2730TInsured Vehicle  
No: GBD2132U

Date of Loss: 24/08/2018

Nature of Claim: TP

Claim  
No: SNM18D04127C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GZ2730T

Make &amp; Model: TOYOTA HIACE, 3.0 D (M)

Engine No: 2KD1416734

Reg. Date: 20/02/2006 (Man. Year: 2006)

Chassis No: JTFHS02P700038730

Colour: Silver

Odometer: 311873 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Sumitomo 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Sumitomo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 28/08/2018

Date Inspected: 31/08/2018 Inspected At:

Mcwell Ventures Pte Ltd (HQ)  
8 Kaki Bukit Ave 4, #01-47/48  
Premier@Kaki Bukit  
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 05 Sep 2018)

**Parts:** N/A TOYOTA HIACE 3.0 D (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for GZ2730T)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >