

2/03/2001

ASS. REC. BY:

REF:

CS31 MSG1801574362430

Special Instruction:

✓

SAVVOY
menmen

GG

ASSIGNMENT (Office)

From (Person):

Irene fan

of

MSG

Date/Time:

20/8/18 @ 10:03am

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

SGY 1327 L

Insured:

SJM 2112K

at Workshop m/s

Demick Motor

Tel:

96333593

of

Blk 9002 Tampines sf. 93 #01-72

Policy No:

29079674 SMA

Claim No:

56 8 593

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/08/2018

CA / REV / REP. / REV 24 HRS

up?

30/8/18

H.O.D. Endorsement:

Date/Time:

10:45am @ 20/8/18

Person Contacted:

Jeremy

Vehicle:

IN/OUT

Date/Time	Action/Instruction	(*) Estimate
	SGY 1327 L - X	
	SJM 2112K - CV / INC / 5003648 / Card	DOA: -

Surveyor

PRS
XRL

REF:

MS6

1107J

(C-222)

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TF / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

Derrick Motor

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

\$22K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ 5 days Res.: Yes or No

Lum Sum: _____ 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 56YB27L Yr Regn: 17 Sep 2007

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios C.C. 1497

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRO 53HY93054013570

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 30-08-18

Survey held at W/S 9AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$2200 - \$4000

31/8/19 Submit PRS Report.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee: 120

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Aug 2018		29 Aug 2018 10:03 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SIA JEE MING DAVID, ID: S8040481F		
Main Claimant:	GOH JIN RUI, ID: S9201107J		
Vehicle Reg. No.:	SGY1327L	Date of Loss:	27/08/2018 22:00 - :59 [131 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 568593	Policy/Cover Note No.:	29079674SMA (Comprehensive) Coverage: 29/04/2018 - 28/04/2019
Vehicle Reg. No. (Insured):	SJM2112K	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Messrs Derrick Motor Works (HQ) BLK 9002 TAMPINES ST 93, #01-72, TAMPINES IND PARK A, 528836 Tampines - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/08/2018]		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK OI NOT REPORTED CONTACT: MR JEREMY 9633 3593		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18015793/Gz4d3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 29-08-2018		
		Code : MSG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SJM 2112K	Veh. Inspected	SGY 1327L	
Policy No.	29079674SMA	Coverage (\$)	0.00	
Claim No.	568593	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAN)	Assign Date	29/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/08/2018	Inspection Date	30/08/2018	
Survey held at	DERRICK MOTOR WORKS BLK 9002 #01-72 TAMPINES ST 93 SINGAPORE 528836			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/08/2018 15:52
Date Of Accident	27/08/2018 22:05
Exact Location Of Accident	WITHIN SIM CAMPUS- CLEMENTI RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGY1327L
Insured/Policyholder	
Name Of Registered Owner	GOH JIN RUI
NRIC No	S9201107J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91138747
Alternative Phone No	OFFICE-91138747

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092794132
Cover Note Number	

Driver

Name of Driver	GOH KAI LIN JORENE
NRIC No	S9502541B
Date Of Birth	20/01/1995
Occupation	INDOOR
Date Of Driving Pass	26/01/2017
Driving Experience	1 YEAR AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91275721
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 334 HOUGANG AVE 5 #03-246
Postcode	530334
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM2112K
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SIA JEE MING DAVID
NRIC/Passport Number	S8040481F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	GOH KAI LIN JORENE
Approximate Age	

Injuries Sustain

2 DAYS MC

Injured person in which vehicle?

SGY1327L

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle A was stopped along the road waiting for traffic in front of me to clear when all of a sudden I felt a bump from the rear of my vehicle A. After I composed myself, I came out of my vehicle and noticed vehicle B had collided with the rear of my vehicle. The driver of vehicle B said sorry to me and we exchanged particulars and left the scene.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Aug 2018		29 Aug 2018 10:03 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------






































CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	SIA JEE MING DAVID, ID: S8040481F			
Main Claimant:	GOH JIN RUI, ID: S9201107J			
Vehicle Reg. No.:	SGY1327L	Date of Loss:	27/08/2018 22:00 - :59 [131 Months and 10 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 568593	Policy/Cover Note No.:	29079674SMA (Comprehensive) Coverage: 29/04/2018 - 28/04/2019	
Vehicle Reg. No. (Insured):	SJM2112K	Policy No. (Claimant):		
		Excess:	S\$500.00	
Repairer:	Messrs Derrick Motor Works (HQ) BLK 9002 TAMPINES ST 93, #01-72, TAMPINES IND PARK A, 528836 Tampines - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 30/08/2018]			
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK OI NOT REPORTED CONTACT: MR JEREMY 9633 3593			































ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SGY1327L (568593)**
[SJM2112K]
TP
GOH JIN RUI
Aug 27 2018 10:00PM
[SIA JEE MING DAVID]
Messrs Derrick Motor Works

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
2	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
3	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
4	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
5	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
6	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
7	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
8	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
9	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
10	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
11	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
12	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
13	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
14	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
15	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
16	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
17	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
18	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
19	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
20	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
21	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
22	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
23	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
24	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
25	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
26	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
27	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
28	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
29	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
30	31/08/18 12:32	General View	 Load JPG	<input checked="" type="checkbox"/>
31	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	03/09/18 08:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/08/18 17:54	PRI - VISION LAW LLC	 Load PDF	
2	28/08/18 17:54	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	
3	28/08/18 17:54	SGY1327L TP E-FILE REPORT	 Load PDF	
4	28/08/18 17:57	EMAIL FROM TP - WHICH WORKSHOP TO SURVEY	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015793/GZ4D3E2

Date: 04/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29079674SMA

Claimant Vehicle No : SGY1327L

Insured Vehicle No : SJM2112K

Date of Loss: 27/08/2018

Nature of Claim: TP

Claim No: 568593

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGY1327L

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 1NZX580360

Reg. Date: 17/09/2007 (Man. Year: 2007)

Chassis No: MR053HY9305013570

Colour: Silver

Odometer: 0 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/08/2018

Date Inspected: 30/08/2018 Inspected At:

Messrs Derrick Motor Works (HQ)
BLK 9002 TAMPINES ST 93, #01-72,
TAMPINES IND PARK A
Singapore 528836

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Sep 2018)

Parts: 143 TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGY1327L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >