

| Date/Time        | Action/Instruction (✓) Estimate             |
|------------------|---------------------------------------------|
|                  | FBB 3796H - X                               |
|                  | SHC8907X-CS3/FCI18003067/Ud3s2 DoA: 10/2/18 |
| 31/8/18 @ 3.50pm | revised to Joanne Yung by email.            |
|                  |                                             |
|                  |                                             |

(08/11/13) waf

ASS REG BY:

Wofey

REF:

FCI

## ASSIGNMENT

From:

Date:

30/8/18

Estimated Cost:

OP ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBB 3796 H

at Workshop m/s

Tee Spray Painting

of

Blk 6 Defu Lane 10 # 01-558

Insured:

62835474

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Afternoon

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

12k.

IDAC Accident Rpt:

Consistent? : Yes or No

(P) / PR Seen:

2

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(Ds)

16/3/2017

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBB 3796 H

Yr Regn:

3, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda CB400

c.c. 399

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JH2NC39916M200670

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120 / 60 R17

R:

160 / 60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

30/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2745344

30/8/18 conf. with L/S # 3200 with Steven (Red \$ 7677.59, 45%)

RECEIVED 03 SEP 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) 03/9 11:00 AM

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, \$

) Photos

) Others

TOTAL

140

50

67

257

Report Format :

TP

Lump Sum / I.B.I. (\$

3200



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18015807/Uqd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 29-08-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                   |                |            |
|--------------|-------------------|----------------|------------|
| Insured Veh. | SHC 8907X         | Veh. Inspected | FBB 3796H  |
| Policy No.   |                   | Coverage (\$)  | 0.00       |
| Claim No.    | D18006297MFSH     | Excess (\$)    | 0.00       |
| Assign From  | CWS (JOANNE YONG) | Assign Date    | 29/08/2018 |

## 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |                                                                                         |                 |            |
|----------------|-----------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 18/08/2018                                                                              | Inspection Date | 30/08/2018 |
| Survey held at | TEO SPRAY PAINTING<br>BLK 6 DEFU LANE 10 DEFU IND PARK C<br>#01-558<br>SINGAPORE 539187 |                 |            |

## 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

**MOTOR SURVEY ASSIGNMENT**

|                    |                                                                                   |                               |
|--------------------|-----------------------------------------------------------------------------------|-------------------------------|
| Date               | 23-08-2018                                                                        | Our Ref No. D18006297MFSH     |
| Accident Date      | 18-08-2018                                                                        | Claim Type. Third Party       |
| Insured Vehicle    | SHC8907X                                                                          | Third Party Vehicle. FBB3796H |
| Survey Location    | BLK 6 DEFU LANE 10 DEFU INDUSTRIAL PARK C#01-558                                  |                               |
| Contact Person.    | IRENE SUAN                                                                        |                               |
| Contact No.        | 62835474/ 0                                                                       | Fax No. 65073849              |
| Survey Type        | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED (NO EST. COR PROVIDED) |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD                                                      |                               |
| Contact Person     | NA                                                                                | Fax No. 68416315              |
| Contact Number.    | NA                                                                                |                               |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                   |                    |                         |
|-------------------|--------------------|-------------------------|
| Cc : Workshop     | TEO SPRAY PAINTING | Attention. NIL          |
| Cc : TP Solicitor | NA                 | TP Solicitor Fax No. NA |
| Officer Incharge  | JOANNEY            |                         |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 31 August 2018 3:50 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18006297MFSH/1  
**Attachments:** CSFCI18015807Uqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of FBB 3796H.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 29 August 2018 2:07 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18006297MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 30/08/2018.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Wednesday, 29 August 2018 12:37 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [JOANNEYONG@MSFIRSTCAPITAL.COM.SG](mailto:JOANNEYONG@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18006297MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note:** All the accident reports are uploaded into CWS for your perusal.

Best Regards,



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006297MFSH

Date: 31 August 2018

Our Ref: CS/FCI18015807/Uqd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF MOTORBIKE NO. FBB 3796H**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/08/2018 at the premises of M/s TEO SPRAY PAINTING, and have the following to report:-

|                          |                       |
|--------------------------|-----------------------|
| Workshop Estimate Amount | : S\$ <u>5,822.59</u> |
| Revised Estimate Amount  | : S\$ <u>4,110.18</u> |
| "Check" Items Amount     | : S\$ <u>-</u>        |
| Market Value             | : S\$ <u>-</u>        |
| LTA Reimbursement Value  | : S\$ <u>-</u>        |
| Nett Value               | : S\$ <u>-</u>        |

**Description of Damage:**

The vehicle sustained damages  
at the n/s body.



Yours faithfully

CHUA KANG SENG  
Licensed Appraiser

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 8761D

**Vehicle Details**

Vehicle No.: FBB3796H

Vehicle to be Exported: No

Intended De-registration Date: 30 Aug 2018

Vehicle Make: HONDA

Vehicle Model: CB400

Primary Colour: Black

Manufacturing Year: 2006

Engine No.: NC23E3100700

Chassis No.: JH2NC39916M200670

Maximum Power Output: -

Open Market Value: \$6,120.00

Original Registration Date: 17 Mar 2007

First Registration Date: 17 Mar 2007

Transfer Count: 5

Actual ARF Paid: \$918.00

**Intended PARF Rebate Details**

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 16 Mar 2027

COE Category: D - Motorcycle

COE Period(Years): 10

PQP Paid: \$6,256.00

COE Rebate Amount: \$5,344.00

**Total Rebate Amount: \$5,344.00**

The information contained herein is correct as at 30 Aug 2018

OK

[REPORT ERROR > \(/LISTING/LISTING/ERROR/USEDBIKE/8999/\)](#)[+ ADD TO SHORTLIST](#)[SHARE \(WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/HONDA-HONDA-CB400-SUPER-4-SPEC-3/8999/\)](#)

## Honda CB400 Super 4 Spec 3

|                   |                                                                                     |
|-------------------|-------------------------------------------------------------------------------------|
| Listing Type      | Paid Ad                                                                             |
| Brand             | Honda (/listing/usedbike/brand/honda/)                                              |
| Model             | Honda CB400 Super 4 Spec 3<br>(/listing/usedbike/model/honda-cb400-super-4-spec-3/) |
| Engine Capacity   | 399cc                                                                               |
| Classification    | 2A                                                                                  |
| Registration Date | 21/09/2007                                                                          |
| COE Expiry Date   | 20/09/2027 (9 years left)                                                           |
| Mileage           | -                                                                                   |
| No. of owners     | -                                                                                   |
| Type of Vehicle   | Street Bikes (/listing/usedbikes/listing/?bike_type=7)                              |

**Price: SGD\$15000**

### DETAILS

Loan available. 0% interest credit card installment plans available. Low down payment, low interest & the highest trade in. Contact us now.

[SIMILAR BIKES](#)[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](#)





# 張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)  
Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558  
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012  
REG. NO. 275084 / 00X

First Capital Insurance Limited  
36 Robinson Road  
#16-01 City House  
Singapore 068877  
Tel: 65073848  
Fax: 65073849

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

28.08.2018

Dear Sir/Madam

RE: THIRD PARTY CLAIMS FOR FBB3796H AGAINST YOUR  
INSURED SHC8907X, ACCIDENT ON 18.08.2018 AT PAN ISLAND  
EXPRESSWAY ALONG PIE NEAR EXIT, JLN EUNOS TOWARDS  
CHANGI AIRPORT.

not Alvin  
dbr  
2/35 3200/2  
Hdy.  
30/8/18  
To the photo of the 1st  
6 256 3561

PG 1

| DESCRIPTION                          | AMOUNT                |
|--------------------------------------|-----------------------|
| 1 HANDLE BAR <i>but</i>              | \$ 234.00             |
| 2 CLUTCH LEVER <i>cut</i>            | \$ 36.40              |
| 3 CLUTCH HOLDER <i>2ye</i>           | \$ 62.40              |
| 4 METER COMP <i>cut</i>              | \$ 1,365.00           |
| 5 HEADLAMP COMP <i>cut</i>           | \$ 689.00             |
| 6 FRONT MUDGUARD <i>cut</i>          | \$ 253.50             |
| 7 BALANCER <i>scn</i>                | \$ 29.90              |
| 8 FUEL TANK <i>cut Local Respray</i> | \$ 1,625.00 X 1805.00 |
| 9 TAIL COVER <i>cut</i>              | \$ 546.00             |
| 10 FRONT FOOTREST LH <i>twi</i>      | \$ 234.00             |
| 11 ENGINE COVER LH <i>an</i>         | \$ 273.00             |
| 12 GASKET <i>an</i>                  | \$ 16.90              |
|                                      | \$ 5,365.10           |
| Less 10%                             | \$ 536.51             |
| Sub Total                            | \$ 4,828.59           |

3450.2  
3108.18

| Nett Item                       |                   |
|---------------------------------|-------------------|
| 1 IU UNIT <i>2ye</i>            | \$ 180.00 165 S.N |
| 2 CRASHBAR <i>BP</i>            | \$ 100.00 S.N     |
| 3 ENGINE OIL \$28 X 3 <i>11</i> | \$ 84.00          |
| 4 LABOUR CHARGES                | \$ 280.00 260     |
| 5 BOX & BRACKET <i>cut/BK</i>   | \$ 350.00 300     |
| Sub Total                       | \$ 994.00         |
| Total                           | \$ 5,822.59       |

THANKS  
TSP



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                                         |                 |                             |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------|-----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                                         |                 | Ref : CS/FC118015807/Uqd3n2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                                         |                 | Date : 06-09-2018           |  |
|                                                                                                                                                                                        |                                                                                         |                 | Code : FCI2                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                                         |                 |                             |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHC 8907X                                                                               | Veh. Inspected  | FBB 3796H                   |                                                                                     |
| Policy No.                                                                                                                                                                             |                                                                                         | Coverage (\$)   | 0.00                        |                                                                                     |
| Claim No.                                                                                                                                                                              | D18006297MFSH                                                                           | Excess (\$)     | 0.00                        |                                                                                     |
| Assign From                                                                                                                                                                            | JOANNE YONG                                                                             | Assign Date     | 29/08/2018                  |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                                         |                 |                             |                                                                                     |
| Make & Model                                                                                                                                                                           | HONDA CB400                                                                             | c.c             | 399                         |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                                  | Year of Reg.    | 2007                        |                                                                                     |
| Chassis No.                                                                                                                                                                            | JH2NC39916M200670                                                                       | Colour          | BLACK                       |                                                                                     |
| Odometer                                                                                                                                                                               | -                                                                                       | Steering        | IN ORDER                    |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                                | Modification    | SPORTS RIM                  |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                                    |                 |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                                         |                 |                             |                                                                                     |
|                                                                                                                                                                                        | Size                                                                                    | Make            | Balance                     |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 120/60 ZR17                                                                             | PIRELLI         | 6 mm                        |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         |                                                                                         |                 | mm                          |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 160/60 ZR17                                                                             | PIRELLI         | 6 mm                        |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          |                                                                                         |                 | mm                          |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                                         |                 |                             |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.                                                                                                                                         |                                                                                         |                 |                             |                                                                                     |
| DAMAGES SEE DETAILS.                                                                                                                                                                   |                                                                                         |                 |                             |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                                         |                 |                             |                                                                                     |
| Accident Date                                                                                                                                                                          | 18/08/2018                                                                              | Inspection Date | 30/08/2018                  |                                                                                     |
| Survey held at                                                                                                                                                                         | TEO SPRAY PAINTING<br>BLK 6 DEFU LANE 10 DEFU IND PARK C<br>#01-558<br>SINGAPORE 539187 |                 |                             |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                                         |                 |                             |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                         |                 |                             |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                                         |                 |                             |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                                         | 4 Working Days  |                             |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBB 3796H

| Qty                                                                         | Description of Parts          | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|-------------------------------|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>                                                 |                               |               |                           |                   |
| 1                                                                           | HANDLE BAR                    | BENT          | 234.00                    | 234.00            |
| 1                                                                           | CLUTCH LEVER                  | CUT           | 36.40                     | 36.40             |
| 1                                                                           | CLUTCH HOLDER                 | DAMAGED       | 62.40                     | 62.40             |
| 1                                                                           | METER COMP                    | CRACKED       | 1,365.00                  | 1,365.00          |
| 1                                                                           | HEADLAMP COMP                 | DENTED        | 689.00                    | 689.00            |
| 1                                                                           | FRONT MUDGUARD                | CUT           | 253.50                    | 253.50            |
| 1                                                                           | BALANCER                      | SCRATCHED     | 29.90                     | 29.90             |
| 1                                                                           | TAIL COVER                    | CUT           | 546.00                    | 546.00            |
| 1                                                                           | FRONT FOOTREST LH             | TWISTED       | 234.00                    | 234.00            |
| 1                                                                           | ENGINE COVER LH               | NOT NECESSARY | 273.00                    | -                 |
| 1                                                                           | GASKET                        | NOT NECESSARY | 16.90                     | -                 |
|                                                                             | LESS 10% DISCOUNT             |               | -374.01                   | -345.02           |
|                                                                             |                               |               | 3,366.09                  | 3,105.18          |
| 1                                                                           | FUEL TANK (LOCAL RESPRAY)(SN) | DENTED        | 1,625.00                  | 180.00            |
|                                                                             | LESS 10% DISCOUNT             |               | -162.50                   | -                 |
|                                                                             |                               |               | 1,462.50                  | 180.00            |
| <b>SPECIAL NETT ITEMS</b>                                                   |                               |               |                           |                   |
| 1                                                                           | IU UNIT (SN)                  | DAMAGED       | 180.00                    | 165.00            |
| 1                                                                           | CRASHBAR (SN)                 | BENT          | 100.00                    | 100.00            |
| 3                                                                           | ENGINE OIL @\$28.00 (SN)      | NOT NECESSARY | 84.00                     | -                 |
| 1                                                                           | BOX & BRACKET (SN)            | CUT / BENT    | 350.00                    | 300.00            |
|                                                                             |                               |               | 714.00                    | 565.00            |
| <b>LABOUR</b>                                                               |                               |               |                           |                   |
|                                                                             | LABOUR CHARGES.               |               | 280.00                    | 260.00            |
|                                                                             |                               |               | 280.00                    | 260.00            |
| <b>GRAND TOTAL</b>                                                          |                               |               | <b>5,822.59</b>           | <b>4,110.18</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                               |               |                           | <b>3,200.00</b>   |



Report Ref No. CS/FCI18015807/Uqd3n2

A handwritten signature in black ink, appearing to be 'Chua' followed by a stylized 'K' and 'S'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.