

ASS. REC. BY: Surveyor REF: CS/EG18015808/Tcd3 ⁿ² Report of Investigation

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time: 28/6/18 @ 6:38pm

Estimated Cost: _____ Bill to: _____

OD/TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGH 9797A Insured: SKH 5923G

at Workshop n/s: Tan chong Tel: 67038916

of 913 Bkt timah

Policy No: _____ Claim No: DSMPC1801399

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A: 17/07/2018
(Client's Record) 30/6/18 @ 10am

CA / REV / REP. / REV 24 HRS ^{hp} H.O.D. Endorsement: _____

Date/Time: 10:01am @ 28/6/18 Person Contacted: zuhri Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SGH 9797A -x</u>
	<u>SKH 5923G -x</u>
	<u>Report 1A via email.</u>
	<u>Confirmed Serial Sig 21766-32 and 3 days with Zuhri. (Ref 4897, 516)</u>

Taylor

REF:

EG1

Survey No.

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop no/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle IN / OUT

Vehicle: SGH 9797A Yt Regn: 2015 July
 Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Nissan Sylphy 1598
 Colour: Grey A/C Insured / Std / NI / NA
 Sp Reading: 68249 T/Radio Insured / Std / NI / NA
 Eng/No: MNT BRAB/770024153
 C/No: _____
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size F: 205/55R16
 R: _____
 BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 Rear: 6
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. D.O.I. 9/8/13C1020
 Survey held at TC BHT timah
 Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 17 APR 2019

Draw/Time File Part No: ☐ : Prel. Report
☐ : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 1

Draw/Time File Return No: _____
 Report Format: TP
 Lump Sum / ☒ P: 1766.32

Add Fee: ☐ Site Insp: 1\$
☐ Littering: 1\$
☐ Traffic: 1\$
☐ Witness: 1\$

Survey Fee: _____
 Transport: _____
 250



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DSMPC1801399
Our Ref: CS/EG118015808/T1rd3

The Motor Claims Department
ERGO Insurance Pte Ltd

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SGH 9797A


We thank you for the instruction on 28/08/2018.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30/08/2018 at the premises of M/s TAN CHONG MOTOR SALES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 2,255.32
Revised Estimate Amount	: S\$ 1,321.32
"Check" Items Amount	: S\$ 44.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully

TAUFIKH
Automotive Assessor

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 28 August 2018 6:38 PM
To: 'admin-d@lkkauto.com'
Subject: OI : SKH5923G / TP : SGH9797A/LKK / DOA : 17/07/2018 (DSMPC1801399)
Attachments: 2ND VEH - OI - SKH5923G - SAS.pdf; SGH9797A - SAS.pdf; SGH9797A - ESTIMATE.pdf; SGH9797A - PRS FORM.pdf; RE: (DSMPC1801399) ACCIDENT INVOLVING SGH9797A & SKH5923G ON 17/07/2018 ... (174 KB)

Dear Catherine/Nivitha

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **TAN CHONG MOTOR SALES PTE LTD**,

ADDRESS : 913 BUKIT TIMAH ROAD
SINGAPORE 589623

PERSON TO CONTACT : ZUHRI @ 6703 8916 / 6466 7711

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on DIRECT SETTLEMENT basis. Please inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li (Ms)
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID +65 6829 9194
Tel +65 6829 9199
Fax +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Wednesday, November 21, 2018 10:26 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Subject: RE: SKH5923G / TP : SGH9797A/LKK / DOA : 17/07/2018 (DSMPC1801399)
Attachments: SGH 9797A .pdf

Dear Sir/ Madam,

Enclosed preliminary revised for SGH 9797A.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, August 29, 2018 3:43 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SKH5923G / TP : SGH9797A/LKK / DOA : 17/07/2018 (DSMPC1801399)

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 30/08/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Tuesday, 28 August 2018 6:38 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : SKH5923G / TP : SGH9797A/LKK / DOA : 17/07/2018 (DSMPC1801399)

Dear Catherine/Nivitha

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5129E
Vehicle Details	
Vehicle No.:	SGH9797A
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	HR16970379B
Chassis No.:	MNTBBAB17Z0024153
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$16,028.00
Original Registration Date:	31 Jul 2015
First Registration Date:	31 Jul 2015
Transfer Count:	0
Actual ARF Paid:	\$16,028.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2025
PARF Rebate Amount:	\$12,021.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,889.00
COE Rebate Amount:	\$37,980.00
Total Rebate Amount:	\$50,001.00

The information contained herein is correct as at 13 Oct 2018

OK



HOTLINE TEL: (65) 6419-3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

NISSAN AUTO PROTECTOR

CERTIFICATE NO. 2100422925-02000

(The below excess is subject to GST)

OWN DAMAGE EXCESS S\$600.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value

INSURING WITH COE/PARF Yes

1) VEHICLE REGISTRATION NO.

SGH9797A

2) NAME OF INSURED

OH EU LIANG DAREN (HU YOU LIANG

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

DAREN)
31 Jul 2017

4) DATE OF EXPIRY OF INSURANCE

30 Jul 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

SUBJECT TO AGE CONDITION : All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDER") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / NISSAN AUTHORISED REPAIRERS

1. Tan Chong Mtr - 913 Bt Timah Rd (T: 64694091/2/3) 2. Tan Chong Mtr - 17 Lor 8 Toa Payoh (T: 63570753/4)

3. TC AutoClinic - No 1 Sixth Lok Yang Rd (T: 62622212) 4. Autolotion Industrial - 19 Ubi Rd 4 (T: 64909666)

5. TC AutoClinic - 25 Lang Kee Rd (T: 67038511/2/3)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

6. ComfortDelgro Engrg - 205 Braddell Rd (T: 63837118) 7. DPS Body & Paint Workshop - 209 Pandan Gardens (T: 65684501)

8. Ethoz - 30 Bukit Batok Cres (T: 66547777) 9. Glass-Fix - 52 Ubi Ave 3 (T: 62780887) - For windscreen only

10. Kan Fook Sing Motor - 61 Defu Lane 12 (T: 67479560) 11. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (T: 64538110)

12. Mova Automotive - 1006 Bukit Merah Lane 3 (Tel: 62723892) 13. Progressive Automotive - 3022A Ubi Rd 1 (T: 67415336)

14. SME Motor - 1 Kaki Bukit Ave 6 Bldg D (T: 67476106)

LOSS OF USE Loss of Use 10 Days (1500 - 1600cc) - Refer to policy wordings for details

* NAMED DRIVER NA

HIRE PURCHASE COMPANY DBS BANK LTD

EMPLOYER'S LOAN

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 4 Jul 2017

AIG Asia Pacific Insurance Pte. Ltd.

500610-360
TAN CHONG CREDIT PTE LTD-NAC
911 BUKIT TIMAH ROAD
TAN CHONG MOTOR CENTRE
SINGAPORE 589622
ANSP-MOTOR

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCQUK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7245129E



OH EU LIANG DAREN
(HU YOU LIANG DAREN)

胡友良

Race

CHINESE

Date of Birth

08-12-1972

Sex

M

Country of Birth

SINGAPORE

3274788



NRIC No. S7245129E



Valid Until

Date of Issue

11-12-2002

1001 ANG MO KIO AVENUE 1 #04-05

SINGAPORE 569979

NRIC No.

S7245129E

Date

11/08/2007 (R)

No.

5605938

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number **S9890531F**

STEFANIE DANA OH QIAORONG

12 Sep 1998
26 Oct 2017

002737593J

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9890531F



Name

STEFANIE DANA OH QIAORONG

胡巧蓉

Race

CHINESE

Date of birth

12-09-1998

Country/Place of birth

UNITED STATES

Sex

F

S9890531F

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$


EFFECTIVE DATE

26 Oct 2017

5173123



NRIC No. **S9890531F**



Date of issue

14-05-2013

Address

**1801 ANG MO KIO AVENUE 1
#04-05
SINGAPORE 669979**



NP 428A

Authorization Letter

To whom it may concern

Date of Accident: 17/07/18

I, Oh Eu Liang Daren of NRIC S7245129E,
owner & policy holder of vehicle number SGH9797A, hereby authorize
Stefanie Dana Oh Qiaorong of NRIC S9890531F

to handle the matter pertaining to the accident dated above.



Signature of owner & policy holder

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/2HR/0322/2018
DATE : 01-AUG-2018

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTH : CLAIM MANAGER

OWNER'S NAME : OH EU LIANG DAREN
ADDRESS : 1801 ANG MO KIO AVE 1
#04-05
S(569979)
TELEPHONE NO : 68585003 / 81825588

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SKH5923G
VEHICLE NO : SGH9797A
MODEL CODE : BDTARC2B17EWA----A
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)
ENGINE NO : HR16970379B
CHASSIS NO : MNT00B01720024153
MILEAGE : 1 KM
DATE IN : 01/08/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 17/07/2018

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

~~CAR AT WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

01/08/2018

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

Tanpin 97475744
- up -
30/8/18 @ 1020.
05 days
Reply before paint
sure@kileauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGH9797A

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	✓
2 EE/001	REPAIR REAR END PANEL, REAR TRUNK LID RENEW REAR BUMPER COVER	780.00	390. 585
3 EE/002	S/PAINT REAR BUMPER COVER, TRUNK LID & REAR END PNL	750.00	250. 500
	TOTAL LABOUR CHARGES	1640.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGH9797A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	REVERSE SENSOR	SENSOR-KP380N			65.00 <i>OK</i> ✓
2	ORNAMENT ASSY L	26565-5C000	55.00	<i>OK</i>	
3	CLIP(10X1.2)	01553-10501	12.00	<i>OK</i>	
4	FASCIA RR BMR	85022-35T0H	620.90	<i>OK</i>	
SUB TOTAL			687.90	0.00	65.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			137.58	0.00	0.00
GRAND TOTAL			550.32	0.00	65.00
OVERALL TOTAL			615.32		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGH9797A

TOTAL LABOUR CHARGES	1640.00
TOTAL SPARE PARTS CHARGES	615.32
GRAND TOTAL	2255.32 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLE NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALISED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/SHR/0322/2018
DATE : 01-AUG-2018

PS => Taufik

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

ZHR

OWNER'S NAME : OH EU LIANG DAREN
ADDRESS : 1801 ANG MO KIO AVE 1
#04-05
S(569979)
TELEPHONE NO : 68585003 / 81825588

(3 Days)

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SKH5923G
VEHICLE NO : SGH9797A
MODEL CODE : BDTARCID17EWA----A
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)
ENGINE NO : HR16970379B
CHASSIS NO : MHTBBAB17E0024153
MILEAGE : 1 KM
DATE IN : 01/08/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD IZHRI
ACCIDENT DATE : 17/07/2018

Lay => PTS

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGH9797A

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	110.00
2 II/001	REPAIR REAR END PANEL, REAR TRUNK LID RENEW REAR BUMPER COVER	780.00	585.00
3 II/002	R/FAINT REAR BUMPER COVER, TRUNK LID & REAR END PNL	750.00	500.00
TOTAL LABOUR CHARGES		1640.00	1195.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGH9797A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	REVERSE SENSOR	SENSOR-XP380N			65.00 OK
2	ORNAMENT ASSY L	26565-5C000	55.00		X
3	CLIP(10X1.2)	01553-10501	12.00		OK
4	FASCIA RR BMFR	85022-3ST0H	620.90		OK
SUB TOTAL			632.90	0.00	65.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			126.58	0.00	0.00
GRAND TOTAL			506.32	0.00	65.00
OVERALL TOTAL			571.32		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SGR9797A

NETT ITEM	632.90
LESS 20.00%)	-126.58
NETT AMOUNT	506.32

LIST ITEM	0.00
LESS 20.00%)	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	65.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	65.00

TOTAL LABOUR CHARGES	1195.00
TOTAL SPARE PARTS CHARGES	571.32

TOTAL CHARGES	1766.32
ADD 7 % GST	123.64

GRAND TOTAL	1889.96
-------------	---------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EG118015808/T1cd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 17-04-2019		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKH 5923G	Veh. Inspected	SGH 9797A	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMPC1801399	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	28/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MNTBBAB17Z0024153	Colour	GREY	
Odometer	68299	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	GOODYEAR	6 mm	
L/H Front Tyre	205/55 R16	GOODYEAR	6 mm	
R/H Rear Tyre	205/55 R16	GOODYEAR	6 mm	
L/H Rear Tyre	205/55 R16	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/07/2018	Inspection Date	30/08/2018	
Survey held at	TAN CHONG MOTOR SALES PTE LTD 913, BUKIT TIMAH RD, SINGAPORE 589623.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGH 9797A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	ORNAMENT ASSY L (N)	NOT NECESSARY	55.00	-
10	CLIP @\$1.20 (N)	NECESSARY	12.00	12.00
1	FASCIA RR BMPR (N)	DEFORMED	620.90	620.90
	LESS 20% DISCOUNT		-137.58	-126.58
			550.32	506.32
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	NOT WORKING	65.00	65.00
			65.00	65.00
	LABOUR			
	REPLACE REVERSE SENSOR,NECESSARY ADJUSTMENT & FUNCTION TEST.		110.00	110.00
	REPAIR REAR END PANEL,REAR TRUNK LID RENEW REAR BUMPER COVER.		780.00	585.00
	S/PAINT REAR BUMPER COVER,TRUNK LID & REAR END PANEL.		750.00	500.00
			1,640.00	1,195.00
	GRAND TOTAL		2,255.32	1,766.32
	RECOMMENDED COST OF REPAIRS			1,766.32

Report Ref No. CS/EGI18015808/T1cd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.