

7/10/2000

ASS. REC. BY:

REF:

<sup>3</sup>CS/FCI/18015809/k2d3<sup>5r</sup>

Special Instructions:

Surveyor  
CWS

GA

ASSIGNMENT (Office)

From (Person):

Shirley

of

FCI

Date/Time:

4:06pm @ 29/8/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKT 3170L

Insured:

SHC 7273Y

at Workshop m/s

Apex Motoring

Tel:

9006 418 4

of

29 Kaki Bkt Rd 4 #01-55

Policy No:

Claim No:

D18006436MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/08/2018

30/08/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

4:45pm @ 29/8/18

Person Contacted:

Shirley

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SKT 3170L-X

SHC 7273Y-CS/FCI/2011459/Uy/k3

DoA: 8/6/12

31/8/18

Dismantled

6.11.2

3/9/18

After repair

(08/11/13) wof

ASS. REC. BY:

PRS

Xnd

REF:

FCI

## ASSIGNMENT

From:

Date:

30/8/18

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKT 3170L

at Workshop m/s

Apex Motoring

of

25 kuki Bkt Rd A # 01-55

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

\$26k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKT3170L

Yr Regn:

8-1

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota AXIO

C.C

1496

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

211288

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NZE 1617104151

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

30-08-18

Survey held at

W/S

4:15pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

31/8/18

Submit PRS Report

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

PRS

Lump Sum / I.B.I. (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS3/FCI18015809/Gz4d3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 29-08-2018



Code : FCI2

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHC 7273Y	Veh. Inspected	SKT 3170L
Policy No.		Coverage (\$)	0.00
Claim No.	D18006436MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	29/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	28/08/2018	Inspection Date	30/08/2018
Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.		

## 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

**MOTOR SURVEY ASSIGNMENT**

Date	28-08-2018	Our Ref No.	D18006436MFSH
Accident Date	28-08-2018	Claim Type.	Third Party
Insured Vehicle	SHC7273Y	Third Party Vehicle.	SKT3170L
Survey Location	25 Kaki Bukit Road 4 #01-55 Synergy @ KB		
Contact Person.	SHIRLEY		
Contact No.	68424992/ 90064184	Fax No.	0
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	APEX MOTORING	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	SITHARA		

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Nivitha (LKK Auto)

**From:** Sithara <Sithara@msfirstcapital.com.sg>  
**Sent:** Wednesday, 29 August 2018 4:27 PM  
**To:** Catherine Chong (LKK Auto); 'assignments@lkkauto.com'; sur@lkkauto.com  
**Subject:** FW: SURVEY ASSESSMENT - D18006436MFSH/1  
**Attachments:** Jobsheet\_D18006436MFSH\_TPD1.pdf

Dear Catherine,

Please note our insured stated there was "no damage" on both vehicles. Please assist to verify the allegations made by insured driver & check consistency of damages & for any inflated damages. Please acknowledge receipt.

### INSTANCES OF THE ACCIDENT

ON . 28 Aug 2018 @ 0635 hrs I veh A
was driving along the above location I
veh A <sup>at</sup> near 4 lane. Suddenly veh B intent
E-brake I veh A slow down and manage
to stop. there were no damage on both
vehicle. at the point of accident veh A
carry a male, pax he was ok.

Thanks and regards,

Sithara G S  
Motor Claims



**Change of email address**  
[Sithara@msfirstcapital.com.sg](mailto:Sithara@msfirstcapital.com.sg)

MS First Capital Insurance Ltd | 36 Robinson Rd #16-01 City House Singapore 068877 | TEL : 6507 3848 | Fax No. : 6507 3849 |  
Company Regn. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP

#### Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.  
Please refer to [www.msfirstcapital.com.sg](http://www.msfirstcapital.com.sg) for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

**From:** CWS Motor Claims  
**Sent:** Wednesday, August 29, 2018 4:06 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18006436MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CS3/FCI18015809/Gz4d3s2 Date: 26-11-2018 Code: FCI2	
			
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	SHC 7273Y	Veh. Inspected	SKT 3170L
Policy No.		Coverage (\$)	0.00
Claim No.	D18006436MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	29/08/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA AXIO	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	NZE1617104151	Colour	SILVER
Odometer	211288 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/60R15	DUNLOP	6 mm
L/H Front Tyre	195/60R15	DUNLOP	6 mm
R/H Rear Tyre	195/60R15	DUNLOP	6 mm
L/H Rear Tyre	195/60R15	DUNLOP	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
<b>5. General Information</b>			
Accident Date	28/08/2018	Inspect Date / Time	30/08/2018 ( 04:15 PM )
Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$26,000.00			

Report Ref No: CS3/FCI18015809/Gz4d3s2

**Inspected By**

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.