


## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG1723D  
 Ref. No : BUS/05/18/5055  
 Reg. Date : 01/06/2018  
 Vehicle Type : BUS -12M  
 Make : A22MAN  
 Model : MAN  
 Name of Driver : K Ravi Shangar P Krishnan  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 29/05/2018 06:30:00 PM  
 Accident Reported Date / Time : 31/05/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : AIG  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No :  
 Special Instruction to ARC, if any :  
 SG1723D - RIGHT REAR PORTION  
 SLG9947E (TP) - INSURED WITH AIG  
 Prepared Date : 01/06/2018 10:28:24 AM



**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on 'Without Prejudice' basis
- No illegal modification is allowed
- Supplementary parts must be approved and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Tanjil 97495747  
 'WP'  
 27/8/18 @ 1700  
 Resurvey after repair  
 sur @ lkkauto.com  
 01 day

## C

Repair Completed Date / Time :

Arc / Surveyor Sing Off Date

2.00

1.00

27/08/2018 05:05:09 PM

Remarks

Prepared Date : 23/08/2018 03:21:12 PM

## Prepared Date :



**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	795.00	530.00
<b>Total Labour</b>	<b>795.00</b>	<b>530.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	324.00	262.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>324.00</b>	<b>262.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

# Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
F01001-CW273		6010062	REAR TAIL LAMP COVER RH	1	974.70	100.00	0.00	Repair	Repair	No
<b>TOTAL MATERIALS</b>								<b>0.00</b>	<b>0.00</b>	
<b>TOTAL MATERIALS(Discounted)</b>								<b>0.00</b>	<b>0.00</b>	
<b>Added Spare Parts / Material Usage After Surveyor Signed off</b>										

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									