

ASS. REC. BY:

REF: CS3/LPC/18015840/Ggdb Special Instruction:

Surveyor: GAO (Boney)

ASSIGNMENT (Office)

From (Person): Ong H Li

of

LPC

Date/Time:

29/8/18 @ 5:27pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBH 42364

Insured:

SKH 2970P

at Workshop m/s

Speedy Motor

Tel:

6482/5567

of

Blk 10, Amik Ind. park 2A #05-21

Policy No:

Claim No:

18/18/18/vpus/020854

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/8/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time: 3pm 30/8/18

Person Contacted:

Miss. Ten

Vehicle: IN/OUT

Date/Time

Action/Instruction (X) Estimate

FBH 42364 - CS3/MSG18067362/G24bs2 DVA: 1/3/18

SKH 2970P-X

03/10/18

Submit PRS.

08/11/13 wof
ASS. REG. BY:

PR3
Xaul

REF: 1PC

ASSIGNMENT

From:

Date:

30/8/18

Estimated Cost:

OP ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBH 4236 U

at Workshop m/s

Speedy motor

of

BLK 10, AMK Ind. park 2A #05-21

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBH 2364

Yr Regn:

- /

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

C.C

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading:

41641

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

90/90-14

R:

100/90-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

METZLER

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

30-08-18

Survey held at

w/s

5:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$3000

repairer didn't provide GIA report.

RECEIVED 04 OCT 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) 09/10 11:55

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

150

Transportation:

S + RS, SI

Photos

Others

TOTAL

150

Report Format :

PR3

Lump Sum / I.B.I. (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC18015840/Gqd3

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 30-08-2018



Code : LPC2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKH 2970P	Veh. Inspected	FBH 4236U
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020854	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	30/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/08/2018	Inspection Date	30/08/2018
Survey held at	SPEEDY MOTOR CYCLE SERVICE CENTRE BLK 10 ANG MO KIO IND.PARK 2A #05-21 SINGAPORE 568047		

5a. Remarks

<p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.</p> <p>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.</p> <p>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p>
--

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 29 August 2018 5:27 PM
To: Tan Mei Ling; assignments@lkkauto.com; Catherine Chong (LKK Auto)
Cc: MT_Claim_SG
Subject: RE: NOTICE OF ACCIDENT - FBH4236U Our Ref: 18/18/18/VP05/020854 Accident involving SKH2970P and FBH4236U on 23/8/2018

Without Prejudice

Dear Mei Ling

We are not agreeable to your list of surveyors and we shall appoint our surveyor to conduct the survey. Please let us have the details of your client's workshop.

Dear Catherine/Nivitha

Please arrange TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: meilinyu@gmail.com [mailto:meilinyu@gmail.com] **On Behalf Of** Tan Mei Ling
Sent: Wednesday, 29 August, 2018 5:23 PM
To: ONG LI LI
Cc: MT_Claim_SG
Subject: Re: NOTICE OF ACCIDENT - FBH4236U Our Ref: 18/18/18/VP05/020854 Accident involving SKH2970P and FBH4236U on 23/8/2018

Dear Sirs

We refer to your email of even date.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

- 1) **UNITED Appraisal And Management Pte Ltd**
- 2) **SK Auto Consultants**
- 3) **Chartered Auto Assessors**
- 4) **LCW APPRAISER PTE LTD**
- 5) **Sincere Appraisal Services**
- 6) **Pal's Appraisal Pte Ltd**
- 7) **Mc-Coy Appraiser Pte Ltd**
- 8) **CM Automotive Consultancy**

Please be informed that if the above is not agreeable by you, our client's motor vehicle is available for pre-repair inspection at the under-stated workshop:-

Speedy Motor Cycle Service Centre

Blk 10 Ang Mo Kio Industrial Park 2A

#05-21 Singapore 568047

Person In-Charge: Mr Lim Sam Hee at Tel: 6481 5567 / 9388 6867

Fax No. 6482 5567

*Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.

On Wed, Aug 29, 2018 at 3:54 PM, ONG LI LI <long@lonpac.com> wrote:

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: meilinyu@gmail.com [mailto:meilinyu@gmail.com] **On Behalf Of** Tan Mei Ling

Sent: Wednesday, 29 August, 2018 3:44 PM

To: MT_Claim_SG

Subject: NOTICE OF ACCIDENT - FBH4236U

Dear Sirs

Please see attached.

--

Regards

Tan Mei Ling

Sent for and on behalf of

JusEquity Law Corporation
Advocates & Solicitors

Commissioner For Oaths

171 Chin Swee Road #02-06 CES Centre Singapore 169877

☎ : (65) 6536 9339 | DID : (65) 6506 0945

📠 : (65) 6536 5368

✉ : ml_tan@juseq.com.sg

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

--

Regards

Tan Mei Ling

Sent for and on behalf of

JusEquity Law Corporation
Advocates & Solicitors

Commissioner For Oaths

171 Chin Swee Road #02-06 CES Centre Singapore 169877

☎ : (65) 6536 9339 | DID : (65) 6506 0945

📠 : (65) 6536 5368

✉ : ml_tan@juseq.com.sg

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC18015840/Gqd3e2		
300 BEACH ROAD		Date: 11-10-2018		
#17-04/07 THE CONCOURSESINGAPORE 199555				
		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SKH 2970P	Veh. Inspected	FBH 4236U	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020854	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	29/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour	BLACK	
Odometer	41641 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	90/90-14	METZELER	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	100/90-14	METZELER	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
5. General Information				
Accident Date	23/08/2018	Inspect Date / Time	30/08/2018 (05:30 PM)	
Survey held at	SPEEDY MOTOR CYCLE SERVICE CENTRE BLK 10 ANG MO KIO IND PARK 2A #05-21 SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC18015840/Gqd3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.