

23/03/2007

ASS. REC. BY:

REF: CS/AIG/18015876/Ggd302

Special Instruction:

Surveyor:  
Mehmen

GO  
Mithoo Singh

ASSIGNMENT (Office)

From (Person):

of

AIG

Date/Time:

30/8/18 @ 3:05pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBK 9964

Insured:

GB F9547A

4th Tet

at Workshop m/s

Taeyhoun Motor

Tel:

678 31948/8113 9137

of

Blk 9004, Impines st - 93 # 01-108

Policy No:

999994951

Claim No:

108240 431559

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

28/08/2018

31/08/2018

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

3:34pm @ 30/8/18

Person Contacted:

Amir

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

FBK 9964-X

GBF 9547-X

007/1/13 wef  
ASS. REC. BY:

*Yarl*

REF: **ALG**

**ASSIGNMENT**

(-2021)

From: Date: **31/08/2018**

Veh No: **FBK 996U** Yr Regn: **17 AUG 2001**

Estimated Cost

Type: **M** Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OP  WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: **FBK 996U**  
at Workshop m/s: **Tachyon Motor**  
of **Blk 9004, Tampines St 93 #01-108**

Make: **Ducati 996 PS** c.c. **996**  
Colour: **Red** A/C: **Insured / Std / NI / NA**  
Sp. Reading: **40216** T/Radio: **Insured / Std / NI / NA**

Insured:

Eng/No:

Policy No.

C/No: **ZPM1PB9VXY-B003179**

Claims No.

Gen. Cond: **Good** / Fair / Poor / Burnt

Sum Insured: Excess:

Steering: **In** Good / Jammed / Leaked / Burnt or

(Client's Record)

Brake: **In** Good / Jammed / Leaked / Burnt or


Make of Veh: **Amir@67831948**

Modi: **M** / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: **120/70 2R17**  
R: **180/55 2R17**

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / **MIC** / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value: **\$7000**

Front: Rear

IDAC Accident Report: Consistent?: Yes or No

R/Bal. **5** mm R/Bal. **5** mm

GIA / PR Seen: Consistent?: Yes or No

L/Bal. mm L/Bal. mm

Est. Repairs: **3** days Res.: Yes or No

D.O.A. D.O.I. **31-08-18**

Lum Sum: **20** % 3 Val.: Yes or No

Survey held at **w/s 5pm**

CA / REV / REP. / 24 HRS **(up)**

Des. of Damages: **Frt** / Rear / **O/S** / **N/S** / U/C / Rooftop or

Date: Person Contacted: Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<del>AMV: \$6000 - \$7000</del>
	Final: <b>\$6200</b> with Tak. (Led \$19298.35, 76%)
	* MV: \$7K (est); LIA: \$6677; NV: \$6373

RECEIVED 12 DEC 2018

Date/Time, File Pass to?  : Preli. Report

Days Of Repair: **3**

1) **12/12/18**  : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:  : Site Insp (\$ )

Survey Fee: **250**

Report Format: **MUR-9P**

Lump Sum / I.B. (\$ **6200** )

: Interview (\$ )

Transportation:

: Tech. Invs (\$ )

S + RS, SI

: Weekend (\$ )

Photos

Others

TOTAL

**270**

**- Pre repair inspection request - FBK996U VS GBF9547A (OI) DOA 28/08/2018**

From: Mithoosingh, Aashweenjeetkaur  
To: admin-a@lkkauto.com, assignments@lkkauto.com  
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Azlan, Syazairdina, Chan, Yoke Shi  
Sent: 30/8/2018 3:05:38 PM  
Attachments:  tmpB31B.TIF

Hi,

Please refer to the enclosed request from CATHERINE LIM LLC.

Claim no : 10824043155G003  
Case Owner : JACLYN MANIAM KESAVAL

If you have any queries/concerns, please let us know.  
Kindly assist to assign Xing Guo Qiang as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)  
AIG  
Express Claims Adjuster II  
SG Claims Operations | AIG Shared Services

---

**From:** info@catherinelimllc.com [mailto:info@catherinelimllc.com]  
**Sent:** Thursday, August 30, 2018 2:33 PM  
**To:** Mithoosingh, Aashweenjeetkaur  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi; info@catherinelimllc.com  
**Subject:** RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBF9547A AND FBK996U ON 28/08/2018

Dear Sir (Without Prejudice)

We refer to your email.

Our client agrees to Lkk xing guo qiang . Please arrange.

Regards

Sally Goh

For Catherine Lim LLC

---

**From:** Mithoosingh, Aashweenjeetkaur  
**Sent:** Thu, 30 Aug 2018 04:16:54 +0000  
**To:** Catherine Lim LLC  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Azlan, Syazairdina, Chan, Yoke Shi  
**Subject:** - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBF9547A AND FBK996U ON 28/08/2018

Without Prejudice

Your Reference : CL/180883/T/TYM.sg  
Our Reference : 10824043155G003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services

EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Aashweenjeet Kaur (Aashween)  
AIG  
Express Claims Adjuster II  
SG Claims Operations | AIG Shared Services

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# CATHERINE LIM LLC

林 林  
ADVOCATES & SOLICITORS  
梁 梁  
NOTARY PUBLIC - 公证官  
玲 玲  
COMMISSIONER FOR OATHS - 宣誓官  
律 律  
CATHERINE C.L.LIM  
即 即  
DIRECTOR  
LL.B (HONS) SINGAPORE-法律系-律师  
M.B.A. (BUSINESS LAW)-商业系-硕士

Your Ref: GBF 9547A  
Our Ref: CL/180883/T/TYM.sg

30 August 2018

AIG Asia Pacific Insurance Pte Ltd  
AIG Building  
78 Shenton Way  
#07-16  
Singapore 079120  
Attn: Motor Claims Department

Daimler Fleet Management Singapore Pte Ltd  
1 Gateway Drive  
#15-08  
Singapore 608531

Dear Sir

via fax: 6415 3727 & By Hand

CERTIFICATE OF POSTING  
(Please be informed that all supporting documents  
have been forwarded to your insurer.)

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO  
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)  
ACCIDENT INVOLVING FBK 996U / GBF 9547A ON 28.08.2018 ALONG TOA PAYOH LORONG 5**

We are instructed by TAY KHONG DUAN ROLAND to notify you of a road traffic accident involving our client's vehicle No. FBK 996U and vehicle No. GBF 9547A driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue: Tachyon Motor  
Blk 900-4 Tampines Street 95  
#01-108  
Singapore 528838

Tel: 67831948 Fax: 67834013

Yours faithfully,



cc: clients

20 Havelock Road #03-01  
Central Square Singapore 059765  
UEN No. 201310922K

Tel: (65) 6438 5500  
Fax: (65) 6438 0111  
www.catherinelimllc.com  
Email: info@catherinelimllc.com  
CATHERINE LIM LLC is a law corporation  
with limited liability



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18015876/Gqd3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 31-08-2018



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 9547A	Veh. Inspected	FBK 996U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MITHOOSINGH	Assign Date	31/08/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	28/08/2018	Inspection Date	31/08/2018
Survey held at	TACHYON MOTOR PTE LTD BLK 9004 TAMPINES ST.93 #01-108 SINGAPORE 528838		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

# CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS  
 翠 NOTARY PUBLIC - 公证官  
 玲 COMMISSIONER FOR OATHS - 宣誓官  
 律  
 師 CATHERINE C.L.LIM  
 館 DIRECTOR  
 LL.B (HONS) SINGAPORE - 法律系 - 律師  
 M.B.A. (BUSINESS LAW) - 商業系 - 碩士

20 Havelock Road #03-01  
 Central Square Singapore 059765  
 UEN No. 201310922K

Tel: (65) 6438 5500  
 Fax: (65) 6438 0111  
 www.catherinelimllc.com  
 Email: info@catherinelimllc.com  
 CATHERINE LIM LLC is a law corporation  
 with limited liability

Your Ref: GBF 9547A  
 Our Ref: CL/180883/T/TYM.sg

30 August 2018

AIG Asia Pacific Insurance Pte Ltd  
 AIG Building  
 78 Shenton Way  
 #07-16  
 Singapore 079120  
 Attn: Motor Claims Department

via fax: 6415 3727 & By Hand

Daimler Fleet Management Singapore Pte Ltd  
 1 Gateway Drive  
 #15-08  
 Singapore 608531

CERTIFICATE OF POSTING  
 (Please be informed that all supporting documents  
 have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO  
 PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

**ACCIDENT INVOLVING FBK 996U / GBF 9547A ON 28.08.2018 ALONG TOA PAYOH LORONG 5**

We are instructed by TAY KHONG DUAN ROLAND to notify you of a road traffic accident involving our client's vehicle No. FBK 996U and vehicle No. GBF 9547A driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue: Tachyon Motor  
 Blk 9004 Tampines Street 93  
 #01-108  
 Singapore 528838

Tel: 67831948 Fax: 67834013

Yours faithfully




cc: clients

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2092H
Vehicle Details	
Vehicle No.:	FBK996U
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2018
Vehicle Make:	DUCATI
Vehicle Model:	996SPS
Primary Colour:	Red
Manufacturing Year:	2000
Engine No.:	ZDM996W4010780
Chassis No.:	ZDM1PB9VXYB003179
Maximum Power Output:	-
Open Market Value:	\$23,685.00
Original Registration Date:	17 Aug 2001
First Registration Date:	17 Aug 2001
Transfer Count:	5
Actual ARF Paid:	\$3,553.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2021
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$2,400.00
COE Rebate Amount:	\$677.00
<b>Total Rebate Amount:</b>	<b>\$677.00</b>
Message	
<p>Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.</p> <p>This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.</p> <p>This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.</p> <p>For more information, please visit <a href="http://www.nea.gov.sg/mtcincentive">http://www.nea.gov.sg/mtcincentive</a> or contact NEA at 1800-2255-632.</p>	

[Print out the Page](#)

The Most Popular Motorcycle Marke

2000, 996 Biposto

SGD 22,000.00



## Listing details

Reference Number: 90

Registered Year: 2000

**Common**

Number Of Owners: More Than 2

License Class: Class 2

Posted: Jan 01, 2018

## Additional information

Vehicle Style: Sport Bikes

## Direct Owner Details

derricky8789  
Direct Owner since Sep 08, 2013

## Personal Details

Contact Number: 92348789

MOR11811934 / ETHOZ Protect Pte Ltd - Bukit Batok  
 ENTRY DATE & TIME: 29/08/2018 13:45  
 SUBMITTED BY: Suhelmi Rin Suharnan

## SINGAPORE ACCIDENT STATEMENT

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	29/08/2018 13:45
Date Of Accident	28/08/2018 09:45
Exact Location Of Accident	ALONG TOA PAYOH LORONG 5
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	FBK996U
<del>Insurance Policy Number</del>	
Name Of Registered Owner	TAY KHONG DUAN ROLAND
NRIC No	S1612092H
Email Address	TAYROLAND@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96955133
Alternative Phone No	OFFICE-96955133

Manufacturer	DUCATI
Model	996SPS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

<del>Insurance Company</del>	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MC/004570075
Cover Note Number	27/02/2018-16/08/2019

<del>Driver</del>	
Name of Driver	TAY KHONG DUAN ROLAND
NRIC No	S1612092H
Date Of Birth	06/10/1963
Occupation	INDOOR
Date Of Driving Pass	14/11/1988
Driving Experience	29 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96955133
Fax Number	
Contact Number	OFFICE-96955133
EMail Address	TAYROLAND@YAHOO.COM.SG

Address BLK 51 LORONG 6 TOA PAYOH  
16-62  
Postcode 310051  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident COLLISION - MAJOR/MINOR RD  
Weather Conditions CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? YES  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name BOON TECK NEIGHBOURHOOD POLICE POST  
Police Station Address ROAD: BLK 207 TOA PAYOH NORTH, POSTCODE: 310207, COUNTRY: SINGAPORE  
Police Station Contact TEL NO: 1800-2549999 - FAX NO: 63554310  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

REFER TO POLICE REPORT

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY :**

Vehicle Registration Number G8F9547A  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	TAY KHONG DUAN ROLAND
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBK996U
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

 Policyholder's Signature Date & Time:	 Driver's Signature (If driver is not the policyholder) Date & Time:	 Reporting Centre Personnel's Signature Name: NRIC/ID No.:
---	--	--

Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

*Refer to Police report*

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Reporting Only
Claim OD
Claim TP
Claim OD / TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*  
 Policyholder's Signature  
 Date & Time:

*[Signature]*  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

*[Signature]*  
 Reporting Centre Personnel's Signature  
 Name:  
 NRC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180828/2128

Police Station Of Origin:  
Boon Teck NPP  
207 Toa Payoh North #01-1231 SINGAPORE  
310207  
Tel No: 1800-2549999

1 of 3  
Report No. T/20180828/2128

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 28/08/2018 18:10	Vide Report No.:	Station Diary No.: 14
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: TAY KHONG DUAN ROLAND		Address: APT BLK 51 LORONG 6 TOA PAYOH #16-62 SINGAPORE 310051	
ID Type / ID No.: NRIC NO / S1612092H		Contact No.: Home/Office: Mobile: 96955133	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 54	Date of Birth: 06/10/1963	Type of Informant: Rider
Race: Chinese		Language: English	Institution / School Name:
Occupation: Dental technician		Driving Licence Information: Class: Date of Expiry:	

**General Information of the Road**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 28/08/2018 09:45	Type of Location: Straight Road
Location: Along Road 1 LORONG 5 TOA PAYOH  Lorong 5 Toa Payoh towards Lorong 4 Toa Payoh, near to the entrance to blk 49-52 Lorong 5 Toa Payoh				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

FBK996U	Motorcycle	DUCATI	999SPS	Red	Slightly Damaged	0
GBF9547A	Van				Damaged	0

**Details of Vehicle Involved**

Vehicle No.:	Insurance Co.:
--------------	----------------

## POLICE REPORT Pg. 2



**SINGAPORE  
POLICE FORCE**



T/20180828/2128

Police Station Of Origin:  
Boon Teck NPP  
207 Toa Payoh North #01-1231 SINGAPORE  
310207  
Tel No: 1800-2549999

2 of 3

Report No. T/20180828/2128

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Policy No.	Effective Date	Expiry Date
FBK996U	DIRECT ASIA INSURANCE (SINGAPORE) PTE, LTD.	MC/00457075	27/02/2018	16/08/2019

Details of Pedestrian Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Riders			
Name	TAY KHONG DUAN ROLAND	ID No.	S1612092H
Related Vehicle	FBK996U (Motorcycle)	Contact No.	96955133
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	28/08/2018	Date Discharge	28/08/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 28/08/2018 at about 0945hrs, I was driving my vehicle (FBK996U) along lorong 5 Toa Payoh, towards the direction of Lorong 4 Toa Payoh. While riding my bike, I notice another vehicle (GBF9547A) from the opposite direction, intending to make a right turn, into the carpark of blk 49-52.

I wish to state that I have the right of way as I am moving straight and the said vehicle was suppose to make sure that no oncoming vehicles before taking the right turn, however the said vehicle just made the turn without checking. Due to this, I was not able to brake my vehicle in time, as such the front of vehicle collided with the front left of the said van.

I wish to further informed that I was conveyed to TTSH and police had attended to my scene. I was given 3 days of MC.

POLICE REPORT Pg. 3



SINGAPORE  
POLICE FORCE



T/20180828/2128

Police Station Of Origin:  
Boon Teck NPP  
207 Toa Payoh North #01-1231 SINGAPORE  
310207  
Tel No: 1800-2549999

3 of 3

Report No. T/20180828/2128

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report  
E/  
Sgt 2 ADAM GOH AIK YONG

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
28/08/2018 18:10

Officer In Charge Of Case:  
TP / GIT /  
Sgt 3 RASHIDAH BINTE AZMAN  
Contact No.: 65474885

Classification Of Case:

Authentication Stamp  
NP168

SINGAPORE  
POLICE FORCE  
SN 062  
SIGNATURE



TACHYON MOTOR PTE LTD  
 Blk 9004 Tampines St 93  
 #01-108 Singapore 528838  
 Tel:67831948

Email: tyt\_tak@hotmail.com

**ASSESSMENT FOR REPAIR : FBK996U**

S/N	Description	Qty	Quotation
1	Top Cowling, Red <i>CPA</i>	1	\$1,725.00 /
2	Windshield <i>cut</i>	1	\$489.00 /
3	Screw and Nut Kit, Windshield <i>ABC</i>	9	\$270.00 /
4	Right Mirror <i>cut</i>	1	\$349.50 /
5	Front Brake Lever <i>cut</i>	1	\$363.00 /
6	Right Handlebar <i>BT</i>	1	\$660.00 /
7	Left Handlebar <i>X NN</i>	1	\$660.00 X
8	Headlamp Assy <i>CPA</i>	1	\$1,992.00 /
9	Right Mirror Bracket <i>BT</i>	1	\$198.00 /
10	Left Mirror Bracket <i>X NN</i>	1	\$198.00 X
11	Front Left Signal <i>cut</i>	1	\$64.50 /
12	Front Right Signal <i>cut</i>	1	\$64.50 /
13	Carbon Air Duct R/H <i>cut</i>	1	\$1,414.50 /
14	Carbon air Duct L/H <i>cut</i>	1	\$1,414.50 /
15	Clutch Outer Cover <i>cut</i>	1	\$480.00 /
16	Front Footrest R/H <i>M.S</i>	1	\$165.00 /
17	Carbon Exhaust Muffler <i>100(SN) .cut</i>	1	\$1,450.00 (local repair)
18	Rear Fairing, Red <i>cut</i>	1	\$3,270.00 /
19	Rear Right Signal <i>cut</i>	1	\$64.50 /
20	Carbon Front Mudguard <i>cut</i>	1	\$1,095.00 /
21	Clutch Lever <i>cut</i>	1	\$450.00 /
22	Upper Half Right Fairing, Red	1	\$2,262.00 /
23	Upper Half Left Fairing, Red <i>M.S</i>	1	\$2,262.00 /
24	Lower Half Right Fairing, Red <i>M.S</i>	1	\$1,452.00 /
25	Lower Half Left Fairing, Red <i>M.S</i>	1	\$1,452.00 /
26	Right Footrest Heel Guard <i>cut</i>	1	\$84.00 /
27	Headlamp Bracket <i>BT</i>	1	\$670.50 /
28	Battery <i>cut</i>	1	\$255.00 (20(SN))
29	Carbon Rear Hugger <i>cut</i>	1	\$900.00 /
30	Brake Pedal <i>cut</i>	1	265.00 /
31	Gasket, Air Duct Right <i>ABC</i>	1	\$25.00 /
32	Gasket, Air Duct Left <i>ABC</i>	1	\$25.00 /
33	Meter Holder <i>BR</i>	1	\$550.00 /
34	Meter White Cover <i>X NN</i>	1	492.00 X
			27531.50
LESS 10%			27,714.50
			-2,771.45
			24,943.05
			24659.5
			22193.55



TACHYON MOTOR PTE LTD  
 Blk 9004 Tampines St 93  
 #01-108 Singapore 528838  
 Tel:67831948

Email: tyt\_tak@hotmail.com

ASSESSMENT FOR REPAIR : FBK996U

<u>S/N</u>	<u>Description</u>	<u>Qty</u>	<u>Quotation</u>
	Front Wheel Repair		200.00 40
	Front Wheel Slider	1set	180.00 120
	REAR Wheel Slider	1set	180.00 120
	FORK ALIGNED		180.00 120
	TRANSPORT CHARGES	2 ways	80.00
	LABOUR CHARGES		400.00 200
		<b>TOTAL</b>	<u>26,163.05</u> 25998.35

3 Days.

Lumpsum repair.

After repair photos.

Emo Qiang - 82880282

31/8/18.

*[Signature]*  
12/9/18.

23092.55

2%: 6200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Aug 2018 <a href="#">Edit Reg</a>		30 Aug 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$6,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$6,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by adjuster]</b>							
Insured:	<b>DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.,</b> Co. Reg. No.: 199803778Z								
Main Claimant:	-								
Vehicle Reg. No.:	<b>FBK996U</b>	Date of Loss:	28/08/2018 00:00 - :59 [204 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 1082404315SG</b>	Policy/Cover Note No.:	0999994751 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>GBF9547A</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Tachyon Motor Pte Ltd (HQ)</b> 9004 TAMPINES ST. 93, #01-108, 528838 Tampines - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Kesaval, Jaclyn-M</b> ] Jaclyn-M.Kesaval@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 11/09/2018]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
<ul style="list-style-type: none"> <li>AIG_SG (04/09/2018): <b>Request To Upload TP GIA Report</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b>			<a href="#">View All</a>	<a href="#">Search Tasks</a>					
			<a href="#">Create New Task</a>	<a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBK996U (1082404315SG)  
[GBF9547A]  
TP  
-

Aug 28 2018 12:00AM  
[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]  
Tachyon Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View	View in Browser
<b>Assessment Reports</b>															1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print			
1	04/09/18 13:10	<b>Accident Statement</b> From:SC - Reg. No: GBF9547A, Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.										1	Load HTM			
<b>Photos/Images</b>															3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
2	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
3	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
4	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
5	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
6	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
7	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
8	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
9	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
10	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
11	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
12	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
13	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
14	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
15	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
16	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
17	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
18	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
19	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
20	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
21	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
22	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
23	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
24	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
25	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
26	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
27	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
28	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
29	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
30	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
31	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
32	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		
33	04/12/18 09:30	<b>General View</b>										1	Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
34	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
35	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
36	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
37	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
38	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
39	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
40	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
41	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
42	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
43	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
44	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
45	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
46	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
47	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
48	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
49	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
50	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
51	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
52	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
53	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
54	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
55	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
56	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
57	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
58	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
59	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
60	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
61	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
62	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
63	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
64	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
65	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
66	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
67	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
68	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
69	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
70	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
71	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
72	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
73	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
74	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
75	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
76	04/12/18 09:30	General View		Load JPG <input checked="" type="checkbox"/>
77	04/12/18 09:31	Chassis Number		Load JPG <input checked="" type="checkbox"/>
78	04/12/18 09:31	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	06/12/18 11:50	Singapore Accident Statement		Load PDF <input type="checkbox"/>
2	06/12/18 11:50	Police Report		Load PDF <input type="checkbox"/>

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIG18015876/GQD3E2**Date:** 19/12/2018REFERENCE

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd.** Policy No: 0999994751  
**Claimant Vehicle No :** FBK996U **Insured Vehicle No :** GBF9547A  
Date of Loss: 28/08/2018 Nature of Claim: TP Claim No: 1082404315SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBK996U**  
Make & Model: DUCATI 996SPS, 996cc Engine No: ZDM996W4010780  
Reg. Date: 17/08/2001 (Man. Year: 2000) Chassis No: ZDM1PB9VXYB003179  
Colour: Red Odometer: 40216 km  
Engine Capacity: 996 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R17 Rear Tyre Size: 180/55Z R17  
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	24,778.35	22,248.85	2,529.50	10.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,220.00	680.00	540.00	44.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>25,998.35</b>	<b>22,928.85</b>	<b>3,069.50</b>	<b>11.81</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>25,998.35</b>	<b>6,200.00</b>	<b>19,798.35</b>	<b>76.15</b>

INSPECTION

Date of Assignment: 30/08/2018  
Date Inspected: 31/08/2018 Inspected At: Tachyon Motor Pte Ltd (HQ)  
9004 TAMPINES ST. 93, #01-108  
Singapore 528838  
Estimated Period of Repair: 3.0 days

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$7,000.00(EST)-LTA REIMBURSEMENT VALUE: \$677.00=NETT VALUE: \$6,323.00

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOP COWLING, RED	Cracked	1,725.00 FL	*1,725.00 FL
2	1		*WINDSHIELD	Cut	489.00 FL	*489.00 FL
3	9		*SCREW AND NUT KIT, WINDSHIELD	Necessary	270.00 FL	*270.00 FL
4	1		*RIGHT MIRROR	Cut	349.50 FL	*349.50 FL
5	1		*FRONT BRAKE LEVER	Cut	363.00 FL	*363.00 FL
6	1		*RIGHT HANDLEBAR	Bent	660.00 FL	*660.00 FL
7	1		*LEFT HANDLEBAR	Not Necessary	660.00 FL	*- FL
8	1		*HEADLAMP ASSY	Cracked	1,992.00 FL	*1,992.00 FL
9	1		*RIGHT MIRROR BRACKET	Bent	198.00 FL	*198.00 FL
10	1		*LEFT MIRROR BRACKET	Not Necessary	198.00 FL	*- FL
11	1		*FRONT LEFT SIGNAL	Cut	64.50 FL	*64.50 FL
12	1		*FRONT RIGHT SIGNAL	Cut	64.50 FL	*64.50 FL
13	1		*CARBON AIR DUCT R/H	Cut	1,414.50 FL	*1,414.50 FL
14	1		*CARBON AIR DUCT L/H	Cut	1,414.50 FL	*1,414.50 FL
15	1		*CLUTCH OUTER COVER	Cut	480.00 FL	*480.00 FL
16	1		*FRONT FOOTREST R/H	Missing	165.00 FL	*165.00 FL
17	1		*CARBON EXHAUST MUFFLER	Cut	1,305.00 FS	*100.00 FS
18	1		*REAR FAIRING, RED	Cut	3,270.00 FL	*3,270.00 FL
19	1		*REAR RIGHT SIGNAL	Cut	64.50 FL	*64.50 FL
20	1		*CARBON FRONT MUDGUARD	Cut	1,095.00 FL	*1,095.00 FL
21	1		*CLUTCH LEVER	Cut	450.00 FL	*450.00 FL
22	1		*UPPER HALF LEFT FAIRING, RED	Missing	2,262.00 FL	*2,262.00 FL
23	1		*LOWER HALF RIGHT FAIRING, RED	Missing	1,452.00 FL	*1,452.00 FL
24	1		*LOWER HALF LEFT FAIRING, RED	Missing	1,452.00 FL	*1,452.00 FL
25	1		*RIGHT FOOTREST HEEL GUARD	Cut	84.00 FL	*84.00 FL
26	1		*HEADLAMP BRACKET	Bent	670.50 FL	*670.50 FL
27	1		*BATTERY	Cut	229.50 FS	*120.00 FS
28	1		*CARBON REAR HUGGER	Cut	900.00 FL	*900.00 FL
29	1		*BRAKEPEDAL	Cut	265.00 FL	*265.00 FL
30	1		*GASKET, AIR DUCT RIGHT	Necessary	25.00 FL	*25.00 FL
31	1		*GASKET, AIR DUCT LEFT	Necessary	25.00 FL	*25.00 FL
32	1		*METER HOLDER	Broken	550.00 FL	*550.00 FL
33	1		*METER WHITE COVER	Not Necessary	492.00 FL	*- FL
34	1		*UPPER HALF RIGHT FAIRING, RED	Missing	2,262.00 FL	*2,262.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>27,361.00</b>	<b>24,696.50</b>
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,582.65	2,447.65
<b>Total Parts (\$\$)</b>	<b>24,778.35</b>	<b>22,248.85</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	FRONT WHEEL REPAIR	New	200.00	40.00
2	SET FRONT WHEEL SLIDER	New	180.00	120.00
3	SET REAR WHEEL SLIDER	New	180.00	120.00
4	FORK ALIGNED	New	180.00	120.00
5	TRANSPORT CHARGES	New	80.00	80.00
6	LABOUR CHARGES	New	400.00	200.00
<b>Gross Labour Cost (\$)</b>			<b>1,220.00</b>	<b>680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >