

ASS. REC. BY:

REP CS3/ALG18015878/G24d3ez

Special Instruction:

SURVivor

menmen

From (Person):

Chin Lee Ying

ASSIGNMENT (Office)

of ALG

Date/Time:

30/8/18 12:51pm

Estimated Cost:

Bill to:

OD / (IP) / WS / TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

FBM 90522

Insured:

SLT 4003T

at Workshop m/s

Mitru Auto

Tel:

92341367

of

2 Kelci Bkt Ave 2 # 02-07

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/8/18

CA / REV / REP. / REV 24 HRS

1up

31/8/18 @ Morning

H.O.D. Endorsement:

Date/Time:

3:25pm @ 30/8/18

Person Contacted:

1 dnis

Vehicle

IN / OUT

Date/Time

Action/Instruction (X) Estimate

FBM 90522 -X

SLT 4003T -X

Dismantle: 4/9/2018

After repair: 13/9/2018

08/11/13 wof
ASS. REC. BY:

REF: AIG

ASSIGNMENT

From: Date: 31/08/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FBM 90522

at Workshop m/s Mitra Auto

of 2 Kaki Bkt Ave 2 #02-07

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Idris @ 90341367
Morning

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 1up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: FBM 90522 Yr Regn: Jun / 2000

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda shadow c.c. - 398

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: NC401001002

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size: F: 160/90-19

Rear R: 140/80-15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Vee Rubber (Frt)

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. mm L/Bal. mm

D.O.A. D.O.I. 31-08-18

Survey held at w/s 11:30 AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

~~\$2000~~ \$3000

Repair days \$

RECEIVED 19 SEP 2018

TGUM

18/9/18

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

180

Transportation:

☐ S + RS, ☐ SI

Photos

Others

20

TOTAL

200

Report Format : SAR.

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18015878/Gz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 31-08-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLT 4003T	Veh. Inspected	FBM 9052Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	31/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/08/2018	Inspection Date	31/08/2018
Survey held at	MITRA AUTO TRADING 2 KAKI BUKIT AVE 2 #02-07 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

• - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 30/8/2018 12:51:29 PM
Attachments:  PRI - 0163644765SG003.tif

Hi LKK,

Please assist to survey, bike is in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



Daniel Poon & Co.

Advocates & Solicitors
Commissioners for Oaths

Daniel Poon Choon Kow
LL. B. (Hons), LL.M

133 New Bridge Road
#11-02 Chinatown Point
Singapore 059413
Tel: +65 6227-2469
Fax: +65 6225-2579
Email: law@dpco.com.sg
(UEN: 53130838C)

Our Ref: DP.sl.isk.10629.18.MAT
Your Ref: _____
Please quote our reference number when replying

Date: 29 AUGUST 2018

M/S AIG ASIA PACIFIC INSURANCE PTE. LTD.
AIG BUILDING
78 SHENTON WAY
#08-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPARTMENT

FAX (6835-7416) ONLY

DEAR SIRs,

PRE-REPAIR INSPECTION

YOUR INSURED VEHICLE REGISTRATION NO: SLT 4003T
ACCIDENT ON 23 AUGUST 2018 INVOLVING FBM 9052Z AND SLT 4003T
ALONG KJE TUNNEL TOWARDS AIRPORT ROAD

We are instructed by Sung Hwan Shin to notify you of a road traffic accident on 23rd August 2018 at about 08:00 hrs along KJE tunnel towards Airport Road involving our client's vehicle registration number FBM 9052Z and vehicle registration number SLT 4003T driven by your insured at the material time. A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair inspection of the vehicle, by the attached list of ten (10) surveyor which our client deemed suitable to be appointed.

If the aforesaid is not agreeable, kindly therefore instruct your appointed surveyor for a pre-repair inspection of our client's vehicle at by making a prior appointment with the repairer stated below:-

M/S MITRA AUTO TRADING
2 KAKI BUKIT AUTO HUB AVENUE 2
#02-07,
SINGAPORE 417921
ATTN: IDRIS (9234-1367)

... 2/-

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	FBM9052Z
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	HONDA
Vehicle Model :	NV400DCYJ
Chassis No. :	NC401001002
Propellant :	Petrol
Engine No. :	NC25E7001057
Engine Capacity :	398 cc
Maximum Power Output :	-
Maximum Laden Weight :	-
Unladen Weight :	-
Year Of Manufacture :	2000
Original Registration Date :	29 Jun 2000
Lifespan Expiry Date :	30 Jun 2028
COE Category :	D - Motorcycle
PQP Paid :	\$1,233.00
COE Expiry Date :	28 Jun 2020
Road Tax Expiry Date :	01 Oct 2018
Inspection Due Date :	01 Apr 2019
Intended Transfer Date :	05 Sep 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 01 Oct 2018. You may renew the road tax from 02 Jul 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 01 Oct 2018, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 02 Oct 2018 to 01 Apr 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	83.00	-	83.00
Total Amount Payable :			108.00

Amount Payable (From 02 Oct 2018 to 01 Oct 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	165.00	-	165.00
Total Amount Payable :			190.00

Message

Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.

This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.

This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.

For more information, please visit <http://www.nea.gov.sg/mtcincentive> or contact NEA at 1800-2255-632.

You may print this page for reference.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3122Z
Vehicle Details	
Vehicle No.:	FBM9052Z
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	NV400DCYJ
Primary Colour:	Purple
Manufacturing Year:	2000
Engine No.:	NC25E7001057
Chassis No.:	NC401001002
Maximum Power Output:	-
Open Market Value:	\$9,050.00
Original Registration Date:	29 Jun 2000
First Registration Date:	29 Jun 2000
Transfer Count:	10
Actual ARF Paid:	\$1,358.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jun 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,233.00
COE Rebate Amount:	\$263.00
Total Rebate Amount:	\$263.00
Message	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit http://www.nea.gov.sg/mtcincentive or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 19 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 24/08/2018 09:38
Date Of Accident 23/08/2018 08:00
Exact Location Of Accident KPE TUNNEL TWDS AIRPORT RD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBM9052Z
Insured/Policyholder
Name Of Registered Owner SUNG HWAN SHIN
NRIC No S8573122Z
Email Address S.H.SHINSAMUELL@GMAIL.COM
Mobile Phone No (LOCAL) +65-83288969
Alternative Phone No Office-NOPHONE

Vehicle Particulars

Manufacturer HONDA
Model SHADOW 400
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken

Vehicle Category THIRD PARTY
MOTORCYCLE

Insurance Company

Name of Insurance Company DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy
Policy Number
Cover Note Number
Driver
Name of Driver
NRIC No
Date Of Birth
Occupation
Date Of Driving Pass
Driving Experience
Gender
Mobile Number
Fax Number
Contact Number
EMail Address
Address
Postcode
Was driver an employee of the Insured's Company
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle
Insurance Company of Driver's Own Vehicle

General Information of the Accident
Type Of Accident
Weather Conditions
Road Surface
Other Information
Was any foreign vehicle involved in this accident?
Number of vehicles involved in the accident
Was any body injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?

NO
MC/00454772
08/03/2018 TO 07/03/2019
SUNG HWAN SHIN
S8573122Z
11/07/1985
INDOOR
25/08/2009
8 YEARS AND 11 MONTHS
MALE
(LOCAL) +65-83288969
OFFICE-NOPHONE
S.H.SHINSAMUELL@GMAIL.COM
APT BLK 205 TOA PAYOH NORTH #09-1149
310205
NO
OWNER
-
-
-
-
-
-
COLLISION - MAJOR/MINOR RD
INSIDE THE TUNNEL
DRY
NO
YES
NO
YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLT4003T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

SUNG HWAN SHIN-S8573122Z

Approximate Age

Injuries Sustain

LEFT KNEE PAIN

Injured person in which vehicle?

FBM9052Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud,

Direct Asia
FBN 90522


1/2 10/10/2018 10:10 AM
regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
(ii) for complying with requirements under any regulations, laws or court orders.

 Policyholder's Signature Date & Time: 20/08/18 10:40 am	 Driver's Signature (If driver is not the policyholder) Date & Time: 20/08/18 10:40 am	 Reporting Centre Personnel's Signature Name: Hui NRIC/FIN No.: 26/08/18
--	---	--



Garfield Street, Singapore

Date of accident: 23/8/18 Time: 8 am Location: KPE Tunnel
My Vehicle A: FEM 9052 Z Vehicle B: SLT 4003 T Vehicle C: —
SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Riding along KPE when Car B signal and cut out. Unable to
stop in time and hit his left rear

This document forms part of your contract with us and should be read together with your Policy Schedule and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

Certificate No.		: MC/00454772
Type of Coverage		: Third-Party Fire and Theft Cover
1) Vehicle Registration No.		: FBM90522
Chassis No.		: NC25E7001057
2) Name of Policy Holder		: Shin, Sung Han
3) Effective Date of Commencement of Insurance for the Purpose of the Act		: 08/03/2018
4) Date of Expiry of Insurance		: 07/03/2019
5) Persons or Classes of Persons Entitled to Drive		
(a) The Insured		
(b) A named driver who is driving on the Insured's order or with his permission.		
Provided that the person driving has a valid Motorcycle driving licence to drive in Singapore and is not under suspension or disqualification from driving.		
6) Limitations as to use*		
Use only for private purposes, in accordance with the declared motorcycle usage stated on your Policy Schedule. The policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trials, speed tests, the carriage of goods for payment or for any purpose in connection with the motor trade business.		
*Limitations rendered inoperative by Section 8 of the Act and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under this heading.		
Sum Insured		: Market Value
Policy Excess		: S\$ 600.00
Main driver		: Shin, Sung Han
Important Note: The policy only cover the main driver and the following named driver:		
Ref	Named Driver	Date of Birth
1	pen ko, ethan	01/11/1989
Finance Company / Hire Purchase		

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

Issued on: 27/06/2018

Direct Asia Insurance (Singapore) Pte. Ltd.


Edip Okur
Chief Underwriting Officer

Direct Asia Insurance (Singapore) Pte Ltd
88 South Bridge Road Singapore 058716
www.DirectAsia.com



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Condition (CON)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

FOR MOTORCYCLE

ACTION (AC)

1. Replace (✓) 2. Repair (X) 3. Check (?)
4. Not Consistent (NC)

May 2005

Motorcycle

NAC	INC	Item	CON	AC	Qty
1001	991886	Front Number Plate			
3001	995065	Front Tyre			
3002	995095	Front Rim			
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard			
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy			
3008	991787	Front Fork Inner Tube	BT	✓	2
3009	991789	Front Fork Outer Tube	BT	✓	2
3010	991167	Front Fork Bracket		✓	
3011	991182	Front Fork Oil Seal	NEC	✓	
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp			
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing			
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror			
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp			
3021	992556	Meter Casing			
3022	992553	Meter Assy			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem			
3027	994427	Steering Cone	NEC	✓	
3028	992299	Handle Bar	BT	✓	
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip			
3031	995184	Handle Bar Balancer LH			
3032	992300	Handle Bar Balancer RH			
1252	992179	Fuel Tank	SCR	✓	
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever			
3035	992293	Hand Brake Lever			
3036	991119	Side Fairing			
3037	994220	Side Fairing Top Garnish			
3038	994219	Side Fairing Inner Garnish			
3039	991118	Fairing Shield			
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish			
3042	990538	Center Fairing			
3043	993378	Rear Fairing			
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower			

Vehicle No: FBM 90523

NAC	INC	Item	CON	AC	Qty
1052	995074	Radiator			
1053	992738	Radiator Cowling			
3046	994146	Seat Assy			
3047	990915	Engine Crash Bar			
3048	990928	Engine Guard			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
3049	991144	Foot Brake			
3050	991154	Front Foot Rest			
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	Clutch Engine Cover			
3055	992478	Kick Starter Rubber			
3056	992477	Kick Starter Lever			
3057	991145	Foot Gear Shifter			
3058	993500	Rear Foot Rest			
3059	993501	Rear Foot Rest Bracket			
3060	992581	Exhaust Muffler Heat Shield	SCR	✓	1
3061	991058	Exhaust Muffler Assy	SCR	✓	1
1053	993719	Rear LH Shock Absorber			
1053	993720	Rear RH Shock Absorber			
3062	995065	Rear Tyre			
3063	991200	Rear Rim			
3064	994872	Rear Tyre Rim Spoke			
3065	993474	Rear Fender Wheel Guard			
3066	993443	Rear Fender Mudflap			
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper			
3069	995236	Rear Spocket			
3070	990585	Chain			
3071	990580	Chain Guard			
3072	994530	Swing Arm			
1420	993819	Rear Sub frame			
3073	995245	Rear LH Signal Lamp			
3074	995246	Rear RH Signal Lamp			
3075	995251	Rear Taillamp			
1187	993626	Rear Number Plate			
3076	994192	Side Box			
3077	992927	Rear Box			
3078	992928	Rear Box Bracket			
3079	991328	Emblem			
1136	990247	Sticker			

No of Items: 8

Assessor: _____

ORIGINAL COPY

TGim Lin

18/9/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Aug 2018 Edit Reg		30 Aug 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: SOH ZHAO KUN (SU ZHAOKUN) , ID: S8301234Z									
Main Claimant: -									
Vehicle Reg. No.: FBM9052Z		Date of Loss: 23/08/2018 00:00 - :59 [217 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 0163644765SG		Policy/Cover Note No.: 1700076198 (Comprehensive) Coverage: 27/10/2017 - 26/10/2018							
Vehicle Reg. No. (Insured): SLT4003T		Policy No. (Claimant):							
		Excess:							
Repairer: Mitra Auto Trading (KB) 2 Kaki Bukit Auto Hub, #02-07, 417921 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 11/09/2018]									
Claimant's Solicitor: DANIEL POON & CO - Tel: 62272469									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (04/09/2018): No OI GIA Report (SLT4003T VS FBM9052Z) - AIG_SG (04/09/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBM9052Z (0163644765SG)**
[SLT4003T]

TP

-

Aug 23 2018 12:00AM
[SOH ZHAO KUN (SU ZHAOKUN)]
Mitra Auto Trading

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Assessment Reports															1 per page		☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	04/09/18 11:49	Accident Statement From:OD - Reg. No: SLT4003T, Claimant: SOH ZHAO KUN													Load HTM			
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	04/09/18 10:49	General View													Load JPG	☒		
2	04/09/18 10:49	General View													Load JPG	☒		
3	04/09/18 10:49	General View													Load JPG	☒		
4	04/09/18 10:49	General View													Load JPG	☒		
5	04/09/18 10:49	General View													Load JPG	☒		
6	04/09/18 10:49	General View													Load JPG	☒		
7	04/09/18 10:49	General View													Load JPG	☒		
8	04/09/18 10:49	General View													Load JPG	☒		
9	04/09/18 10:49	General View													Load JPG	☒		
10	04/09/18 10:49	General View													Load JPG	☒		
11	04/09/18 10:49	General View													Load JPG	☒		
12	04/09/18 10:49	General View													Load JPG	☒		
13	04/09/18 10:49	General View													Load JPG	☒		
14	04/09/18 10:49	General View													Load JPG	☒		
15	04/09/18 10:49	General View													Load JPG	☒		
16	04/09/18 10:49	General View													Load JPG	☒		
17	04/09/18 10:49	General View													Load JPG	☒		
18	04/09/18 10:49	General View													Load JPG	☒		
19	04/09/18 10:49	General View													Load JPG	☒		
20	04/09/18 10:49	General View													Load JPG	☒		
21	04/09/18 10:49	General View													Load JPG	☒		
22	04/09/18 10:49	General View													Load JPG	☒		
23	04/09/18 10:49	General View													Load JPG	☒		
24	04/09/18 10:49	General View													Load JPG	☒		
25	04/09/18 10:49	General View													Load JPG	☒		
26	04/09/18 10:49	General View													Load JPG	☒		
27	04/09/18 10:49	General View													Load JPG	☒		
28	04/09/18 10:49	General View													Load JPG	☒		
29	04/09/18 10:49	General View													Load JPG	☒		
30	04/09/18 10:49	General View													Load JPG	☒		
31	04/09/18 10:49	General View													Load JPG	☒		
32	04/09/18 10:49	General View													Load JPG	☒		
33	04/09/18 10:49	General View													Load JPG	☒		

Assessment Reports			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	04/09/18 10:49	General View	 Load JPG	☒
35	04/09/18 10:49	General View	 Load JPG	☒
36	04/09/18 10:49	General View	 Load JPG	☒
37	04/09/18 10:49	General View	 Load JPG	☒
38	04/09/18 10:49	General View	 Load JPG	☒
39	06/09/18 20:45	Engine Compartment	 Load JPG	☒
40	06/09/18 20:45	Engine Compartment	 Load JPG	☒
41	06/09/18 20:45	Engine Compartment	 Load JPG	☒
42	06/09/18 20:45	Engine Compartment	 Load JPG	☒
43	06/09/18 20:45	Engine Compartment	 Load JPG	☒
44	06/09/18 20:45	Engine Compartment	 Load JPG	☒
45	06/09/18 20:45	Engine Compartment	 Load JPG	☒
46	06/09/18 20:45	Engine Compartment	 Load JPG	☒
47	06/09/18 20:45	Engine Compartment	 Load JPG	☒
48	06/09/18 20:45	Engine Compartment	 Load JPG	☒
49	06/09/18 20:45	Engine Compartment	 Load JPG	☒
50	06/09/18 20:45	Engine Compartment	 Load JPG	☒
51	06/09/18 20:45	Engine Compartment	 Load JPG	☒
52	06/09/18 20:45	Engine Compartment	 Load JPG	☒
53	19/09/18 13:48	Photo After Spray	 Load JPG	☒
54	19/09/18 13:48	Photo After Spray	 Load JPG	☒
55	19/09/18 13:48	Photo After Spray	 Load JPG	☒
56	19/09/18 13:48	Photo After Spray	 Load JPG	☒
57	19/09/18 13:48	Photo After Spray	 Load JPG	☒
58	19/09/18 13:48	Photo After Spray	 Load JPG	☒
59	19/09/18 13:48	Photo After Spray	 Load JPG	☒
60	19/09/18 13:48	Photo After Spray	 Load JPG	☒
61	19/09/18 13:48	Photo After Spray	 Load JPG	☒
62	19/09/18 13:48	Photo After Spray	 Load JPG	☒
63	19/09/18 13:48	Photo After Spray	 Load JPG	☒
64	19/09/18 13:48	Photo After Spray	 Load JPG	☒
65	19/09/18 13:48	Photo After Spray	 Load JPG	☒
66	19/09/18 13:48	Photo After Spray	 Load JPG	☒
67	19/09/18 13:48	Photo After Spray	 Load JPG	☒
68	19/09/18 13:48	Photo After Spray	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18015878/GZ4D3E2

Date: 20/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1700076198

Claimant Vehicle No : FBM9052Z

Insured Vehicle No : SLT4003T

Date of Loss: 23/08/2018

Nature of Claim: TP

Claim No: 0163644765SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBM9052Z

Make & Model: HONDA NV400C, 398cc (M)

Engine No: NC25E7001057

Reg. Date: 29/06/2000 (Man. Year: 2000)

Chassis No: NC401001002

Colour: Black

Odometer: 0 km

Engine Capacity: 398 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/90-19

Rear Tyre Size: 140/80-15

Front Left Side: Vee Rubber 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/08/2018

Date Inspected: 31/08/2018 Inspected At:

Mitra Auto Trading (KB)
2 Kaki Bukit Auto Hub, #02-07
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK INNER TUBE	Bent	0.00 F	*- F
2	2		*FRONT FORK OUTER TUBE	Bent	0.00 F	*- F
3	1		*FRONT FORK BRACKET	* Check	0.00 F	*- F
4	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
5	1		*STEERING CONE	Necessary	0.00 F	*- F
6	1		*HANDLE BAR	Bent	0.00 F	*- F
7	1		*FUEL TANK	Scratched	0.00 F	*- F
8	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*- F
9	1		*EXHAUST MUFFLER ASSY	Scratched	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >